

22/03/2002

ASS. REC. BY:

REF: CS/SPF17023170 / Gvb21

Special Instruction:

Surveyor: GU ASSIGNMENT (Office)From (Person): Perry He of SPF Date/Time: 05.12.2017 4:56pm

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: QX 329A Insured: _____
at Workshop m/s Indeco Tel: 8511 4276 | Sunny
of 39 Defu Lane 12 8449 6770

Policy No: _____

Claim No: HOMSPFET016000399

Sum Insured: _____

Excess: _____

D.O.A. _____

Make of Veh: _____
(Client's Record)

H.O.D. Endorsement: _____

CA / REV / REP. / REV 24 HRS

Date/Time: 06.12.2017 9:15am Person Contacted: AnsonVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	Ref: 05.11.2017
	<u>QX 329A - CS/SPF17022189 / Avb</u>	
<u>11/12/17</u>	<u>Email to Perry</u>	
<u>14/12/17</u>	<u>Submit Constructive T/L</u>	

0036C

TOTAL

☐ Weekend (\$)

RECEIVED IN DECEMBER 1964

Survey Department Check List (Case Handler)

Reference No. : CS/SPF17023172/Gvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 14/12/17
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF17023172/Gvb		
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 06-12-2017		
		Code : SPF3		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 329A	
Policy No.	Coverage (\$)		0.00	
Claim No. HOMSPFETQ16000399	Excess (\$)		0.00	
Assign From PERRY HE	Assign Date		05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	Inspection Date		06/12/2017	
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 11 December, 2017 3:25 PM
To: Perry HE (SPF) (Perry_HE@spf.gov.sg)
Cc: Wei Yea LIM (SPF) (LIM_Wei_Yea@spf.gov.sg); Kwee Huat TAN (SPF) (TAN_Kwee_Huat@spf.gov.sg); Kim Pang CHAY (SPF) (CHAY_Kim_Pang@spf.gov.sg)
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A
Attachments: PHOTOS.pdf; QX 329A.xlsx

Dear Perry,

Kindly refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Tuesday, 5 December, 2017 4:56 PM
To: assignments <assignments@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Hi Catherine and Ashley,

Please provide Appraisal Service for the following SPF vehicle at INDECO Engineers.

1) QX329A

Parts:

BONNET
BONNET HINGE RH
BONNET HINGE LH
BONNET LOCK
HEADLAMP RH
HEADLAMP LH

FRT BUMPER
FRT BUMPER RETAINER RH
FRT BUMPER RETAINER LH
FRT BUMPER REINFORCEMENT
FRT BUMPER CLIPS
FRT BUMPER LOWER GRILLE
FRT NUMBER PLATE
FRT BUMPER TOP RUBBER STRIP
FOGLAMP COVER LH
TOYOTA LOGO
FRT SUPPORT PANEL ASSY
CONDENSER
RADIATOR
RADIATOR FAN BLADE
RADIATOR FAN MOTOR
RADIATOR FAN COWLING
ENGINE UNDER COVER RH
ENGINE UNDER COVER LH
ENGINE MOUNTING FRT
ENGINE MOUNTING LH
FRT WINDSCREEN
FRT WINDSCREEN MOULDING
SEALANT
INNER SEAL TAPE
IU STICKER
DASHBOARD
DASHBOARD AIRBAG
STEERING AIRBAG
AIRBAG ECU
SEATBELT RH
SEATBELT LH
LHF DOOR
LHF DOOR HINGE TOP

LHF DOOR HINGE BOTTOM
LHF DOOR BLACK STICKER
LHR DOOR
LHR DOOR HINGE TOP
LHR DOOR HINGE BOTTOM
LHR DOOR BLACK STICKER
LH ROCKER PANEL GARNISH
LHR FENDER
LHR FENDER INNER SHIELD
LHR WHEEL HOUSE
LHR WHEEL HOUSE AIR DUCT
LHR FENDER INNER TRIM
PETROL TANK COVER
PETROL TANK COVER LOCK
PETROL TANK
REAR WINDSCREEN MOULDING
SEALANT
INNER SEAL TAPE
SPEAKER BOARD
SPEAKER BOARD PANEL
PETROL TANK COVER LOCK CABLE
RHF DOOR
RHF DOOR HINGE TOP
RHF DOOR HINGE BOTTOM
RHF DOOR BLACK STICKER
RHR DOOR
RHR DOOR HINGE TOP
RHR DOOR HINGE BOTTOM
RHR DOOR BLACK STICKER
RH ROCKER PANEL GARNISH
RHR FENDER
RHR FENDER INNER SHIELD
RHR WHEEL HOUSE

RHR WHEEL HOUSE AIR DUCT
RHR FENDER INNER TRIM
RHF DOOR PROTECTOR W CHROME
RHR DOOR PROTECTOR W CHROME
RHR DOOR LOCK
RHR DOOR LOCK CATCH
BOOT LID
BOOT HINGE RH
BOOT HINGE LH
LOGO ALTIS
LOGO 1.6
LOGO COROLLA
EMBLEM TOYOTA
BOOT CHROME MOULDING
BOOT REFLECTOR RH
BOOT REFLECTOR LH
BOOT REFLECTOR BACK COVER RH
BOOT REFLECTOR BACK COVER LH
BOOT LOCK
BOOT LOCK CATCH
TAILLAMP RH
TAILLAMP LH
TAILLAMP PANEL RH
TAILLAMP PANEL LH
TAILLAMP LOWER BEAM RH
TAILLAMP LOWER BEAM LH
REAR NUMBER PLATE
REAR NUMBER PLATE LAMP
BOOT OUTER LOCK
BOOT INSULATOR
REAR BUMPER
REAR BUMPER REFLECTOR RH
REAR BUMPER REFLECTOR LH

REAR BUMPER CLIP
REVERSE SENSOR
REAR BUMPER CLIP
REAR BUMPER RETAINER RH (LONG)
REAR BUMPER RETAINER LH (LONG)
REAR BUMPER RETAINER RH (SHORT)
REAR BUMPER RETAINER LH (SHORT)
REAR BUMPER REINFORCEMENT
REAR BUMPER REINFORCEMENT BRACKET RH
REAR BUMPER REINFORCEMENT BRACKET LH
REAR BUMPER SPONGE
REAR END PANEL
REAR END PANEL GARNISH
BOOT WEATHER STRIP
EXHAUST MUFFLER
EXHAUST MUFFLER MOUNTING
CHASSIS INNER SIDE MEMBER RH 57411A
CHASSIS INNER SIDE MEMBER LH 57412A
CHASSIS INNER SUB MEMBER RH 57601
CHASSIS INNER SUB MEMBER LH 57602
CHASSIS OUTER SUB MEMBER RH 57615A
CHASSIS OUTER SUB MEMBER LH 57616A
TRANSPORT HOOK RH 51967E
TRANSPORT HOOK LH 51963D
SUB MEMBER 57605B
SUB MEMBER 57606C
REAR SEAT FRAME LH 71015
REAR SEAT PAD LH 71652S
REAR SEAT SIDE PAD LH 71550A
REAR AXLE ASSY
RHR WHEEL BEARING
LHR WHEEL BEARING
RHR S.ABSORBER

LHR S.SBSORBER
RHR TYRE 195/65/15
LHR TYRE 195/65/15
WHEEL ALIGNMENT

Labour:

TO ALIGN,REPLACE AND RESPRAY BONNET,HINGES
TO REPLACE AND REPSRAY FRT BUMPER
TO REPAIR AND RESPRAY RHF FENDER
TO REPAIR AND RESPRAY LHF FENDER
TO REPLACE AND RESPRAY SUPPORT PANEL
TO REPLACE,CONDENSER,RADIATOR AND TOP UP AC GAS
TO REPLACE AND RESPRAY REINFORCEMENT
TO REPLACE AND RESPRAY LHF DOOR
TO REPLACE AND RESPRAY LHR DOOR
TO REPLACE AND RESPRAY LH ROCKER PANEL GARNISH
TO ALIGN,REPAIR AND RESPRAY LH DOORS FRAME
TO REPLACE AND RESPRAY LHR FENDER
TO REPLACE AND RESPRAY LHF WHEEL HOUSE
TO REPLACE AND RESPRAY BOOT LID
TO REPLACE AND RESPRAY REAR BUMPER
TO REPLACE AND RESPRAY REAR END PANEL
TO ALIGN, REPLACE AND RESPRAY REAR CHASSIS,SUB MEMBERS
TO REPLACE AND RESPRAY RHR WHEEL HOUSE
TO REPLACE AND RESPRAY RHR FENDER
TO REPLACE AND RESPRAY RHR DOOR
TO REPLACE AND RESPRAY RHF DOOR
TO REPLACE AND RESPRAY RH ROCKER PANEL GARNISH
TO REPAIR AND RESPRAY RH DOORS FRAME
TO REMOVE AND REFIX FRT WINDSCREEN
TO REMOVE AND REFIX REAR WINDSCREEN
TO REPLACE REAR AXLE AND UNDERCARRIAGE
TO REMOVE AND REPLACE REAR SEAT FRAME,PAD,COVER

TO REMOVE AND REPLACE PETROL TANK
TO REMOVE AND REFIX ROOF LINING TO ASSIST WORK
TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK
TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK
TO PERFORM 4 WHEEL ALIGNMENT

Thank you.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725

THE HOME TEAM CELEBRATES
NS50



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Catherine Chong (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Tuesday, 5 December, 2017 4:56 PM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Hi Catherine and Ashley,

Please provide Appraisal Service for the following SPF vehicle at INDECO Engineers.

- 1) QX329A

Parts:

BONNET
BONNET HINGE RH
BONNET HINGE LH
BONNET LOCK
HEADLAMP RH
HEADLAMP LH
FRT BUMPER
FRT BUMPER RETAINER RH
FRT BUMPER RETAINER LH
FRT BUMPER REINFORCEMENT
FRT BUMPER CLIPS
FRT BUMPER LOWER GRILLE
FRT NUMBER PLATE
FRT BUMPER TOP RUBBER STRIP
FOGLAMP COVER LH
TOYOTA LOGO
FRT SUPPORT PANEL ASSY
CONDENSER
RADIATOR
RADIATOR FAN BLADE
RADIATOR FAN MOTOR
RADIATOR FAN COWLING

ENGINE UNDER COVER RH
ENGINE UNDER COVER LH
ENGINE MOUNTING FRT
ENGINE MOUNTING LH
FRT WINDSCREEN
FRT WINDSCREEN MOULDING
SEALANT
INNER SEAL TAPE
IU STICKER
DASHBOARD
DASHBOARD AIRBAG
STEERING AIRBAG
AIRBAG ECU
SEATBELT RH
SEATBELT LH
LHF DOOR
LHF DOOR HINGE TOP
LHF DOOR HINGE BOTTOM
LHF DOOR BLACK STICKER
LHR DOOR
LHR DOOR HINGE TOP
LHR DOOR HINGE BOTTOM
LHR DOOR BLACK STICKER
LH ROCKER PANEL GARNISH
LHR FENDER
LHR FENDER INNER SHIELD
LHR WHEEL HOUSE
LHR WHEEL HOUSE AIR DUCT
LHR FENDER INNER TRIM
PETROL TANK COVER
PETROL TANK COVER LOCK
PETROL TANK
REAR WINDSCREEN MOULDING

SEALANT
INNER SEAL TAPE
SPEAKER BOARD
SPEAKER BOARD PANEL
PETROL TANK COVER LOCK CABLE
RHF DOOR
RHF DOOR HINGE TOP
RHF DOOR HINGE BOTTOM
RHF DOOR BLACK STICKER
RHR DOOR
RHR DOOR HINGE TOP
RHR DOOR HINGE BOTTOM
RHR DOOR BLACK STICKER
RH ROCKER PANEL GARNISH
RHR FENDER
RHR FENDER INNER SHIELD
RHR WHEEL HOUSE
RHR WHEEL HOUSE AIR DUCT
RHR FENDER INNER TRIM
RHF DOOR PROTECTOR W CHROME
RHR DOOR PROTECTOR W CHROME
RHR DOOR LOCK
RHR DOOR LOCK CATCH
BOOT LID
BOOT HINGE RH
BOOT HINGE LH
LOGO ALTIS
LOGO 1.6
LOGO COROLLA
EMBLEM TOYOTA
BOOT CHROME MOULDING
BOOT REFLECTOR RH
BOOT REFLECTOR LH

BOOT REFLECTOR BACK COVER RH
BOOT REFLECTOR BACK COVER LH
BOOT LOCK
BOOT LOCK CATCH
TAILLAMP RH
TAILLAMP LH
TAILLAMP PANEL RH
TAILLAMP PANEL LH
TAILLAMP LOWER BEAM RH
TAILLAMP LOWER BEAM LH
REAR NUMBER PLATE
REAR NUMBER PLATE LAMP
BOOT OUTER LOCK
BOOT INSULATOR
REAR BUMPER
REAR BUMPER REFLECTOR RH
REAR BUMPER REFLECTOR LH
REAR BUMPER CLIP
REVERSE SENSOR
REAR BUMPER CLIP
REAR BUMPER RETAINER RH (LONG)
REAR BUMPER RETAINER LH (LONG)
REAR BUMPER RETAINER RH (SHORT)
REAR BUMPER RETAINER LH (SHORT)
REAR BUMPER REINFORCEMENT
REAR BUMPER REINFORCEMENT BRACKET RH
REAR BUMPER REINFORCEMENT BRACKET LH
REAR BUMPER SPONGE
REAR END PANEL
REAR END PANEL GARNISH
BOOT WEATHER STRIP
EXHAUST MUFFLER
EXHAUST MUFFLER MOUNTING

CHASSIS INNER SIDE MEMBER RH 57411A
CHASSIS INNER SIDE MEMBER LH 57412A
CHASSIS INNER SUB MEMBER RH 57601
CHASSIS INNER SUB MEMBER LH 57602
CHASSIS OUTER SUB MEMBER RH 57615A
CHASSIS OUTER SUB MEMBER LH 57616A
TRANSPORT HOOK RH 51967E
TRANSPORT HOOK LH 51963D
SUB MEMBER 57605B
SUB MEMBER 57606C
REAR SEAT FRAME LH 71015
REAR SEAT PAD LH 71652S
REAR SEAT SIDE PAD LH 71550A
REAR AXLE ASSY
RHR WHEEL BEARING
LHR WHEEL BEARING
RHR S.ABSORBER
LHR S.SBSORBER
RHR TYRE 195/65/15
LHR TYRE 195/65/15
WHEEL ALIGNMENT

Labour:

TO ALIGN,REPLACE AND RESPRAY BONNET,HINGES
TO REPLACE AND REPSRAY FRT BUMPER
TO REPAIR AND RESPRAY RHF FENDER
TO REPAIR AND RESPRAY LHF FENDER
TO REPLACE AND RESPRAY SUPPORT PANEL
TO REPLACE,CONDENSER,RADIATOR AND TOP UP AC GAS
TO REPLACE AND RESPRAY REINFORCEMENT
TO REPLACE AND RESPRAY LHF DOOR
TO REPLACE AND RESPRAY LHR DOOR
TO REPLACE AND RESPRAY LH ROCKER PANEL GARNISH

TO ALIGN,REPAIR AND RESPRAY LH DOORS FRAME
TO REPLACE AND RESPRAY LHR FENDER
TO REPLACE AND RESPRAY LHF WHEEL HOUSE
TO REPLACE AND RESPRAY BOOT LID
TO REPLACE AND RESPRAY REAR BUMPER
TO REPLACE AND RESPRAY REAR END PANEL
TO ALIGN, REPLACE AND RESPRAY REAR CHASSIS,SUB MEMBERS
TO REPLACE AND RESPRAY RHR WHEEL HOUSE
TO REPLACE AND RESPRAY RHR FENDER
TO REPLACE AND RESPRAY RHR DOOR
TO REPLACE AND RESPRAY RHF DOOR
TO REPLACE AND RESPRAY RH ROCKER PANEL GARNISH
TO REPAIR AND RESPRAY RH DOORS FRAME
TO REMOVE AND REFIX FRT WINDSCREEN
TO REMOVE AND REFIX REAR WINDSCREEN
TO REPLACE REAR AXLE AND UNDERCARRIAGE
TO REMOVE AND REPLACE REAR SEAT FRAME,PAD,COVER
TO REMOVE AND REPLACE PETROL TANK
TO REMOVE AND REFIX ROOF LINING TO ASSIST WORK
TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK
TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK
TO PERFORM 4 WHEEL ALIGNMENT

Thank you.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725

THE HOME TEAM CELEBRATES
NS50



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Government
Owner ID	0036C

Vehicle Details

Vehicle No.	QX329A
Vehicle to be Exported	No
Intended De-registration Date	07 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA ALTIS 1.6 AUTO
Primary Colour	White
Manufacturing Year	2008
Engine No.	3ZZ4770727
Chassis No.	MR053ZEE106109694
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$16,777.00
Original Registration Date	26 Sep 2008
First Registration Date	26 Sep 2008
Transfer Count	0
Actual ARF Paid	\$0.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	25 Sep 2018
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Rebate Amount	\$0.00
Total Rebate Amount	\$0.00

The information contained herein is correct as at 07 Dec 2017

OK



ACCIDENT/DAMAGE REPAIR AND AD HOC WORKS REQUEST FORM

Vehicle No	81 3294	Division/Unit	TP
Vehicle Type (e.g. FRC, minibus)	m/car Toyota	Date	5/11/17
Vehicle Make & Model	A/H3	Mileage (km)	336,200 km

Description	Pls tick	Police Report No & Date of Accident (If applicable)
NP168 (Accident involve 3 rd Party)	☒	NP168 T/2017/103/2024
NP168 (Accident do not involve 3 rd Party)	☐	
NP299 Discovered Damage	☐	
NP299 Vandalism	☐	
Ad hoc, pls specify		

Description of affected area/required works (e.g. dented, cracked, grazed etc)




- ① Rear portion badly damaged and dented
- ② Right portion / front and rear door dented
- ③ front portion badly damaged / dented

Rear portion
badly dented

Pls mark affected area with X



④ to do alignment
check
req



Rank/Name

Asst Lian AL Chuan

Signature



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:


CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	TP
VEH NO :	QX329A	FRC	REPAIR TYPE:	ACCIDENT
VEH MAKE/MODEL:	TOYOTA ALTIS	Mileage:		

Reference No.
MHA/SPF/2017/11-0029

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	BONNET / <i>huc</i>	210.00	1	18%	247.80	247.80
1.2	BONNET HINGE RH / <i>huc</i>	20.00	1	18%	23.60	23.60
1.3	BONNET HINGE LH / <i>huc</i>	20.00	1	18%	23.60	23.60
1.4	BONNET LOCK / <i>huc</i>	40.00	1	18%	47.20	47.20
1.5	HEADLAMP RH / <i>huc</i>	130.00	1	18%	153.40	153.40
1.6	HEADLAMP LH / <i>huc</i>	130.00	1	18%	153.40	153.40
1.7	FRT BUMPER / <i>huc</i>	160.00	1	18%	188.80	188.80
1.8	FRT BUMPER RETAINER RH / <i>huc</i>	20.00	1	18%	23.60	23.60
1.9	FRT BUMPER RETAINER LH / <i>huc</i>	20.00	1	18%	23.60	23.60
1.10	FRT BUMPER REINFORCEMENT / <i>huc</i>	115.00	1	18%	135.70	135.70
1.11	FRT BUMPER CLIPS / <i>huc</i>	1.00	10	18%	1.18	11.80
1.12	FRT BUMPER LOWER GRILLE / <i>huc</i>	30.00	1	18%	35.40	35.40
1.13	FRT NUMBER PLATE / <i>huc</i>	30.00	1	18%	35.40	35.40
1.14	FRT BUMPER TOP RUBBER STRIP / <i>huc</i>	22.00	1	18%	25.96	25.96
1.15	FOGLAMP COVER LH / <i>huc</i>	22.00	1	18%	25.96	25.96
1.16	TOYOTA LOGO / <i>huc</i>	25.00	1	18%	29.50	29.50
1.17	FRT SUPPORT PANEL ASSY / <i>huc</i>	180.00	1	18%	212.40	212.40
1.18	CONDENSER / <i>huc</i>	250.00	1	18%	295.00	295.00
1.19	RADIATOR / <i>huc</i>	380.00	1	18%	448.40	448.40
1.20	RADIATOR FAN BLADE / <i>huc</i>	45.00	1	18%	53.10	53.10
1.21	RADIATOR FAN MOTOR / <i>huc</i>	100.00	1	18%	118.00	118.00
1.22	RADIATOR FAN COWLING / <i>huc</i>	68.00	1	18%	80.24	80.24
1.23	ENGINE UNDER COVER RH / <i>huc</i>	60.00	1	18%	70.80	70.80
1.24	ENGINE UNDER COVER LH / <i>huc</i>	50.00	1	18%	59.00	59.00
1.25	ENGINE MOUNTING FRT / <i>huc</i>	65.00	1	18%	76.70	76.70
1.26	ENGINE MOUNTING LH / <i>huc</i>	70.00	1	18%	82.60	82.60
1.27	FRT WINDSCREEN / <i>huc</i>	350.00	1	18%	413.00	413.00
1.28	FRT WINDSCREEN MOULDING / <i>huc</i>	40.00	1	18%	47.20	47.20
1.29	SEALANT / <i>huc</i>	20.00	2	18%	23.60	47.20
1.30	INNER SEAL TAPE / <i>huc</i>	30.00	1	18%	35.40	35.40
1.31	IU STICKER / <i>huc</i>	5.00	1	18%	5.90	5.90
1.32	DASHBOARD / <i>huc</i>	300.00	1	18%	354.00	354.00
1.33	DASHBOARD AIRBAG / <i>huc</i>	550.00	1	18%	649.00	649.00
1.34	STEERING AIRBAG / <i>huc</i>	500.00	1	18%	590.00	590.00
1.35	AIRBAG ECU / <i>huc</i>	330.00	1	18%	389.40	389.40
1.36	SEATBELT RH / <i>huc</i>	180.00	1	18%	212.40	212.40
1.37	SEATBELT LH / <i>huc</i>	180.00	1	18%	212.40	212.40
1.38	LHF DOOR / <i>huc</i>	380.00	1	18%	448.40	448.40
1.39	LHF DOOR HINGE TOP / <i>huc</i>	30.00	1	18%	35.40	35.40
1.40	LHF DOOR HINGE BOTTOM / <i>huc</i>	30.00	1	18%	35.40	35.40
1.41	LHF DOOR BLACK STICKER / <i>huc</i>	22.00	1	18%	25.96	25.96
1.42	LHR DOOR / <i>huc</i>	330.00	1	18%	389.40	389.40
1.43	LHR DOOR HINGE TOP / <i>huc</i>	30.00	1	18%	35.40	35.40
1.44	LHR DOOR HINGE BOTTOM / <i>huc</i>	30.00	1	18%	35.40	35.40
1.45	LHR DOOR BLACK STICKER / <i>huc</i>	22.00	1	18%	25.96	25.96
1.46	LH ROCKER PANEL GARNISH / <i>huc</i>	240.00	1	18%	283.20	283.20
1.47	LHR FENDER / <i>huc</i>	330.00	1	18%	389.40	389.40
1.48	LHR FENDER INNER SHIELD / <i>huc</i>	22.00	1	18%	25.96	25.96
1.49	LHR WHEEL HOUSE / <i>huc</i>	230.00	1	18%	271.40	271.40
1.50	LHR WHEEL HOUSE AIR DUCT / <i>huc</i>	45.00	1	18%	53.10	53.10
1.51	LHR FENDER INNER TRIM / <i>huc</i>	130.00	1	18%	153.40	153.40
1.52	PETROL TANK COVER / <i>huc</i>	35.00	1	18%	41.30	41.30
1.53	PETROL TANK COVER LOCK / <i>huc</i>	10.00	1	18%	11.80	11.80
1.54	PETROL TANK / <i>huc</i>	300.00	1	18%	354.00	354.00
1.55	REAR WINDSCREEN MOULDING / <i>huc</i>	40.00	1	18%	47.20	47.20
1.56	SEALANT / <i>huc</i>	20.00	2	18%	23.60	47.20
1.57	INNER SEAL TAPE / <i>huc</i>	30.00	1	18%	35.40	35.40
1.58	SPEAKER BOARD / <i>huc</i>	400.00	1	18%	472.00	472.00
1.59	SPEAKER BOARD PANEL / <i>huc</i>	350.00	1	18%	413.00	413.00
1.60	PETROL TANK COVER LOCK CABLE / <i>huc</i>	35.00	1	18%	41.30	41.30
1.61	RHF DOOR / <i>huc</i>	380.00	1	18%	448.40	448.40
1.62	RHF DOOR HINGE TOP / <i>huc</i>	30.00	1	18%	35.40	35.40
1.63	RHF DOOR HINGE BOTTOM / <i>huc</i>	30.00	1	18%	35.40	35.40
1.64	RHF DOOR BLACK STICKER / <i>huc</i>	28.00	1	18%	33.04	33.04
1.65	RHR DOOR / <i>huc</i>	380.00	1	18%	448.40	448.40
1.66	RHR DOOR HINGE TOP / <i>huc</i>	30.00	1	18%	35.40	35.40
1.67	RHR DOOR HINGE BOTTOM / <i>huc</i>	30.00	1	18%	35.40	35.40
1.68	RHR DOOR BLACK STICKER / <i>huc</i>	28.00	1	18%	33.04	33.04

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
Scope Of Repairs				
1		53.80	6	322.80
1.1	TO ALIGN, REPLACE AND RESPRAY BONNET, HINGES	53.80	5	269.00
1.2	TO REPLACE AND RESPRAY FRT BUMPER	53.80	4	215.20
1.3	TO REPAIR AND RESPRAY RHF FENDER	53.80	4	215.20
1.4	TO REPAIR AND RESPRAY LHF FENDER	53.80	4	215.20
1.5	TO REPLACE AND RESPRAY SUPPORT PANEL	53.80	2	107.60
1.6	TO REPLACE CONDENSER, RADIATOR AND TOP UP AC GAS	53.80	1	53.80
1.7	TO REPLACE AND RESPRAY REINFORCEMENT	53.80	6	322.80
1.8	TO REPLACE AND RESPRAY LHF DOOR	53.80	6	322.80
1.9	TO REPLACE AND RESPRAY LHR DOOR	53.80	2	107.60
1.10	TO REPLACE AND RESPRAY LH ROCKER PANEL GARNISH	53.80	8	430.40
1.11	TO ALIGN, REPAIR AND RESPRAY LH DOORS FRAME	53.80	8	430.40
1.12	TO REPLACE AND RESPRAY LHR FENDER	53.80	10	538.00
1.13	TO REPLACE AND RESPRAY LHF WHEEL HOUSE	53.80	6	322.80
1.14	TO REPLACE AND RESPRAY BOOT LID	53.80	5	269.00
1.15	TO REPLACE AND RESPRAY REAR BUMPER	53.80	6	322.80
1.16	TO REPLACE AND RESPRAY REAR END PANEL	53.80	30	1614.00
1.17	TO ALIGN, REPLACE AND RESPRAY REAR CHASSIS SUB MEMBERS	53.80	10	538.00
1.18	TO REPLACE AND RESPRAY RHR WHEEL HOUSE	53.80	8	430.40
1.19	TO REPLACE AND RESPRAY RHR FENDER	53.80	6	322.80
1.20	TO REPLACE AND RESPRAY RHR DOOR	53.80	6	322.80
1.21	TO REPLACE AND RESPRAY RHF DOOR	53.80	2	107.60
1.22	TO REPLACE AND RESPRAY RH ROCKER PANEL GARNISH	53.80	8	430.40
1.23	TO REPAIR AND RESPRAY RH DOORS FRAME	53.80	4	215.20
1.24	TO REMOVE AND REFIX FRT WINDSCREEN	53.80	4	215.20
1.25	TO REMOVE AND REFIX REAR WINDSCREEN	53.80	3	161.40
1.26	TO REPLACE REAR AXLE AND UNDERCARRIAGE	53.80	4	215.20
1.27	TO REMOVE AND REPLACE REAR SEAT FRAME, PAD, COVER	53.80	2	107.60
1.28	TO REMOVE AND REPLACE PETROL TANK	53.80	2	107.60
1.29	TO REMOVE AND REFIX ROOF LINING TO ASSIST WORK	53.80	3	161.40
1.30	TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK	53.80	10	538.00
1.31	TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK	53.80	1	53.80
1.32	TO PERFORM 4 WHEEL ALIGNMENT			
Additional Services				
2		22.00		0.00
Labour Total:				\$ 10,006.80
GRAND TOTAL:				\$ 30,788.10

Contractor shall complete the entire repair within **35** working days upon quotation approved date.

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	Gan Hun Tinng	Name:		Name:	
Date:	30/11/17	Date:		Date:	
Sign:		Sign:		Sign:	
					
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					

Not Authorised.

Gue Qing - 888 0282

06/12/17

part by part.

before paint photos.


11/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 December, 2017 3:12 PM
To: 'Perry HE (SPF)'
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Guo Qiang (LKKAUTO); SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Dear Perry,

Will check and revert.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Wednesday, 13 December, 2017 3:08 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Hi Veron,

Pls provide assessment on the following parts as this concerns whether should we proceed on with the repair.

1.122	CHASSIS INNER SIDE MEMBER RH 57411A
1.123	CHASSIS INNER SIDE MEMBER LH 57412A
1.124	CHASSIS INNER SUB MEMBER RH 57601
1.125	CHASSIS INNER SUB MEMBER LH 57602
1.126	CHASSIS OUTER SUB MEMBER RH 57615A
1.127	CHASSIS OUTER SUB MEMBER LH 57616A

Thank you.

Due to chassis member badly damaged.
It's unsafe to repair the vehicle.



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref : HOMSPFETQ16000399

Date: 20th December 2017

Our Ref : CS/SPF17023172/Gvbs2

M/s Automotive Engineering & MGT Divison

Contract Management Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF VEHICLE QX 329A

Instruction was received to inspect the vehicle Reg. No. QX 329A. The inspection was conducted on 06/12/2017 at the premises of M/s INDECO Engineers Pte Ltd, 39 Defu Lane 12 Singapore 539139.

The following vehicle information was recorded:

Registration Number	: QX 329A
Make/Model	: Toyota Corolla Altis
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: MR053ZEE106109694
Engine Capacity	: 1598

The following are our comments:-

- (a) The vehicle sustained damages at the front and rear portion, o/s and n/s body. The undercarriage affected due to collision. (Details see photographs enclosed)

- (b) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989**, that:

no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle.
and we therefore recommend it to be written off as **"Total Loss"**

Vehicle Inspected By:



XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.