



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

General Details

Involving

1 2016 MAZDA 3 1.5 SALOON (SLC7045S)

Date of Loss

26 November 2017

Time of Loss

11.55

Loss Description

SLC7045S (INSD) C/W SJM7480P (TP)

Comment

Workshop Details

Total Rebate Amount

48642

Nett Loss Amount

\$29,358.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

21/03/2018



Days of work completion *



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#
SLC7045S

Registration State
SINGAPORE

Mileage
15832

Purchase Date
dd/mm/yyyy

Registration Date *
24/05/2016

Age of Vehicle
1

CATEGORY	Manufacturing Year
POLICY INFORMATION	2016
ASSESSMENT INFORMATION	2016

CATEGORY	Make
POLICY INFORMATION	MAZDA

CATEGORY Model

POLICY INFORMATION 3 1.5 SALOON

ASSESSMENT INFORMATION MAZDA34-DOOR SEDAN 1.5L SP.6EAT

CATEGORY Type

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY Type of Paint

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY Chassis No

POLICY INFORMATION JM6BM42A8G0334295

ASSESSMENT INFORMATION JM6BM42A8G0334295

CATEGORY Engine No

POLICY INFORMATION P520350038

ASSESSMENT INFORMATION P520350038

CATEGORY Engine Capacity

POLICY INFORMATION

CATEGORYSum Insured

POLICY INFORMATION0

ASSESSMENT INFORMATION0

CATEGORYMarket Value

POLICY INFORMATION0

ASSESSMENT INFORMATION78000

Driver Details

CATEGORYDriver Name

FNOL INFORMATIONLIM LI HIA

POST SURVEY INFORMATION

CATEGORYDate of Birth

FNOL INFORMATION8 April 1961

POST SURVEY INFORMATIONdd/mm/yyyy

CATEGORYAge

FNOL INFORMATION56

POST SURVEY INFORMATION

CATEGORYOccupation

FNOL INFORMATIONUnknown

CATEGORYEducation Qualification

FNOL INFORMATIONOther

POST SURVEY INFORMATION

CATEGORYDriving Experience

FNOL INFORMATION36

POST SURVEY INFORMATION

CATEGORYDriver License #

FNOL INFORMATION

POST SURVEY INFORMATION

CATEGORYLicense Type

FNOL INFORMATION

POST SURVEY INFORMATION

CATEGORYLicense Issue Date

FNOL INFORMATION

POST SURVEY INFORMATION

dd/mm/yyyy

CATEGORYLicense Expiration Date

FNOL INFORMATION

POST SURVEY INFORMATION

dd/mm/yyyy

FNOL INFORMATION

BLK 319 #10-23, 530319, Singapore

POST SURVEY INFORMATION

CATEGORY

Address type

FNOL INFORMATION

Residential

POST SURVEY INFORMATION

CATEGORY

Gender

FNOL INFORMATION

Female

POST SURVEY INFORMATION

CATEGORY

Marital status

FNOL INFORMATION

Single

POST SURVEY INFORMATION

CATEGORY

Identification #

FNOL INFORMATION

S1499652D

POST SURVEY INFORMATION



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Discount%

20

Salvage%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

☐

1

1

BONNET

Damaged

1122.3

20

897.84

Reviewing



2

1

BONNET CATCH

Serviceable

0

0

0

0

0

Deny



3

1

BONNET LOCK

Damaged

211.2

20

168.96

Reviewing



4

2

BONNET HINGE

Serviceable

0

0

0

0

0

Deny



5

2

BONNET STOPPER

Serviceable

0

0

0

0

0

Deny



6

1

BONNET WEATHERSTRIP

Serviceable

0

0

0

0

0

Deny



7

1

FRONT BUMPER

Damaged

1022

20

817.6

Reviewing



8

2

FRONT BUMPER SIDE RETAINER

Necessary

42.3

20

67.68

Reviewing



9

1

FRONT BUMPER TOWING COVER

Damaged

55

20

44

Reviewing



10

1

FRONT BUMPER FOG LAMP RH

Damaged

180

20

144

Reviewing



11

1

FRONT BUMPER FOG LAMP LH

Serviceable

0

0

0

0

0

Deny



12

1

FRONT BUMPER FOGLAMP GARNISH RH

Damaged

89.2

20

71.36

Reviewing



13

1

FRONT BUMPER FOGLAMP GARNISH LH

Serviceable

0

0

0

0

0

Deny



14

1

FRONT BUMPER LOWER GRILLE

Deformed

128.6

20

102.88

Reviewing



15

1

FRONT BUMPER REINFORCEMENT

Bent

522.3

20

417.84

Reviewing



16

1

FRONT BUMPER REINFORCEMENT COVER

Deformed

120.3

20

96.24

Reviewing



17

1

FRONT BUMPER TOP PANEL (BASE)

Damaged

103.2

20

82.56

Reviewing



18

1

FRONT BUMPER TOP PANEL (OUTER)

Damaged

366.9

20

293.52

Reviewing





19

1

ENGINE COVER

Deformed

133.2

20

106.56

Reviewing



20

1

CENTRE GRILLE

Damaged

355.2

20

284.16

Reviewing



21

1

CENTRE GRILLE (LEFT)

Cracked

177.2

20

141.76

Reviewing



22

1

CENTRE GRILLE (RIGHT)

Cracked

177.2

20

141.76

Reviewing



23

1

CENTRE GRILLE (LOGO)

Necessary

62

20

49.6

Reviewing



24

2

HEADLAMP RH

Cracked

1890

20

3024

Reviewing



25

2

FRONT FENDER

Repair

0

0

0

0

0

Deny



26

2

FRONT FENDER INNER COWLING

Serviceable

0

0

0

0

0

Deny



27

1

SUPPORT PANEL

Cracked

630

20

504

Reviewing



28

1

SUPPORT PANEL TOP COVER

Cracked

145

20

116

Reviewing



29

1

HORN

Cracked

80

20

64

Reviewing



30

1

AIR-CON CONDENSER

Damaged

1122

20

897.6

Reviewing



31

1

RADIATOR

Damaged

1125.3

20

900.24

Reviewing



32

1

FRONT BONNET PANEL

Bent

62.3

20

49.84

Reviewing



33

2

FRONT BUMPER TRIANGLE GARNISH

Damaged

52.3

20

83.68

Reviewing



34

1

FRONT BUMPER INNER GARNISH

Deformed

173.8

20

139.04

Reviewing



35

2

FRONT RADIATOR SIDE GARNISH

Deformed

80.9

20

129.44

Reviewing



Labour

Add

Approve

Deny



1

PANEL BEATING, REMOVAL AND REPLACING PARTS

800

0

0

Reviewing



2

TO SPRAY PAINT AFFECTED AREA

800

0

0

Reviewing





3

TUFF COAT

50

0

0

Reviewing



4

WIRING CHECK

30

0

0

Reviewing





5

REMOVE AND REFIX AIRCON CONDENSOR AND REFILL
AIRCON GAS

60

0

0

Reviewing



6

REMOVE AND REFIX RADIATOR AND CONDUCT
PRESSURE TEST

60

0

0

Reviewing





7

TO REFOCUS HEADLAMP BEAM

0

0

0

Deny



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

1

FRONT NUMBER PLATE

Reviewing

50

CRACKED

2

SET FRONT BUMPER CLIP

Reviewing

22

NECESSARY

3

SET FRONT BUMPER TOP PANEL
OUTER CLIP

Reviewing

20

NECESSARY



4

SET CENTRE GRILLE CLIP

Reviewing

20

NECESSARY



5

SET SUPPORT PANEL TOP COVER
CLIPS

Reviewing

20

NECESSARY



6

SET HEADLAMP CLIP

Reviewing

21

NECESSARY



7

FRONT FENDER SEALANT - 2PCS

Deny

0

NOT NECESSARY



8

SET FRONT FENDER INNER
COWLING CLIP

Deny

0

NOT NECESSARY



9

RADIATOR COOLANT

Reviewing

50

NECESSARY



10

DAYS OF REPAIR : 7 DAYS

Reviewing



◀

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount
\$11,039.16

CATEGORY Labour

ESTIMATE \$1,800.00

REVISED AMOUNT \$1,800.00

CATEGORY Spare Parts

ESTIMATE \$9,836.16

REVISED AMOUNT \$9,836.16

CATEGORY Miscellaneous

ESTIMATE \$203.00

REVISED AMOUNT \$203.00

CATEGORY Excess

ESTIMATE -\$800.00

REVISED AMOUNT -\$800.00



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

☐

EDIT



SR NO

1

NAME

FINAL LUMP SUM

ACTION

Reviewing

AMOUNT

9450

COMMENT

REMOVE





Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount
\$8,650.00

CATEGORY	Miscellaneous
ESTIMATE	\$9,450.00
REVISED AMOUNT	\$9,450.00
CATEGORY	Excess
ESTIMATE	-\$800.00
REVISED AMOUNT	-\$800.00

Submit for Review

