

INS. CASE OWNER:

CC

3TP  
HH1702

3190

Fw639

LKK:

IDAC:

Surveyor:

FSC

DOI:

6/12/11

Date / Time:

5/12/11

Registered in Merimen:

6/12/11

Pre-assign / CCU / FTL



Insured Vehicle No. : SH13 8663D

Name of Insured :

Insured Tel No. : HP:

Excess Sec II :S\$

D.O.A: 04/12/11

Is driver the owner? ( YES / NO )

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SHB 8663D

SHL 5678X

SHD 8666R



INSRS:

WSP:

Tel:

Liability:

RMKS:

U1



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans  
CAM

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SHL 5678X - X

SHB 8663D - 46/12/11 01:00:00 / 12/11/11

insured under ntnc. submit independent

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

PIE Tourist (Heavy) Airport  
 10m23 10m23 10m21  
 V Road work  
 A 57c 7066  
 B 5415 3427

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the Police Report
Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim
under your own comprehensive policy. Please check with your policy for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

15

Policyholder's Signature \_\_\_\_\_ Date & Time: \_\_\_\_\_  
 Driver's Signature \_\_\_\_\_ (If driver is not the policyholder)  
 Name: \_\_\_\_\_  
 Reporting Centre Personnel's Signature \_\_\_\_\_  
 Date & Time: \_\_\_\_\_  
 NRIC/PIN No.: \_\_\_\_\_  
 ( ) Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
 ( ) Claim OD/TP at other workshop ( ) \_\_\_\_\_  
 2

ASS. REC. BY:

REF: III /**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

18

days

Res: Yes or No

Lum Sum: \_\_\_\_\_

20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

SHC 5688X

Yr Regn: \_\_\_\_\_

11, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_

Kenworth Canada

c.c.

1995

Colour: \_\_\_\_\_

M. White (R)

A/C: \_\_\_\_\_

Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_

432887

T/Radio: \_\_\_\_\_

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

VF1A BL15AUC 279627Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: Giti215/60R16R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. \_\_\_\_\_

8

mm

R/Bal. \_\_\_\_\_

6

mm

L/Bal. \_\_\_\_\_

8

mm

L/Bal. \_\_\_\_\_

6

mm

D.O.A. \_\_\_\_\_

4/12/17

D.O.I. \_\_\_\_\_

5/12/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/12File pass to Coroner13/12/17Confirm clm \$2950.00 with 18 working days(Ref. # 101509.50  
82%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: \_\_\_\_\_

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \$

Photos

Other

170 + 17405039802079

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

116 x 15 = 174013/12/17



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/12/2017 16:03
Date Of Accident	04/12/2017 00:05
Exact Location Of Accident	AIRPORT BOULEVARD TOWARDS T2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5628X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	RAZALI BIN OTHMAN
NRIC No	S1365080B
Date Of Birth	26/05/1959
Occupation	OUTDOOR
Date Of Driving Pass	09/12/1980
Driving Experience	36 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97517830
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	BLK 925 HOUGANG STREET 91 #03-47
Postcode	530925
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT: T/20171204/2030

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB8663D
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name





Phone Number

Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHD8566R

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address

#### DETAILS OF INJURED PERSON 1

Name RAZALI BIN OTHMAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5628X

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? NO

Address

Postcode



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan #2 Pg. 1



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to police report -

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:





**SINGAPORE  
POLICE FORCE**



T/20171204/2030

Police Station Of Origin:  
Toa Payoh N.P.C  
93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

1 of 4

Report No. T/20171204/2030

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 04/12/2017 11:31		Vide Report No.:		Station Diary No.: 66
<b>Informant's Particulars</b>				
Name of Informant: RAZALI BIN OTHMAN		Address: APT BLK 925 HOUGANG STREET 91 #03-47 SINGAPORE 530925		
ID Type / ID No.: NRIC NO / S1365080B		Contact No.: Home/Office: Mobile: 97517830		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 58	Date of Birth: 26/05/1959	Type of Informant: Driver	
Race: Malay		Language:	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/12/2017 00:05	Type of Location: Straight Road
Location: Along Road 1 AIRPORT BOULEVARD Towards Terminal 2				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Moving Vehicle against Stationary Vehicle			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB8663D	Car				Seriously Damaged	0
SHC5628X	Car				Seriously Damaged	0
SHD8566R	Car				Slightly Damaged	0





## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171204/2030

2 of 4

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20171204/2030

## CONTINUATION OF REPORT

<b>Details of Person Involved:</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver:</b>			
Name	SUMSUDIN BIN AHMAD	ID No.	S01098872
Related Vehicle	SHB8663D (Car)	Contact No.	94287867
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver:</b>			
Name	RAZALI BIN OTHMAN	ID No.	S1365080B
Related Vehicle	SHC5628X (Car)	Contact No.	97517830
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	NIL
<b>Driver:</b>			
Name	SNG JUSTIN	ID No.	S8207416C
Related Vehicle	SHD8566R (Car)	Contact No.	86120057
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 04/12/2017 at about 0005hrs, I was in my vehicle which is a taxi cab (SHC5628X) and was travelling along airport boulevard along the second lane from the right. I was in a line of vehicles waiting to turn into Terminal 2. My vehicle was stationary when another vehicle (SHB8663D) had suddenly collided onto the rear of my vehicle. The impact had thrust my vehicle forward resulting in my vehicle colliding against another vehicle (SHD8566R) which was directly ahead of me. The TP and LTA officers which were at scene had attended to my incident. My vehicle had suffered serious damages to the rear.

I had exchanged particulars with the other drivers. The TP officers had given me an IO In-charge of the





**SINGAPORE  
POLICE FORCE**



T/20171204/2030

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

3 of 4

Report No. T/20171204/2030

CONTINUATION OF REPORT

case IO Esmund Phua (Contact No: 65472077). Vide Report (T/20171204/2005). The driver that had collided onto me was conveyed by ambulance due to chest pains. I had also visited a doctor as I felt some pain and was given 5 days of medical leave. My vehicle does not have an in-car camera but the vehicle behind me had a front in-car camera. I am also lodging this report for insurance purposes.





**SINGAPORE  
POLICE FORCE**



T/20171204/2030

Police Station Of Origin:  
Toa Payoh N.P.C  
93 Toa Payoh Central #01-02 Toa Payoh  
Community Building SINGAPORE 319194  
Tel No: 1800-2519999

4 of 4

Report No. T/20171204/2030

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
E /  
Sgt 2 JOVI BENEDICK TAN WEI MING

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
04/12/2017 11:31

Officer In Charge Of Case:  
TP / GIT /

Classification Of Case:

Contact No.:

SN 168

Authentication Stamp  
NP168



Signature -

Singapore Police Force



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3878K

### Vehicle Details

Vehicle No.	SHC5628X
Vehicle to be Exported	Yes
Intended De-registration Date	04 Dec 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2014
Engine No.	M9R8839C002052
Chassis No.	VF1ABL15AUC279627
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	04 Nov 2014
First Registration Date	04 Nov 2014
Transfer Count	0
Actual ARF Paid	\$12,498.00

### Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 Nov 2022
PARF Rebate Amount	\$9,373.00

### Intended COE Rebate Details

COE Expiry Date	03 Nov 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$51,337.00
COE Rebate Amount	\$31,535.00
<b>Total Rebate Amount</b>	<b>\$40,908.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Dec 2017





## Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	06 Dec 2017 16:55	Cim Veh Model Changed	(205083) RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A).		[A] Lau Shu Pei
2	06 Dec 2017 16:55	Cim Created	Reg No: SHC5628X. Acct Date: 2017/12/04, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)		[A] Lau Shu Pei
3	06 Dec 2017 16:55	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] Lau Shu Pei
4	06 Dec 2017 16:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/15		[A] Lau Shu Pei
5	06 Dec 2017 16:55	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] Lau Shu Pei
6	06 Dec 2017 16:56	Label Added	(30653):Direct Settlement.		[A] Lau Shu Pei
7	06 Dec 2017 16:56	Adj Adjuster Assigned	[None] -> KENNETH KONG		[A] Lau Shu Pei
8	06 Dec 2017 17:11	Adj Rpt Initiated			[A] Lau Shu Pei
9	06 Dec 2017 17:12	Cim Dtl Modified	Claimant's Name: -> -, Claimant's ID: -> -.		[A] Lau Shu Pei
10	06 Dec 2017 17:12	Cim Details Notified			[A] Lau Shu Pei
11	07 Dec 2017 08:33	Cim Cancelled	Cancelled:SHB8663D is not insured under us. SHB8663D is insured by NTUC		[I] Gabriel Wee

## ACTIVITY

No record

## Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1659854	06/12/2017 17:12	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHC5628X		10.70



**TRANS-CAB AUTO SERVICES PTE LTD**

NO. 27 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5628X -****AAD1712-033***Not Authorized  
11 Sep 8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC5628X - JHOW**

VF1ABL15AUC279627

RENAULT

LATITUDE

04.12.2017

**III****PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Pr</i> 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75	X
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68	X
4	1	BUMPER RETAINER FRT LH	\$	<i>Pr</i> 151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	} X
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77	
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21	
12	1	BUMPER BEAM FRT	\$	<i>Pr</i> 914.08	
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61	
14	1	RADAIOR GRILLE	\$	<i>SL</i> 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36	} X
16	1	RADAIOR GRILLE FRAME	\$	<i>SL</i> 1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Pr</i> 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>Pr</i> 89.79	
19	1	FRONT BRACE PANEL	\$	<i>Pr</i> 177.22	
20	1	HORN	\$	<i>SL</i> 314.17	
21	1	HORN BRACKET	\$	<i>Pr</i> 40.45	
22	1	HEADLAMP LH	\$	<i>SL</i> 1,184.43	✓
23	1	HEADLAMP RH	\$	<i>SL</i> 1,184.43	X
24	1	HEADLAMP PANEL FRT LH	\$	<i>Pr</i> 152.15	X
25	1	HEADLAMP PANEL FRT RH	\$	<i>Pr</i> 152.15	X
26	1	BONNET	\$	<i>Pr</i> 1,941.63	X
27	1	BONNET INSULATOR	\$	<i>SL</i> 405.73	X
28	1	BONNET STRUT LH	\$	<i>SL</i> 88.61	X
29	1	BONNET STRUT RH	\$	<i>SL</i> 88.61	X
30	1	BONNET HINGE LH	\$	<i>Pr</i> 348.31	X
31	1	BONNET HINGE RH	\$	<i>Pr</i> 348.31	X
32	1	BONNET LOCK	\$	<i>Pr</i> 305.48	X
33	1	BONNET CABLE	\$	<i>SL</i> 119.19	X
34	1	BONNET CABLE COVER	\$	<i>SL</i> 161.03	X



**TRANS-CAB AUTO SERVICES PTE LTD**
**AAD1712-033**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5628X -**

35	1	BONNET SEAL OUTER	\$	Sin	92.36	X
36	1	FENDER PANEL FRT LH	\$	R	783.83	
37	1	FENDER PANEL FRT RH	\$	R	783.83	
38	1	WHEELARCH FRT LH	\$	Sin	278.84	
39	1	WHEELARCH FRT RH	\$	Sin	278.84	
40	1	FENDER BRACKET LOWER LH	\$	Sin	15.79	
41	1	FENDER BRACKET LOWER RH	\$	Sin	15.79	
42	1	FENDER INSULATOR LH	\$	Sin	130.84	
43	1	FENDER INSULATOR RH	\$	Sin	130.84	
44	1	AIR CLEANER LOWER	\$	Sin	271.26	
45	1	AIR CLEANER HOSE	\$	Sin	76.14	
46	1	AUTO COMPUTER	\$	Sin	5,032.17	
47	1	STEERING PUMP ELECTRIC	\$	Sin	2,306.90	
48	1	A/C CONDENSER	\$	Sin	2,020.37	
49	1	A/C CONDENSER GARNISH LH UPPER	\$	Sin	39.67	
50	1	A/C CONDENSER GARNISH RH UPPER	\$	Sin	39.67	
51	1	A/C CONDENSER GARNISH LH	\$	Sin	58.81	
52	1	A/C CONDENSER GARNISH RH	\$	Sin	59.60	
53	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sin	208.39	
54	1	A/C PIPE CONDENSER TO EXPENSION VALV	\$	Sin	658.72	
55	1	A/C PIPE COMPRESSOR	\$	Sin	334.29	
56	1	A/C PIPE	\$	Sin	658.72	
57	1	A/C COMRPRESSOR	\$	Sin	2,684.61	
58	1	AIR COOLER	\$	Sin	792.60	
59	1	AIR INTERCOOLER HOSE (LONG)	\$	Sin	1,014.13	
60	1	AIR INTERCOOLER HOSE (Short)	\$	Sin	375.14	
61	1	TRANSMISSION COOLER	\$	Sin	1,219.30	
62	1	TRANSMISSION COOLER PAD	\$	Sin	17.96	
63	1	RADIATOR	\$	Sin	1,202.20	
64	2	RADIATOR STUD UPPER	\$	Sin	14.41	
65	2	RADIATOR BUSH UPPER	\$	Sin	50.12	
66	2	RADIATOR MTG LOWER	\$	Sin	55.85	
67	1	RADAITOR FAN COWLING	\$	Sin	820.54	
68	1	RADIATOR FAN MOTOR LH	\$	Sin	967.36	
69	1	RADIATOR FAN MOTOR RH	\$	Sin	1,479.46	
70	1	RADIATOR TANK	\$	Sin	324.62	
71	1	RADIATOR HOSE UPPER	\$	Sin	240.56	
72	1	RADIATOR HOSE LOWER	\$	Sin	491.18	
73	1	RADIATOR TANK HOSE	\$	Sin	61.18	
74	1	BUMPER COVER REAR	\$	Bz	1,108.46	
75	1	BUMPER LOWER REAR	\$	Bz	768.84	
76	1	BUMPER BRACKET CTR REAR	\$	D.1	113.47	



**TRANS-CAB AUTO SERVICES PTE LTD**
**AAD1712-033**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5628X -**

77	1	BUMEP R BRACKET SIDE LH REAR	\$	D/S	135.97	✓
78	1	BUMEP R BRACKET CTR LH REAR	\$	D/S	44.99	✓
79	1	BUMEP R BRACKET SIDE RH REAR	\$	Nelson	135.97	✓
80	1	BUMEP R BRACKET CTR RH REAR	\$	SL	44.99	X
81	1	BUMPER BEAM REAR	\$	Ry	777.52	✓
82	1	BUMPER BEAM BRACKET LH REAR	\$	Ry	225.95	✓
83	1	BUMPER BEAM BRACKET RH REAR	\$	R	225.95	X
84	1	BUMPER REFLECTOR LH	\$	CRM	43.61	✓
85	1	BUMPER REFLECTOR RH	\$	SL	43.61	X
86	1	BOOT REAR	\$	Ry	2,872.68	✓
87	2	BOOT RUBBER PLUG	\$	SL	221.81	X
88	1	BOOT FINISHER	\$	SL	470.06	X
89	1	BOOT SWITCH	\$	SL	168.13	X
90	1	BOOT TRIM BOARD	\$	Nelson	914.87	✓
91	1	BOOT LOCK	\$	RM	202.67	✓
92	1	BOOT LOCK CATCH	\$	R	74.40	X
93	1	BOOT LOCK LINKAGE	\$	SL	34.53	X
94	1	BOOT LOCK LINKAGE HOLDER	\$	SL	154.52	X
95	1	BOOT LOCK CATCH TRIM BOARD	\$	SL	249.24	X
96	1	BOOT WHEATERSTRIP	\$	Nelson	323.05	✓
97	1	BOOT REFLECTOR LAMP LH	\$	CRM	493.35	✓
98	1	BOOT REFLECTOR LAMP RH	\$	CRM	493.35	✓
99	1	BOOT BADGE 'RENAULT'	\$	Ry	225.36	✓
100	1	BOOT BADGE	\$	Ry	225.36	✓
101	1	BOOT STRUT LH	\$	SL	276.08	X
102	1	BOOT STRUT RH	\$	SL	276.08	X
103	1	BOOT HINGE LH	\$	R	367.84	X
104	1	BOOT HINGE RH	\$	R	367.84	X
105	2	LICENCE PLATE LAMP	\$	SL	50.52	X
106	1	WINDSCREEN REAR	\$	SL	1,463.28	X
107	1	WINDSCREEN GARNISH INNER LH	\$	SL	263.74	X
108	1	WINDSCREEN GARNISH INNER RH	\$	SL	263.74	X
109	1	TAILLAMP LH	\$	CRM	552.55	✓
110	1	TAILLAMP PANEL LH	\$	Ry	986.70	✓
111	1	TAILLAMP RH	\$	SL	552.55	X
112	1	TAILLAMP PANEL RH	\$	R	986.70	X
113	1	CHASSIS PANEL REAR LH	\$	Ry	3,766.43	✓
114	1	FENDER PANEL REAR LH	\$	Ry	3,299.13	✓
115	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
116	1	WHEELARCH REAR LH	\$	SL	543.47	X
117	1	WHEELARCH REAR RH	\$	SL	543.47	X
118	1	FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	X





**TRANS-CAB AUTO SERVICES PTE LTD**
**AAD1712-033**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5628X -**

119	1	FENDER PANEL INNER TRIM REAR LH	\$	Reform	671.45	✓
120	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	R	3,039.04	✓
121	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	R	3,039.04	✓
122	1	LOWER ARM REAR LH	\$	Sm	905.99	✓
123	1	KUCKLE ARM REAR LH	\$	Sm	736.67	✓
124	1	ABSORBER REAR LH	\$	Sm	389.75	}
125	1	ABSORBER BOLT REAR LH	\$	Sm	52.10	
126	1	ABSORBER DUST COVER REAR LH	\$	Sm	92.16	
127	1	AIR VENT RH	\$	Sm	97.28	
128	1	REAR AXLE	\$	Sm	4,167.03	
129	1	AXLE ARM ROD	\$	Sm	117.22	}
130	1	AXLE ARM LH	\$	Sm	117.22	
131	1	AXLE ARM RH	\$	Sm	117.22	
132	1	AXLE ARM SHIELD LH	\$	Sm	9.08	
133	1	AXLE ARM SHIELD RH	\$	Sm	9.08	
134	1	AXLE SPRING ARM LH	\$	Sm	376.92	}
135	1	AXLE SPRING ARM RH	\$	Sm	376.92	
136	1	STABILIZER BAR REAR	\$	Sm	604.65	
137	1	STABILIZER LINK REAR LH	\$	Sm	92.36	
138	1	STABILIZER LINK REAR RH	\$	Sm	92.36	
139	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	B/Bu	2,189.88	✓
140	1	SPARE WHEEL PANEL TRIM (Luggage Floor F	\$	Reform	612.21	✓
141	1	SPARE WHEEL PANEL BRACKET LH	\$	R	123.73	✓
142	1	SPARE WHEEL PANEL BRACKET RH	\$	R	121.36	✓
143	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
144	1	OUTER PANEL REAR (End Panel)TRIM	\$	CR	401.02	✓
145	1	EXHAUST REAR	\$	R	7,489.05	}
146	1	EXHAUST CAP REAR	\$	R	230.49	
147	1	EXHAUST MOUNTING REAR	\$	Sm	31.97	
148	1	EXHAUST BRACKET REAR	\$	R	39.86	
149	1	EXHAUST HEAT SHIELD REAR	\$	R	99.06	
150	1	SHIELD - HEAT - TUNNEL	\$	Sm	225.16	}
151	1	FUEL FLAP	\$	Sm	343.57	
152	1	FUEL TANK NECK	\$	Sm	684.77	
153	1	FUEL CAP	\$	Sm	233.02	
154	1	DOOR PANEL REAR LH	\$	R	2,844.66	
155	1	DOOR SEAL REAR LH	\$	Sm	187.08	}
156	1	DOOR PANEL REAR RH	\$	R	2,844.66	
157	1	DOOR SEAL REAR RH	\$	Sm	162.02	

<b>TOTAL</b>	<b>\$</b>	<b>106,336.20</b>
<b>10%</b>	<b>\$</b>	<b>10,633.62</b>
	<b>\$</b>	<b>95,702.58</b>



**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-033**

NO.2'ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5628X -****Specical Nett**

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	nn	52.00	X
2	1SET	BUMPER CLIP FRT	\$	nn	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	}
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
7	1	TOW COVER FRT	\$	sn	14.50	
8	1SET	RADAITOR GRILLE SCREW	\$	nn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
13	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	}
14	1SET	WHEELARCH CLIP FRT RH	\$	nn	29.40	
15	1	CAP HUB LH FRT	\$	sn	35.00	
16	1	RIM LH FRT	\$	sn	385.00	
17	1	TYRE LH FRT	\$	sn	330.00	
18	1	CAP HUB RH FRT	\$	sn	35.00	
19	1	RIM RH FRT	\$	sn	385.00	
20	1	TYRE RH FRT	\$	sn	330.00	
21	1SET	BUMPER RR CLIP	\$	nn	66.00	✓
22	1SET	BUMPER BEAM BOLT	\$	nn	22.22	X
23	1SET	PARKING AID	\$	shot	600.00	✓
24	1	BUMPER BRACKET CLIP CTR REAR	\$	nn	15.00	}
25	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	nn	12.00	
26	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40	
27	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00	
28	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40	
29	1	CAP HUB LH RR	\$	sn	35.00	
30	1	RIM LH RR	\$	sn	385.00	
31	1	TYRE LH RR	\$	sn	330.00	
32	1	CAP HUB RH RR	\$	sn	35.00	
33	1	RIM RH RR	\$	sn	385.00	
34	1	TYRE RH RR	\$	sn	330.00	}
35	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	
36	1	SPARE TYRE	\$	sn	330.00	
37	1SET	BOOT FINISHER CLIP	\$	nn	25.10	
38	1	Rear boots sticker "trans-cab"	\$	nn	30.00	✓
39	1	Rear boots sticker "6555-3333"	\$	nn	30.00	✓
40	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	nn	22.00	X
41	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	nn	22.00	X



**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-033**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5628X -**

42	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X
43	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X
44	2	Rear windscreen sealant	\$	nn	80.00	401n
45	1	Windscreen moulding	\$	nn	100.00	✓
46	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	301n
47	1	EXHAUST MOUNTING REAR	\$	nn	65.50	X
48	1	EXHAUST BRACKET REAR	\$	nn	22.22	X
49	1SET	Front licence plate with holder	\$	nn	80.00	X
50	1SET	Rear licence plate with holder	\$	nn	80.00	X
51	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
52	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X

<b>TOTAL</b>	<b>\$</b>	<b>5,786.92</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>101,489.50</b>

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	8,400.00	2200
Towing Fees.	\$	120.00	50
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Putty and spray painting of the affected	\$	9,000.00	1540
To rust-proofing of the affected areas.	\$	-170.00	120
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	-380.00	100
To check steering geometry and computer wheel alignment	\$	-220.00	60
To transfer of tire, rim and on wheel	\$	nn-170.00	X
To Check Electrical Lighting Concerned.	\$	-170.00	20
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 250
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	-380.00	



**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-033**

NO.2'ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5628X -**

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>Repair</i>	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>✓</i>	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$		380.00	<i>Boi</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	<i>Boi</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>Repair</i>	380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$		170.00	<i>Boi</i>
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$		380.00	<i>1200</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>Boi</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$		280.00	} <i>Boi</i>
To repair and realign rear exhaust pipe.	\$		170.00	
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>nn</i>	380.00	X
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	<i>nn</i>	380.00	X
To drop rear axle assy, remove and renewal of the necessary parts	\$	<i>nn</i>	380.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i>	440.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$		380.00	<i>Boi</i>





**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-033**

NO.2'ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5628X -**

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00 X
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00 X
To replace, refix and top up coolant for	\$	~ 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00 X

<b>TOTAL</b>	<b>\$</b>	<b>22,970.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>124,459.50</b>

&lt; parts by parts &gt; Repair Days

~~30~~ DAYS  
18 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD			Ref : CC3/TP17023190/Kwb3q2	
NO.2 ANG MO KIO STREET 63SINGAPORE 569111			Date : 08-01-2017	
			Code : TP378	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.			Veh. Inspected	SHC 5628X
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	05/12/2017
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279627	Colour	METALLIC WHITE/RED	
Odometer	432887	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	FALKEN	6 mm	
L/H Rear Tyre	215/60 R16	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/12/2017	Inspection Date	05/12/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			18 Working Days	





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 9

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5628X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER FRT	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLW LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	TO REPAIR SEE LABOUR	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	CUT	1,184.43	1,184.43
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-

Report Ref No. CC3/TP17023190/Kwb3q2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	STEERING PUMP ELECTRIC	SERVICEABLE	2,306.90	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALV	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-

Report Ref No. CC3/TP17023190/Kwb3q2







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	BENT	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE LH REAR	DISTORTED	135.97	135.97
1	BUMPER BRACKET CTR LH REAR	DISTORTED	44.99	44.99
1	BUMPER BRACKET SIDE RH REAR	NECESSARY	135.97	135.97
1	BUMPER BRACKET CTR RH REAR	SERVICEABLE	44.99	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BOOT REAR	BENT	2,872.68	2,872.68
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT TRIM BOARD	DEFORMED	914.87	914.87
1	BOOT LOCK	DENTED	202.67	202.67
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
1	BOOT LOCK LINKAGE	SERVICEABLE	34.53	-
1	BOOT LOCK LINKAGE HOLDER	SERVICEABLE	154.52	-
1	BOOT LOCK CATCH TRIM BOARD	SERVICEABLE	249.24	-
1	BOOT WEATHERSTRIP	DENTED / CUT	323.05	323.05

Report Ref No. CC3/TP17023190/Kwb3q2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
1	WINDSCREEN REAR	SERVICEABLE	1,463.28	-
1	WINDSCREEN GARNISH INNER LH	SERVICEABLE	263.74	-
1	WINDSCREEN GARNISH INNER RH	SERVICEABLE	263.74	-
1	TAILLAMP LH	CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	BENT	986.70	986.70
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	CHASSIS PANEL REAR LH	BENT	3,766.43	3,766.43
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL INNER TRIM REAR LH	DEFORMED	671.45	671.45
1	FENDER WHEEL HOUSE PANEL REAR LH	TO REPAIR SEE LABOUR	3,039.04	-
1	FENDER WHEEL HOUSE PANEL REAR RH	TO REPAIR SEE LABOUR	3,039.04	-
1	LOWER RRM REAR LH	SERVICEABLE	905.99	-
1	KNUCKLE ARM REAR LH	SERVICEABLE	736.67	-
1	ABSORBER REAR LH	SERVICEABLE	389.75	-
1	ABSORBER BOLT REAR LH	SERVICEABLE	52.10	-
1	ABSORBER DUST COVER REAR LH	SERVICEABLE	92.16	-
1	AIR VENT RH	SERVICEABLE	97.28	-
1	REAR AXLE	SERVICEABLE	4,167.03	-

Report Ref No. CC3/TP17023190/Kwb3q2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AXLE ARM ROD	SERVICEABLE	117.22	-
1	AXLE ARM LH	SERVICEABLE	117.22	-
1	AXLE ARM RH	SERVICEABLE	117.22	-
1	AXLE ARM SHIELD LH	SERVICEABLE	9.08	-
1	AXLE ARM SHIELD RH	SERVICEABLE	9.08	-
1	AXLE SPRING ARM LH	SERVICEABLE	376.92	-
1	AXLE SPRING ARM RH	SERVICEABLE	376.92	-
1	STABILIZER BAR REAR	SERVICEABLE	604.65	-
1	STABILIZER LINK REAR LH	SERVICEABLE	92.36	-
1	STABILIZER LINK REAR RH	SERVICEABLE	92.36	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL )	BENT / BUCKLED	2,189.88	2,189.88
1	SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL)	DEFORMED	612.21	612.21
1	SPARE WHEEL PANEL BRACKET LH	BENT	123.73	123.73
1	SPARE WHEEL PANEL BRACKET RH	TO REPAIR SEE LABOUR	121.36	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL)TRIM	CRACKED	401.02	401.02
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	EXHAUST MOUNTING REAR	SERVICEABLE	31.97	-
1	EXHAUST BRACKET REAR	TO REPAIR SEE LABOUR	39.86	-
1	EXHAUST HEAT SHIELD REAR	TO REPAIR SEE LABOUR	99.06	-
1	SHIELD -HEAT-TUNNEL	SERVICEABLE	225.16	-
1	FUEL FLAP	SERVICEABLE	343.57	-
1	FUEL TANK NECK	SERVICEABLE	684.77	-
1	FUEL CAP	SERVICEABLE	233.02	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	187.08	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
	LESS 10% DISCOUNT		-10,633.62	-2,577.56
			95,702.57	23,198.04

Report Ref No. CC3/TP17023190/Kwb3q2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>SPECIAL NETT ITEMS</b>			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	29.40	-
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	CAP HUB RH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE RH FRT (SN)	SERVICEABLE	330.00	-
1	SET BUMPER RR CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BEAM BOLT (SN)	SERVICEABLE	22.22	-
1	SET PARKING AID (SN)	SHORTED	600.00	600.00
1	BUMPER BRACKET CLIP CTR REAR (SN)	NOT NECESSARY	15.00	-
1	BUMPER BRACKET SIDE CLIP LH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP LH REAR (SN)	NOT NECESSARY	10.40	-
1	BUMPER BRACKET SIDE CLIP RH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP RH REAR (SN)	NOT NECESSARY	10.40	-
1	CAP HUB LH RR (SN)	SERVICEABLE	35.00	-
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	CAP HUB RH RR (SN)	SERVICEABLE	35.00	-
1	RIM RH RR (SN)	SERVICEABLE	385.00	-
1	TYRE RH RR (SN)	SERVICEABLE	330.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-

Report Ref No. CC3/TP17023190/Kwb3q2







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	25.10	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
1	FENDER PANEL INNER TRIM CLIP REAR RH (SN)	NOT NECESSARY	22.00	-
1	FENDER PANEL INNER TRIM CLIP REAR LH (SN)	NOT NECESSARY	22.00	-
1	SET WHEELARCH CLIP LH RR (SN)	NOT NECESSARY	32.34	-
1	SET WHEELARCH CLIP RH RR (SN)	NOT NECESSARY	32.34	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	65.50	-
1	EXHAUST BRACKET REAR (SN)	SERVICEABLE	22.22	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	SET REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	DOOR STICKER '6555-3333' LH (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER '6555-3333' RH (SN)	NOT NECESSARY	80.00	-
			5,786.92	962.00
	<b>LABOUR</b>			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,FRAME FULL SUPPORT PANEL,FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL,HORN BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,FENDER PANEL FRT LH,FENDER PANEL FRT RH,BUMPER BEAM BRACKET RH REAR, )		8,400.00	2,200.00
	BOOT LOCK CATCH,BOOT HINGE LH,BOOT HINGE RH,TAILLAMP PANEL RH,FENDER PANEL REAR RH,FENDER WHEEL HOUSE PANEL REAR LH,FENDER WHEEL HOUSE PANEL REAR RH,SPARE WHEEL PANEL BRACKET RH,EXHAUST REAR,EXHAUST CAP REAR,EXHAUST BRACKET REAR,EXHAUST HEAT SHIELD REAR,DOOR PANEL REAR LH AND DOOR PANEL REAR RH.)		-	-
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT .	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED .		9,000.00	1,540.00

Report Ref No. CC3/TP17023190/Kwb3q2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. }		380.00	250.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. }		380.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	80.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	REPEATED	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	120.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		280.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }		170.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DROP REAR AXLE ASSY, REMOVE AND RENEWAL OF THE NECESSARY PARTS.	NOT NECESSARY	380.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-

Report Ref No. CC3/TP17023190/Kwb3q2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:9 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DROP DIESEL TANK ,PIPES ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING.		380.00	60.00
	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR CONDENSER .	NOT NECESSARY	380.00	-
	TO REPLACE ,REFIX AND TOP UP COOLANT FOR.	NOT NECESSARY	170.00	-
	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			25,500.00	4,840.00
<b>GRAND TOTAL</b>			<b>126,989.49</b>	<b>29,000.04</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>22,950.00</b>

Report Ref No. CC3/TP17023190/Kwb3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

