

ASS. REC. BY:

REF: CS/FCI17023234/Dgbn Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): WS Eileen Lee

of FCI

Date/Time: 6/12/17 @ 6:08pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJR 5132G

Insured:

SHC 82984

at Workshop m/s

Teamwork Garage

Tel:

6844 2475

of

Blk 53 Ubi Ave 1 # 01-24, 408934

Policy No:

Claim No:

D17 010746 MPST

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/11/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 10:10am @ 7/12/17

Person Contacted:


Chris

Vehicle IN COUP

Date/Time	Action/Instruction (✓) Estimate
	SJR 5132G - NA/EQT 17022129/h4 D.O.A: 17/11/2017
	SHC 82984 - NA/EQT 17022129/h4 D.O.A: 17/11/2017
08/12/17 @ 2:07pm	Revised to MV TR by email.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SSR 5132G Yr Regn: 2009 June
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mitsubishi Lancer C.C. 1584
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: N.A. T/Radio: Insured / Std / NI / NA
 Eng/No: 4G18KC5554
 C/No: 3MYSTC33A9U005606
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / SP / STD A/Rim or
 Tyre Size: F: 195/60 R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Triangle

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 17/11/2017 D.O.I. 08/12/2017
 Survey held at Teamwork Page 4th
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	First cap SHC 8298 U
	MV 20K 20K (EST)
	VIA 9.11K 9101
	HL 10.91K 10899
14/05/18	Invoice 2/5 10,700 - with 8 days 2 v (check 10,586.82, 50%)
RECEIVED 15 MAY 2018	

Date/Time, File Pass to? ☐ : Preli. Report

1) 15/5 10/5/18 ☐ : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$) 10700

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation

S + RS \$

Photos 580

Others

TOTAL 15/5/18

11x15: 165

170+165

50

30+50

146

631



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17/10746
Our Ref: CS/FCI17023234/Dqb

Date: 08 May 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJR 5132G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/07/2017 at the premises of M/s TEAMWORK GARAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ 21,586.82 .
Revised Estimate Amount	: S\$ 13,374.78 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

Nivitha (LKK Auto)

From: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Sent: Wednesday, 6 December, 2017 6:08 PM
To: 'assignments@lkkauto.com'
Cc: Eileen Lee
Subject: OUR REF: D17/10746
Attachments: 20171206151419012.pdf

Importance: High

Dear LKK

Please assist.

Thanks and Regards,
SK Teo
First Capital Insurance Ltd.
Motor Claims Dept

First Capital Insurance Ltd | A FAIRFAX Company
36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C
D: 6507 3848 | F: 6507 3849
email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Rosliza Bte AB Rahman
Sent: Wednesday, December 06, 2017 4:30 PM
To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>
Subject: FW: OUR REF: 1711-47 // YOUR REF: SHC8298U PRE-REPAIR INSPECTION FOR SJR5132G // ACCIDENT INVOLVING SJR5132G & SHC8298U ON 17.11.2017
Importance: High

PRI CTPL

Thank You

Rosliza Ab Rahman
Support Staff / Motor Claims Department / First Capital Insurance Limited / T 6507 3848 / F 6507 3849 / 36 Robinson Road / #16-01 City House / Singapore 068877

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: claims@teamworkgarage.com [<mailto:claims@teamworkgarage.com>]

Sent: Wednesday, December 6, 2017 3:20 PM

To: Motor_Claims <Motor_Claims@first-insurance.com.sg>; Harminder Kaur <harminder@first-insurance.com.sg>;
Rosliza Bte AB Rahman <rosliza@first-insurance.com.sg>

Subject: OUR REF: 1711-47 // YOUR REF: SHC8298U PRE-REPAIR INSPECTION FOR SJR5132G // ACCIDENT
INVOLVING SJR5132G & SHC8298U ON 17.11.2017

Importance: High

WITHOUT PREJUDICE

OUR REF: 1711-47

YOUR REF: SHC8298U

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SJR5132G

ACCIDENT INVOLVING SJR5132G & SHC8298U ON 17.11.2017

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

Please take note: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.

Regards,

Ja

Teamwork Garage Pte Ltd

Blk 53 Ubi Avenue 1

#01-24

Paya Ubi Industrial Park

Singapore 408934

Tel: 6844 2475

Fax: 6844 2474

Season's Greetings
@

Happy New Year



.....
IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.
.....

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 8 May 2018 2:02 PM
To: 'Teo Swee Keong'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: OUR REF: D17/10746
Attachments: CSFCI17023234Dqb.pdf

Dear Mr Teo,

Enclosed herewith preliminary advice of SJR 5132G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 7 December 2017 10:13 AM
To: 'Teo Swee Keong' <TeoSweeKeong@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@first-insurance.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OUR REF: D17/10746

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo Swee Keong [<mailto:TeoSweeKeong@first-insurance.com.sg>]
Sent: Wednesday, 6 December, 2017 6:08 PM
To: 'assignments@lkkauto.com'
Cc: Eileen Lee
Subject: OUR REF: D17/10746
Importance: High

Dear LKK

Please assist.

Thanks and Regards,



Pte Ltd

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

Vehicle number	SHR5132G
Make / Model	MITSUBISHI/LANCER
Chassis number	JMYSTCS3A9U005606
Accident date	08 December 2017
Reference	1711-47

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS				
1	FRONT BUMPER <i>src</i>	688.00	852.00	✓
2	FRONT BUMPER SIDE BEAM <i>src</i>		96.00	✓
1	FRONT BUMPER REINFORCEMENT <i>src</i>		165.60	✓
1	FRONT NUMBER PLATE GARNISH <i>Painted</i>		82.80	✓
1	FRONT BUMPER LOWER LIP <i>HF</i>		653.00	X
1	FRONT BUMPER GRILLE <i>defunct</i>		91.20	✓
1	FRONT BUMPER LOWER MESH <i>HF</i>		80.40	X
2	FRONT BUMPER LOWER GARNISH MOULDING <i>HF</i>		91.20	X
1	FRONT BUMPER LOWER INNER GARNISH <i>HF</i>		93.60	X
2	FRONT BUMPER FOG LAMP COVER <i>defunct o/s n/s src</i>	96.05	192.10	✓
2	FRONT BUMPER FOG LAMP <i>HF</i>		579.00	X
2	FRONT GRILLE <i>broken</i>		176.00	✓
1	FRONT SUPPORT PANEL <i>src</i>	558.00	669.60	✓
2	FRONT HEADLAMP ASSY <i>broken</i>		1046.40	✓
2	FRONT FENDER <i>Painted</i>		1106.40	✓
2	FRONT FENDER OUTER GARNISH <i>src</i>		67.20	X
2	FRONT FENDER OUTER SHIELD <i>defunct</i>		242.20	✓
1	BONNET <i>src</i>		726.00	✓
1	BONNET LOCK <i>src</i>		57.60	✓
2	BONNET HINGE <i>src</i>		115.20	✓
1	BONNET CABLE <i>src</i>		45.60	X
1	AIRCON CONDENSER ASSY <i>Practured</i>		1016.00	✓
1	AIRCON FAN ASSY <i>broken</i>		956.40	✓
1	AIRCON SUCTION PIPE - LOW <i>src</i>		211.29	X
1	AIRCON DISCHARGE PIPE - HIGH <i>src</i>		223.20	X
1	RADIATOR <i>Practured</i>		997.20	✓
1	RADIATOR FAN ASSY <i>Dam</i>		414.00	✓
1	WIPER TOP GARNISH <i>cut</i>		112.80	✓
2	RADIATOR BRACKET <i>src</i>		48.00	X
1	RADIATOR TOP HOSE <i>defunct</i>		33.60	✓
1	RADIATOR BOTTOM HOSE <i>src</i>		38.40	X
1	RADIATOR EXPANSION TANK <i>HF</i>		51.60	X
1	RADIATOR FAN ELECTRONIC UNIT <i>Dam</i>		169.20	✓
1	AIR DUCT <i>broken</i>		112.80	✓
1	AIR CLEANER RESONATOR <i>broken</i>		223.20	✓
1	WIPER WASHER TANK <i>broken</i>		105.60	✓

1	FRONT RH CHASSIS FRAME <i>1st</i>	812.30 ✓
1	FRONT RH WHEELHOUSE <i>rem</i>	710.20 x
1	FRONT CROSS MEMEBR <i>HN</i>	1290.10 x
1	FRONT ENGINE MOUNTNG <i>1st</i>	237.00 381.02 ✓
1	SIDE ENGINE MOUNTING <i>HN</i>	281.20 x
1	REAR GEARBOX MOUNTING <i>HN</i>	216.54 x
1	FRONT WINDSCREEN GLASS <i>CRACK</i>	632.00 1021.40 ✓
1	FRONT WINDSCREEEN MOULDING <i>HN</i>	130.20 ✓
		16785.35
	Less 10%	1678.53
	Subtotal	15106.82
	Balance C/F	15106.82
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>	
	Balance B/F	15106.82
1	FRONT NUMBER PLATE <i>dislodged</i>	60.00 45/-
1 SET	FRONT BUMPER CLIP <i>HN</i>	50.00 20/-
1 SET	FRONT FENDER INNER TRIM CLIP <i>HN</i>	50.00 ✓
1	COOLANT <i>HN</i>	60.00 40/-
	Subtotal	220.00
	Balance C/F	15326.82
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	15326.82
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 20/-
2	REMOVE AND RENEW CONDENSER AND TOP UP GAS	200.00 120/-
3	REMOVE AND RENEW RADIATOR AND TOP UP COOLANT	200.00 50/-
4	REMOVE AND REPLACE FRONT WINDSCREEN	150.00 120/-
5	REMOVE AND REFIT DASHBOARD	500.00 HN
6	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	500.00 150/-
7	CHECK FRONT WHEEL ALIGNMENT	200.00 HN
8	PANEL BEATING ON AFFECTED AREAS	2500.00 1400/-
9	SPRAY PAINTING ON AFFECTED AREAS	1800.00 1200/-
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 60/-
	Subtotal	6260.00
	Grand total	21586.82
		13373.87
		4/5 10700/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hot Andrew

2/sum

8 days

2KK Auto

7

08/12/2017 @ 1030m




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FC117023234/Dqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8298U	Veh. Inspected	SJR 5132G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17010746MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JMYSTCS3A9U005606	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	TRIANGLE	5 mm	
L/H Front Tyre	195/60 R15	TRIANGLE	5 mm	
R/H Rear Tyre	195/60 R15	TRIANGLE	5 mm	
L/H Rear Tyre	195/60 R15	TRIANGLE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/11/2017	Inspection Date	08/12/2017	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 5132G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED	852.00	688.00
2	FRONT BUMPER SIDE BEAM	BENT	96.00	96.00
1	FRONT BUMPER REINFORCEMENT	BUCKLED	165.60	165.60
1	FRONT NUMBER PLATE GARNISH	DENTED	82.80	82.80
1	FRONT BUMPER LOWER LIP	NOT FITTED	653.00	-
1	FRONT BUMPER GRILLE	DEFORMED	91.20	91.20
1	FRONT BUMPER LOWER MESH	NOT FITTED	80.40	-
2	FRONT BUMPER LOWER GARNISH MOULDING	NOT FITTED	91.20	-
1	FRONT BUMPER LOWER INNER GARNISH	NOT FITTED	93.60	-
2	FRONT BUMPER FOG LAMP COVER	O/S DEFORMED / N/S SERVICEABLE	192.10	96.05
2	FRONT BUMPER FOG LAMP	NOT FITTED	579.00	-
2	FRONT GRILLE	BROKEN	176.00	176.00
1	FRONT SUPPORT PANEL	BUCKLED	669.60	558.00
2	FRONT HEADLAMP ASSY	BROKEN	1,046.40	1,046.40
2	FRONT FENDER	DENTED	1,106.40	1,106.40
2	FRONT FENDER OUTER GARNISH	SERVICEABLE	67.20	-
2	FRONT FENDER OUTER SHIELD	DEFORMED	242.20	242.20
1	BONNET	BUCKLED	726.00	726.00
1	BONNET LOCK	BENT	57.60	57.60
2	BONNET HINGE	BENT	115.20	115.20
1	BONNET CABLE	SERVICEABLE	45.60	-
1	AIRCON CONDENSER ASSY	PUNCTURE	1,016.00	1,016.00
1	AIRCON FAN ASSY	BROKEN	956.40	956.40
1	AIRCON SUCTION PIPE-LOW	SERVICEABLE	211.29	-
1	AIRCON DISCHARGE PIPE-HIGH	SERVICEABLE	223.20	-
1	RADIATOR	PUNCTURE	997.20	997.20
1	RADIATOR FAN ASSY	DAMAGED	414.00	414.00
1	WIPER TOP GARNISH	CUT	112.80	112.80
2	RADIATOR BRACKET	TO REPAIR SEE LABOUR	48.00	-

Report Ref No. CS/FC117023234/Dqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR TOP HOSE	DEFORMED	33.60	33.60
1	RADIATOR BOTTOM HOSE	SERVICEABLE	38.40	-
1	RADIATOR EXPANSION TANK	NOT NECESSARY	51.60	-
1	RADIATOR FAN ELECTRONIC UNIT	DAMAGED	169.20	169.20
1	AIR DUCT	BROKEN	112.80	112.80
1	AIR CLEANER RESONATOR	BROKEN	223.20	223.20
1	WIPER WASHER TANK	BROKEN	105.60	105.60
1	FRONT RH CHASSIS FRAME	BENT	812.30	812.30
1	FRONT RH WHEELHOUSE	TO REPAIR SEE LABOUR	710.20	-
1	FRONT CROSS MEMBER	NOT NECESSARY	1,290.10	-
1	FRONT ENGINE MOUNTING	BENT	381.02	237.00
1	SIDE ENGINE MOUNTING	NOT NECESSARY	281.20	-
1	REAR GEARBOX MOUNTING	NOT NECESSARY	216.54	-
1	FRONT WINDSCREEN GLASS	CRACKED	1,021.40	632.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	130.20	130.20
	LESS 10% DISCOUNT		-1,678.53	-1,119.98
			15,106.82	10,079.77
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	DISLODGE	60.00	45.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER INNER TRIM CLIP (SN)	NECESSARY	50.00	50.00
1	COOLANT (SN)	NECESSARY	60.00	40.00
			220.00	165.00
	LABOUR			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND RENEW CONDENSER AND TOP UP GAS.		200.00	120.00
	REMOVE AND RENEW RADIATOR AND TOP UP COOLANT.		200.00	50.00
	REMOVE AND REPLACE FRONT WINDSCREEN.		150.00	120.00
	REMOVE AND REFIT DASHBOARD.	NOT NECESSARY	500.00	-
	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT.		500.00	150.00

Report Ref No. CS/FCI17023234/Dqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK FRONT WHEEL ALIGNMENT.	NOT NECESSARY	200.00	-
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF RADIATOR BRACKET AND FRONT RH WHEELHOUSE.		2,500.00	1,400.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,800.00	1,200.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	60.00
			6,260.00	3,130.00
GRAND TOTAL			21,586.82	13,374.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,700.00

Report Ref No. CS/FCI17023234/Dqbn2

MARKET VALUE: \$20,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,101.00=NETT VALUE: \$10,899.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.