

**CITY CAB PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 8106B

MAKE :

MODEL : HYUNDAI i40

CHINA

DATE 6/12/2017 10:06

DOA: 05.12.17

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover X repair			\$ 1,052.20
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Fender (LH) /			\$ 619.00
	<b>SUB TOTAL</b>			<b>\$ 1,695.80</b>
	<b>LESS 20%</b>			<b>\$ 339.16</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,356.64</b>
	<b>Labour Charge</b>			200
	Panel Beating			\$ <del>560.00</del>
	Spray Painting Charge			\$ <del>400.00</del> 760
	<b>TOTAL LABOUR</b>			<b>\$ 960.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,316.64</b>
	<p>Kalua 16/6/17</p> <p>6/12/17 1415 hrs</p> <p>2 days</p> <p>PIP</p> <p>Before paint photo</p>			
	<p>Larry Ng</p>			
	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p>			
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>			