

12/03/2003

ASS. REC. BY:

REF: CS/FCL17023340 / T14bn2 Special Instructions:

Surveyor: Taufik ASSIGNMENT (Office)From (Person): CWS May Chua of FCL Date/Time: 08122017 8:44am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 370G Insured: SHA 7990Xat Workshop m/s Ding Auto Tel: 8131 5518of 31 Corporation RdPolicy No: _____ Claim No: D17011247MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 04.12.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement: _____

Date/Time: 08122017 9:23am Person Contacted: Lucas Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHA 370G - CS/ENC09002082/Yc	Def: 220109
	SHA 7990X - NS/ENC11016786/Hlyln	Def: 160011
	11/12 @ 5:23pm email preli advise	

Tanpik

REF: FCL

ASSIGNMENT

From: _____ Date: 08/12/07

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHA 3706

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Lucas

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'DB'

Vehicle IN / OUT

Date:

Person Contacted:

Veh No

SHA 3706 Regn: 2017 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Toyota Prius Hybrid cc 1798

Colour

Yellow

Insured / Std / NI / NA

Sp/Reading

44573

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

STDK 63F4403562867

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

145/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

1/12/2011/45

Survey held at:

Ding Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4372600, 3dys. (Red: 241966; 437)

RECEIVED 08 JAN 2010

Date/Time File Pass to?

8/1 Typist

☐

: Prel. Report

☒

: Final Report

Date/Time File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Transportation

3-PS

Food

Other

TOTAL

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Technical \$

☐

Weekend \$

Report Format:

Lump Sum / I.B.I. \$

TP

2600

145
50

17

212



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023340/T1tb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7990X	Veh. Inspected	SHA 370G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011247MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	08/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/12/2017	Inspection Date	08/12/2017	
Survey held at	31 CORPORATION RD			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	05-12-2017	Our Ref No. D17011247MFSH
Accident Date	04-12-2017	Claim Type. Third Party
Insured Vehicle	SHA7990X	Third Party Vehicle. SHA370G
Survey Location	BLK 10, #01-20 SIN MING INDUSTRIAL ESTATESECTOR C	
Contact Person.	LUCAS CHOW	
Contact No.	81316518/ 81316518	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	DING AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231498)



PRI Documents



Close



PRI Header Details

Claim No	D17011247MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & DI
Workshop Name	DING AUTOMOTIVE PTE LTD (Contact Person : LUCAS CHOW)	Survey Location & Contact Details	BLK 10, #01-20 SIN MING INDUSTRIAL ESTAT Mobile: 81316518 , Phone: 81316518 , Fax: EmailId: TAXISCS@STENGG.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7990X	TP Vehicle No	SHA37
PRI Recieved Date	05-12-2017 10:02:21 PM	Surveyor Appointed Date	08-12-2017 08:44:49 AM	Surveyor Accept Date	08-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-12-2017	Upload Survey Report *:	
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 11 December, 2017 5:28 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011247MFSH/1
Attachments: PRELI ADVISED SHA 370G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHA 370G**
Number of days: 3 day

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 8 December, 2017 9:24 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011247MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@first-insurance.com.sg]
Sent: Friday, 8 December, 2017 8:44 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; MAYCHUA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011247MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011247MFSH

Date: 11/12/2017

Our Ref: CS/FCI17023340/T1tb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 370G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 8/12/2017 at the premises of M/s Ding Auto at and have the following to report:-

Workshop Estimate Amount	: S\$ 6,429.66
Revised Estimate Amount	: S\$ 4,056.49
"Check" Items Amount	: S\$ 68.50 -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:
The vehicle sustained damages
At front o/s portion.



Repair days: 3

Yours faithfully

Taufikh

Motor Surveyor

Ding Automotive Pte Ltd

Blk 10 Sin Ming Industrial Est. Sector C, #01-20, Singapore 575645

Tel:6452 1208, Fax:6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

05/12/2017 17:35

JOB-NO: 50110378

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA0370G TRANS: AUTO
MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT
OWNER'S INSURER: FIRST CAPITAL INSURANCE LIMITED
JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: JTDKB3FU403562867
ENGINE: 2ZRS060051

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE AND REPLACE FRONT WINDSCREEN	1.00	300.00	0.00	300.00		Y	120
2 TO CHECK WIRING AND LIGHTING SYSTEM	1.00	60.00	0.00	60.00		Y	X
3 TO APPLY UNDERCOATING ON AFFECTED AREAS	1.00	50.00	0.00	50.00		Y	30
4 TO REPAIR, REPLACE AND REALIGN DAMAGE AREAS	1.00	500.00	0.00	500.00		Y	350.300
5 TO SPRAY PAINTING ON FRONT FENDER RH	1.00	250.00	0.00	250.00		Y	200
6 TO SPRAY PAINTING ON BONNET	1.00	250.00	0.00	250.00		Y	200
TOTAL:		1,410.00	0.00	1,410.00			850

MATERIALS

1 FRONT FENDER RH	1.00	933.10	0.00	933.10	L	Y	bl-
2 FRONT FENDER INNER SHIELD	1.00	201.67	0.00	201.67	L	Y	X 47
3 FRONT FENDER EMBELM-HYBIRD	1.00	44.17	0.00	44.17	L	Y	new
4 FRONT FENDER QTR GARNISH RH	1.00	68.50	0.00	68.50	L	Y	new
5 BONNET	1.00	872.40	0.00	872.40	L	Y	new
6 BONNET HINGE RH	1.00	71.20	0.00	71.20	L	Y	X 47
7 BONNET INSULATOR	1.00	399.70	0.00	399.70	L	Y	X 47
8 FRONT BUMPER RETAINER RH	1.00	79.70	0.00	79.70	L	Y	X 47
9 FRONT WINDSCREEN	1.00	1,794.30	0.00	1,794.30	L	Y	new
10 FRONT WINDSCREEN MOULDING	1.00	79.02	0.00	79.02	L	Y	new
11 FRONT WINDSCREEN SIDE GARNISH RH	1.00	125.90	0.00	125.90	L	Y	new
12 FRONT FENDER INNER SHIELD CLIP SET	1.00	45.00	0.00	45.00	S	Y	X 47
13 BONNET INSULATOR CLIP SET	1.00	35.00	0.00	35.00	S	Y	X 47
14 FRONT WINDSCREEN INNER SEAL	1.00	40.00	0.00	40.00	S	Y	new
15 FRONT WINDSCREEN ADS STICKER-COMFORT DELGRO	1.00	160.00	0.00	160.00	S	Y	120. new
16 WINDSCREEN ERP STICKER	1.00	20.00	0.00	20.00	S	Y	new
17 WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	new
TOTAL:		5,019.66	0.00	5,019.66			

TOTAL PARTS & LABOUR :

EXCESS/LOADING:SS 0.00

No. Of Day: 3

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: SS

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance

Acknowledged by Repairer

Signature:

Date:

2976.49

2232.57

SN - 230

850

3342.37

41582600

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

DATE OF SURVEY: 8 12 12SURVEYED BY: Tanpin

sur@vikaauto.com

CONTACT NO: 97495249 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023340/T1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7990X	Veh. Inspected	SHA 370G	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011247MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	08/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU403562867	Colour	YELLOW	
Odometer	44573	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2017	Inspection Date	08/12/2017	
Survey held at	31 CORPORATION RD			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 370G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH	BENT	933.10	933.10
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	201.67	-
1	FRONT FENDER EMBLEM-HYBRID	NECESSARY	44.17	44.17
1	FRONT FENDER QTR GARNISH RH	NOT NECESSARY	68.50	-
1	BONNET	TO REPAIR SEE LABOUR	872.40	-
1	BONNET HINGE RH	NOT NECESSARY	71.20	-
1	BONNET INSULATOR	NOT NECESSARY	399.70	-
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	79.70	-
1	FRONT WINDSCREEN	CRACKED	1,794.30	1,794.30
1	FRONT WINDSCREEN MOULDING	NECESSARY	79.02	79.02
1	FRONT WINDSCREEN SIDE GARNISH RH	CUT	125.90	125.90
	LESS 25% DISCOUNT		-	-744.12
			4,669.66	2,232.37
SPECIAL NETT ITEMS				
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	35.00	-
1	FRONT WINDSCREEN INNER SEAL (SN)	NECESSARY	40.00	40.00
1	FRONT WINDSCREEN ADS STICKER-COMFORT DELGRO (SN)	NECESSARY	160.00	120.00
1	WINDSCREEN ERP STICKER (SN)	NECESSARY	20.00	20.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
			350.00	230.00
LABOUR				
	TO REMOVE AND REPLACE FRONT WINDSCREEN.		300.00	120.00
	TO CHECK WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	60.00	-
	TO APPLY UNDERCOATING ON AFFECTED AREAS.		50.00	30.00
	TO REPAIR, REPLACE AND REALIGN DAMAGE AREAS. INCLUSIVE OF THE REPAIR OF BONNET.		500.00	300.00
	TO SPRAY PAINTING ON FRONT FENDER RH.		250.00	200.00

Report Ref No. CS/FCI17023340/T1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON BONNET.		250.00	200.00
			1,410.00	850.00
GRAND TOTAL			6,429.66	3,312.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/FC117023340/T1tbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.