

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC17023343/AQBE2**Date:** 15/03/2018REFERENCE

Insured/Claimant: EMILY NEO AH TOOK Policy No: Z17/VP05/016433
Date of Loss: 05/12/2017 Nature of Claim: OD Claim No: 17/17/17/VP05/020257

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ5152S**
Make & Model: MINI JOHN COOPER WORKS, 1.6 (M) Engine No: A561J360N18B16C
Reg. Date: 22/03/2013 (Man. Year: 2012) Chassis No: WMWSU92020T627566
Colour: Black Odometer: 62022 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$95,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,396.83	13,988.03	8,408.80	37.54
Miscellaneous Items	1,363.29	851.44	511.85	37.55
Labour	3,560.00	1,860.00	1,700.00	47.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,320.12	16,699.47	10,620.65	38.87
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
Nett Amount (S\$)	24,320.12	13,699.47	10,620.65	43.67

INSPECTION

Date of Assignment: 07/12/2017 Present Location: VAC Auto Centre Pte Ltd (HQ)
Date Inspected: 08/12/2017 Inspected At: 1 Kaki Bukit Ave 6 #02-11
Singapore 417883
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2018)
Parts:	144	MINI JOHN COOPER WORKS 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ5152S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Distorted	950.00 F	*950.00 F
2	1		*FRONT BONNET AIR SCOP (WCP)	Cracked	180.00 F	*180.00 F
3	2		*FRONT BONNET LOCK - LH/RH (WCP)	Damaged	150.00 F	*150.00 F
4	2		*FRONT BONNET LOCK STICKER (WCP)	Not Necessary	70.00 F	*- F
5	1		*FRONT BONNET SAFETY LOCK CATCH (WCP)	Not Necessary	45.00 F	*- F
6	2		*FRONT BONNET HINGES - LH/RH (WCP)	Bent	150.00 F	*150.00 F
7	2		*FRONT BONNET DAMPERS - LH/RH (WCP)	Not Necessary	150.00 F	*- F
8	1		*FRONT BONNET LOGO (WCP)	Necessary	95.00 F	*95.00 F
9	1		*FRONT BONNET CHROME MOULDING (WCP)	Cracked	130.00 F	*130.00 F
10	1		*FRONT BONNET CHROME MOULDING - REAR (WCP)	Not Necessary	185.00 F	*- F
11	1		*FRONT BUMPER (WCP)	Distorted	620.00 F	*620.00 F
12	1		*FRONT BUMPER TOW COVER (WCP)	Not Necessary	18.00 F	*- F
13	2		*FRONT BUMPER FOG LAMPS - LH/RH (WCP)	Not Necessary	370.00 F	*- F
14	2		*FRONT BUMPER FOG LAMP COVERS - LH/RH (WCP)	Not Necessary	84.00 F	*- F
15	1		*FRONT BUMPER GRILLE - LOWER (WCP)	Not Necessary	220.00 F	*- F
16	1		*FRONT BUMPER SPONGE (WCP)	Cracked	110.00 F	*110.00 F
17	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	580.00 F	*580.00 F
18	2		*FRONT BUMPER SIDE RETAINERS (WCP)	Necessary	56.00 F	*56.00 F
19	10		*FRONT BUMPER CLIPS (WCP)	Necessary	45.00 F	*45.00 F
20	2		*FRONT FENDERS LH/RH (WCP)	Repair	560.00 F	*- F
21	2		*FRONT FENDERS OUTER GARNISH (WCP)	Not Necessary	320.00 F	*- F
22	2		*FRONT FENDER INNER SHIELDS (WCP)	Not Necessary	220.00 F	*- F
23	1		*FRONT GRILLE (WCP)	Cracked	155.00 F	*155.00 F
24	5		*FRONT GRILLE CLIPS (WCP)	Necessary	22.50 F	*22.50 F
25	2		*FRONT HEADLAMPS LH/RH (WCP)	Cracked	1,800.00 F	*1,800.00 F
26	2		*FRONT HEADLAMPS HID BULB (WCP)	Not Necessary	320.00 F	*- F
27	2		*FRONT HEADLAMP CONTROL UNITS (WCP)	Not Necessary	900.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*FRONT HEADLAMP CHROME RIMS (WCP)	Missing	170.00 F	*170.00 F
29	1		*FRONT SUPPORT PANEL ASSEMBLY (WCP)	Not Necessary	550.00 F	*- F
30	1		*FRONT SUPPORT TOP PANEL (WCP)	Buckled	280.00 F	*280.00 F
31	2		*HORN (WCP)	Damaged	170.00 F	*170.00 F
32	1		*AIRCON CONDENSER (WCP)	Dented	780.00 F	*780.00 F
33	1		*AIRCON DISCHARGE PIPE (WCP)	Bent	200.00 F	*200.00 F
34	1		*AIRCON SUCTION PIPE (WCP)	Not Necessary	220.00 F	*- F
35	1		*AIRCON LIQUID PIPE (WCP)	Not Necessary	150.00 F	*- F
36	1		*BONNET LOCK CABLE (WCP)	Not Necessary	85.00 F	*- F
37	1		*AIRCON COMPRESSOR (WCP)	Not Necessary	980.00 F	*- F
38	1		*AIR CLEANER INTAKE DUCT (WCP)	Cracked	110.00 F	*110.00 F
39	1		*AIR INTERCOOLER (WCP)	Not Necessary	550.00 F	*- F
40	2		*AIR INTERCOOLER HOSE - INLET/OUTLET (WCP)	Not Necessary	360.00 F	*- F
41	1		*AIR INTERCOOLER INTAKE PIPE (WCP)	Not Necessary	195.00 F	*- F
42	1		*RADIATOR (WCP)	Distorted	550.00 F	*550.00 F
43	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	70.00 F	*- F
44	1		*RADIATOR BOTTOM HOSE (WCP)	Not Necessary	150.00 F	*- F
45	1		*RADIATOR AUXILIARY FAN ASSEMBLY (WCP)	Cracked	600.00 F	*600.00 F
46	1		*EXHAUST MANIFOLD COVER (WCP)	Dented	150.00 F	*150.00 F
47	1		*EXHAUST MANIFOLD SENSOR (WCP)	Damaged	360.00 F	*360.00 F
48	2		*ENGINE MOUNTINGS LH/RH (WCP)	Not Necessary	420.00 F	*- F
49	1		*WASHER TANK (WCP)	Not Necessary	100.00 F	*- F
50	1		*NUMBER PLATE (WCP)	Cut	20.00 F	*20.00 F
51	1		*RADIATOR COOLANT (WCP)	Necessary	60.00 F	*40.00 F
52	1		*AIRCON OIL (WCP)	Necessary	45.00 F	*45.00 F
53	1		*FRONT GRILLE CHROME MOULDING - LOWER (WCP)	Missing	145.00 F	*145.00 F
Supplementary #1						
54	1		*TURBOCHARGER ASSEMBLY (WCP)	Cracked	3,500.00 F	*3,500.00 F

F=Franchise part.

Sub Total (\$)	19,475.50	12,163.50
+ Margin on L,N Items 15.00/15.00% (\$)	2,921.33	1,824.53
Total Parts (\$)	22,396.83	13,988.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	GST	1,118.29	851.44
<u>Supplementary #1</u>				
2	1	GST	245.00	0.00
Sub Total (\$)			1,363.29	851.44

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES	New	60.00	60.00
2	TO CHECK FRONT ELECTRICAL WIRINGS	New	50.00	30.00
3	TO REMOVE, REFIX AIRCON CONDENSER AND REFILL AIRCON GAS	New	150.00	120.00
4	TO REMOVE, REFIX ENGINE PARTS	New	250.00	0.00
5	TO DIAGNOSE AND ERASE FAULT CODES/MEMORY AFTER REPAIRS	New	450.00	150.00
6	TO RESPRAY PAINTING AND ETC	New	1,200.00	700.00
7	LABOUR CHARGE TO PANEL BEAT, REMOVE AND REPLACE ABOVE PARTS	New	1,300.00	800.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
8	LABOUR CHARGE TO REMOVE AND REPLACE PARTS	New	100.00	0.00
Gross Labour Cost (\$)			3,560.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >