



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2007 HONDA FIT 1.3 (SJB6573U)

Date of Loss

28 November 2017

Time of Loss

14.55

Loss Description

SJB6573U (INSD) HIT REAR OF SJK7418G

Comment

Workshop Details

Total Rebate Amount

6663

Nett Loss Amount

-\$6,663.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

26/03/2018



Days of work completion *

108

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

08/12/2017



Total Loss

☒ Yes

☐ No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1100

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/50R15

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

☐ Yes

☒ No

Footbrake (Serviceable)

☐ Yes

☒ No

Handbrake (Serviceable)

☐ Yes

☒ No

Engine Modification

☒ Yes

☐ No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

195/50R15

Front left side

MICHELIN5mm

Front right side

MICHELIN5mm

Rear left side

MICHELIN5mm

Rear right side

MICHELIN5mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC COUNT%	SALV AGE%	PART PRICE(NET)	ACTO (PART)
☐		1	1			BONNET			Buckled	210				210	Review
☐		2	1			BONNET LOCK			Bent	60				60	Review
☐		3	1			BONNET RUBBER - LH			Necessary	10				10	Review
☐		4	1			BONNET RUBBER - RH			Necessary	10				10	Review
☐		5	1			BONNET HINGE - LH			Serviceable	0	0	0	0	0	Deny
☐		6	1			BONNET HINGE - RH			Serviceable	0	0	0	0	0	Deny
☐		7	4			BONNET AIR DUCT CLIP			Necessary	2				8	Review
☐		8	1			FRONT BUMPER			Deformed	145				145	Review
☐		9	10			FRONT BUMPER CLIPS			Necessary	1				10	Review
☐		10	1			FRONT BUMPER SIDE HOLDER - LH			Necessary	10				10	Review
☐		11	1			FRONT BUMPER SIDE HOLDER - RH			Necessary	10				10	Review
☐		12	1			FRONT BUMPER REINFORCEMENT			Bent	75				75	Review

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		13	1			FRONT BUMPER CENTRE LOWER GRILLE (*CHECK)				0				0	Review
☐		14	1			FRONT BUMPER TOWING COVER - LH			Damaged	8				8	Review
☐		15	1			FRONT FENDER - RH			Repair	0	0	0	0	0	Deny
☐		16	10			FRONT FENDER COWLING CLIPS - RH			Necessary	2				20	Review
☐		17	1			HEAD LAMP UNIT - LH			Cracked	310				310	Review
☐		18	1			HEAD LAMP UNIT - RH			Cracked	310				310	Review
☐		19	1			HEAD LAMP LOWER RETAINER - LH (*CHECK)				0				0	Review
☐		20	1			HEAD LAMP LOWER RETAINER - RH (*CHECK)				0				0	Review
☐		21	1			GRILLE ASSY			Damaged	65				65	Review
☐		22	1			GRILLE LOGO			Necessary	15				15	Review
☐		23	4			GRILLE CLIPS			Necessary	1				4	Review
☐		24	1			SUPPORT PANEL ASSY			Bent	130				130	Review
☐		25	1			CONDENSER			Bent	240				240	Review
☐		26	1			RADIATOR (*CHECK)				0				0	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/J BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		27	1			AIRCON FAN MOTOR (*CHECK)				0				0	Review
		28	1			AIRCON FAN COWLING (*CHECK)				0				0	Review
		29	1			AIRCON FAN BLADE (*CHECK)				0				0	Review
		30	1			RADIATOR FAN MOTOR (*CHECK)				0				0	Review
		31	1			RADIATOR FAN BLADE (*CHECK)				0				0	Review
		32	1			WIPER TANK (*CHECK)				0				0	Review
		33	1			RADIATOR FAN COWLING (*CHECK)				0				0	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
		1		TO KNOCK OUT DENTS, CUT/WELD, SUPPORT PANEL, REMOVE, REPLACE ACCIDENT PARTS	600	0	0	Reviewing		1
		2		TO RESPRAY PAINT ON ACCIDENT PORTIONS	600	0	0	Reviewing		1
		3		TO CHECK WIRING	20	0	0	Reviewing		1
		4		TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100	0	0	Reviewing		1

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FRONT NUMBER PLATE WITH CASING	Reviewing	35	SCRATCHED	
		2	COOLANT	Reviewing	20	NECESSARY	
		3	(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$818.00 NETT)	Reviewing			

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount \$1,925.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,520.00	\$1,320.00
Spare Parts	\$2,604.00	\$1,650.00
Miscellaneous	\$55.00	\$55.00
Excess	-\$1,100.00	-\$1,100.00