

CC31M8617023368/UTb2

REF:

Singaporean

msic/

ASSIGNMENT

From: + Date:
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SYN1860K
at Workshop m/s RP.
of
Insured: SE 3000D
Policy No.
Claims No.
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SYN1860K Yr Regn: 6 2 09
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or GA
Make: Suzuki, SX4 C.C. 1586
Colour: Maroon A/C: Insured / Std / NI / NA
Sp. Reading: 131741 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: JSAGY4C215 00203055
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / SRim / STD A/Rim or
Tyre Size: F: 195/65R15
R:

BS / DUN / EXNOVA / GY / F5 / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or MAXXIS falken

Front 6 mm Rear 6 mm
R/Bal. mm R/Bal. mm
L/Bal. mm L/Bal. mm
D.O.A. 1/12/17 D.O.I. 8/12/17
Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 8603

Tullong 288.15

top hand 285.32

12/12/17 confirmed L/S @ 3500 with Alan (Red: 8143.92 : 69%)

RECEIVED 21 DEC 2017

Date/Time, File Pass to?

1) 21/12/2017

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

) \$ + RS. \$

) Photos

) Others

Report Format: TP

Lump Sum / I.B.I.: (\$ 3500/-)

TOTAL

310

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 21 December, 2017 10:26 AM
To: elaine_ngu@sg.msig-asia.com; Nabilah Rasol
Cc: SUR; Christopher Chionh; Accounts (LKKAUTO); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 1/12/2017, SJN 1860K (TP VEHICLE), SE 3000D (OI VEHICLE)

Dear Elaine/Nabilah,

Please be informed that we had inspected the vehicle SJN 1860K at M/s: FASTECH AUTO PTE LTD

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Date of Accident: 1ST DEC 2017	Accident Time: 9.30AM.	
Vehicle (A) No: SJN 1860 K	Make Model: SUZUKI SX 4.	
Location: DUNEARN ROAD TOWARDS CITY ON LANE 2.		
Owner Name: NORHAYATI Binte Ahmad		
Owner Address: BLK 59, MARINE TERRACE #07-105 SPORE 440059		
Owner NRIC:	Email: -	
HP: 97113823	Home: -	Office: -
Insurance Company: AXA (Comprehensive / Third Party / Third Party Fire & Theft)		Insurance Policy No:
Driver Name: RONNIE SETIAWAN		
Driver NRIC: S1206091 B	Date of Birth: 28/9/1956.	
Driver Contact No: 97113823	Occupation: indoor	
Driving License Pass Date: 10/5/1978	Relationship With Owner: husband	

Claiming Under: (Own Damage Claim / Third Party Claim / Reporting Only)

Weather Condition: (Clear / Raining / Drizzling / After Rained)

Road Surface: (Wet / Dry)

Damage Portion of Vehicle(A): (Rear / Front / Right Side / Left Side / Chain Collision)

Anyone Injured: YES / NO	Name:
Police Report: YES / NO	If YES, Where:
Passenger In Vehicle (A):	
Witness Name:	NRIC: HP:

Vehicle (B) No: SE 3000 D	Vehicle (C) No:
Driver Name: WONG YAN REW MATHIEU	Driver Name:
Driver NRIC:	Driver NRIC:
Contact No:	Contact No:
Insurance: MSIG	Insurance:
Damage portion of vehicle(B):	Damage portion of vehicle(C):

Vehicle (D) No:	Vehicle (E) No:
Driver Name:	Driver Name:
Driver NRIC:	Driver NRIC:
Contact No:	Contact No:
Insurance:	Insurance:
Damage portion of vehicle(D):	Damage portion of vehicle(E):

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

X
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON THE 1ST DEC 2017 AT ABOUT 9.30AM I WAS DRIVING MY SUZUKI SX4 SJN 1860 K, ALONG DUNEARN ROAD ON LANE 2 TOWARDS CITY.

THE VEHICLE IN FRONT OF ME SLOW DOWN AND CAME TO A STOP AND I FOLLOW SUIT.

SUDDENLY I HEAR A LOUD BANG FROM THE REAR OF MY CAR. THE CAR MODEL HONDA CIVICS SE 3000 D, DRIVEN BY MR WONG WONG YAN MATHIEU HAD 'BANG' INTO THE REAR OF MY CAR.

MR WONG HAD INITIALLY WANTED TO DO A PRIVATE SETTLEMENT BUT AFTER 2 DAYS, MR WONG HAD INFORMED ME VERBALLY THAT HIS FATHER DID NOT AGREE TO DO A PRIVATE SETTLEMENT.

AS I HAD AN OVERSEAS APPT ON THE 3RD DEC 2017, I DID NOT HAVE THE TIME TO MAKE AN INSURANCE REPORT.

AFTER A FEW DAYS MY WIFE, INFORMED ME THAT I HAVE TO MAKE AN ACCIDENT REPORT AND SINCE I AM STILL OUT OF TOWN I HAVE AUTHORIZED MY WIFE TO DO THE ACCIDENT REPORT ON MY BEHALF.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	6504A
Vehicle Details	
Vehicle No.	SJN1860K
Vehicle to be Exported	No
Intended De-registration Date	11 Dec 2017
Vehicle Make	SUZUKI
Vehicle Model	SX4 1.6NB AT
Primary Colour	Red
Manufacturing Year	2008
Engine No.	M16A1446591
Chassis No.	JSAGYC21S00203055
Maximum Power Output	75.0 kW (100 bhp)
Open Market Value	\$15,079.00
Original Registration Date	06 Feb 2009
First Registration Date	06 Feb 2009
Transfer Count	1
Actual ARF Paid	\$15,079.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	05 Feb 2019
PARF Rebate Amount	\$8,293.00
Intended COE Rebate Details	
COE Expiry Date	05 Feb 2019
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$2,693.00
COE Rebate Amount	\$310.00
Total Rebate Amount	\$8,603.00

The information contained herein is correct as at 11 Dec 2017

OK

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20021

Date : 12.12.2017

Vehicle Num : SJN1860K

Make/Model : SUZUKI SX4

Accident Date : 01.12.2017

Claim No : 1217-20021

Qty Particular

List Item

1 pc Rear boot lid		\$ 2 672.90	✓
1 pc Rear logo		\$ 11 36.00	✓
2 pc Rear boot lid hinges@101.20		\$ 11 202.40	✓
1 pc Rear boot lid inner lock		\$ 11 126.00	✓
1 pc Rear boot emblem (SX4)		\$ 11 35.00	✓
1 pc Rear boot lid weatherstrip		\$ 11 112.50	✓
2 pc Rear tail lamp @ 550	289.15' x 22.578.30	Dyed/\$ 1,100.00	✓
1 pc Rear bumper	549.65	\$ PIS 1,549.65	✓
2 pc Rear bumper side retainer @ 32.60		\$ 11 65.20	✓
1 pc Rear bumper lower skirting	600	\$ 11 1,200.00	✓
1 set Rear bumper clip		\$ 11 45.00	✓
1 pc Rear bumper beam		\$ 11 227.47	✓
2 pc Rear bumper reflector@45		\$ 11 90.00	✓
1 pc Rear end panel		\$ 11 493.60	✓
1 pc Rear end panel garnish		\$ 11 127.00	✓
1 pc Rear floor panel		\$ 11 866.20	✓
1 pc Rear floor panel top board	285.32	\$ 11 685.00	✓
List Item Total :		\$ 7,633.92	

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2956.04

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20021

Date : 12.12.2017

Vehicle Num : SJN1860K

Make/Model : SUZUKI SX4

Chassis/Engine no :

Accident Date : 01.12.2017

Claim No : 1217-20021

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Special Nett Item</u>		
1 set	Rear bumper reverse sensor	\$ <i>shd</i> 300.00 <i>200</i>
1 pc	Rear panel sealant	\$ <i>ru</i> 50.00 <i>✓</i>
1 set	Rear floor panel insulator	\$ <i>11</i> 300.00 <i>X</i>
Special Nett Total :		\$ 650.00
<u>Labour charge :</u>		
	To check wiring and reset	\$ 80.00 <i>30</i>
	Remove and replace bootlid mechanism	\$ <i>11</i> 80.00 <i>X</i>
	Remove and replace reverse sensor	\$ 100.00 <i>50</i>
	Remove and replace seat,cushion upholstery	\$ 120.00 <i>60</i>
	Remove and replace exhaust pipe	\$ <i>11</i> 100.00 <i>X</i>
	Remove and replace reverse sensor	\$ <i>Replaced</i> 80.00 <i>X</i>
	To spray rust proofing	\$ 100.00 <i>30</i>
	To remove and replace spare part and panel beating	\$ 1,200.00 <i>680</i>
	To spray painting and etc	\$ 1,500.00 <i>800</i>
Labour Charge Total :		\$ 3,360.00

11643.92

FASTECH AUTO PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Dec 2017		21 Dec 2017 13:35 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: WONG LOONG WAI, ID: S0027586G, Tel: +6596999955

Main Claimant: NORHAYATI BINTE AHMAD, ID: S1246504A

Vehicle Reg. No.: SJN1860K **Date of Loss:** 01/12/2017 09:00 - :59

Claim Type: TP / 539165 **Policy/Cover Note No.:** A80308382QMX (Comprehensive)
Coverage: 02/09/2017 - 01/09/2018

Vehicle Reg. No. (Insured): SE3000D **Policy No. (Claimant):**

Excess: S\$500.00

Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ...
[Imm.Advice due 22/12/2017]

Driver/Custodian (Insured): WONG YAN REN MATHIEU (), NRIC: S8737726A

Adj Asg. Remarks: DIRECT SURVEY BY LKK

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN1860K (539165)
[SE3000D]
TP
NORHAYATI BINTE AHMAD
Dec 1 2017 9:00AM
[WONG LOONG WAI]
Fastech Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer	
Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/12/17 13:35	Accident Statement From:OD - Reg. No: SE3000D, Claimant: WONG LOONG WAI		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/12/17 16:18	General View		Load JPG	☒
2	21/12/17 16:18	General View		Load JPG	☒
3	21/12/17 16:18	General View		Load JPG	☒
4	21/12/17 16:18	General View		Load JPG	☒
5	21/12/17 16:18	General View		Load JPG	☒
6	21/12/17 16:18	General View		Load JPG	☒
7	21/12/17 16:18	General View		Load JPG	☒
8	21/12/17 16:18	General View		Load JPG	☒
9	21/12/17 16:18	General View		Load JPG	☒
10	21/12/17 16:18	General View		Load JPG	☒
11	21/12/17 16:18	General View		Load JPG	☒
12	21/12/17 16:18	General View		Load JPG	☒
13	21/12/17 16:18	General View		Load JPG	☒
14	21/12/17 16:18	General View		Load JPG	☒
15	21/12/17 16:18	General View		Load JPG	☒
16	21/12/17 16:18	General View		Load JPG	☒
17	21/12/17 16:18	General View		Load JPG	☒
18	21/12/17 16:18	General View		Load JPG	☒
19	21/12/17 16:18	General View		Load JPG	☒
20	21/12/17 16:18	General View		Load JPG	☒
21	21/12/17 16:18	General View		Load JPG	☒
22	21/12/17 16:18	General View		Load JPG	☒
23	21/12/17 16:18	General View		Load JPG	☒
24	21/12/17 16:18	General View		Load JPG	☒
25	21/12/17 16:18	General View		Load JPG	☒
26	21/12/17 16:18	General View		Load JPG	☒
27	21/12/17 16:18	General View		Load JPG	☒
28	21/12/17 16:18	General View		Load JPG	☒
29	21/12/17 16:18	General View		Load JPG	☒
30	21/12/17 16:18	General View		Load JPG	☒
31	21/12/17 16:18	General View		Load JPG	☒
32	21/12/17 16:18	General View		Load JPG	☒
33	21/12/17 16:18	General View		Load JPG	☒
34	21/12/17 16:18	General View		Load JPG	☒

35	21/12/17 16:18	General View		Load JPG	☒
36	21/12/17 16:18	General View		Load JPG	☒
37	21/12/17 16:18	General View		Load JPG	☒
38	21/12/17 16:18	General View		Load JPG	☒
39	21/12/17 16:18	General View		Load JPG	☒
40	21/12/17 16:18	General View		Load JPG	☒
41	21/12/17 16:18	General View		Load JPG	☒
42	21/12/17 16:18	General View		Load JPG	☒
43	21/12/17 16:18	General View		Load JPG	☒
44	21/12/17 16:18	General View		Load JPG	☒
45	21/12/17 16:18	General View		Load JPG	☒
46	21/12/17 16:18	General View		Load JPG	☒
47	21/12/17 16:18	General View		Load JPG	☒
48	21/12/17 16:18	General View		Load JPG	☒
49	21/12/17 16:18	General View		Load JPG	☒
50	21/12/17 16:18	General View		Load JPG	☒
51	21/12/17 16:18	General View		Load JPG	☒
52	21/12/17 16:18	General View		Load JPG	☒
53	21/12/17 16:18	General View		Load JPG	☒
54	21/12/17 16:18	General View		Load JPG	☒
55	21/12/17 16:18	General View		Load JPG	☒
56	21/12/17 16:18	General View		Load JPG	☒
57	21/12/17 16:18	General View		Load JPG	☒
58	21/12/17 16:18	General View		Load JPG	☒
59	21/12/17 16:18	General View		Load JPG	☒
60	21/12/17 16:18	General View		Load JPG	☒
61	21/12/17 16:18	General View		Load JPG	☒
62	21/12/17 16:18	General View		Load JPG	☒
63	21/12/17 16:18	General View		Load JPG	☒
64	21/12/17 16:18	General View		Load JPG	☒
65	21/12/17 16:18	General View		Load JPG	☒
66	21/12/17 16:18	General View		Load JPG	☒
67	21/12/17 16:19	Reinspection Photo		Load JPG	☒
68	21/12/17 16:19	Reinspection Photo		Load JPG	☒
69	21/12/17 16:19	Reinspection Photo		Load JPG	☒
70	21/12/17 16:19	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/12/17 10:56	TPD SJN1860K GIA REPORT.		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG17023368/UTBE2

Date: 22/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80308382QMX
Claimant Vehicle No :	SJN1860K	Insured Vehicle No :	SE3000D
Date of Loss:	01/12/2017	Nature of Claim:	TP
		Claim No:	539165

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN1860K		Engine No:	M16A1446591
Make & Model:	SUZUKI SX4, 1.6 NB (A)		Chassis No:	JSAGYC21S00203055
Reg. Date:	06/02/2009 (Man. Year: 2008)		Odometer:	131741 km
Colour:	Maroon			
Engine Capacity:	1586 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,283.92	2,763.48	5,520.44	66.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	1,650.00	1,710.00	50.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,643.92	4,413.48	7,230.44	62.10
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	11,643.92	3,500.00	8,143.92	69.94
+ GST 7.00/7.00% (S\$)	815.07	245.00	570.07	69.94
Nett Amount (S\$)	12,458.99	3,745.00	8,713.99	69.94

INSPECTION

Date of Assignment:	21/12/2017	
Date Inspected:	08/12/2017 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2017)
Parts:	144	SUZUKI SX4 1.6 NB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN1860K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	672.90 F	*- FL
2	1		*REAR LOGO	Not Necessary	36.00 F	*- FL
3	2		*REAR BOOT LID HINGES	Not Necessary	202.40 F	*- FL
4	1		*REAR BOOT LID INNER LOCK	Not Necessary	126.00 F	*- FL
5	1		*REAR BOOT EMBLEM (SX4)	Not Necessary	35.00 F	*- FL
6	1		*REAR BOOT LID WEATHERSTRIP	Twisted	112.50 F	*112.50 FL
7	2		*REAR TAIL LAMP	Damaged / Cracked	1,100.00 F	*578.30 FL
8	1		*REAR BUMPER	Distorted	1,549.65 F	*549.65 FL
9	2		*REAR BUMPER SIDE RETAINER	Necessary	65.20 F	*65.20 FL
10	1		*REAR BUMPER LOWER SKIRTING	Deformed	1,200.00 F	*600.00 FL
11	1		*SET REAR BUMPER CLIP	Necessary	45.00 F	*45.00 FL
12	1		*REAR BUMPER BEAM	Bent	227.47 F	*227.47 FL
13	2		*REAR BUMPER REFLECTOR	Not Necessary	90.00 F	*- FL
14	1		*REAR END PANEL	Dented	493.60 F	*493.60 FL
15	1		*REAR END PANEL GARNISH	Not Necessary	127.00 F	*- FL
16	1		*REAR FLOOR PANEL	Repair	866.20 F	*- FL
17	1		*REAR FLOOR PANEL TOP BOARD	Warped	685.00 F	*285.32 FL
18	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
19	1		*REAR PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
20	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,283.92	3,207.04
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	443.56
Total Parts (\$\$)	8,283.92	2,763.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET	New	80.00	30.00
2	REMOVE AND REPLACE BOOTLID MECHANISM	New	80.00	0.00
3	REMOVE AND REPLACE REVERSE SENSOR	New	100.00	50.00
4	REMOVE AND REPLACE SEAT, CUSHION UPHOLSTERY	New	120.00	60.00
5	REMOVE AND REPLACE EXHAUST PIPE	New	100.00	0.00
6	REMOVE AND REPLACE REVERSE SENSOR	New	80.00	0.00
7	TO SPRAY RUST PROOFING	New	100.00	30.00
8	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,200.00	680.00
9	TO SPRAY PAINTING AND ETC	New	1,500.00	800.00
Gross Labour Cost (S\$)			3,360.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >