



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2005 MERCEDES S280 (SBR9138J)

Date of Loss

5 December 2017

Time of Loss

17.30

Loss Description

SBR9138J(INSJ) HIT REAR OF SHD9184C (TP)

Comment

Workshop Details

Total Rebate Amount

39041

Nett Loss Amount

\$33,959.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

15/04/2018



Days of work completion *

27



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SBR9138J

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

30/05/2006



Mileage

93442

Age of Vehicle

11

Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2005

CATEGORY

Driver Name

ASSESSMENT INFO...

2005

FNOL INFORMATI...

SOUCIK VICTOR

CATEGORY	Make	POST SURVEY INF...	
POLICY INFORMAT...	MERCEDES	CATEGORY	Date of Birth
ASSESSMENT INFO...	MERCEDES BENZ	FNOL INFORMATI...	30 January 1976
CATEGORY	Model	POST SURVEY INF...	dd/mm/yyyy 
POLICY INFORMAT...	S280	CATEGORY	Age
ASSESSMENT INFO...	S280	FNOL INFORMATI...	42
CATEGORY	Type	POST SURVEY INF...	
POLICY INFORMAT...		CATEGORY	Occupation
ASSESSMENT INFO...		FNOL INFORMATI...	Unknown
CATEGORY	Type of Paint	POST SURVEY INF...	
POLICY INFORMAT...		CATEGORY	Education Qualification
ASSESSMENT INFO...		FNOL INFORMATI...	Other
CATEGORY	Chassis No	POST SURVEY INF...	
POLICY INFORMAT...	WDB2200632A483952	CATEGORY	Driving Experience

ASSESSMENT INFO... WDB2200632A483952

CATEGORY Engine No

POLICY INFORMAT... 11292232001116

ASSESSMENT INFO... 11292232001116

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 2799

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 73000

FNOL INFORMATI... 7

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI... S7664776C

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI... 3

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 7 February 2011

POST SURVEY INF...

dd/mm/yyyy



CATEGORY License Expiration Date

FNOL INFORMATI... 13 October 2047

POST SURVEY INF...

dd/mm/yyyy



CATEGORY	Address
FNOL INFORMATI...	Singapore
POST SURVEY INF...	

CATEGORY	Address type
FNOL INFORMATI...	Personal Correspondence
POST SURVEY INF...	

CATEGORY	Gender
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Marital status
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Identification #
----------	------------------

FNOL INFORMATI... S7664776C

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

08/12/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1000

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

245/45R18

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

245/45R18

Front left side

GOODYEAR6mm

Rear left side

GOODYEAR6mm

Front right side

GOODYEAR6mm

Rear right side

GOODYEAR6mm

Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts					
Add Approve Deny															
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PARTS)
		1	1			FRONT BUMPER			Damaged	870				870	Review
		2	10			FRONT BUMPER CLIPS			Necessary	2.8				28	Review
		3	1			FRONT BUMPER SIDE HOLDER - LH - NO PRICE & NO STOCK			Serviceable	0	0	0	0	0	Deny
		4	1			FRONT BUMPER SIDE HOLDER - RH - NO PRICE & NO STOCK			Serviceable	0	0	0	0	0	Deny
		5	3			FRONT BUMPER SENSOR			Damaged	88				264	Review
		6	1			FRONT BUMPER INNER FRAME			Cracked	92				92	Review
		7	1			FRONT BUMPER FOAM			Serviceable	0	0	0	0	0	Deny
		8	1			FRONT BUMPER REINFORCEMENT			Bent	1770				1770	Review
		9	1			FRONT BUMPER LOWER GRILLE CHROME - NO PRICE & NO STOCK			Serviceable	0	0	0	0	0	Deny
		10	1			FRONT BRAKE PAD W/CHROME MOULDING - LH			Damaged	240				240	Review
		11	1			FRONT BRAKE PAD W/CHROME MOULDING - RH			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
		12	1			FRONT BUMPER NOZZLE COVER & BRACKET - LH			Cracked	50				50	Review
		13	1			BONNET			Bent	2050				2050	Review
		14	1			BONNET LOGO WITH STAR			Necessary	35				35	Review
		15	1			BONNET INSULATOR			Deformed	215				215	Review
		16	21			BONNET INSULATOR CLIPS			Necessary	2.8				58.8	Review
		17	2			BONNET TOP SPRING - LH & RH			Serviceable	0	0	0	0	0	Deny
		18	2			BONNET BOTTOM LOCK - LH & RH			Serviceable	0	0	0	0	0	Deny
		19	1			BONNET TOP LOCK - CENTRE			Serviceable	0	0	0	0	0	Deny
		20	1			BONNET ABSORBER - LH			Serviceable	0	0	0	0	0	Deny
		21	1			BONNET ABSORBER - RH			Serviceable	0	0	0	0	0	Deny
		22	1			BONNET GRILLE ASSY			Cracked	300				300	Review
		23	1			GRILLE BRACKET			Serviceable	0	0	0	0	0	Deny
		24	1			TOP PANEL			Bent	220				220	Review
		25	1			HEAD LAMP PANEL - LH			Bent	116				116	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR / BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		26	1			HEAD LAMP SIDE PANEL - LH - NO PRICE & NO STOCK			Serviceable	0	0	0	0	0	Deny
		27	1			HEAD LAMP UNIT - LH			Damaged	850				850	Review
		28	1			HEAD LAMP TOP RUBBER - LH			Necessary	70				70	Review
		29	1			HEAD LAMP TOP RUBBER - RH			Serviceable	0	0	0	0	0	Deny
		30	1			ABS PUMP			Serviceable	0	0	0	0	0	Deny
		31	1			ABS PIPE			Serviceable	0	0	0	0	0	Deny
		32	1			POWER STEERING PUMP			Serviceable	0	0	0	0	0	Deny
		33	1			FAN BELT			Serviceable	0	0	0	0	0	Deny
		34	1			GRILLE ASSY			Serviceable	0	0	0	0	0	Deny
		35	1			GRILLE LOGO - NO PRICE & NO STOCK			Serviceable	0	0	0	0	0	Deny
		36	1			FRONT FENDER - LH			Bent	800				800	Review
		37	1			FRONT FENDER PROTECTOR & CHROME - LH			Necessary	66				66	Review
		38	1			AIR CLEANER END HOSE			Deformed	40				40	Review
		39	1			RADIATOR			Cracked	850				850	Review
		40	1			AIR CONDENSER			Bent	860				860	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
		41	1			AIRCON FAN MOTOR ASSY			Cracked	1550				1550	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		TO KNOCK OUT DENTS, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	700	0	0	Reviewing		1
		2		TO RESPARY PAINT ON ACCIDENT PORTIONS	700	0	0	Reviewing		1
		3		TO CHECK WIRING	20	0	0	Reviewing		1
		4		TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100	0	0	Reviewing		1
		5		TO REMOVE, REPLACE ABS PUMP, PIPES, BELT, POWER STEERING PUMP AND RELATED PARTS	150	0	0	Reviewing		1
		6		TO RESET CHECK LIGHT	40	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

FRONT NUMBER
PLACE WITH
CASING

Deny

0



2

FRONT BUMPER
FOGLAMP COVER
- LH

Reviewing

16

(CRACKED)
SUPPLEMENTARY
16/01/2018



3

FRONT BUMPER
REINFORCEMENT
TOP BRACKET -
LH

Reviewing

65

(BENT)
SUPPLEMENTARY
16/01/2018



4

BONNET
STOPPER - LH

Reviewing

5

(NECESSARY)
SUPPLEMENTARY
16/01/2018



5

RADIATOR TOP
BRACKET - LH

Reviewing

6

(NECESSARY)
SUPPLEMENTARY
16/01/2018



6

RADIATOR TOP
HOSE

Reviewing

100

(TWISTED)
SUPPLEMENTARY
16/01/2018



EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		7	AIRCON CONDENSER SIDE GARNISH - LH	Reviewing	40	(CRACKED) SUPPLEMENTARY 16/01/2018	
		8	FRONT BUMPER FOG LAMP SIDE COVER - LH	Reviewing	16	(CUT)SUPPLEMENTARY 16/01/2018	
		9	BONNET TOP SPRING - CENTRE	Reviewing	11	(BENT) SUPPLEMENTARY 16/01/2018	
		10	DAYS OF REPAIR : 7 DAYS	Reviewing			

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount \$12,363.80

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,480.00	\$1,710.00
Spare Parts	\$17,222.80	\$11,394.80
Miscellaneous	\$35.00	\$259.00
Excess	-\$1,000.00	-\$1,000.00