

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC17023386/K1vbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	26-12-2017 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJL 8592Z	Veh. Ir	nspected	SHB 4898U	
	Policy No.	5067588920-02	Cover	age (\$)	0.00	
	Claim No.	MT/0972754-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	08/12/2017	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI SONATA	c.c		1991	
	Engine No.	HIDDEN	Year o	f Reg.	2011	
	Chassis No.	KMHET41VMBA815165	Colou	•	YELLOW	
	Odometer	288704	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	MAXXI		7 mm	
	L/H Front Tyre	215/60 R16	MAXXI	8	7 mm	
	R/H Rear Tyre	215/60 R16	TRIANG		7 mm	
	L/H Rear Tyre	215/60 R16	TRIANG	GLE	7 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/12/2017	Inspec	tion Date	08/12/2017	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					