

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD9184C - AXA

AAD1712-053

Not Authored
1/1/17 @ ?

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD9184C - JHOW
 LK1LA69RJB057998
 CHEVROLET
 EPICA 2.0
 05.12.2017
AXA

		PART		LIST
1	1	Rear Bumper	\$	<i>Btcm</i> 1,202.00 —
2	1	Rear Bumper Beam	\$	<i>Bt</i> 239.94 —
3	1	Rear Bumper Centre Absorber	\$	<i>Sn</i> 260.00 X
4	1	Rear Bumper Side Retainer RH	\$	<i>Crt</i> 68.76 —
5	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i> 68.76 X
6	1	Rear Bumper Reflectors RH	\$	<i>Bt</i> 119.74 —
7	1	Rear Bumper Reflectors LH	\$	<i>mtcm</i> 119.74 —
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00 X
9	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00 X
10	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i> 63.50 X
11	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00 X
12	1	Rear End Panel Outer	\$	<i>Bt</i> 623.76 —
13	1	Rear End Panel Inner Trim	\$	<i>Sn</i> 263.84
14	1	Bootlid	\$	<i>R</i> 973.00
15	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00
16	1	Bootlid Weatherstrip	\$	<i>Sn</i> 344.28
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>rr</i> 120.62
19	1	Bootlid Logo	\$	<i>rr</i> 138.84
20	1	Bootlid 'EPICA LT' Badge	\$	<i>rr</i> 119.84
21	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97
22	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40
23	1	Bootlid Reflector LH	\$	<i>Sn</i> 128.40
24	1	Bootlid Hinge RH	\$	<i>R</i> 120.00
25	1	Bootlid Hinge LH	\$	<i>R</i> 120.00
26	1	Rear Tail Lamp RH	\$	<i>Sn</i> 479.30
27	1	Rear Tail Lamp Panel RH	\$	<i>R</i> 359.00
28	1	Rear Tail Lamp LH	\$	<i>Sn</i> 479.30
29	1	Rear Tail Lamp Panel LH	\$	<i>R</i> 359.00
30	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00

X

31	1	Rear Fender RH	\$	1,145.00 X
32	1	Rear Fender Inner Trim RH	\$	418.44 X
33	1	Rear Fender LH	\$	1,145.00 X
34	1	Rear Fender Inner Trim LH	\$	418.44 X
35	1	Rear Fender Inner Cowling RH	\$	76.60 X

TOTAL	\$	13,742.03
10%	\$	1,374.20
	\$	12,367.83

Specical Nett

1	1Set	Licence Plate With Holder	\$	60.00 X
2	1Set	Bootlid inner trim board Clip	\$	40.00 X
3	1Set	Rear Bumper Parking Sensor	\$	300.00
4	1Set	Rear Bumper Fastener Clip	\$	44.00
5	1Set	Rear Fender Inner Trim Clip LH	\$	30.00 X
6	1Set	Rear Fender Inner Trim Clip RH	\$	30.00 X
7	1Set	Rear Bumper End Dust Cover Clip	\$	30.00 X
8	1	Rear Boot Sticker 'Trans-cab'	\$	30.00 X
9	1	Rear Boot Sticker '6555-3333'	\$	10.00 X
10	1	Rear Exhaust Mounting	\$	80.00 X
11	2	Rear Windscreen Sealant	\$	100.00 X
12	1	Rear Windscreen Inner Sponge Seal	\$	180.00 X
13	1	Spare Tyre	\$	126.74 X
14	1	Spare Wheel Rim	\$	

TOTAL	\$	1,090.74
TOTAL PARTS	\$	13,458.57

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$ 4,050.00

To Check Electrical Lighting Concerned.

\$ 170.00

To Rust-Proofing Of The Affected Areas.

\$ 170.00

Putty And Spray Painting Of The Affected
 Portion.

\$ 4,200.00

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	} 801
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	170.00	
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	nn X
To transfer of boot fittings and conduct water seepage test.	\$	170.00	nn X
Towing fees	\$	120.00	nn X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	nn X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	nn X
To check steering geometry and computer wheel alignment	\$	220.00	nn X
		\$ 10,330.00	
TOTAL	\$	23,788.57	

Repair Days

~~15 Days~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: