

22/03/2012

ASS. REC. BY:

REF:

CS/FCL7023455 / Agbnd

Special Instructions:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person): W/S Joanna Yong of FCL Date/Time: 11-12-2017 2:26pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGD 9312L Insured: SHA 7867Uat Workshop m/s MCS Garage Tel: 9270 0917of 10 Kaki Bukit Rd 2 #03-15Policy No: P-15072701MESH Claim No: D17011334 MESH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06/2/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

12.12.2017 @ after lunch.

H.O.D. Endorsement: _____

Date/Time: 11-12-2017 3:05pm Person Contacted: Kendrick Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGD 9312L - NA / MSB 16000524 / h4
	SHA 7867U - CS / FCL 13002505 / Unbdl
13/12-	Revert <u>predi</u> pending estimate
12/13/18 @ 11:56am	revised to Joanna Yong by email.
	CS @ 2500, 3 days (Red @ 9,32.28, 79%/-)

REF:

C 54443

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGD9312L Yr Regn: 14/01/2015Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW cc 1997Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 43900 T. Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA4A120106K . 06028Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35R20R: 255/35R20BS / DUN / EXNOVA / GY / FS / LIZA (MIC) / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 13/12/17Survey held at: MCSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 26 MAR 2018

Date/Time, File Pass to?

☐

Preli. Report

11/6/13 Sumit☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS \$

Phone

Others

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Invs \$

☐

Weekend \$

Report Format: TPLump Sum / I.B.A. (\$) 500

170 + 15

50

50

36

321



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023455/Aqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 11-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7867U	Veh. Inspected	SGD 9312L
Policy No.		Coverage (\$)	0.00
Claim No.	D17011334MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/12/2017	Inspection Date	12/12/2017
Survey held at	MCS GARAGE 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011334MFSH

Date: 19 March 2018

Our Ref: CS/FCI17023455/Aqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGD 9312L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/12/2017 at the premises of M/s MCS GARAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,632.28</u> .
Revised Estimate Amount	: S\$ <u>2,500.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	08-12-2017	Our Ref No. D17011334MFSH
Accident Date	06-12-2017	Claim Type. Third Party
Insured Vehicle	SHA7867U	Third Party Vehicle. SGD9312L
Survey Location	10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE	
Contact Person.	MR KENDRICK	
Contact No.	92700917/ 92700917	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MCS GARAGE	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231624)



PRI Documents



Close



PRI Header Details

Claim No	D17011334MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & VIS
Workshop Name	MCS GARAGE (Contact Person : MR KENDRICK)	Survey Location & Contact Details	10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CI Mobile: 92700917 , Phone: 92700917 , Fax: EmailId: CT-ADMIN@VISIONLAWLLC.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7867U	TP Vehicle No	SGD93
PRI Recieved Date	08-12-2017 03:49:59 PM	Surveyor Appointed Date	11-12-2017 02:26:23 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-12-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 19 March 2018 11:56 AM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011334MFSH/1
Attachments: CSFCI17023455Aqb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SGD 9312L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 13 December 2017 6:11 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011334MFSH/1

Dear Sir/Madam

Please be informed that we have inspected the vehicle SGD 9312L 13/12/2017
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 11 December, 2017 3:07 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011334MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 13 December, 2017 6:11 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011334MFSH/1

Dear Sir/Madam

Please be informed that we have inspected the vehicle SGD 9312L 13/12/2017
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 11 December, 2017 3:07 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011334MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Monday, 11 December, 2017 2:26 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011334MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

MCS Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868

Tel: 9270 0917 6538 4322

TP 1st Cap Xiao Chen

Vehicle No.: SGD 9312L

Model: BMW 420i

QTY	List Price:	Prices \$
1	Rear bumper <i>del d</i>	1583.86 ✓
1	Rear bumper difusser <i>del d</i>	641.23 ✓
2	Rear bumper reflector- R/L @ 89.95 <i>new</i>	179.90 x
4	Rear bumper PDC sensor @ 313.75 <i>1 piece damaged</i>	1255.00 313.75
1	Rear bumper top guide <i>new</i>	145.00 +
1	Rear bumper CTR pad	131.50 x
2	Rear bumper side guide- R/L @ 89.50 <i>new</i>	179.00 +
1	Rear bumper reinforcement <i>new</i>	745.00 +
2	Rear bumper side brackets- R/L @ 65.00 <i>new</i>	130.00 x
1	Rear exhaust insulator <i>new</i>	160.95 +
3	Rear exhaust mountings @ 42.50 <i>new</i>	127.50 +
1	Rear end panel <i>new</i>	1018.20 x
		6297.14
Less 5%		(314.86)
Subtotal		5982.28

Special Nett Items:

1	Rear exhaust muffler sport assy <i>new</i>	3500.00 +
1 Set	Rear bumper matte sticker <i>new</i>	600.00 300
Subtotal		4100.00

Vehicle No.:SGD 9312L

Labour Charges:

To checking R/electrical wiring	50.00	30
To remove, refix R/interior trims to assist repair	120.00	x
To remove, refix exhaust silencer	120.00	x
To respray undercoating	60.00	x
To respray painting and etc	600.00	250
Panel beating, remove and replacing above parts	600.00	250
Subtotal	1550.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 11632.28

total : 3241.89
L/S : 25K
03Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023455/Aqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7867U	Veh. Inspected	SGD 9312L	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011334MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	BMW	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA4A12010GK06028	Colour	SILVER	
Odometer	43900	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/35 R20	MICHELIN	6 mm	
L/H Front Tyre	255/35 R20	MICHELIN	6 mm	
R/H Rear Tyre	255/35 R20	MICHELIN	6 mm	
L/H Rear Tyre	255/35 R20	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/12/2017	Inspection Date	13/12/2017	
Survey held at	MCS GARAGE 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 9312L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,583.86	1,583.86
1	REAR BUMPER DIFUSSER	DEFORMED	641.23	641.23
2	REAR BUMPER REFLECTOR-R/L @\$89.95	NOT NECESSARY	179.90	-
4	REAR BUMPER PDC SENSOR @\$313.75	DAMAGED (1 PC ONLY)	1,255.00	313.75
1	REAR BUMPER TOP GUIDE	NOT NECESSARY	145.00	-
1	REAR BUMPER CTR PAD	NOT NECESSARY	131.50	-
2	REAR BUMPER SIDE GUIDE-R/L @\$89.50	NOT NECESSARY	179.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	745.00	-
2	REAR BUMPER SIDE BRACKETS-R/L @\$65.00	NOT NECESSARY	130.00	-
1	REAR EXHAUST INSULATOR	NOT NECESSARY	160.95	-
3	REAR EXHAUST MOUNTINGS @\$42.50	NOT NECESSARY	127.50	-
1	REAR END PANEL	NOT NECESSARY	1,018.20	-
	LESS 5% DISCOUNT		-314.86	-126.94
			5,982.28	2,411.90
SPECIAL NETT ITEMS				
1	REAR EXHAUST MUFFLER SPORT ASSY (SN)	NOT NECESSARY	3,500.00	-
1	SET REAR BUMPER MATTE STICKER (SN)	NECESSARY	600.00	300.00
			4,100.00	300.00
LABOUR				
	TO CHECKING R/ELECTRICAL WIRING.		50.00	30.00
	TO REMOVE,REFIX R/INTERIOR TRIMS TO ASSIST REPAIR.	NOT NECESSARY	120.00	-
	TO REMOVE,REFIX EXHAUST SILENCER.	NOT NECESSARY	120.00	-
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	60.00	-
	TO RESPRAY PAINTING AND ETC.		600.00	250.00
	PANEL BEATING,REMOVE AND REPLACING ABOVE PARTS.		600.00	250.00
			1,550.00	530.00
GRAND TOTAL			11,632.28	3,241.90

Report Ref No. CS/FC117023455/Aqbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00
---	--	--	----------

Report Ref No. CS/FCI17023455/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.