

ASS. REC. BY:

REF: CS/FC17023465/Kabn2 Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): CWS Pung Yin Min of FCL Date/Time: 08/12/2017 4:37pm

Estimated Cost: Bill to:

OD / (H) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHF 766Y Insured: SHB 3306T

at Workshop m/s: Trams Co Tel: 6287 6666

of No. 2 AMK St 63

Policy No: P-15072702MFSH Claim No: D17011331MTSH

Sum Insured: Excess:

Make of Veh: D.O.A. 06/22017
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP' 11.12.2017 H.O.D. Endorsement:

Date/Time: 08/12/2017 5pm Person Contacted: Candy Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHF 766Y - CS/FC17017155/Kabn2 DUA: 100917
	SHB 3306T - CS/FC13016484/Kabn2 DUA: 200613
12/12/17 @ 11.07am	revised to Pung Yin Min by email.
	Final Pay \$5244.52 (Red \$37610.12, 88%)

REP:

FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHF 766 Y

at Workshop m/s Trade - Lab

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res: Yes or No

Lum Sum: 1.131 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SHF 766 Y

Yr Regn:

06 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perash London

cc

1995

Colour:

M. White / Red

A/C

Insured / Std / NI / NA

Sp. Reading:

255602

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No: VIFIABL15AUC 283221

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt / or

Brake: In order / Jammed / Leaked / Burnt / or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal:

9

mm

Rear:

R/Bal:

8

mm

L/Bal:

9

mm

L/Bal:

8

mm

D.O.A:

6/12/17

D.O.I:

11/12/17

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/12 File pass to Corhem

RECEIVED 12 DEC 2017

Date/Time File Pass to?

12/12 14:55

☐

: Preli. Report

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Weekend: \$

Survey Fee

Transportation

31-12-17

Project

Client

TOTAL

12/12/17

32x15=480

170+480

50

50

16

766

Report Format:

Lump Sum / L.B.I

TP

1.B.I

5244.52



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023465/Kqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3306T	Veh. Inspected	SHF 766Y
Policy No.		Coverage (\$)	0.00
Claim No.	D17011331MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	08/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/12/2017	Inspection Date	11/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Reference No.: ES/FCI/7073465/K96
Policy Type: OD / TP / TP RES / TL / EVA

SNF 766Y

Typist

Admin (Carter): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

<u>Y-Date</u>	<u>N-Date</u>
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	

Surveyor (Kenneth): Case handler to make sure the surveyor completed all required information.

C	Vehicle No	✓		
C	Regn Month/Year	✓		
N	Vehicle Type	✓		
N	Make & Model	✓		
C	Engine Capacity. (C.C)	✓		
N	Colour	✓		
C	Odometer. (Sp.Reading)	✓		
C	Chassis No	✓		
N	General Condition	✓		
N	Steering	✓		
N	Brake	✓		
N	Modification (Modi)	✓		
C	Tyre Size	✓		
N	Tyre Make	✓		
C	Tyre Balance	✓		
C	Date of Inspection	✓		
N	Survey held	✓		
N	Des.of Damages	✓		

C	Damaged Vehicle Photographs Uploaded			
---	--------------------------------------	---	--	--

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

C	Resurvey photo uploaded	☒	☐	☐
---	-------------------------	-------------------------------------	--------------------------	--------------------------

Case Handler [Signature] Date 12/12/17

Case Handler

Date _____

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No: 195000106C
GST Reg. No: M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	08-12-2017	Our Ref No. D17011331MFSH
Accident Date	06-12-2017	Claim Type. Third Party
Insured Vehicle	SHB3306T	Third Party Vehicle. SHF766Y
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231620)

PRI Documents

Close X

PRI Header Details

Claim No	D17011331MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & TR, PTE LTD
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 6257133 EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORT		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3306T	TP Vehicle No	SHF760
PRI Recieved Date	08-12-2017 03:46:31 PM	Surveyor Appointed Date	08-12-2017 04:37:38 PM	Surveyor Accept Date	08-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-12-2017	Upload Survey Report *:	
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 12 December, 2017 11:41 AM
To: 'Claim Workflow System'; assignments
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011331MFSH/1
Attachments: CSFCI17023465Kqb.pdf

Dear Yin Min,

Please ignore previously attached.
Enclosed herewith latest preliminary advice.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 12 December, 2017 11:07 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011331MFSH/1

Dear Yin Min,

Enclosed herewith preliminary advice of SHF 766Y.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 8 December, 2017 5:07 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011331MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011331MFSH

Date: 12 December 2017

Our Ref: CS/FCI17023465/Kqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHF 766Y.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/12/2017 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>42,854.64</u> .
Revised Estimate Amount	: S\$ <u>5,244.52</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3878K
Vehicle Details	
Vehicle No.	SHF766Y
Vehicle to be Exported	Yes
Intended De-registration Date	07 Dec 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2015
Engine No.	M9R8839C002986
Chassis No.	VF1ABL15AUC283221
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	30 Jun 2016
First Registration Date	30 Jun 2016
Transfer Count	0
Actual ARF Paid	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	29 Jun 2024
PARF Rebate Amount	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date	29 Jun 2024
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$37,164.00
COE Rebate Amount	\$29,731.00
Total Rebate Amount	\$44,729.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Dec 2017

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF766Y - FCIL**AAD1712-062***Not Authenticated*
Phoney B4 part
5244.52

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF766Y - CANDY

VF1ABL15AUC283221

RENAULT

LATITUDE

06.12.2017

FCIL**PART****LIST**

1	1	BUMPER COVER FRT	\$	Bu 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	D.I 181.75	✓
3	1	BUMPER ABSORBER FRT	\$	SL 394.68	X
4	1	BUMPER RETAINER FRT LH	\$	D.I SL 151.41	✓
5	1	BUMPER SUPPORT FRT	\$	SL 123.88	X
6	1	BUMPER RETAINER FRT RH	\$	SL 150.77	X
7	1	BUMPER SUPPORT FRT	\$	SL 123.88	X
8	1	BUMPER UNDERTRAY FRT	\$	SL 472.83	X
9	1	BUMPER GRILLE LOWER FRT	\$	SL 266.80	X
10	1	BUMPER FOG LAMP GRILLE LH	\$	SL 207.21	X
11	1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.21	X
12	1	BUMPER BEAM FRT	\$	R 914.08	X
13	1	TOW COVER FRT	\$	SL 28.61	X
14	1	RADAIOR GRILLE	\$	mycom 1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R 225.36	✓
16	1	RADAIOR GRILLE FRAME	\$	CMA 1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	SL 615.90	X
18	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79	
19	1	FRONT BRACE PANEL	\$	R 177.22	
20	1	HORN	\$	SL 314.17	
21	1	HORN BRACKET	\$	R 40.45	
22	1	HEADLAMP LH	\$	SL 1,184.43	
23	1	HEADLAMP RH	\$	SL 1,184.43	
24	1	HEADLAMP PANEL FRT LH	\$	R 152.15	
25	1	HEADLAMP PANEL FRT RH	\$	R 152.15	
26	1	BONNET	\$	R 1,941.63	
27	1	BONNET INSULATOR	\$	SL 405.73	
28	1	BONNET LOCK	\$	R 305.48	
29	1	BONNET CABLE	\$	SL 119.19	
30	1	BONNET CABLE COVER	\$	SL 161.03	
31	1	BONNET SEAL OUTER	\$	SL 92.36	
32	1	FENDER PANEL FRT LH	\$	R 783.83	
33	1	FENDER PANEL FRT RH	\$	R 783.83	
34	1	WHEELARCH FRT LH	\$	SL 278.84	

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF766Y - FCIL**AAD1712-062**

35	1	WHEELARCH FRT RH	\$	Sin	278.84	}
36	1	FENDER BRACKET LOWER LH	\$	Sin	15.79	
37	1	FENDER BRACKET LOWER RH	\$	Sin	15.79	
38	1	FENDER INSULATOR LH	\$	Sin	130.84	
39	1	FENDER INSULATOR RH	\$	Sin	130.84	
40	1	A/C CONDENSER	\$	Sin	2,020.37	
41	1	A/C CONDENSER GARNISH LH UPPER	\$	Sin	39.67	
42	1	A/C CONDENSER GARNISH RH UPPER	\$	Sin	39.67	
43	1	A/C CONDENSER GARNISH LH	\$	Sin	58.81	
44	1	A/C CONDENSER GARNISH RH	\$	Sin	59.60	
45	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sin	208.39	
46	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sin	658.72	
47	1	A/C PIPE COMPRESSOR	\$	Sin	334.29	
48	1	A/C PIPE	\$	Sin	658.72	
49	1	A/C COMRPESSOR	\$	Sin	2,684.61	
50	1	AIR COOLER	\$	Sin	792.60	
51	1	AIR INTERCOOLER HOSE (LONG)	\$	Sin	1,014.13	
52	1	AIR INTERCOOLER HOSE (Short)	\$	Sin	375.14	
53	1	TRANSMISSION COOLER	\$	Sin	1,219.30	
54	1	TRANSMISSION COOLER PAD	\$	Sin	17.96	
55	1	RADIATOR	\$	Sin	1,202.20	} X
56	2	RADIATOR STUD UPPER	\$	Sin	14.41	
57	2	RADIATOR BUSH UPPER	\$	Sin	50.12	
58	2	RADIATOR MTG LOWER	\$	Sin	55.85	
59	1	RADAITOR FAN COWLING	\$	Sin	820.54	
60	1	RADIATOR FAN MOTOR LH	\$	Sin	967.36	
61	1	RADIATOR FAN MOTOR RH	\$	Sin	1,479.46	
62	1	RADIATOR TANK	\$	Sin	324.62	
63	1	RADIATOR HOSE UPPER	\$	Sin	240.56	
64	1	RADIATOR HOSE LOWER	\$	Sin	491.18	
65	1	RADIATOR TANK HOSE	\$	Sin	61.18	

TOTAL	\$	33,013.60
10%	\$	3,301.36
	\$	29,712.24

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	na	52.00	—
2	1SET	BUMPER CLIP FRT	\$	na	66.00	—
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF766Y - FCIL**AAD1712-062**

6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	} X
7	1	TOW COVER FRT	\$	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
13	1SET	WHEELARCH CLIP FRT LH	\$	30.50	
14	1SET	WHEELARCH CLIP FRT RH	\$	29.40	
15	1	CAP HUB LH FRT	\$	35.00	
16	1	RIM LH FRT	\$	385.00	}
17	1	TYRE LH FRT	\$	330.00	
18	1	CAP HUB RH FRT	\$	35.00	
19	1	RIM RH FRT	\$	385.00	
20	1	TYRE RH FRT	\$	330.00	

TOTAL	\$	1,942.40
TOTAL PARTS	\$	31,654.64

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 *500*

Towing Fees.

\$ *nn* 120.00 X

To apply paint protection system (PPS) maintain and enhancement

\$ *nn* 380.00 X

Putty and spray painting of the affected portion.

\$ 4,500.00 *220*

To rust-proofing of the affected areas.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *15*

To vacuum, replace, refix and recharge air condenser

\$ *nn* 380.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-062**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF766Y - FCILTo replace, refix and top up coolant for radiator \$ *nn* 170.00 XTo vacuum, replace, refix and recharge Air
Intercooler \$ *nn* 170.00 XTo Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test. \$ *nn* 170.00 X

TOTAL	\$	11,200.00
Over All Total	\$	42,854.64

< parts by parts > Repair Days

~~15 DAYS~~*3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023465/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3306T	Veh. Inspected	SHF 766Y	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011331MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	08/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC283221	Colour	METALLIC WHITE / RED	
Odometer	255602	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	WEST LAKE	9 mm	
L/H Front Tyre	215/60 R16	WEST LAKE	9 mm	
R/H Rear Tyre	215/60 R16	WEST LAKE	8 mm	
L/H Rear Tyre	215/60 R16	WEST LAKE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/12/2017	Inspection Date	11/12/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 766Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	DISTORTED	181.75	181.75
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	MTG CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-

Report Ref No. CS/FCI17023465/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSHER	SERVICEABLE	50.12	-

Report Ref No. CS/FCI17023465/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
	LESS 10% DISCOUNT		-3,301.35	-487.95
			29,712.24	4,391.52
SPECIAL NETT ITEMS				
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	29.40	-
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	CAP HUB RH FRT (SN)	SERVICEABLE	35.00	-
1	RIM RH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE RH FRT (SN)	SERVICEABLE	330.00	-
			1,942.40	118.00

Report Ref No. CS/FCI17023465/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT, FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, HEADLAMP PANEL FRT LH, HEADLAMP PANEL FRT RH, BONNET, BONNET LOCK, FENDER PANEL FRT LH AND FENDER PANEL FRT RH.		4,200.00	500.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			11,200.00	735.00
	GRAND TOTAL		42,854.64	5,244.52
	RECOMMENDED COST OF REPAIRS			5,244.52

Report Ref No. CS/FCI17023465/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.