



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:


CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	E DIV	Reference No.
VEH NO :	QX509Y	FRC	REPAIR TYPE:	ACCIDENT	MHA/SPF/2017/12-0004
VEH MAKE/MODEL:	TOYOTA ALTIS	Mileage:			

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	BONNET / <i>acc</i>	210.00	1	18%	247.80	247.80
1.2	BONNET HINGE RH	25.00	1	18%	29.50	29.50
1.3	BONNET HINGE LH	25.00	1	18%	29.50	29.50
1.4	BONNET HINGE GARNISH LH	20.00	1	18%	23.60	23.60
1.5	BONNET LOCK	40.00	1	18%	47.20	47.20
1.6	FRT BUMPER	170.00	1	18%	200.60	200.60
1.7	FRT BUMPER LOWER GRILLE	30.00	1	18%	35.40	35.40
1.8	FRT BUMPER CLIP	1.30	10	18%	1.53	15.34
1.9	FOG LAMP COVER LH	25.00	1	18%	29.50	29.50
1.10	FRT BUMPER SPONGE	0	1	18%	0.00	0.00
1.11	FRT BUMPER REINFORCEMENT	120.00	1	18%	141.60	141.60
1.12	HEADLAMP LH	130.00	1	18%	153.40	153.40
1.13	RHF FENDER INNER SHIELD	45.00	1	18%	53.10	53.10
1.14	LHF FENDER	140.00	1	18%	165.20	165.20
1.15	LHF FENDER INNER SHIELD	50.00	1	18%	59.00	59.00
1.16	FENDER INNER SHIELD CLIPS	1.50	12	18%	1.77	21.24
1.17	LHF WHEEL HOUSE	165.00	1	18%	194.70	194.70
1.18	FRT SUPPORT PANEL ASSY	220.00	1	18%	259.60	259.60
1.19	BRACE PANEL	40.00	1	18%	47.20	47.20
1.20	CONDENSER	270.00	1	18%	318.60	318.60
1.21	RADIATOR	380.00	1	18%	448.40	448.40
1.22	RADIATOR TOP BRACKET LH	20.00	1	18%	23.60	23.60
1.23	RADIATOR TOP BRACKET MOUNTING LH	8.00	1	18%	9.44	9.44
1.24	FRT BUMPER RETAINER RH	20.00	1	18%	23.60	23.60
1.25	FRT NUMBER PLATE	30.00	1	18%	35.40	35.40
1.26	LHF FENDER SIDE PROTECTOR	30.00	1	18%	35.40	35.40
1.27	AIR CLEANER TOP	260.00	1	18%	306.80	306.80
1.28	AIR CLEANER BOTTOM	20.00	1	18%	23.60	23.60
1.29	AIR CLEANER INLET 1 17751-37060	45.00	1	18%	53.10	53.10
1.30	AIR CLEANER INLET 2 17752-37070	65.00	1	18%	76.70	76.70
1.31	AIR RESONATOR 17893-22030	75.00	1	18%	88.50	88.50
1.32	ENGINE MOUNTING LH 12370-0D190	65.00	1	18%	76.70	76.70
1.33	ENGINE MOUNTING FRT	1900.00	1	18%	2242.00	2242.00
1.34	ENGINE ECU	75.00	1	18%	88.50	88.50
1.35	FUSE BOX ASSY	35.00	1	18%	41.30	41.30
1.36	FUSE BOX TOP COVER	40.00	1	18%	47.20	47.20
1.37	FUSE BOTTOM COVER	390.00	1	18%	460.20	460.20
1.38	LHF DOOR	30.00	1	18%	35.40	35.40
1.39	LHF DOOR HINGE TOP	35.00	1	18%	41.30	41.30
1.40	LHF DOOR HINGE BOTTOM	55.00	1	18%	64.90	64.90
1.41	LHF DOOR CHECKER	25.00	1	18%	29.50	29.50
1.42	LHF DOOR BLACK STICKER	45.00	1	18%	53.10	53.10
1.43	LHF DOOR PROTECTOR WITH CHROME	260.00	1	18%	306.80	306.80
1.44	LH SIDE MIRROR ASSY	350.00	1	18%	413.00	413.00
1.45	LHR DOOR	28.00	1	18%	33.04	33.04
1.46	LHR DOOR OUTER HANDLE	10.00	1	18%	11.80	11.80
1.47	LHR DOOR OUTER HANDLE SIDE COVER	45.00	1	18%	53.10	53.10
1.48	LHF DOOR GLASS OUTER MOULDING	35.00	1	18%	41.30	41.30
1.49	LHR DOOR BLACK STICKER	170.00	1	18%	200.60	200.60
1.50	REAR BUMPER	130.00	1	18%	153.40	153.40
1.51	TAILLAMP RH	130.00	1	18%	153.40	153.40
1.52	TAILLAMP LH	1.50	10	18%	1.77	17.70
1.53	REAR BUMPER CLIP	55.00	1	18%	64.90	64.90
1.54	ENGINE UNDER COVER RH	55.00	1	18%	64.90	64.90
1.55	ENGINE UNDER COVER LH	680.00	1	18%	802.40	802.40
1.56	ENGINE CROSS MEMBER	160.00	1	18%	188.80	188.80
1.57	ENGINE CROSS MEMBER SUB 21204-02090	130.00	1	18%	153.40	153.40
1.58	RHF S/ABSORBER	75.00	1	18%	88.50	88.50
1.59	RHF LOWER ARM	60.00	1	18%	70.80	70.80
1.60	RHF LOWER ARM BALL JOINT	145.00	1	18%	171.10	171.10
1.61	RHF KNUCKLE ARM	25.00	1	18%	29.50	29.50
1.62	RHF WHEEL BEARING ASSY	75.00	1	18%	88.50	88.50
1.63	RHF TIE ROD	60.00	1	18%	70.80	70.80
1.64	RHF TIE ROD END	55.00	1	18%	64.90	64.90
1.65	RHF ANTI ROLL BAR LINK	125.00	1	18%	147.50	147.50
1.66	ANTI ROLL BAR	130.00	1	18%	153.40	153.40
1.67	LHF S/ABSORBER	75.00	1	18%	88.50	88.50
1.68	LHF LOWER ARM	60.00	1	18%	70.80	70.80
1.69	LHF LOWER ARM BALL JOINT	145.00	1	18%	171.10	171.10
1.70	LHF KNUCKLE	25.00	1	18%	29.50	29.50
1.71	LHF WHEEL BEARING ASSY	75.00	1	18%	88.50	88.50
1.72	LHF TIE ROD	60.00	1	18%	70.80	70.80
1.73	LHF TIE ROD END	55.00	1	18%	64.90	64.90
1.74	LHF ANTI ROLL BAR LINK	125.00	1	18%	147.50	147.50
1.75	LHF BRAKE PIPE ASSY	145.00	1	18%	171.10	171.10
1.76	LHF ABS SENSOR	450.00	1	18%	531.00	531.00
1.77	LHF DRIVE SHAFT	450.00	1	18%	531.00	531.00
1.78	RHF DRIVE SHAFT	250.00	4	18%	295.00	1180.00
1.79	SPORT RIM 1 SET	115.21	4		115.21	460.84
1.80	195/65/15 TYRE	750.00	1	18%	885.00	885.00
1.81	REAR AXLE BEAM ASSY	75.00	1	18%	88.50	88.50
1.82	LHR S/ABSORBER	75.00	1	18%	88.50	88.50
1.83	RHR S/ABSORBER	190.00	1	18%	224.20	224.20
1.84	LHR WHEEL BEARING	190.00	1	18%	224.20	224.20
1.85	RHR WHEEL BEARING	105.00	1	18%	123.90	123.90
1.86	LHF DISC ROTOR	65.00	1	18%	76.70	76.70
1.87	FRT BRAKE PAD	165.00	1	18%	194.70	194.70
1.88	WIPER PANEL GARNISH LH	20.00	1	18%	23.60	23.60
1.89	COOLANT	60.00	1	18%	70.80	70.80
1.90	WHEEL ALIGNMENT					

Front - Cut 2pc
Rear 2pc
Cut

		Additional Services					
2.1	DRIVER SEAT COVER	210.00	1	18%	247.80	247.80	
2.2	RHF DOOR FRAME WEATHER STRIP	90.00	1	18%	106.20	106.20	
2.3	LHF DOOR FRAME WEATHER STRIP	90.00	1	18%	106.20	106.20	
2.4	COWL TRIM RH	85.00	1	18%	100.30	100.30	
2.5	COWL TRIM LH	85.00	1	18%	100.30	100.30	
2.6	LHF SCUFF PLATE	75.00	1	18%	88.50	88.50	
2.7	RHF SCUFF PLATE	75.00	1	18%	88.50	88.50	
2.8	RH SEATBELT LOWER GARNISH	120.00	1	18%	141.60	141.60	
2.9	LH SEATBELT LOWER GARNISH	120.00	1	18%	141.60	141.60	
2.10	LHR SCUFF PLATE	85.00	1	18%	100.30	100.30	
2.11	RHR SCUFF PLATE	85.00	1	18%	100.30	100.30	
2.12	DASHBOARD COIN BOX	40.00	1	18%	47.20	47.20	
Remarks:		ITEM 2.2 - 2.12 ORDER BY AIR, ETA 4 - 6 WEEKS. ITEM 2.1 IS A 3RD PARTY QUOTE.				Parts Total:	\$ 16,812.10

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	TO ALIGN, REPLACE, RESPRAY BONNET AND HINGES	53.80	6	322.80
1.2	TO ALIGN, REPLACE AND RESPRAY SUPPORT PANEL	53.80	4	215.20
1.3	TO REPLACE AND RESPRAY FRT BUMPER	53.80	5	269.00
1.4	TO ALIGN, REPLACE AND RESPRAY REINFORCEMENT	53.80	1	53.80
1.5	TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK	53.80	10	538.00
1.6	TO ALIGN, REPAIR AND RESPRAY CHASSIS, WHEEL HOUSE	53.80	6	322.80
1.7	TO REPLACE LHF WHEEL HOUSE	53.80	10	538.00
1.8	TO REPLACE AND RESPRAY LHF FENDER	53.80	4	215.20
1.9	TO REPALCE AND RESPRAY LHF DOOR	53.80	6	322.80
1.10	TO REPLACE AND RESPRAY LHR DOOR	53.80	6	322.80
1.11	TO REPAIR AND RESPRAY LHR FENDER	53.80	12	645.60
1.12	TO REMOVE AND REFIX REAR PASSENGER AND UPHOISTERY TO ASSIST WORK	53.80	2	107.60
1.13	TO REPAIR AND RESRAY REAR BUMPER	53.80	6	322.80
1.14	TO REPLACE REAR AXLE AND UNDERCARRIAGE	53.80	3	161.40
1.15	TO REPLACE FRT UNDER CARRIAGE PARTS	53.80	4	215.20
1.16	TO PERFORM 4 WHEEL ALIGNMENT	53.80	1	53.80
1.17	TO REPLACE, CONDENSER, RADIATOR AND TOP UP AC GAS	53.80	2	107.60
2	Additional Services			
2.1	TO REPLACE ADDITIONAL ITEM	53.80	1	53.80
		22.00		0.00
		22.00		0.00
		Labour Total:		\$ 4,788.20
		GRAND TOTAL :		\$ 21,600.30
Contractor shall complete the entire repair within 18 working days upon quotation approved date.				

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	Gan Hin Tong	Name:		Name:	
Date:	5/12/17	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made

Eno. Giong - 82880282

11/12/17

part by part.

before paint photos.
Not Authorized.


13/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: