

22/03/2002

ASS. REC. BY:

REF: C93 / ICS 17023480 / Wbez

Special Instruction:

range & days

Survivor: Wilson

ASSIGNMENT (Office)

From (Person): Janice Gan of ICS Date/Time: 11-12-2017 11:07am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBF 76B Insured: SDG 24Y

at Workshop m/s: Lish Automotive Tel: 9796 6979

of 8 Kaki Bukit Ave 4 # 03-47

Policy No: Claim No: DMPCL700733H

Sum Insured: Excess:

Make of Veh: D.O.A. 07-12-2017
(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time: 11-12-2017 11:20am Person Contacted: Max Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SBF 76B - X
	SDG 24Y - X
	Dismantle part: 14-12-2017
	After repair: 26-12-2017

PRS

REF: TCS

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop / Mile: Hugh Motor
of 8 Baker Bldg. Ave. 4 #03 - 47
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time: _____ Action / Instruction: _____

Veh No: SBF 76 B Reg: Not Available
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes C180 Reg: Not Available

Colour: Black A.C. Insured / Std / Nil / NA

Sp. Reading: 146822 T. Radio: Insured / Std / Nil / NA

Eng. No: _____

C. No: WDD 2040452 A431885

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 45 R17
R: 225 / 45 R17

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Michelin

Front	Rear
R. Bal. <u>4</u> mm	R. Bal. <u>4</u> mm
L. Bal. <u>4</u> mm	L. Bal. <u>4</u> mm

D.O.A: _____ D.O: 12/12/2017

Survey held at: At Above @ 1.19pm

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

RHR 3:30

The U/C / Chassis frame / Body Structure affected due to collision

Accident Report Not Given

Range - \$4900 - \$5900

4 Days Repair 9/4/2018

* Catherine tried asked C.I.A from Lawyer - declined!

RECEIVED: 1 APR 2018

Date/Time File Pass to: ☐ : Preli. Report

10.04.2018

☐ : Final Report

Date/Time File Return to: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

Photo

Other

Add Fee: ☐ Site Insp. \$

☐ Interview \$

☐ Tech. Insp. \$

☐ Weekend \$

Report Format: PRS

Lump Sum / I.B.I. \$

100

100+100

300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS3/ICS17023480/Wb

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 11-12-2017



Code : ICS

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SDG 24Y	Veh. Inspected	SBF 76B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/12/2017	Inspection Date	12/12/2017
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 11 December, 2017 11:07 AM
To: Yvonne; 'assignments'
Cc: ECICS Claims
Subject: RE: [PRI] ECICS insured SDG24Y - 2017.5339.MK.ya - SBF76B

Without Prejudice

Hi Yvonne

Thank you for your email.

We are not agreed with your list of surveyor and we will appoint LKK for PRI.

Aside to LKK

Please refer to the email below and arrange for PRI.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Yvonne [<mailto:yvonne@ealc.com.sg>]
Sent: Monday, 11 December, 2017 11:00 AM
To: ECICS Claims
Subject: [PRI] ECICS insured SDG24Y - 2017.5339.MK.ya - SBF76B

Our ref : 2017.5339.**SBF76B**.MK.ya
Your ref : **SDG24Y**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s ECICS Limited		
Vehicle SBF76B inspected as follows by Name:		
Before repair	Parts removed	After repair
_____ Signature	_____ Signature	_____ Signature
_____ Date/ Time:	_____ Date/ Time:	_____ Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: KWAN LAI WAN JENNY

**ACCIDENT INVOLVING SBF76B & SDG24Y ON 7 DECEMBER 2017 ALONG 253 ALEXANDRA ROAD (OUTSIDE KOMOCO MOTORS)
AT ABOUT 1050 HOURS**

We refer to the above matter wherein we are instructed to act for **KWAN LAI WAN JENNY**, the owner of vehicle no. **SBF76B**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SBF76B** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Lush Automotive Pte Ltd
No. 8 Kaki Bukit Avenue 4,
#03-47 Premier@Kaki Bukit,
Singapore 415875
Tel: 97966979 (Mr Max)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

		
---	---	---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No				
C Claim No				
C Insurance Authorisation (CA /REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition				
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair				
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded				
---------------------------	--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

ECICS LTD

Ref: CS3/ICS17023480/Wbe2

7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER
ONESINGAPORE 038987

Date: 11-04-2018



Code: ICS

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SDG 24Y	Veh. Inspected	SBF 76B
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC1700733H	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	11/12/2017

2. Vehicle Particulars & Condition


Make & Model	MERCEDES C180	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WDD2040452A431885	Colour	BLACK
Odometer	146822 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	4 mm
L/H Front Tyre	225/45 R17	MICHELIN	4 mm
R/H Rear Tyre	225/45 R17	MICHELIN	4 mm
L/H Rear Tyre	225/45 R17	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.

**5. General Information**

Accident Date	07/12/2017	Inspect Date / Time	12/12/2017 (01:19 PM)
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,900-\$5,900

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

Report Ref No. CS3/ICS17023480/Wbe2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.