

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop no: _____

SP: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 3 days Res: Yes or NoLump Sum: 20 % 3 Valid Yes or No

CA / REV / REP. / 24 HRS.

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date Time Action Instruction

AIG SJP 38594

Veh No: SKH225XPage: June 2012Type: ☒ Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer /

Make: Mercedes Benz C180

1597

Colour: White

A/D Insured: Std / N / NA

Stc Reading: 127943

T/Paid Insured: Std / N / NA

Eng No: 27191031355524O No: WDD2040452A720455Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrakes: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☒ Nil / ☐ S/R / ☐ STD A/Rim orTyre Size: R: 255/35 R18R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodyear

Front

Rear

R.Bal. 5' mmR.Bal. 5' mmL.Bal. 5' mmL.Bal. 5' mmD.O.A. 03/12/2017D.O.A. 18/12/2017Survey held at Tecmover Page ubiDes. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/O / ☐ Rooftop orRear O/S

The U/O / Chassis frame / Body Structure affected due to collision

Date Time File Pass to:



Prel. Report

Days Of Repair:

1



Final Report

Resurvey No. of Trip:

Survey Fee

Date Time File Return to:

Transportation

2

Add Fee:



Site Insd \$

Lump Sum \$



Interf \$

Rental



Tech Ins \$

Fuel



Map \$

Other

Report Format:

Lump Sum / LB \$:

