



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

General Details

Involving
1 2008 SUBARU EXIGA MPV 2.0I AWD 4AT SUBXXX (SJL1360Y)

Date of Loss
December 7, 2017

Time of Loss
22.30

Loss Description
SJL1360Y (INSD) C/W SKB2642T (TP)

Comment
EXCESS : \$2000.00

Workshop Details

Total Rebate Amount
13747

Nett Loss Amount
\$11,253.00

Assigned Workshop
LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *
02/19/2018

Days of work completion *
70

«

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#

SJL1360Y

Registration State

SINGAPORE

Mileage

149938

Purchase Date

mm/dd/yyyy

Registration Date *

11/15/2008

Age of Vehicle

9

CATEGORY

Manufacturing Year

POLICY INFORMATION

2008

ASSESSMENT INFORMATION

2008

CATEGORY

Make

POLICY INFORMATION

SUBARU EXIGA MPV 2.0i AWD 4AT

CATEGORY Model

POLICY INFORMATION SUBXXX

ASSESSMENT INFORMATION EXIGA MPV 2.0i AWD 4AT ABS AIRBAG

CATEGORY Type

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY Type of Paint

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY Chassis No

POLICY INFORMATION YA5009792

ASSESSMENT INFORMATION YA5009792

CATEGORY Engine No

POLICY INFORMATION EJ20D605537

ASSESSMENT INFORMATION EJ20D605537

CATEGORY Engine Capacity

POLICY INFORMATION

ASSESSMENT INFORMATION 1994



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

12/13/2017

Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

205/60R16

Front left side

YOKOHAMA6mm

Front right side

YOKOHAMA6mm

Spare wheel

Rear Tyre Size

205/60R16

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

https://vp.smartclaims.axa.com.sg/claim-portal/html/index-vendor-service-requests.html#/service-requests/assessment/?serviceRequestNumber=216... 1/10

1

FRT BUMPER SIDE RETAINER LH

Damaged

12

12

Reviewing



3

1

FRT BUMPER SIDE RETAINER RH

Serviceable

0

0

0

0

0

Deny



4

10

FRT BUMPER CLIPS

Necessary

2

20

Reviewing





5

1

FRT BUMPER INNER SPONGE

Serviceable

0

0

0

0

0

Deny



6

1

FRT BUMPER REINFORCEMENT

Serviceable

0

0

0

0

0

Deny



7

1

FRT BUMPER BEAM (BELOW HEAD LAMP) LH (NPA)

Serviceable

0

0

0

0

0

Deny







8

1

FRT HEADLAMP LH

Serviceable

0

0

0

0

0

Deny







9

1

FRT FENDER LH

Buckled

160

160

Reviewing



10

1

FRT FENDER INNER COWLING LH

Serviceable

0

0

0

0

0

Deny



11

10

FRT FENDER INNER COWLING CLIPS

Serviceable

0

0

0

0

0

Deny



Labour

Add

Approve

Deny



1

WIRE CHECKING.

20

0

0

Reviewing



2

LABOUR CHARGE.

300

0

0

Reviewing



3

SPRAY PAINTING.

450

0

0

Reviewing





Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount
\$1,282.00

CATEGORY Labour

ESTIMATE \$770.00

REVISED AMOUNT \$770.00

CATEGORY Spare Parts

ESTIMATE \$512.00

REVISED AMOUNT \$512.00

Submit for Review

