

SS. REC. BY:

REF: CS/FCU7023486/Ugb⁰⁷

Special Instruction:

SURVAYOR

ASSIGNMENT (Office) ✓

From (Person): (WS) Luene Jan of FCI Date/Time: 11/12/2017 255pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: G8G 7572J Insured: SHC 7650S

at Workshop m/s Jin Auto Tel: 6289 8126

of Blk 111 Defu Lane #01-410 / 412

Policy No: 015072707MFSH Claim No: D17011337MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 07/12/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1 H.O.D. Endorsement:

Date/Time: 11/12/2017 309pm Person Contacted: Jouis Vehicle: IN / OUT


Date/Time	Action/Instruction (✓) Estimate
	G8G 7572J - X
	SHC 7650S - CS/TML6005660/mlyh2
13/12/17 @ 10.27am	revised to Luene by email

Surveillance *morris*

REF: *TCI*

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *GRG 7572J*
at Workshop m/s: *Y.1 Auto 9*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
G/L / PR Seen: *2* Consistent? : Yes or No
Est. Repairs: *3* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No *6867W*

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: *GRG 7572J* Yr Regn: *10 / 17*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *M*
Make: *Nissan NV350* c.c. *2488*
Colour: *white* A/C: Insured / Std / NI / NA
Sp. Reading: *1142* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *JN1MC2E2620008460*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: *In order* / Jammed / Leaked / Burnt or
Brake: *In order* / Jammed / Leaked / Burnt or
Mod: *2.0* / S/Rim / STD A/Rim or
Tyre Size: F: *195-215*
R: _____
BS / *DUN* / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front *6* mm Rear *6* mm
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. *7/12/17* D.O.I. *12/12/17*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
4/1/18 confirmed L/S \$1400 with Jones.
(Red \$891.54, 30/10)

RECEIVED 09 JAN 2018

Date/Time, File Pass to? ☐ : Preli. Report
09/1 twist ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: *3*
Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)
Survey Fee: _____
Transportation: _____ \$ + RS _____ \$
Photos _____
Others _____

Report Format : *TP*
Lump Sum / I.B.I. (\$) *1400*

110
50
19
179

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023486/Uqb

36 ROBINSON ROAD

#16-01 CITY HOUSES SINGAPORE 068877

Date : 11-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7650S	Veh. Inspected	GBG 7572J
Policy No.		Coverage (\$)	0.00
Claim No.	D17011337MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	11/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/12/2017	Inspection Date
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011337MFSH

Date: 13 December 2017

Our Ref: CS/FCI17023486/Uqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBG 7572J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/12/2017 at the premises of M/s JIN AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,291.54 .
Revised Estimate Amount	: S\$ 1,756.07 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the o/s rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

21/05/2014

MOTOR SURVEY ASSIGNMENT

Date	08-12-2017	Our Ref No. D17011337MFSH
Accident Date	07-12-2017	Claim Type. Third Party
Insured Vehicle	SHC7650S	Third Party Vehicle. GBG7572J
Survey Location	BLK 14 #01-410/412 DEFU LANE 10	
Contact Person.	JOUIS SEOW	
Contact No.	62898126/ 0	Fax No. 62870590
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	JIN AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231631)

PRI Documents

Close X

PRI Header Details

Claim No	D17011337MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & JIN
Workshop Name	JIN AUTO SERVICES PTE LTD (Contact Person : JOUIS SEOW)	Survey Location & Contact Details	BLK 14 #01-410/412 DEFU LANE 10 Mobile: 0 , Phone: 62898126 , Fax: 6287059 EmailId: JOUIS@JINAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7650S	TP Vehicle No	GBG75
PRI Recieved Date	11-12-2017 04:46:32 PM	Surveyor Appointed Date	11-12-2017 02:54:27 PM	Surveyor Accept Date	11-12-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-12-2017	Upload Survey Report *:	
------------------------------------	---	-----------------------------	------------	--------------------------------	---

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 13 December, 2017 10:27 AM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011337MFSH/1
Attachments: CSFCI17023486Uqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of GBG 7572J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 11 December, 2017 3:11 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011337MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Monday, 11 December, 2017 2:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011337MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	6167W

Vehicle Details

Vehicle No.	GBG7572J
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	NISSAN
Vehicle Model	NV350 PANEL VAN 2.5 5MT 5DR
Primary Colour	White
Manufacturing Year	2017
Engine No.	YD25420391A
Chassis No.	JN1MC2E26Z0008460
Maximum Power Output	-
Open Market Value	\$25,062.00
Original Registration Date	25 Oct 2017
First Registration Date	25 Oct 2017
Transfer Count	0
Actual ARF Paid	\$1,254.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	24 Oct 2027
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
PQP Paid	\$34,839.00
COE Rebate Amount	\$34,370.00
Total Rebate Amount	\$34,370.00

The information contained herein is correct as at 12 Dec 2017

OK

JIN AUTO SERVICES PTE LTD

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62894656 Fax: 62870590

Company Reg No: 200704370C GST Reg No: 200704370C

M/S

DEAR SIR

ESTIMATED REPAIR COST FOR VEHICLE GBG7572J (NV350)

- List Items
- 1 REAR BUMPER
 - 1 REAR BUMPER CLIPS
 - 1 REAR RH SIDE RETAINER
 - 1 REAR END PANEL
 - 1 TAILLAMP 2/5

LESS 30%

COMPANY ART WORK S.N
To remove and refit rear electrical wiring,
To remove and replace the above damaged parts,
To spray paint on the replaced and repaired parts,

Reep (u)	\$	632.70	✓
re	\$	30.00	✓
re	\$	66.10	α
re	\$	356.00	α
one	\$	417.40	✓
	\$	1,502.20	
	\$	(450.66)	
	\$	1,051.54	
re	\$	280.00	✓
	\$	40.00	20
	\$	420.00	300
	\$	500.00	400
TOTAL :	\$	2,291.54	

Not Adult
atk
take phl. reinsurance.

327.
12/1/17

2/5 \$1400/-

1080-1
756-07
1756-07

JKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to prior approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023486/Uqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7650S	Veh. Inspected	GBG 7572J	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011337MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 (M)	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JN1MC2E26Z0008460	Colour	WHITE	
Odometer	1142	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	DUNLOP	6 mm	
L/H Front Tyre	195 R15	DUNLOP	6 mm	
R/H Rear Tyre	195 R15	DUNLOP	6 mm	
L/H Rear Tyre	195 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/12/2017	Inspection Date	12/12/2017	
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 7572J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEEP CUT	632.70	632.70
1	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR RH SIDE RETAINER	NOT NECESSARY	66.10	-
1	REAR END PANEL	NOT NECESSARY	356.00	-
1	TAILLAMP O/S	CRACKED	417.40	417.40
	LESS 30% DISCOUNT		-450.66	-324.03
			1,051.54	756.07
	<u>SPECIAL NETT ITEMS</u>			
1	COMPANY ART WORK (SN)	NECESSARY	280.00	280.00
			280.00	280.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING.		40.00	20.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS.		420.00	300.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS.		500.00	400.00
			960.00	720.00
	GRAND TOTAL		2,291.54	1,756.07
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS/FCI17023486/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.