

ASS. REC. BY:

REF: CS/CTI/7023549/Krbn2 Special Instruction:

SYNOPSIS:

Kenneeth

ASSIGNMENT (Office)

From (Person):

Joel Goh

of CTI

Date/Time: 12/12/17 @ 10:48am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJH 2034D

Insured:

SKG8932R

at Workshop m/s

Car times Automobile

Tel:

6471 5111

of

160 Sin Ming Drive #02-04

Policy No:

BMPCSN3100311701

Claim No:

SNM17D07018 C02 / 2T

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/12/2017

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time: 11:43am @ 12/12/17

Person Contacted:

Gai Cheng

Vehicle: UN/OUT

Date/Time

Action/Instruction (☒) Estimate

SJH 2034D - X

SKG8932R - X

Confirm Ls \$1,700.00, 4 days

Red: \$2520.83, 60%.

ASS. REC. BY:

REF: C72/Kennerth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Ce Timeof 02-04

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJH 2034D Yr Regn: 07, 08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vios G c.c. 1497Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 134706 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR0531479305072289Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: Compasol 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm R/Bal. 5 mmL/Bal. 2 mm L/Bal. 5 mmD.O.A. 7/12/17 D.O.I. 12/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/12 File sent to Customer

RECEIVED 23 JAN 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 41) by prof☒ : Final ReportResurvey No. of Trip: -

Date/Time, File Return to?

2)

Report Format: TPLump Sum / I.B.I. (\$) 1700Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI17023549/Krb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 12-12-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKG 8932R	Veh. Inspected	SJH 2034D	
Policy No.	DMPCSN3100311701	Coverage (\$)	0.00	
Claim No.	SNM17D07018C021/2T	Excess (\$)	0.00	
Assign From	MERIMEN (JOEL GOH)	Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/12/2017	Inspection Date	12/12/2017	
Survey held at	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Int Auth'd	Status
Main	12 Dec 2017		12 Dec 2017 10:48 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TAY CHENG HAI, ID: S0159581D		
Main Claimant:	EZTHOMAS TRANSPORT, Co. Reg. No.: 53353334A		
Vehicle Reg. No.:	SJH2034D	Date of Loss:	07/12/2017 19:00 - :59
Claim Type:	TP / SNM17D07018C02/2T	Policy/Cover Note No.:	DMPCSN3100311701 (Comprehensive)
Vehicle Reg. No. (Insured):	SKG8932R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Car Times Autolution Pte Ltd (HQ) 160 SIN MING DRIVE AUTOCITY #02-04, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/12/2017]		
Driver/Custodian (Insured):	TAY MEI MEI AMELIA(ZHENG MEI MEI AMELIA) (33 / Female), NRIC: S8431825F, Tel: +6598308899		
Adj Asg. Remarks:	NO ESTIMATES. GUO QIANG SELECTED AS SJE FOR WP PRS		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Chassis No. MR053HY9305072299

Not Authorial
Lib 8?
Pursing After Point
4 days
KennethKong@1Kkguto.com

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	900.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (pearl white)	800.00	440
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	120.00	20
	Labour Total :	1820.00	
	TOTAL (PARTS & LABOUR):	4220.83	



CARTIMES

autolution

Vehicle No. SJH2034D

Car Model : TOYOTA VIOS

Chassis No. MR053HY9305072299

Vehicle No. SM20340		Car Model : TOYOTA VIOS		Chassis No. MR053HY9305072299	
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT(S\$)	
1	Rear bumper	Damaged	Bu 489.80	—	
1	Rear boot	Damaged	Bu 789.40	—	
1	Exhaust	Damaged	Bu 568.40	X	
1	End panel	Damaged	Bu 485.60	X	
1	RHS reflector	Damaged	ngm 78.87	—	
1	RHS taillamp	Damaged	Bu 287.40	X	
1	Retainer	Damaged	Bu 68.04	X	
			25%		
			25%	2767.51	1645.47
			25%	691.88	411.37
				2075.63	1234.10
<u>SPECIAL NETT ITEMS</u>					
1	Reverse sensor	Necessary	shan 200.00	✓	
1	Toyota logo	Necessary	Bu 65.50	—	
1	Vios wording	Necessary	Bu 59.70	—	
			325.20	325.20	
TOTAL PARTS			2400.83	1559.30	

Kenneth
96910663

Not Authorised
Liby B 1700h
Pursing Atu Pains
4 days

Kenneth.Kang@1Kkauto.com

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	900.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (pearl white)	800.00	400
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	120.00	200
	Labour Total :	1820.00	800
	TOTAL (PARTS & LABOUR):	4220.83	2419.30

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117023549/KRBN2

Date: 24/01/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3100311701	
Claimant Vehicle No :	SJH2034D	Insured Vehicle No :	SKG8932R	
Date of Loss:	07/12/2017	Nature of Claim:	TP	Claim No: SNM17D07018C02/2T

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH2034D	Engine No:	1NZX780396
Make & Model:	TOYOTA VIOS, 1.5 G (A)	Chassis No:	MR053HY9305072299
Reg. Date:	29/07/2008 (Man. Year: 2008)	Odometer:	134706 km
Colour:	Metallic Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Compasal 2 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Compasal 2 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,400.83	1,312.44	1,088.39	45.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	860.00	960.00	52.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,220.83	2,172.44	2,048.39	48.53
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	4,220.83	1,700.00	2,520.83	59.72

INSPECTION

Date of Assignment:	12/12/2017	
Date Inspected:	12/12/2017	Inspected At: Car Times Autolution Pte Ltd (HQ) 160 Sin Ming Drive #02-04, AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2018)
Parts:	143	TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH2034D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	489.80 FL	*489.80 FL
2	1		*REAR BOOT	Buckled	789.40 FL	*789.40 FL
3	1		*EXHAUST	Repair	568.40 FL	*- FL
4	1		*END PANEL	Repair	485.60 FL	*- FL
5	1		*RHS REFLECTOR	Mtg Cracked	78.87 FL	*78.87 FL
6	1		*RHS TAILLAMP	Serviceable	287.40 FL	*- FL
7	1		*RETAINER	Serviceable	68.04 FL	*- FL
8	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
9	1		*TOYOTA LOGO	Necessary	65.50 FS	*49.12 FS
10	1		*VIOS WORDING	Necessary	59.70 FS	*44.77 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,092.71	1,651.96
- List Item Discount on L Items 25.00/25.00% (\$\$)	691.88	339.52
Total Parts (\$\$)	2,400.83	1,312.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	900.00	400.00
2	TO SUPPLY PAINT MATERIALS;EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED (PEARL WHITE)	New	800.00	440.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELETRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	120.00	20.00
Gross Labour Cost (S\$)			1,820.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >