

REPAIR ESTIMATE*

VEHICLE NO : SHC 8567T

DATE 11/12/2017

MAKE :

MODEL : HYUNDAI i40

Aig Asia - Lsum TS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover ✓			\$ 562.30	
	Front Bumper Sponge ?			\$ 142.20	
	Front Bumper Reinforcement ?			\$ 526.10	
	Front Bumper Bracket Top (LH) ?			\$ 22.40	
	Front Bumper Bracket (LH) ?			\$ 24.60	
	Front Bumper Retainer Mounting ?			\$ 9.20	
	Headlamp Support Panel Assy ?			\$ 1,067.50	
	Headlamp (LH) ✓			\$ 1,388.00	
	Front Fender (LH) ✓			\$ 619.00	
	Front Fender Shield (LH) ?			\$ 169.80	
	Front Fender Retainer ×			\$ 9.20	
	Front Wheel Rim (LH) ×			\$ 351.90	
	Front Wheel Hub Cap (LH) ✓			\$ 150.70	
	SUB TOTAL			\$ 5,042.90	
	LESS 20%			\$ 1,008.58	
	DISCOUNTED TOTAL			\$ 4,034.32	
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00	Nett
	Front Tyre (LH) ×			\$ 215.00	Nett
				\$ 315.00	
	Labour Charge				
	Panel Beating			\$ 850.00 400	
	Spray Painting Charge			\$ 400.00 20	
	Wiring Charge			\$ 50.00 20	
	Tuff Kote			\$ 50.00 20	
	Frt Wheel Alignment			\$ 80.00 ×	
	TOTAL LABOUR			\$ 1,430.00	
	ESTIMATE TOTAL			\$ 5,779.32	
<i>Kalvin 11/12/17</i> <i>11/12/17 1400hrs</i> <i>3 Days</i> <i>8/12</i> <i>Before Paint photo</i>					
LKK Auto Consultants hence notify the Repairer of the following: • To repair before/after spray painting • To display damaged parts for resurvey • Parts prices are subject to confirmation • The repair is on an "Without Prejudice" basis • No illegal modification is allowed • Supplemental items must be resurveyed and is subject to final approval from insurance company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					