

ASS. REC. BY:

REF: <S/EG117023584/Rltbm2 Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Yee Pei Li of CGI Date/Time: 12/12/17 @ 3:05pm

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 4500L Insured: YP 5943R

at Workshop m/s SMRT Automotive Tel: 6866 2671

of 60 Woodlands Ind. Park E4, 757705

Policy No: Claim No: DSMCV1702950

Sum Insured: Excess:

Make of Veh: D.O.A. 11/12/2017
(Client's Record) 13/12/2017 MDMing

CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement:

Date/Time: 3:42pm @ 12/12/17 Person Contacted: Alex Vehicle: ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 4500L - NS/INC17018428 / St/bc 2 - D.O.A: 23/09/2017
	YP 5943 R - x

Signature: *Poon*

REF: EGI

ASSIGNMENT

From: _____ Date: 13/12/17

Estimated Cost: _____

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHC 4500L
at Workshop m/s SMRT
of 60 woodlands Ind. Park E4, 757705

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Morning



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *'wp'*

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 4500L Yr Regn: 2014 / 86P

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS C.C. 1798

Colour: MARON A/C: Insured / Std / NI / NA

Sp. Reading: 337881 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN 36U 4057481-76

Gen. Cond: Good ☒ Fair ☐ Poor ☐ Burnt

Steering: In order ☒ Jammed ☐ Leaked ☐ Burnt or

Brake: In order ☒ Jammed ☐ Leaked ☐ Burnt or

Modi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size: F: 195/65R15
R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 11/12/17 D.O.I. 13/12/17

Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/1 10.03am Confirmed LS \$4,750 and 8 days with Poh Guan.
(Red. FF46.90, 61.2)

12/17/2062

ERHU

Yp 5943R

RECEIVED 10 JAN 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1 S + RS 1 Si

1 Photos

1 Others

TOTAL

350

Report Format: TP

Lump Sum / I.B.I: (\$ 4750)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Survey Department Check List (Case Handler)

Reference No. : CE/EG117023584/ R14b.
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Raoul): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Catherine 18/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EG17023584/R1tb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 12-12-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 5943R	Veh. Inspected	SHC 4500L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/12/2017	Inspection Date	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Celine Fong (LKKAuto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 17 January 2018 9:14 AM
To: Admin-D (LKKAuto)
Cc: assignments; SUR
Subject: RE: YP5943R / TP : SHC4500L/LKK / DOA : 11/12/2017

DSMCV1702950

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 16 January, 2018 3:15 PM
To: Survey Report (ERGO Insurance Pte. Ltd.)
Cc: assignments@lkkauto.com; 'SUR'
Subject: RE: YP5943R / TP : SHC4500L/LKK / DOA : 11/12/2017

Dear Pei Li,

Kindly provide us the claim number.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 12 December, 2017 3:45 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: YP5943R / TP : SHC4500L/LKK / DOA : 11/12/2017

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 12 December, 2017 3:05 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YP5943R / TP : SHC4500L/LKK / DOA : 11/12/2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 12 December, 2017 3:05 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YP5943R / TP : SHC4500L/LKK / DOA : 11/12/2017
Attachments: SHC4500L - SAS.pdf; SHC4500L - ESTIMATE.pdf; RE: SHC4500L - Survey (Ergo) (1.48 MB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**,

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

PERSON TO CONTACT : SHANTI @ 6866 2671/2

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel : 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Tuesday, 16 January, 2018 10:03 AM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'; Rasul (LKKAUTO)
Subject: RE: SHC4500L

Dear Poh Suan,

Confirmed lump sum \$4,750.00, 8 days.

Best Regards,
Celine Fong
LKK Auto Consultants Pte Ltd
phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 8 January, 2018 3:29 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Subject: SHC4500L

Hi Rasul,

Attached herewith the repair estimate of SHC 4500L having Case No: TAX/12/17/2062.

There is no change to the approved amount of \$4,750 @ 8 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: 08 January 2018 03:28
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4500L
Vehicle to be Exported:	No
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1399661
Chassis No.:	JTDKN36U405748176
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	04 Sep 2014
First Registration Date:	04 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	03 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$29,374.00
Total Rebate Amount:	\$35,440.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Jan 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4500L
 Ref. No : TAX/12/17/2062
 Reg. Date : 04/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TING TIN CHUN
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 11/12/2017 02:45:00 PM
 Accident Reported Date / Time : 11/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093549
 Special Instruction to ARC, if any :
 YP5943R - ERGO */ Repair after repair*
 Prepared Date : 11/12/2017 04:51:30 PM



LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405748176

Mileage



0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 2,052.00	0.00
Total Material Charges	: 4,693.24	4,693.24
Other Charges	: 1,185.00	0.00
TOTAL	: 9,113.24	0.00
Lum Sum Total	: 9,100.00	0.00
No. of Repair Days	: 7.00	0.00 <i>7 days - longer</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 12/12/2017 11:16:13 AM	01/01/1900 12:00:00 AM


13/12/17 @ 1540

Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/12/2017 11:15:24 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/12/2017 11:17:50 AM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,183.00	0.00 800
Total Labour	1,183.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 X
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 X
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	2,052.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 60
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE / REFIT SEAT	120.00	0.00 60
TO TRANSFER DOOR MECHANISM	240.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 125
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	1,185.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace <i>Repair</i>	No
69210-74030			DOOR OUTER HANDLE FRT/LH	1	370.80	25.00	278.10	Replace	Replace <i>X</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>new</i>	No
87940-47310		6505599	MIRROR ASSY, LH	1	1,224.90	25.00	918.67	Replace	Replace <i>X</i>	No
81740-52040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.77	Replace	Replace <i>SC</i>	No
87945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace <i>X</i>	No
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace <i>Repair</i>	No
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace <i>M</i>	No
69211-74020			DOOR OUTER HANDLE RR/LH	1	69.80	25.00	52.35	Replace	Replace <i>X</i>	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace <i>PT</i>	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>new</i>	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>new</i>	No
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace <i>new</i>	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>new</i>	No
65638-47021		6505477	FENDER LINER RR/LH	1	141.30	25.00	105.97	Replace	Replace <i>X</i>	No
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace <i>SC</i>	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>Repair</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>new</i>	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								5,866.57	5,866.55	
TOTAL MATERIALS(Discounted)							4,693.24	4,693.24		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Attached
Supplementary

Green

+ 1 Day

21-12-17 / 12:37


21-12-17 / 16:37

SMRT Accident Vehicle Repair Estimates

17-12-17 / 16:37

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4500L
Ref. No : TAX/12/17/2062
Reg. Date : 04/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : TING TIN CHUN
Type of Accident : SIDE SWIPE
Date / Time of Accident : 11/12/2017 02:45:00 PM
Accident Reported Date / Time : 11/12/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Rasul
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093549
Special Instruction to ARC, if any :
YP5943R - ERGO
Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com
lumpsum repair
Prepared Date : 11/12/2017 04:51:30 PM



20/12/17 18:30 PMS

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date

13-12-17

2nd witness

Date

E 1/2 F
KM 337879

Vehicle to Wega Date in:	14/12	Towing:	Peng
Time in:	1420	Driver:	
Wega Job No:	14023/12		
Vehicle sent to SMRT Date in:	20/12/17	Towing:	
Time in:	1605	Driver:	Ch
Received by (SMRT):			

Classis No : JTDKN36U405748176

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	800.00
Total Spray Painting Charges	: 2,052.00	900.00
Total Material Charges	: 2,271.89	2,271.89
Other Charges	: 1,535.00	755.00
TOTAL	: 7,041.89	4,726.89
Lum Sum Total	: 7,050.00	4,750.00
No. of Repair Days	: 9.00	8.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sing Off Date	: 12/12/2017 11:16:13 AM	13/12/2017 04:37:57 PM



Prepared / Adjusted Date

Remarks :

Prepared Date : 12/12/2017 11:15:24 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : **QN-1801-0197**
Quotation Date : **8/1**
Invoice Amount : 0.00

Invoice No :
Invoice Date :
Prepared Date : 12/12/2017 11:17:50 AM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,183.00	800.00
Total Labour	1,183.00	800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	200.00
TO RESPRAY REAR DOOR LH	378.00	200.00
TO RESPRAY VIEW MIRROR	180.00	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	100.00
TO RESPRAY REAR FENDER LH	378.00	200.00
TO RESPRAY RIM	180.00	0.00
TO REPSRAY REAR BUMPER	378.00	200.00
Total Spray Painting & Panel Beating	2,052.00	900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	60.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00
TO REMOVE / REFIT SEAT	120.00	60.00
TO TRANSFER DOOR MECHANISM	240.00	60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00 nec
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	40.00
TO CHECK & RESET SYSTEM FUNCTION	350.00	150.00
Total Other Costs	1,535.00	755.00 ✓

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7002-7070		6505529	DOOR FRT/LH	R 1	894.40	100.00	0.00	Replace	Repair	No R
9210-4030			DOOR OUTER HANDLE FRT/LH	X 0	370.80	25.00	0.00	Replace	Not given	No X _{src}
			STICKER DECAL SMRT (DOOR)	✓	60.00	0.00	60.00	Replace	Replace	No ✓ _{src}
7940-7310		6505599	MIRROR ASSY, LH	X 0	1,224.90	25.00	0.00	Replace	Not given	No X _{NH}
1740-2040		6505465	MIRROR LAMP LH	✓ 1	65.30	10.00	58.77	Replace	Replace	No ✓ _{src}
7945-4010		6505597	COVER, OUTER MIRROR, LH	X 0	107.40	25.00	0.00	Replace	Not given	No X _{NH}
5852-7900			MOULDING BODY, LH	R 1	673.60	100.00	0.00	Replace	Repair	No R
7004-7080		6505487	DOOR RR/LH	✓	954.50	25.00	715.87	Replace	Replace	No ✓ _{BT}
9211-4020			DOOR OUTER HANDLE RR/LH	X 0	69.80	25.00	0.00	Replace	Not given	No X _{src}
1602-7091		6505476	FENDER RR/LH	✓ 1	766.80	25.00	575.10	Replace	Replace	No ✓ _{BT}
	COMMO N		STICKER DECAL 6555 8888	✓	21.60	0.00	21.60	Replace	Replace	No ✓ _{src}
	COMMO N		SMRT LOGO	✓	7.80	0.00	7.80	Replace	Replace	No ✓ _{src}
2720-7031			QUARTER GLASS RR/LH	✓	168.10	25.00	126.07	Replace	Replace	No ✓ _{src}
	COMMO N		SEALANT W/SCREEN	✓	37.00	0.00	37.00	Replace	Replace	No ✓ _{src}
5638-7021		6505477	FENDER LINER RR/LH	X 0	141.30	25.00	0.00	Replace	Not given	No X _{src}
2611-7140		6505658	WHEEL, DISC	✓ 1	1,490.20	25.00	1,117.65	Replace	Replace	No ✓ _{src}
2159-7905		6505548	BUMPER REAR	R 1	458.60	100.00	0.00	Replace	Repair	No R
			PIXEL STICKER	✓ 2	60.00	0.00	120.00	Replace	Replace	No ✓ _{src}
2576-7020		6505550	BUMPER SIDE RETAINER RR/LH	X 0	94.80	25.00	0.00	Replace	Not given	No X _{src}
TOTAL MATERIALS							2,839.87	2,839.86		
TOTAL MATERIALS(Discounted)							2,271.89	2,271.89		

Added Spare Parts / Material Usage After Surveyor Signed off

12,496.90

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

2839.86
 - 202
 2271.89
 + 800.00
 + 1655.00

 4726.89

45\$4750/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG17023584/R1tbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 22-01-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 5943R	Veh. Inspected	SHC 4500L	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1702950	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U405748176	Colour	MAROON	
Odometer	337881	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	5 mm	
L/H Front Tyre	195/65 R15	FALKEN	5 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2017	Inspection Date	13/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4500L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR RR/LH (DISC 25%)	BENT	954.50	715.87
1	FENDER RR/LH (DISC 25%)	BENT	766.80	575.10
1	QUARTER GLASS RR/LH (DISC 25%)	NECESSARY	168.10	126.07
1	WHEEL,DISC (DISC 25%)	SCRATCHED	1,490.20	1,117.65
1	MIRROR LAMP LH (DISC 10%)	SCRATCHED	65.30	58.77
1	STICKER DECAL SMRT (DOOR)(SN)	NECESSARY	60.00	60.00
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SOLAR FILM (SN)	NECESSARY	125.00	125.00
1	MIRROR ASSY,LH	NOT NECESSARY	1,224.90	-
1	COVER,OUTER MIRROR,LH	NOT NECESSARY	107.40	-
1	FENDER LINER RR/LH	NOT NECESSARY	141.30	-
1	DOOR OUTER HANDLE FRT/LH	SERVICEABLE	370.80	-
1	DOOR OUTER HANDLE RR/LH	SERVICEABLE	69.80	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	DOOR FRT/LH	TO REPAIR SEE LABOUR	894.40	-
1	MOULDING BODY,LH	TO REPAIR SEE LABOUR	673.60	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
			7,851.90	2,964.86
LABOUR				
PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF DOOR FRT/LH,MOULDING BODY,LH AND BUMPER REAR.			1,183.00	800.00
SPRAY PAINT.			2,052.00	900.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	60.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	60.00
TO DO WHEEL ALIGNMENT/TYRE BALANCING.			120.00	60.00

Report Ref No. CS/EGI17023584/R1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE/REFIT SEAT.		120.00	60.00
	TO TRANSFER DOOR MECHANISM.		240.00	60.00
	TO REMOVE & REFIT REAR QUARTER GLASS LH.		120.00	60.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	60.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.		60.00	40.00
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	150.00
			4,645.00	2,330.00
GRAND TOTAL			12,496.90	5,294.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,750.00

Report Ref No. CS/EGI17023584/R1tbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.