

Surveyor: _____
REF: CS3/m3617023589/Dqber2

Special Instruction:
L/s: \$7550.00
Third Parties:
Claimant:
Surveyor: Absolute Appraisal
Workshop: Kok Wang

ASSIGNMENT (Office)
From (Person): Irene Tan of MSH Date/Time: 04/04/2018
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation
To Inspect Vehicle No: SFS 133D Insured: SJR 4532Y
at Workshop m/s Kok Wang Car Tel: 9183 5633
of 1 Soon Lee St #06-40
Policy No: 287737180MV Claim No: 539336/TT
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 02122017
(Client's Record)

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT
Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 8 days)
Date/Time: _____ Submit Final Fig _____, _____ days (Red \$ _____ / _____ %; Original _____ days)

H.O.D. Endorsement/Date: _____

Date/Time	Action/Instruction
	SFS 133D - x
	SJR 4532Y - NP/AC(1)09715/m2
	Submit report ASAP
11/04/18	To Submit 1/551501 - with 5 days 2 yr. (Red \$ 2400, 32%)
	PR8 photos seen
	OJ GIA seen
	Part was checked.

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED APR 2018

Para(3) : Nett Value

Market Value : _____
Salvage Value : _____
Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:
Basic & Add
Transport
Photos
Others
Total

Date: PRS + PS

1) Date/Time 11/4/18 File Pass to tyrisa
3) Date/Time _____ File Pass to _____
5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____
4) Date/Time _____ File Return to _____
6) Date/Time _____ File Return to _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17023589/T1qb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 12-12-2017		
		Code : MSG		
1. Policy Particulars : (THIRD PARTY CLAIM)				
Insured Veh.	SJR 4582Y	Veh. Inspected	SFS 133D	
Policy No.	P28773218DMV	Coverage (\$)	0.00	
Claim No.	539336	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/12/2017	Inspection Date	13/12/2017	
Survey held at	KOK WANG CAR GROOMING (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Mennen

Wahch

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time: 12/12/17 @ 3:23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFS133D

Insured:

SJR 4582Y

at Workshop m/s

Kok Wang Car Grooming

Tel:

9183 9633

of

1 Soon Lee Street # 06-40 627605

Policy No:

P28773218DMV

Claim No:

539336

Sum Insured:

Excess:

Make of Veh:

(Client's Record):

D.O.A.

02/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

13/12/2017

H.O.D. Endorsement:

Date/Time:

3:25pm @ 12/12/17

Person Contacted:

Mr. Kok

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SFS133D - X
	SJR 4582Y - NA/INC12019718/m2
	Dismantle Part: 18.12.2017

200118 1147am Email to Irene Tan Hui Mennen



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17023589/T1b

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 12-12-2017



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJR 4582Y	Veh. Inspected	SFS 133D
Policy No.	P28773218DMV	Coverage (\$)	0.00
Claim No.	539336	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/12/2017	Inspection Date	13/12/2017
Survey held at	KOK WANG CAR GROOMING (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Dec 2017		12 Dec 2017 15:23 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN PENG FOONG, ID: S1506188Z		
Main Claimant:	LAY AUTO LEASING PTE LTD, Co. Reg. No.: 201310521C		
Vehicle Reg. No.:	SFS133D	Date of Loss:	02/12/2017 13:00 - :59
Claim Type:	TP / 539336	Policy/Cover Note No.:	P28773218DMV (Comprehensive) Coverage: 10/07/2017 - 09/07/2018
Vehicle Reg. No. (Insured):	SJR4582Y	Policy No. (Claimant):	
		Excess:	S\$3,700.00
Repairer:	Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE, 627605 Pioneer - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/12/2017]		
Driver/Custodian (Insured):	TAN YU WEI NORRIS (/ Male), NRIC: S9337295F		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

CYOGARAJAH LLC

ADVOCATES & SOLICITORS

Our Ref : CY.SFS133D.17.KWC.wp(Lh)

Your Ref : Your insured vehicle **SJR 4582Y**

883 North Bridge Road
#19-05 Southbank
Singapore 198785
T: 6292 5838
F: 6292 5938
(UEN No. 201333127N)
(GST Reg No. 201333127N)

12 December 2017

REG/CS/PAY/FA

12 DEC 2017

TAN PENG FOONG
c/o Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

By Fax : 68277809 /6643 1349


Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SFS 133D & SJR 4582Y ON 02.12.2017 @ 13:10HRS ALONG AYE TOWARDS TUAS

We are instructed by M/S LAY AUTO LEASING PTE LTD to notify you of a road traffic accident on 02.12.2017 @ 13:10hrs along AYE towards Tuas involving our client's customer's vehicle registration number SFS 133D and vehicle registration number SJR 4582Y driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


C. Yogarajah LLC
Enc

cc: M/s. Kok Wang Car Grooming
1 Soon Lee Street #06 – 40 Pioneer Centre (S) 627605
Mr. Kok (9183 9633)
By fax 6694 4864

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Disclaimer: Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, C. Yogarajah LLC cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

US317105210 / STA INSPECTION PTE LTD - Sean Lay
ENTRY DATE & TIME: 04/12/2017 10:46

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be submitted by the Police for and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, I hereby consent to the archiving of this report at the centre and copies of the report being made available.

ACCIDENT STATEMENT

Date Of Report 04/12/2017 10:46
Date Of Accident 02/12/2017 13:10
Exact Location Of Accident AYE TOWARDS TUAS BEFORE BUKIT MERAH
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SF8133D
Insured/Policyholder
Name Of Registered Owner LAY AUTO LEASING PTE LTD
Co Reg No 201310521C
Email Address JOEL@LAYAUTO.COM
Mobile Phone No
Alternative Phone No OFFICE-93874866
Vehicle Particulars
Manufacturer HONDA
Model VEZEL
Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 8070622212-02
Cover Note Number
Driver
Name of Driver MOHAMED FADILAH BIN SULAIMAN
NRIC No S1817578H
Date Of Birth 27/01/1982
Occupation OUTDOOR
Date Of Driving Pass 12/06/2003
Driving Experience 14 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-82715395
Fax Number
Contact Number
Email Address NOEMAIL

Address BLK 281A SENGKANG EAST AVENUE
#02-623
Postcode 541281
Was driver an employee of the Insurer's Company NO
If No, Relationship of the Driver with Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims settlement. NO
Number of Passengers (including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SUR4582Y

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver NA

NRIC/Passport Number

Contact Number NA

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statement may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers") the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of my claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/ can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature:
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Receiving Centre Personnel's Signature
Name:
NRIC / IN No.:

SKETCH PLAN

ME
Twas



A-SF1133D
B-SJR4877

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02/12/17, around 1210HRS, I was driving towards
 ME Twas on the most right lane. Suddenly vehicle
 B at the back of my vehicle bang bang against
 my vehicle SF 133D causing damage to the rear
 of my vehicle.

DECLARATION

I/We hereby declare foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/ID No:

View Sent Message

This mail is associated with :

***SFS133D (539336)**
[SJR4582Y]

TP
LAY AUTO LEASING PTE LTD
Dec 2 2017 1:00PM
[TAN PENG FOONG]
Kok Wang Car Grooming

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **20/01/2018 11:47 AM.**
To MSI_ITAN
Subject Pre-repair Inspection

Dear Irene,

Refer to your assignment on 12.12.2017 at 3.23PM.

Please be informed that we have inspected the vehicle SFS 133D on 13.12.2017 at 3.30PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.


Our Ref : CY.9752.18.KWC.wp(Lh)

Your Ref : 539336

02 April 2018

Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807

883 North Bridge Road
#19-05 Southbank
Singapore 198785
T: 6292 5838
F: 6292 5938
(UEN No. 201333127N)
(GST Reg No. 201333127N)



BY HAND

EA,
1. Upload
2. M/L 1 & 2 here
4/4/18

Dear Sirs

ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SFS 133D & SJR 4582Y ON 02.12.2017 @ 13:10HRS ALONG AYE TOWARDS TUAS

We are instructed by **M/s Lay Auto Leasing Pte Ltd** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SFS 133D** was damaged by vehicle **SJR 4582Y** by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1) Repair costs	\$ 7,550.00
2) Loss of Use	\$ 1,200.00
3) Survey Report Fee	\$ 745.00
4) LTA fee	\$ 5.35
5) Accident report fee	\$ 29.00
6) Costs & Incidental	\$ 1,000.00
7) GST on costs & Incidentals	\$ 70.00
	<u>\$10,599.35</u>

A copy each of the following supporting documents is enclosed:-

- 1) Accident report on our client's vehicle
- 2) Survey Report on SJR 4582Y with 100 coloured photographs
- 3) Final repair bill
- 4) LTA search on SJR 4582Y

We had on **12 December 2017** notified your company of the above accident and a pre-repair inspection was carried out by your appointed surveyor.

Please let us know within the next seven (7) days upon receipt of this letter whether you intend to re-inspect our client's vehicle failing which the said vehicle will no longer be available for the same.

(CY.9752.18.KWC.wp(Lh))

Page 2

Please note that you should send to us an acknowledgment of receipt of this letter within fourteen(14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you.

Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully



C. YOGARAJAH LLC
Enc

cc **TAN PENG FOONG**
Block 288A Bukit Batok St 25
#15 - 226
Singapore 650288
(Documents were enclosed to your insurers)



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Invoice

Customer: Lay Auto Leasing Pte Ltd
48 Toh Guan Rd E
Singapore 608586

Date: 02.01.2018

Invoice No: NS-1712-476

Description		Amount
Vehicle No:	SFS133D	
Make & Model:	Honda Vezel (A)	
Our reference:	AAS/2017/476	
Services rendered for appraiser / inspection report		
Survey Fee		
Photographs		
Transport Fees		
Re-inspection Fees		
SGD Dollar : Seven hundred forty five dollar only	Total:	SGD \$ 745.00

Notes:

All cheques payment should be crossed and made payment to "Absolute Appraisal Services Pte Ltd"

Please indicate our "Invoice No." on the reverse side of the cheque.

Please do not hesitate to contact us should you have any enquires.



Absolute Appraisal Services Pte Ltd



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7596
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Lay Auto Leasing Pte Ltd
48 Toh Guan Rd E
Singapore 608586

Date of report: 02.01.2018
Date of request: 12.12.2017
Date of inspection: 12.12.2017
Date of accident: 02.12.2017
Claim type: Third Party Claim

Report No: AAS/2017/476

Particulars of affected vehicle:

Registration no: SFS133D
Make/Model: Honda Vezel (A)
Year of registration: 2016
Colour: Metallic Blue

Odometer: 27747 km
Engine Capacity: 1496 cc
Engine no: L15B4404946
Chassis no: RU11204961

Condition of tires:

Front Left: 6mm
Make: Dunlop
Rear Left: 6mm
Make: Dunlop

Front Right: 6mm
Make: Dunlop
Rear Right: 6mm
Make: Dunlop

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conducted at M/s. Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605

(Subsequent inspection was conducted)


Assessment

Repairer's estimate: \$ 14,475.44

Revised estimate: \$ 9,424.64

Recommended reserve: \$ 7,550.00 (Lump sum)

Estimated normal duration of repairs : 8 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SFS133D

Report No: AAS/2017/476

W/O PREJUDICE

Point of impact

At the rear portion.

General description of damages

The tailgate, tailgate lamps, tail lamps, rear bumper, rear bumper side, exhaust silencer, rear end panel, floor panel, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Kok Wang Car Grooming as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$9,424.64

Conclusion


The repairer has agreed to undertake the repair at a lumpsum of SGD \$7,550.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 8 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a 'Without Prejudice' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 100 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7896

Email: absolute.app.svcs@gmail.com

Vehicle No: SFS133D

Report No: AAS/2017/476

Appraisement Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est	
1	Tailgate	1	Dented		\$ 1,371.00	1100.90 \$ 1,371.00	✓
2	Tailgate glass top moulding	1	Necessary		\$ 45.00	\$ 45.00	✓
3	Tailgate glass lower moulding	1	Necessary		\$ 45.00	\$ 45.00	✓
4	Tailgate glass side moulding LH/RH	2	Necessary	\$ 35.00	\$ 70.00	\$ 70.00	✓
5	Tailgate outer garnish	1	Serviceable		\$ 452.00	-	
6	Tailgate outer garnish clips	12	Necessary	\$ 4.00	\$ 48.00	\$ 48.00	NN
7	Tailgate emblem	1	Not Necessary		\$ 35.00	-	
8	Tailgate lamp LH/RH	2	Grazed/Cut	\$ 252.00	\$ 504.00	\$ 504.00	✓
9	Tailgate nameplate 'Vezel'	1	Necessary		\$ 55.00	\$ 55.00	✓
10	Tailgate wiper motor	1	Serviceable		\$ 402.00	-	
11	Tailgate lock	1	Distorted		\$ 162.00	\$ 162.00	NN
12	Tailgate catch	1	Distorted		\$ 45.00	\$ 45.00	NN
13	Tailgate weather-strip	1	Necessary		\$ 178.00	\$ 178.00	✓
14	Tailgate absorber LH/RH	2	Bent/Leaked	\$ 220.00	\$ 440.00	\$ 440.00	NN
15	Tailgate trim	1	Deformed/Cracked		\$ 550.00	262.70 \$ 550.00	✓
16	Tailgate trim clips	15	Necessary	\$ 4.00	\$ 60.00	\$ 60.00	✓
17	Tail lamp LH/RH	2	Grazed/Cut	\$ 430.00	\$ 860.00	\$ 860.00	✓
18	Rear bumper	1	Dented		\$ 871.00	\$ 871.00	✓
19	Rear bumper side LH/RH	2	Dented/Repair	\$ 256.00	\$ 512.00	-	
20	Rear bumper reflector LH/RH	2	Cracked	\$ 150.00	\$ 300.00	\$ 300.00	NN
21	Rear bumper retainer LH/RH	2	Cracked	\$ 55.00	\$ 110.00	\$ 110.00	NN
22	Rear bumper undercover	1	Serviceable		\$ 265.00	-	
23	Rear bumper clips	8	Necessary	\$ 4.00	\$ 32.00	\$ 32.00	✓
24	Rear fender wheel arch garnish LH/RH	2	Loop Broken	\$ 187.00	\$ 374.00	\$ 374.00	NN
25	Rear fender wheel arch garnish clips	16	Necessary	\$ 4.00	\$ 64.00	\$ 64.00	NN
26	Rear end panel	1	Dented		\$ 607.00	576.10 \$ 607.00	✓
27	Rear end panel top trim	1	Deformed/Cracked		\$ 90.00	\$ 90.00	✓
28	Rear fender inner trim LH/RH	2	Serviceable	\$ 640.00	\$ 1,280.00	-	
29	Spare tyre panel	1	Distorted/Repair		\$ 1,160.00	-	
30	Spare tyre cover	1	Serviceable		\$ 280.00	-	
31	Tow hook	1	Serviceable		\$ 65.00	-	
32	Tool sponge	1	Cracked		\$ 256.00	\$ 256.00	NN
33	Exhaust silencer	1	BT		\$ 751.90	\$ 751.90	✓
34	Exhaust silencer mountings	2		\$ 14.70	\$ 29.40	\$ 29.40	NN
				Total:	\$ 12,369.30	\$ 7,918.30	
				-20%	\$ 2,473.86	\$ 1,583.66	
				List total:	\$ 9,895.44	\$ 6,334.64	

550150

4401.20



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SFS133D

Report No: AAS/2017/476

1	Tailgate glass sealant	1	Necessary		\$ 60.00	\$ 40.00 ✓
2	Reverse camera	1set	Serviceable		\$ 380.00	-
3	Reverse sensor	2set	Malfunctioned	\$ 300.00	\$ 600.00	\$ 500.00 220
4	Joint sealant	1	Necessary		\$ 60.00	\$ 40.00 ✓
				300/-	Special nett total:	\$ 1,100.00
						\$ 580.00

Parts Total: \$ 10,995.44 \$ 6,914.64

S/N	Labour Description	Repairer's Est	Revised Est
1	Remove & reinstall rear trimmings.	\$ 100.00	\$ 60.00 ✓
2	Remove & transfer tailgate component.	\$ 120.00	\$ 100.00 60
3	Remove & transfer tailgate glass.	\$ 180.00	\$ 150.00 120
4	Remove & transfer reverse camera.	\$ 120.00	\$ 80.00 NH
5	Renew reverse sensor.(2set)	\$ 100.00	\$ 60.00 ✓
6	Renew exhaust silencer.	\$ 100.00	\$ 60.00 ✓
7	Rust proofing on rear affected & replacement panels.	\$ 100.00	\$ 80.00 ✓
8	To check rear lightings & wirings.	\$ 60.00	\$ 40.00 ✓
9	Spray painting on rear affected & replacement panels.	\$ 1,400.00	\$ 1,000.00 600
10	Conduct panel beating, straightening, cutting & reforming. Renew rear damaged parts. Re-align all affected area.	\$ 1,200.00	\$ 880.00 700
Labour Total:		\$ 3,480.00	\$ 2,510.00

Grand Total: \$ 14,475.44 \$ 9,424.64

The final adjusted lump sum amount is \$7,550.00

Under normal circumstances, the repair should be completed within a reasonable period of 8 working days.

100 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

KOK WANG CAR GROOMING

1 Soon Lee Street #06-40 Pioneer Centre Singapore 627605

15 March 2018

Lay Auto Leasing Pte Ltd
48 Toh Guan Road E
Singapore 608586

FINAL REPAIR BILL FOR VEHICLE NO. SFS 133D

Lump sum repair cost

\$7,550.00

Thank you



Phee Lay San has successfully logged out.

Your last login date and time was 12 Dec 2017, 10:07:53.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset</u> <u>Type</u>	<u>Asset ID</u>	<u>Asset</u> <u>Owner ID</u>	<u>Transaction Type</u>	<u>Transaction</u> <u>Amount(\$\$)</u>	<u>Log</u> <u>Date/Time</u>
1	Vehicle	SJR4582Y	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	5.35	12 Dec 2017 / 10:08:43

Enquire Vehicle & Owner Information (Vehicle No. SJR4582Y As At 02 Dec 2017 / 13:10:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CY.SFS133D.17.KWC.WP

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S1506188Z

Owner Name: TAN PENG FOONG

Registered Address Type: HDB / HUDC

Registered Block/House No.: 288A

Registered Street Name: BUKIT BATOK STREET 25

Registered Unit No.: # 15 - 226

Registered Building Name: -

Registered Postal Code: 650288

Current Vehicle Details

Vehicle No.: SJR4582Y

Make Description/Model: HYUNDAI / HD AVANTE 2.0 A

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Dec 2017		12 Dec 2017 15:23 Edit Adj Rpt	S\$5,150.00 Edit Estimates	S\$5,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN PENG FOONG , ID: S1506188Z		
Main Claimant:	LAY AUTO LEASING PTE LTD , Co. Reg. No.: 201310521C		
Vehicle Reg. No.:	SFS133D	Date of Loss:	02/12/2017 13:00 - :59 [14 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 539336	Policy/Cover Note No.:	P28773218DMV (Comprehensive) Coverage: 10/07/2017 - 09/07/2018
Vehicle Reg. No. (Insured):	SJR4582Y	Policy No. (Claimant):	
		Excess:	S\$3,700.00
Repairer:	Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE, 627605 Pioneer - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 13/12/2017]		
Driver/Custodian (Insured):	TAN YU WEI NORRIS (/ Male), NRIC: S9337295F		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents



















































***SFS133D (539336)**
[SJR4582Y]
TP
LAY AUTO LEASING PTE LTD
Dec 2 2017 1:00PM
[TAN PENG FOONG]
Kok Wang Car Grooming

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/12/17 15:10	Accident Statement <small>From: OD - Reg. No: SJR4582Y, Claimant: TAN PENG FOONG</small>	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/01/18 11:45	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
2	20/01/18 11:45	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
3	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	20/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	20/01/18 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/01/18 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/01/18 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/01/18 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/01/18 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/01/18 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/01/18 11:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/01/18 11:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	20/01/18 11:46	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
85	20/01/18 11:46	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
86	20/01/18 11:46	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
87	20/01/18 11:46	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
88	20/01/18 11:46	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
89	20/01/18 11:46	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
90	20/01/18 11:46	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	20/01/18 11:46	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/12/17 15:10	SFS133D GIA Report From:OD - Reg. No: SJR4582Y, Claimant: TAN PENG FOONG		<input type="checkbox"/>
2	12/12/17 15:12	PRI		<input type="checkbox"/>
3	12/12/17 15:23	EMAIL to TP reject their list of sje		<input type="checkbox"/>
4	04/04/18 13:23	LOD		<input type="checkbox"/>
5	04/04/18 13:23	SURVEY REPORT		<input type="checkbox"/>
6	04/04/18 13:23	SURVEY PHOTOS		<input type="checkbox"/>
7	04/04/18 13:25	SURVEY PHOTOS		<input type="checkbox"/>
8	04/04/18 13:25	FINAL REPAIR BILL & LTA SEARCH		<input type="checkbox"/>
9	04/04/18 19:46	our instruction to LKK to prepare and upload final survey report		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17023589/DQBE2

Date: 11/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: P28773218DMV

Claimant Vehicle No : SFS133D

Insured Vehicle No : SJR4582Y

Date of Loss: 02/12/2017

Nature of Claim: TP

Claim No: 539336

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFS133D

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4404946

Reg. Date: 26/09/2016 (Man. Year: 2016)

Chassis No: RU11204961

Colour: Blue

Odometer: 27749 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,995.44	4,701.20	6,294.24	57.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,780.00	1,700.00	48.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,475.44	6,481.20	7,994.24	55.23
Approved Total (Overridden) (S\$)		5,150.00		
Nett Amount (S\$)	14,475.44	5,150.00	9,325.44	64.42

INSPECTION

Date of Assignment: 12/12/2017

Date Inspected: 13/12/2017 Inspected At:

Kok Wang Car Grooming (HQ)
1 SOON LEE STREET #06-40 PIONEER
CENTRE
Singapore 627605

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFS133D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	1,371.00 FL	*1,100.90 FL
2	1	*TAILGATE GLASS TOP MOULDING	Necessary	45.00 FL	*45.00 FL
3	1	*TAILGATE GLASS LOWER MOULDING	Necessary	45.00 FL	*45.00 FL
4	2	*TAILGATE GLASS SIDE MOULDING LH / RH	Necessary	70.00 FL	*70.00 FL
5	1	*TAILGATE OUTER GARNISH	Serviceable	452.00 FL	*- FL
6	12	*TAILGATE OUTER GARNISH CLIPS	Not Necessary	48.00 FL	*- FL
7	1	*TAILGATE EMBLEM	Not Necessary	35.00 FL	*- FL
8	2	*TAILGATE LAMP LH / RH	Grazed / Cut	504.00 FL	*504.00 FL
9	1	*TAILGATE NAMEPLATE VEZEL	Necessary	55.00 FL	*55.00 FL
10	1	*TAILGATE WIPER MOTOR	Serviceable	402.00 FL	*- FL
11	1	*TAILGATE LOCK	Not Necessary	162.00 FL	*- FL
12	1	*TAILGATE CATCH	Not Necessary	45.00 FL	*- FL
13	1	*TAILGATE WEATHER STRIP	Necessary	178.00 FL	*178.00 FL
14	2	*TAILGATE ABSORBER LH / RH	Not Necessary	440.00 FL	*- FL
15	1	*TAILGATE TRIM	Deformed / Cracked	550.00 FL	*262.70 FL
16	15	*TAILGATE TRIM CLIPS	Necessary	60.00 FL	*60.00 FL
17	2	*TAIL LAMP LH / RH	Grazed / Cut	860.00 FL	*860.00 FL
18	1	*REAR BUMPER	Dented	871.00 FL	*871.00 FL
19	2	*REAR BUMPER SIDE LH / RH	Repair	512.00 FL	*- FL
20	2	*REAR BUMPER REFLECTOR LH / RH	Not Necessary	300.00 FL	*- FL
21	2	*REAR BUMPER RETAINER LH / RH	Not Necessary	110.00 FL	*- FL
22	1	*REAR BUMPER UNDERCOVER	Serviceable	265.00 FL	*- FL
23	8	*REAR BUMPER CLIPS	Necessary	32.00 FL	*32.00 FL
24	2	*FRONT FENDER WHEEL ARCH GARNISH LH / RH	Not Necessary	374.00 FL	*- FL
25	16	*REAR FENDER WHEEL ARCH GARNISH CLIPS	Not Necessary	64.00 FL	*- FL
26	1	*REAR END PANEL	Dented	607.00 FL	*576.00 FL
27	1	*REAR END PANEL TOP TRIM	Deformed / Cracked	90.00 FL	*90.00 FL
28	2	*REAR FENDER INNER TRIM LH / RH	Serviceable	1,280.00 FL	*- FL
29	1	*SPARE TYRE PANEL	Repair	1,160.00 FL	*- FL
30	1	*SPARE TYRE COVER	Serviceable	280.00 FL	*- FL
31	1	*TOW HOOK	Serviceable	65.00 FL	*- FL
32	1	*TOOL SPONGE	Not Necessary	256.00 FL	*- FL
33	1	*EXHAUST SILENCER	Bent	751.90 FL	*751.90 FL
34	2	*EXHAUST SILENCER MOUNTINGS	Not Necessary	29.40 FL	*- FL
35	1	*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
36	1	*SET REVERSE CAMERA	Serviceable	380.00 FS	*- FS
37	2	*SET REVERSE SENSOR	Malfunctioned	600.00 FS	*220.00 FS
38	1	*JOINT SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (S\$)	13,469.30
					5,801.50	
					- List Item Discount on L Items 20.00/20.00% (S\$)	2,473.86
						1,100.30
					Total Parts (S\$)	10,995.44
						4,701.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REINSTALL REAR TRIMMINGS	New	100.00	60.00
2	REMOVE & TRANSFER TAILGATE COMPONENTS	New	120.00	60.00
3	REMOVE & TRANSFER TAILGATE GLASS	New	180.00	120.00
4	REMOVE & TRANSFER REVERSE CAMERA	New	120.00	0.00
5	RENEW REVERSE SENSOR (2 SET)	New	100.00	60.00
6	RENEW EXHAUST SILENCER	New	100.00	60.00
7	RUST PROOFING ON REAR AFFECTED & REPLACEMENT PANELS	New	100.00	80.00
8	TO CHECK REAR LIGHTINGS & WIRINGS	New	60.00	40.00
9	SPRAY PAINTING ON REAR AFFECTED & REPLACEMENT PANELS	New	1,400.00	600.00
10	CONDUCT PANEL BEATING, STRAIGHTENING, CUTTING & REFORMING. RENEW REAR DAMAGED PARTS. RE-ALIGN ALL AFFECTED AREA	New	1,200.00	700.00
Gross Labour Cost (S\$)			3,480.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

