

HITACHI
 Inspire the Next
INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/16-002450	Date of Loss:	10/12/2017
Vehicle Reg. No.:	SKX315K	Driveable?	
Driver Age/Info:	62 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD		
Driver:	SARITH VAIKUNTAN		
Make/Model:	TOYOTA HARRIER, 2.0 PREMIUM (A)	Vehicle Reg. Date:	25/11/2015
Vehicle Colour:	BLUE/BLACK		
Engine No:	3ZRB667382	Chassis No:	ZSU600062100
Odometer:	20000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

*Tanpin 97495249
Ex \$1500 13/12/17 @ 1715
Resurvey before paint
7 days Present.
Sur @ lkkauto.com*

COST OF CLAIMS

	Amount
Parts	5,788.00
Miscellaneous Items	0.00
Labour	3,580.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$\$)	9,368.00
- Excess (\$\$)	1,500.00
(\$\$)	7,868.00
+ GST 7.00% (\$\$)	550.76
Nett Amount (\$\$)	8,418.76

This claim is Insured by: **GRANT CHONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Dec 2017)

Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SKX315K/12/12/2017 14:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bumper	0.00	0.00	*520.00 F <i>de</i>
2	10		*Front bumper clips	0.00	0.00	*15.00 F <i>nei</i>
3	2		*Front bumper retainer outer LH/RH	0.00	0.00	*70.00 F <i>35</i>
4	2		*Front bumper retainer inner LH/RH	0.00	0.00	*10.00 F <i>10</i>
5	1		*Front bumper lower skirting	0.00	0.00	*130.00 F <i>x</i>
6	1		*Front fog lamp cover RH	0.00	0.00	*25.00 F <i>x</i>
7	1		*Front fog lamp RH	0.00	0.00	*110.00 F <i>x</i>
8	1		*Headlamp RH	0.00	0.00	*950.00 F <i>x</i>
9	1		*Front fender RH	0.00	0.00	*300.00 F <i>bt</i>
10	1		*Bonnet	0.00	0.00	- <i>x</i>
			Repair and respray			
11	1		*Front fender shield RH	0.00	0.00	*140.00 F <i>de</i>
12	10		*Front fender shield clips RH	0.00	0.00	*15.00 F <i>nei</i>
13	1		*Front original RIM 18 RH	0.00	0.00	*950.00 F <i>ent</i>
14	1		*Front tyre RH	0	0.00	*420.00 FS <i>? 80%</i>
15	1		*Driver door	0.00	0.00	*550.00 F <i>bt</i>
16	2		*Driver door sticker set	0.00	0.00	*70.00 F <i>nei</i>
17	1		*Front fender quarter garnish RH	0.00	0.00	*25.00 F <i>?</i>
18	1		*Wiper garnish side RH	0.00	0.00	*25.00 F <i>?</i>
19	2		*Driver door hinge top and bottom	0.00	0.00	*60.00 F <i>?</i>
20	1		*Driver door checker	0.00	0.00	*65.00 F <i>?</i>
21	1		*Driver door lower chrome protector	0.00	0.00	*55.00 F <i>ent</i>
22	1		*Rear door RH	0.00	0.00	- <i>x NC</i>
			Repair and respray			
23	1		*RH side skirting moulding	0.00	0.00	*65.00 F <i>?</i>
24	1		*Front shock absorber RH	0.00	0.00	*175.00 F <i>?</i>
25	1		*Front knuckle arm RH	0.00	0.00	*160.00 F <i>?</i>
26	1		*Front wheel bearing with wheel hub assembly RH	0.00	0.00	*165.00 F <i>?</i>
27	1		*Front lower arm RH	0.00	0.00	*165.00 F <i>?</i>
28	1		*Front lower arm ball joint RH	0.00	0.00	*65.00 F <i>?</i>

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,300.00
+ Margin on L,N Items 10.00% (\$\$)	488.00
Total Parts (\$\$)	5,788.00

Hitachi Capital Asia Pacific Pte. Ltd/SKX315K/12/12/2017 14:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align & replace damaged parts of affected area	New	700 1,400.00
2	Putty, blend and paint affected area	New	800 1,200.00
3	Check Wiring and ensure proper function	New	30 80.00
4	Conduct four wheel alignment / side slip test	New	80 150.00
5	Remove, replace & balance rim / tire	New	80 40.00
6	Remove, replace & re-install undercarriage parts	New	photo 7 120 280.00
7	Transfer door lock & mechanism to new door	New	60 180.00
8	Diagnostic Check & Reset	New	120 250.00
Gross Labour Cost (S\$)			3,580.00

Hitachi Capital Asia Pacific Pte. Ltd/SKX315K/12/12/2017 14:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591