



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnnong@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SV 804BP
HONDA VEZEL
37528
CHASIS EC 300 215/60 R16 95H
RUI - 1102746

ATTN:		
QTY	DESCRIPTION - PARTS	PRICE
1.	front head lamp (R) R / CEA	
1	front head lamp clip (K) X	
1.	front bumper X	NN
1.	front bumper clip X	
2	front bumper bracket (L+K) X	
2.	front bumper retainer (L+R) RH - MCL	
1.	Front Bonnet X NN	repair
1.	Front fender (R) - MCL	
1.	Front fender coving clip (K) - MCL	
1.	Front fender coving clip garnish (K) - RL	
1.	Front fender coving garnish clip (K). - MCL.	
1.	Front door (K) - MCL.	
1.	Front door power motor (K) X NN	
1.	Front door regulator (K). R / BT	
1.	Front door window sticker (K). - MCL.	
1.	Front door lock (K) X	NN
1.	Front door handle (K). X	
1.	Front door outer mould (K). X	
1.	Front door board board (K) X	
1.	Front door weather strip (K). R / MCL	
1.	Front door pillar (K). X repair.	
1.	Front door hinge up / down (K). - BT	
1.	Front door checker (K). R / BT	
1.	Front door inner weather strip (K) X NN	
1.	Front door lower rubber (K) R / MCL	
1.	Front fender inner panel (K) X repair.	
1.	Front Rocker Panel R / (K) BUL	
1.	Front Rocker Panel Garnish. (K) - RL.	
1.	Front Rocker Panel Garnish Clip (K) - MCL.	
1.	Front door step garnish (K). X	NN
1.	Front door step garnish clip (K) X	
1.	Front windscreen glass mould. X	
1.	Front tyre absorber (K) X	
1.	Front tyre knuckle (K) X	
1.	Front tyre knuckle Bearing (K) - MCL	
1.	Front tyre lower arm X NN	

Special Netf				
Front Rim	X	(R)	NN	500
Front tyre	-	(R)	SCR	100 300
Front door pillar sealant	(R)	X	} NN	100
Rocker panel sealant	(R)	X		100
Front windscreen glass sealant	(R)	X		80

QTY	DESCRIPTION - PARTS	LABOUR	PRICE
1.	To RnR Accident affected (Front)	600 800	1800
1.	To RnR al respray accident affected (Front)	800	1600
1.	To rust proof accident affected area (Front)	60	90
1.	To reassemble door mechanism	60	120
1.	To check wiring, input and headlamp focus	30	120
1.	To RnR front windscreen glass	X	150
1.	To RnR front dashboard mechanism	200 X	400
1.	To RnR upholstery & attachment parts	60	300
1.	To RnR front undercarriage system	40	280
1.	To check wheel alignment	60	150
1.	To check chassis alignment	NN { X	400
1.	To check water seepage	X	80

7 Days.

Guo Qiang - 82880282

Guo Qiang@lkkauto.com

Lumpsum repair.

After repair photos.

11/12/17.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: