

ASS. REC. BY:

REF:

09/SPF17023595 / Gtb ez

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Perry He

of

SPF

Date/Time:

12.12.2017 3:50pm

Estimated Cost:

Bill to:

OB / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 581L

Insured:

at Workshop m/s

Indeco Engineers

Tel:

8511 4276

of

39 Deftu Lane 12

Policy No:

Claim No:

HUMSPFETQ16000399

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

13.12.2017

H.O.D. Endorsement:

Date/Time:

12/12/2017 5:07pm

Person Contacted:

Anson

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

QX 581L - X

14/12/17 - 2:33pm - sent email to perry.

8/3-

Perry say can close file

8/3-

Parts \$6407.40, man HR. 61

REF: SPF

ASSIGNMENT

From:

Date:

13/12/17

Estimated Cost:

☒ OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

QX 581L

at Workshop mis

Indeco Engineers

of

39 Bepi Lane 12

insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA : PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

QX 581L

Yr Reg:

13 May 2018

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Hyundai Avante 1591

Colour

white

A/C

Insured / Std / NI / NA

Sp. Reading

-

T Radio: Insured / Std / NI / NA

Eng. No:

C/No:

KMH1DU4LB M-AH023464

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.A.

13-12-17

Survey held at

w/s

12pm

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop orThe ☒ U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 16 MAR 2018

Date/Time File Pass to:

☐

: Preli. Report

8/3 Typist

☒

: Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

FUEL - Petrol

Parking

Other

TOTAL

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Technical \$

☐

Witness \$

Report Format:

Lump Sum / I.B.I. \$

290

290



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF17023595/Gtb

CONTRACT MANAGEMENT SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD

Date : 12-12-2017



BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Code : SPF3

1. Policy Particulars - OWN DAMAGE

Insured Veh.	Veh. Inspected	QX 581L
Policy No.	Coverage (\$)	0.00
Claim No. HOMSPFETQ16000399	Excess (\$)	0.00
Assign From PERRY HE	Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	Inspection Date	13/12/2017
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 SINGAPORE 539139	

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Tuesday, 12 December, 2017 3:50 PM
To: assignments
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto)
Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX581L

Hi Catherine and Ashley,

Please provide Appraisal Service for the following SPF vehicle at INDECO Engineers.

1) QX581L

Parts:

WIPER PANEL GARNISH
FRT WINDSCREEN
FRT WINDSCREEN MOULDING
SEALANT
INNER SEAL TAPE
IU STICKER
BONNET
BONNET HINGE RH
BONNET HINGE LH
HEADLAMP LH
HEADLAMP LOWER BEAM LH
FRT BUMPER
FRT BUMPER LOWER GRILLE
FRT BUMPER LOWER LIP
FRT BUMPER RETAINER LH
FRT BUMPER RETAINER RH
FRT BUMPER CLIP
FOGLAMP COVER LH
ENGINE UNDER COVER FRT 29110-2H200
RHF FENDER
LHF FENDER
LHF FENDER INNER SHIELD
LHF FENDER INNER SHIELD CLIP
FRT SUPPORT PANEL
FRT BUMPER REINFORCEMENT
FRT BUMPER SPONGE
LH CHASSIS
BONNET LOCK
LHF FENDER INNER GARNISH
AIR DUCT @ SUPPORT PANEL
AIR DUCT HOSE
BATTERY TRAY
RADIATOR
CONDENSER
RADIATOR FAN BLADE (WITH ITEM 1.37)
RADIATOR FAN MOTOR
RADIATOR FAN COWLING (WITH ITEM 1.37)

RADIATOR TOP BRACKET LH
RADIATOR TOP BRACKET MOUNTING LH (WITH ITEM 1.39)
RADIATOR TOP HOSE
LHF LOWER ARM
LHF KNUCKLE ARM
LHF S/ABSORBER
LHF WHEEL BEARING
ENGINE CROSS MEMBER
ENGINE UNDER COVER LH 29110-2H000
CHASSIS COVER LH 29120-2H050
CROSS MEMBER MOUNTING
CROSS MEMBER STAY LH 62476-2H000
LHF LOWER ARM BALL JOINT
LHF ANTI ROLL BAR LINK

Labour:

TO ALIGN, REPLACE, RESPRAY BONNET AND
HINGES
TO ALIGN, REPLACE AND RESPRAY SUPPORT
PANEL
TO REPLACE AND RESPRAY FRT
BUMPER
TO ALIGN, REPLACE AND RESPRAY
REINFORCEMENT
TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST
WORK
TO ALIGN, REPAIR AND RESPRAY CHASSIS WHEEL
HOUSE
TO REPAIR AND RESPRAY LHF WHEEL
HOUSE
TO REPLACE AND RESPRAY LHF FENDER
TO REPLACE AND RESPRAY RHF FENDER
TO REPLACE FRT UNDER CARRIAGE
PARTS
TO PERFORM 4 WHEEL ALIGNMENT
TO REPLACE, CONDENSER, RADIATOR AND TOP UP AC
GAS
TO CHECK AND REWIRE WIRE
HARDNESS

Thank you.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725

THE HOME TEAM CELEBRATES
NS50



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Denise Tay (LKKAUTO)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Friday, 15 December, 2017 2:09 PM
To: Denise Tay (LKKAUTO)
Cc: assignments; SUR; Wei Yea LIM (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAUTO); Shiau Chan (LKKAUTO)
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX581L

Hi Denise,

There are many unconfirmed items especially on the undercarriage part.

Pls inform your assessor to check on these items too.

Do let me know if INDECO is unwilling to hoist this vehicle up for undercarriage check.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 14 December, 2017 2:33 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>; Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX581L

Dear Perry,

Please refer attached.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Tuesday, 12 December, 2017 3:50 PM
To: assignments <assignments@lkkauto.com>

Denise Tay (LKKAuto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Friday, 15 December, 2017 2:10 PM
To: Veron Chen (LKKAuto)
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX509Y

Hi Veron,

There are many unconfirmed items especially on the undercarriage part.

Pls inform your assessor to check on these items too.

Do let me know if INDECO is unwilling to hoist this vehicle up for undercarriage check.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 14 December, 2017 2:38 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX509Y

Dear Perry,

Kindly refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 20 December, 2017 9:41 AM
To: 'wgleong@sg.indeco.cwtlimited.com'
Cc: 'tanch@sg.indeco.cwtlimited.com'; SUR
Subject: QX 581L & QX 509Y SPF CASE

Dear Sir,

As per conversation with Anson and Guo Qiang, hereby is the screenshot email by SPF



Fri 15/12/2017 2:09 PM

Perry HE (SPF) <Perry.HE@spl.gov.sg>

RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX581L

To: Denise Tay (IQ(Auto))

Cc: BI assignments; BI SUR; Wei Yee LIM (SPF); Kim Pong CHAY (SPF); Al Ping (IQ(Auto)); Shau Chan (IQ(Auto))

You replied to this message on 15/12/2017 4:21 PM

Action Items

Hi Denise,

There are many unconfirmed items especially on the undercarriage part.

Pls inform your assessor to check on these items too.

Do let me know if INDECO is unwilling to hoist this vehicle up for undercarriage check.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5726



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not or 213) Please notify the sender immediately if you receive this in error."



Fri 15/12/2017 2:10 PM

Perry HE (SPF) <Perry.HE@spf.gov.sg>

RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFET016000399 - QX509Y

To: Veron Chen (LKKAuto)

Cc: Wei Yea (SPF); Kwee Huat TAN (SPF); Kai Pang CHAI (SPF); B SUR

Hi Veron,

There are many unconfirmed items especially on the undercarriage part.

Pls inform your assessor to check on these items too.

Do let me know if INDECO is unwilling to hoist this vehicle up for undercarriage check.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you m 213). Please notify the sender immediately if you receive this in error."

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Friday, 15 December, 2017 2:09 PM
To: Denise Tay (LKKAuto)
Cc: assignments; SUR; Wei Yea LIM (SPF); Kim Pang CHAY (SPF); Ai Phing (LKKAuto); Shiau Chan (LKKAuto)
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX581L

Hi Denise,

There are many unconfirmed items especially on the undercarriage part.

Pls inform your assessor to check on these items too.

Do let me know if INDECO is unwilling to hoist this vehicle up for undercarriage check.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4869 | HP: (65) 9191 5725



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 14 December, 2017 2:33 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>; Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX581L

Dear Perry,

Please refer attached.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Tuesday, 12 December, 2017 3:50 PM
To: assignments <assignments@lkkauto.com>



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	Indeco Engineers Pte Ltd	VEH TYPE :	UNIT :	A DIV	Reference No.
VEH NO :	QX581L	FRC	REPAIR TYPE:	ACCIDENT	MHA/SPF/2017/12-0015
VEH MAKE/MODEL	HYUNDAI AVANTE	Mileage:			

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	WIPER PANEL GARNISH / CNA	40.00	1	18%	47.20	47.20
1.2	FRT WINDSCREEN / CNA	530.00	1	18%	625.40	625.40
1.3	FRT WINDSCREEN MOULDING / AC	40.00	1	18%	47.20	47.20
1.4	SEALANT	20.00	2	18%	23.60	47.20
1.5	INNER SEAL TAPE / AC	30.00	1	18%	35.40	35.40
1.6	IU STICKER	5.00	1	18%	5.90	5.90
1.7	BONNET / AC	495.00	1	18%	584.10	584.10
1.8	BONNET HINGE RH / BT	30.00	1	18%	35.40	35.40
1.9	BONNET HINGE LH / BT	30.00	1	18%	35.40	35.40
1.10	HEADLAMP LH / CNA	170.00	1	18%	200.60	200.60
1.11	HEADLAMP LOWER BEAM LH / BT	26.00	1	18%	30.68	30.68
1.12	FRT BUMPER / CNA	195.00	1	18%	230.10	230.10
1.13	FRT BUMPER LOWER GRILLE / AC	30.00	1	18%	35.40	35.40
1.14	FRT BUMPER LOWER LIP / BT	28.00	1	18%	33.04	33.04
1.15	FRT BUMPER RETAINER LH / AC	20.00	1	18%	23.60	23.60
1.16	FRT BUMPER RETAINER RH / AC	20.00	1	18%	23.60	23.60
1.17	FRT BUMPER CLIP	1.50	10	18%	1.77	17.70
1.18	FOGLAMP COVER LH / AC	18.00	1	18%	21.24	21.24
1.19	ENGINE UNDER COVER FRT 29110-2H200 / AC	32.00	1	18%	37.76	37.76
1.20	RHF FENDER / AC	145.00	1	18%	171.10	171.10
1.21	LHF FENDER / AC	145.00	1	18%	171.10	171.10
1.22	LHF FENDER INNER SHIELD / BT	30.00	1	18%	35.40	35.40
1.23	LHF FENDER INNER SHIELD CLIP / AC	1.50	6	18%	1.77	10.62
1.24	FRT SUPPORT PANEL / BT	320.00	1	18%	377.60	377.60
1.25	FRT BUMPER REINFORCEMENT / BT	115.00	1	18%	135.70	135.70
1.26	FRT BUMPER SPONGE / CNA	58.00	1	18%	68.44	68.44
1.27	LH CHASSIS	580.00	1	18%	684.40	684.40
1.28	BONNET LOCK / BT	35.00	1	18%	41.30	41.30
1.29	LHF FENDER INNER GARNISH / AC	18.00	1	18%	21.24	21.24
1.30	AIR DUCT @ SUPPORT PANEL / AC	60.00	1	18%	70.80	70.80
1.31	AIR DUCT HOSE / BT	140.00	1	18%	165.20	165.20
1.32	BATTERY TRAY / CNA	20.00	1	18%	23.60	23.60
1.33	RADIATOR	230.00	1	18%	271.40	271.40
1.34	CONDENSER / BT	155.00	1	18%	182.90	182.90
1.35	RADIATOR FAN BLADE (WITH ITEM 1.37) ?	0.00	1	18%	0.00	0.00
1.36	RADIATOR FAN MOTOR ?	155.00	1	18%	182.90	182.90
1.37	RADIATOR FAN COWLING (WITH ITEM 1.37) ?	0.00	1	18%	0.00	0.00
1.38	RADIATOR TOP BRACKET LH / BT	15.00	1	18%	17.70	17.70
1.39	RADIATOR TOP BRACKET MOUNTING LH (WITH ITEM 1.38) / AC	0.00	1	18%	0.00	0.00
1.40	RADIATOR TOP HOSE ?	28.00	1	18%	33.04	33.04
1.41	LHF LOWER ARM / BT	115.00	1	18%	135.70	135.70
1.42	LHF KNUCKLE ARM / BT	165.00	1	18%	194.70	194.70
1.43	LHF S/ABSORBER / BT	115.00	1	18%	135.70	135.70
1.44	LHF WHEEL BEARING / AC	55.00	1	18%	64.90	64.90
1.45	ENGINE CROSS MEMBER / BT	680.00	1	18%	802.40	802.40
1.46	ENGINE UNDER COVER LH 29110-2H000 ?	20.00	1	18%	23.60	23.60
1.47	CHASSIS COVER LH 29120-2H050 ?	20.00	1	18%	23.60	23.60
1.48	CROSS MEMBER MOUNTING / BT	20.00	4	18%	23.60	94.40
1.49	CROSS MEMBER STAY LH 62476-2H000 / BT	55.00	1	18%	64.90	64.90
1.50	LHF LOWER ARM BALL JOINT / BT	35.00	1	18%	41.30	41.30
1.51	LHF ANTI ROLL BAR LINK / BT	38.00	1	18%	44.84	44.84
2	Additional Services					
Remarks:					Parts Total:	\$ 6,407.40

7 penjur close.

Monday 11






ACCIDENT/DAMAGE REPAIR AND AD HOC WORKS REQUEST FORM

Vehicle No	Rx581L	Division/Unit	For A.D.V
Vehicle Type (e.g. FRC, minibus)	FRC	Date	4/12/17
Vehicle Make & Model	Hyundai Avante	Mileage (km)	

Description	Pls tick	Police Report No & Date of Accident (if applicable)
NP168 (Accident involve 3 rd Party)	☒	T/20121204/2006
NP168 (Accident do not involve 3 rd Party)	☐	
NP299 Discovered Damage	☐	
NP299 Vandalism	☐	
Ad hoc, pls specify	☐	

Description of affected area/required works (e.g. dented, cracked, grazed etc)
Front bumper dented and cracked

Pls mark affected area with **X**



Rank/Name Sg Eki Yuen	Signature
--------------------------	---------------

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Government
Owner ID	0036C

Vehicle Details

Vehicle No.	QX581L
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	HYUNDAI
Vehicle Model	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour	White
Manufacturing Year	2010
Engine No.	G4FCGUR21628
Chassis No.	KMH DU41BMAU023464
Maximum Power Output	89.7 kW (120 bhp)
Open Market Value	\$16,309.00
Original Registration Date	13 May 2010
First Registration Date	13 May 2010
Transfer Count	0
Actual ARF Paid	\$0.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	12 May 2020
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Rebate Amount	\$0.00
Total Rebate Amount	\$0.00

Message

Transfer of ownership or de-registration is not allowed for this vehicle. Please contact LTA at 1800-CALL LTA (1800-2255 582) for further assistance.

The information contained herein is correct as at 14 Dec 2017

OK

Registration No. QX581L

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	WIPER PANEL GARNISH	1	CRACKED	\$47.20	\$47.20	
1.2	FRONT WINDSCREEN	1	CRACKED	\$625.40	\$625.40	
1.3	FRONT WINDSCREEN MOULDING	1	NECESSARY	\$47.20	\$47.20	
1.4	SEALANT	2	NECESSARY	\$23.60	\$47.20	
1.5	INNER SEAL TAPE	1	NECESSARY	\$35.40	\$35.40	
1.6	IU STICKER	1	NECESSARY	\$5.90	\$5.90	
1.7	BONNET	1	BUCKLED	\$584.10	\$584.10	
1.8	BONNET HINGE RH	1	BENT	\$35.40	\$35.40	
1.9	BONNET HINGE LH	1	BENT	\$35.40	\$35.40	
1.10	HEADLAMP LH	1	CRACKED	\$200.60	\$200.60	
1.11	HEADLAMP LOWER BEAM LH	1	BENT	\$30.68	\$30.68	
1.12	FRONT BUMPER	1	CRACKED	\$230.10	\$230.10	
1.13	FRONT BUMPER LOWER GRILLE	1	BROKEN	\$35.40	\$35.40	
1.14	FRONT BUMPER LOWER LIP	1	DISTORTED	\$33.04	\$33.04	
1.15	FRONT BUMPER RETAINER LH	1	NECESSARY	\$23.60	\$23.60	
1.16	FRONT BUMPER RETAINER RH	1	NECESSARY	\$23.60	\$23.60	
1.17	FRONT BUMPER CLIP	10	NECESSARY	\$1.77	\$17.70	
1.18	FOGLAMP COVER LH	2	DISTORTED	\$21.24	\$21.24	
1.19	ENGINE UNDER COVER FRONT 29110-2H200	2	DEFORMED	\$37.76	\$37.76	
1.20	RHF FENDER	1	BUCKLED	\$171.10	\$171.10	
1.21	LHF FENDER	1	BUCKLED	\$171.10	\$171.10	
1.22	LHF FENDER INNER SHIELD	1	TORN	\$35.40	\$35.40	

1.23	LHF FENDER INNER SHIELD CLIP	6	NECESSARY	\$1.77	\$10.62	
1.24	FRONT SUPPORT PANEL	1	DISTORTED	\$377.60	\$377.60	
1.25	FRONT BUMPER REINFORCEMENT	1	BENT	\$135.70	\$135.70	
1.26	FRONT BUMPER SPONGE	1	CRACKED	\$68.44	\$68.44	
1.27	LH CHASSIS	1	UNCONFIRM	\$684.40	\$684.40	
1.28	BONNET LOCK	1	BENT	\$41.30	\$41.30	
1.29	LHF FENDER INNER GARNISH	1	DENTED	\$21.24	\$21.24	
1.30	AIR DUCT @ SUPPORT PANEL	1	CUT	\$70.80	\$70.80	
1.31	AIR DUCT HOSE	1	TWISTED	\$165.20	\$165.20	
1.32	BATTERY TRAY	1	CRACKED	\$23.60	\$23.60	
1.33	RADIATOR	1	UNCONFIRM	\$271.40	\$271.40	
1.34	CONDENSER	1	BENT	\$182.90	\$182.90	
1.35	RADIATOR FAN BLADE(WITH ITEM 1.37)	1	UNCONFIRM	\$0.00	\$0.00	
1.36	RADIATOR FAN MOTOR	1	UNCONFIRM	\$182.90	\$182.90	
1.37	RADIATOR FAN COWLING(WITH ITEM 1.37)	1	UNCONFIRM	\$0.00	\$0.00	
1.38	RADIATOR TOP BRACKET LH	1	BENT	\$17.70	\$17.70	
1.39	RADIATOR TOP BRACKET MOUNTING LH (WITH ITEM 1.37)	1	NECESSARY	\$0.00	\$0.00	
1.40	RADIATOR TOP HOSE	1	UNCONFIRM	\$33.04	\$33.04	
1.41	LHF LOWER ARM	1	BENT	\$135.70	\$135.70	
1.42	LHF KNUCKLE ARM	1	BENT	\$194.70	\$194.70	
1.43	LHF S/ABSORBER	1	BENT	\$135.70	\$135.70	
1.44	LHF WHEEL BEARING	1	NECESSARY	\$64.90	\$64.90	
1.45	ENGINE CROSS MEMBER	1	BENT	\$802.40	\$802.40	
1.46	ENGINE UNDER COVER LH 29110-2H000	1	UNCONFIRM	\$23.60	\$23.60	
1.47	CHASSIS COVER LH 29120-2H050	1	UNCONFIRM	\$23.60	\$23.60	
1.48	CROSS MEMBER MOUNTING	4	BENT	\$23.60	\$94.40	
1.49	CROSS MEMBER STAY LH 62476-2H000	1	BENT	\$64.90	\$64.90	
1.50	LHF LOWER ARM BALL JOINT	1	BENT	\$41.30	\$41.30	
1.51	LHF ANTI ROLL BAR LINK	1	BENT	\$44.84	\$44.84	

3	SCOPE OF REPAIRS					
3.1	TO ALIGN, REPLACE, RESPARY BONNET AND HINGE					6
3.2	TO ALIGN, REPLACE AND RESPARY SUPPORT PANEL					4
3.3	TO REPLACE AND RESPARY FRONT BUMPER					5
3.4	TO ALIGN, REPLACE AND RESPARY REINFORCEMENT					1
3.5	TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK			UNCONFIRM		10
3.6	TO ALIGN, REPAIR AND RESPARY CHASSIS WHEEL HOUSE					6
3.7	TO REPAIR AND RESPRAY LHF WHEEL HOUSE					10
3.8	TO REPLACE AND RESPARY LHF FENDER					4
3.9	TO REPLACE AND RESPRAY RHF FENDER					4
4	TO REPLACE FRONT UNDER CARRIAGE PARTS			UNCONFIRM		4
4.1	TO PERFORM 4 WHEEL ALIGNMENT					1
4.2	TO REPLACE, CONDENSER RADIATOR AND TOP UP AC GAS					2
4.3	TO CHECK AND REWIRE WIRE HARDNESS					4
COSTING						
				TOTAL PARTS COST	\$6,407.40	
				TOTAL MAN-HOUR		61



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF17023595/Gtbe2

CONTRACT MANAGEMENT SECTION

(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 12-03-2018



Code : SPF3

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	QX 581L
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ16000399	Excess (\$)	0.00
Assign From	PERRY HE	Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KMH DU41BMAU023464	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	FALKEN	6 mm
L/H Front Tyre	185/65 R15	FALKEN	6 mm
R/H Rear Tyre	185/65 R15	FALKEN	6 mm
L/H Rear Tyre	185/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date		Inspection Date	13/12/2017
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		

5a. Remarks

--	--



**Auto
Consultants
Pte Ltd**

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. QX581L

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	WIPER PANEL GARNISH	1	CRACKED	\$47.20	\$47.20	
1.2	FRONT WINDSCREEN	1	CRACKED	\$625.40	\$625.40	
1.3	FRONT WINDSCREEN MOULDING	1	NECESSARY	\$47.20	\$47.20	
1.4	SEALENT	2	NECESSARY	\$23.60	\$47.20	
1.5	INNER SEAL TAPE	1	NECESSARY	\$35.40	\$35.40	
1.6	IU STICKER	1	NECESSARY	\$5.90	\$5.90	
1.7	BONNET	1	BUCKLED	\$584.10	\$584.10	
1.8	BONNET HINGE RH	1	BENT	\$35.40	\$35.40	
1.9	BONNET HINGE LH	1	BENT	\$35.40	\$35.40	
1.10	HEADLAMP LH	1	CRACKED	\$200.60	\$200.60	
1.11	HEADLAMP LOWER BEAM LH	1	BENT	\$30.68	\$30.68	
1.12	FRONT BUMPER	1	CRACKED	\$230.10	\$230.10	
1.13	FRONT BUMPER LOWER GRILLE	1	BROKEN	\$35.40	\$35.40	
1.14	FRONT BUMPER LOWER LIP	1	DISTORTED	\$33.04	\$33.04	
1.15	FRONT BUMPER RETAINER LH	1	NECESSARY	\$23.60	\$23.60	
1.16	FRONT BUMPER RETAINER RH	1	NECESSARY	\$23.60	\$23.60	
1.17	FRONT BUMPER CLIP	10	NECESSARY	\$1.77	\$17.70	
1.18	FOGLAMP COVER LH	2	DISTORTED	\$21.24	\$21.24	
1.19	ENGINE UNDER COVER FRONT 29110-2H200	2	DEFORMED	\$37.76	\$37.76	
1.20	RHF FENDER	1	BUCKLED	\$171.10	\$171.10	
1.21	LHF FENDER	1	BUCKLED	\$171.10	\$171.10	
1.22	LHF FENDER INNER SHIELD	1	TORN	\$35.40	\$35.40	
1.23	LHF FENDER INNER SHIELD CLIP	6	NECESSARY	\$1.77	\$10.62	
1.24	FRONT SUPPORT PANEL	1	DISTORTED	\$377.60	\$377.60	
1.25	FRONT BUMPER REINFORCEMENT	1	BENT	\$135.70	\$135.70	
1.26	FRONT BUMPER SPONGE	1	CRACKED	\$68.44	\$68.44	

1.27	LH CHASSIS	1	UNCONFIRM	\$684.40	\$684.40	
1.28	BONNET LOCK	1	BENT	\$41.30	\$41.30	
1.29	LHF FENDER INNER GARNISH	1	DENTED	\$21.24	\$21.24	
1.30	AIR DUCT @ SUPPORT PANEL	1	CUT	\$70.80	\$70.80	
1.31	AIR DUCT HOSE	1	TWISTED	\$165.20	\$165.20	
1.32	BATTERY TRAY	1	CRACKED	\$23.60	\$23.60	
1.33	RADIATOR	1	UNCONFIRM	\$271.40	\$271.40	
1.34	CONDENSER	1	BENT	\$182.90	\$182.90	
1.35	RADIATOR FAN BLADE(WITH ITEM 1.37)	1	UNCONFIRM	\$0.00	\$0.00	
1.36	RADIATOR FAN MOTOR	1	UNCONFIRM	\$182.90	\$182.90	
1.37	RADIATOR FAN COWLING(WITH ITEM 1.37)	1	UNCONFIRM	\$0.00	\$0.00	
1.38	RADIATOR TOP BRACKET LH	1	BENT	\$17.70	\$17.70	
1.39	RADIATOR TOP BRACKET MOUNTING LH (WITH ITEM 1.37)	1	NECESSARY	\$0.00	\$0.00	
1.40	RADIATOR TOP HOSE	1	UNCONFIRM	\$33.04	\$33.04	
1.41	LHF LOWER ARM	1	BENT	\$135.70	\$135.70	
1.42	LHF KNUCKLE ARM	1	BENT	\$194.70	\$194.70	
1.43	LHF S/ABSORBER	1	BENT	\$135.70	\$135.70	
1.44	LHF WHEEL BEARING	1	NECESSARY	\$64.90	\$64.90	
1.45	ENGINE CROSS MEMBER	1	BENT	\$802.40	\$802.40	
1.46	ENGINE UNDER COVER LH 29110-2H000	1	UNCONFIRM	\$23.60	\$23.60	
1.47	CHASSIS COVER LH 29120-2H050	1	UNCONFIRM	\$23.60	\$23.60	
1.48	CROSS MEMBER MOUNTING	4	BENT	\$23.60	\$94.40	
1.49	CROSS MEMBER STAY LH 62476-2H000	1	BENT	\$64.90	\$64.90	
1.50	LHF LOWER ARM BALL JOINT	1	BENT	\$41.30	\$41.30	
1.51	LHF ANTI ROLL BAR LINK	1	BENT	\$44.84	\$44.84	
3	SCOPE OF REPAIRS					
3.1	TO ALIGN, REPLACE, RESPARTY BONNET AND HINGE					6
3.2	TO ALIGN, REPLACE AND RESPARTY SUPPORT PANEL					4
3.3	TO REPLACE AND RESPARTY FRONT BUMPER					5
3.4	TO ALIGN, REPLACE AND RESPARTY REINFORCEMENT					1
3.5	TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK		UNCONFIRM			10
3.6	TO ALIGN, REPAIR AND RESPARTY CHASSIS WHEEL HOUSE					6
3.7	TO REPAIR AND RESPRAY LHF WHEEL HOUSE					10
3.8	TO REPLACE AND RESPARTY LHF FENDER					4
3.9	TO REPLACE AND RESPRAY RHF FENDER					4
4	TO REPLACE FRONT UNDER CARRIAGE PARTS		UNCONFIRM			4

4.1	TO PERFORM 4 WHEEL ALIGNMENT					1
4.2	TO REPLACE, CONDENSER RADIATOR AND TOP UP AC GAS					2
4.3	TO CHECK AND REWIRE WIRE HARDNESS					4
COSTING		TOTAL PARTS COST			\$6,407.40	
		TOTAL MAN-HOUR				61

Registration No. QX581L

Vehicle Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.