

ASS. REC. BY:

REF: CS/FCI17023601 / Krbn4

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

1.43pm @ 12/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 3364 H

Insured:

SH 73862

at Workshop m/s

Carfimes Autolution

Tel:

64715111

of

160 Sin Ming Drive Autocity #02-04

Policy No:

Claim No:

D17011380MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

13/12/17

H.O.D. Endorsement:

Date/Time:

5.03pm @ 12/12/17

Person Contacted:

Hai ching

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SLT 3364 H - X
	SH 73862 - CS/FCI17012763 / U/vbn2
	D.O.A.; 25/06/2017
	Sent pics through email



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023601/Krb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7386Z	Veh. Inspected	SLT 3364H
Policy No.		Coverage (\$)	0.00
Claim No.	D17011380MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	12/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/12/2017	Inspection Date	
Survey held at	-		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	11-12-2017	Our Ref No. D17011380MFSH
Accident Date	09-12-2017	Claim Type. Third Party
Insured Vehicle	SH7386Z	Third Party Vehicle. SLT3364H
Survey Location	160 Sin Ming Drive Autocity #02-04	
Contact Person.	CAI CHENG	
Contact No.	64715111/ 64715111	Fax No. 0
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED INSURED WILL DO ADDENDUM ON IV POSITION (SHOULD BE IV HTR TPV)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CAR TIMES AUTOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231712)



PRI Documents



Close X

PRI Header Details

Claim No	D17011380MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CAR TIME
Workshop Name	CAR TIMES AUTOLUTION PTE LTD (Contact Person : CAI CHENG)	Survey Location & Contact Details	160 Sin Ming Drive Autocity #02-04 Mobile: 64715111 , Phone: 64715111 , Fax: 0 EmailId: CLAIMS@CARTIMES.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED INSURED WI POSITION (SHOULD BE IV HTR TPV)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7386Z	TP Vehicle No	SLT3364H
PRI Recieved Date	12-12-2017 02:53:23 PM	Surveyor Appointed Date	12-12-2017 04:42:17 PM	Surveyor Accept Date	12-12-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011380MFSH

Our Ref: CS/FCI17023601/Krb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 3364H

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/12/2017 at the premises of M/s CARTIMES AUTOLUTION and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,065.85</u>
Revised Estimate Amount	: S\$ <u>3,855.23</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at rear o/s portion.



Yours faithfully

KENNETH
Automotive Assessor

CARTIMES

autolution

Vehicle No. SLT3364H

Car Model : TOYOTA SIENTA

Chassis No. NHP1707062575

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYORS ADJUSTMENT(S\$)
1	TAILGATE	Damaged	<i>As</i> 1197.60	<i>✓</i>
1	REAR END PANEL	Damaged	<i>As</i> 775.60	<i>✓</i>
1	RHS TAILGATE LAMP	Damaged	<i>Sm</i> 380.50	<i>x</i>
1	REAR BUMPER	Damaged	<i>Bu</i> 400.50	<i>✓</i>
1	REFLECTOR RHS	Damaged	<i>CM</i> 128.20	<i>✓</i>
1	BUMPER RHS GARNISH	Damaged	<i>Bu</i> 315.50	<i>✓</i>
1	BUMPER CENTER GARNISH	Damaged	<i>Pe</i> 198.50	<i>✓</i>
1	REAR TAILGATE WINDSCREEN RUBBER	Damaged	<i>Me</i> 85.50	<i>✓</i>
1	RHS TAILLAMP	Damaged	<i>Sm</i> 367.00	<i>x</i>
1	RHS RETAINER	Damaged	<i>Di</i> 78.90	<i>✓</i>
			3927.80	
			25% 981.95	25%
			2945.85	
<u>SPECIAL NETT ITEMS</u>				
1	WINDSCREEN SEAL	Necessary	<i>Me</i> 100.00	<i>40sm</i>
1	REVERSE SENSOR	Necessary	<i>Pe</i> 150.00	<i>✓</i>
			250.00	
TOTAL PARTS			3195.85	

Not Authorised
 Kenneth
 96810663
 1st LBR 83050
 Resurvey B4 painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	900.00 540	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (pearl white)	700.00 600	
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	120.00 200	
4	To remove and refix rear tailgate windscreen	150.00 1200	
	Labour Total :	1870.00	
	TOTAL (PARTS & LABOUR):	5065.85	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023601/Krbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7386Z	Veh. Inspected	SLT 3364H	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011380MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	NHP1707062575	Colour	METALLIC SILVER	
Odometer	10923	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	4 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	4 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	3 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/12/2017	Inspection Date	13/12/2017	
Survey held at	160 SIN MING DRIVE AUTOCITY #02-04			
Repairer	CAR TIMES AUTOLUTION PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 3364H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	1,197.60	1,197.60
1	REAR END PANEL	BENT	775.60	775.60
1	RHS TAILGATE LAMP	SERVICEABLE	380.50	-
1	REAR BUMPER	BUCKLED	400.50	400.50
1	REFLECTOR RHS	CRACKED	128.20	128.20
1	BUMPER RHS GARNISH	BUCKLED	315.50	315.50
1	BUMPER CENTER GARNISH	DENTED	198.50	198.50
1	REAR TAILGATE WINDSCREEN RUBBER	NECESSARY	85.50	85.50
1	RHS TAILLAMP	SERVICEABLE	367.00	-
1	RHS RETAINER	DISTORTED	78.90	78.90
	LESS 25% DISCOUNT		-981.95	-795.07
			2,945.85	2,385.23
	<u>SPECIAL NETT ITEMS</u>			
1	WINDSCREEN SEAL (SN)	NECESSARY	100.00	40.00
1	REVERSE SENSOR (SN)	DENTED	150.00	150.00
			250.00	190.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS.		900.00	540.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED (PEARL WHITE).		700.00	600.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		120.00	20.00
	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN.		150.00	120.00
			1,870.00	1,280.00
	GRAND TOTAL		5,065.85	3,855.23
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,050.00

Report Ref No. CS/FCI17023601/Krbn2



Report Ref No. CS/FCI17023601/Krbn2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.