

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHB7759T - AXA

AAD1712-076

Not Authored
1/1500

Vehicle No.:	SHB7759T - Dongfeng
Chassis No.:	KL1LA69RJBB104385
Vehicle Make:	CHEVROLET
Vehicle Model:	CHEVROLET EPICA 2.0
Date of Accident :	08.12.2017
Third Party Insurer :	AXA

		PART		LIST	
1	1	Rear Door RH	\$	<i>R</i> 1,133.00	X
2	1	Rear Door Guide RH Chrome Moulding	\$	<i>Sh</i> 60.00	X
3	1	Rear Door Outer Handle RH	\$	<i>Sh</i> 125.00	X
4	1	Rear Door Weatherstrip RH	\$	<i>Sh</i> 138.79	X
5	1	Rear Fender RH	\$	<i>R</i> 1,145.00	X
6	1	Rear Fender Inner Cowling RH	\$	<i>Sh</i> 298.00	X
7	1	Rear Tail Lamp RH	\$	<i>Sh</i> 479.30	X
8	1	Rear Bumper	\$	<i>Bu</i> 1,202.00	✓
9	1	Rear Bumper Beam	\$	<i>R</i> 239.94	X
10	1	Rear Bumper Centre Absorber	\$	<i>Sh</i> 260.00	X
11	1	Rear Bumper Side Retainer RH	\$	<i>Sh</i> 68.76	✓
12	1	Rear Bumper Reflectors RH	\$	<i>Sh</i> 119.74	X
13	1	Rear Bumper Tow Hook Cover	\$	<i>Sh</i> 93.00	X
TOTAL			\$	5,362.53	
10%			\$	536.25	
			\$	4,826.28	

Special Nett

1	1 Set	Front Fender Liner Clip RH	\$	<i>Sh</i> 30.00	X
2	1	Door Sticker "Trans-cab" RH	\$	<i>Sh</i> 80.00	X
3	1	Door Sticker "6555-3333" RH	\$	<i>Sh</i> 80.00	X
4	1set	Side Rocker Panel Garnish Clip RH	\$	<i>Sh</i> 60.00	X
5	1	Rear Tyre RH	\$	<i>Sh</i> 360.00	X
6	1	Rear Wheel Rim RH	\$	<i>Sh</i> 254.00	X
7	2	Rear Windscreen Sealant	\$	<i>Sh</i> 80.00	X
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>Sh</i> 100.00	X
9	1Set	Rear Bumper Parking Sensor	\$	<i>Sh</i> 300.00	X
10	1Set	Rear Bumper Fastener Clip	\$	<i>Sh</i> 30.00	✓

11 1Set Rear Fender inner cowling clip RH \$ *na* 30.00 X

TOTAL	\$	1,404.00
TOTAL PARTS	\$	6,230.28

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,700.00 <i>3001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 220.00 X
Putty and Spray Painting Of The Affected Portion.	\$	2,800.00 <i>4001</i>
To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 X
Towing Fees	\$	<i>na</i> 120.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 X

TOTAL	\$	6,910.00
Over All Total	\$	13,140.28

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All claims are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

REPAIR DAYS

Acknowledged by Repairer:
 Signature:
 Date:

10-DAYS
2 day