

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTU	ITUC INCOME INSURANCE CO-OPERATIVE LTD			Ref: NS/INC17023616/K1tbe2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	02-01-2018 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBC 3770B	Veh. Ir	nspected	SHD 4121S
	Policy No.	5081694701-01	Cover	age (\$)	0.00
	Claim No.	MT/0973396-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	12/12/2017
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI SONATA	c.c		1991
	Engine No.	HIDDEN	Year o	f Reg.	2012
	Chassis No.	KMHET41VMCA824325	Colou	r	BLUE
	Odometer	44087	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/60 R16	WEST		7 mm
	L/H Front Tyre	215/60 R16	WEST		7 mm
	R/H Rear Tyre	215/60 R16	WEST		7 mm
	L/H Rear Tyre	215/60 R16	WEST		7 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/12/2017		tion Date	12/12/2017
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD  59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				