

ASS: REC BY: _____ REF: CS/FCI17023641 / T1qd3n2 Special Instruction: _____
 Surveyor: Taukikh ASSIGNMENT (Office)
 CWS
 From (Person): May Chua of FCI Date/Time: 551pm @ 12/12/17
 Estimated Cost: _____ Bill to: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SFS 6666 T Insured: SH8780L
 at Workshop m/s: Performance Tel: 63190174
 of 303 Alexandra Road
 Policy No: D15072701MFSH Claim No: D17011424 MFSH
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 10/12/17
 (Client's Record)
 CA / REV / REP. / REV 24 HRS (up) E.O.D. Endorsement: _____
 Date/Time: 10:27am @ 13/12/17 Person Contacted: Caroline Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SFS 666T-X
	SH8780L - NS/INC16014362/M1/bc2 - D.O.A.: 01/08/2016
19/12/17 @ 5.13pm	revised to May Chua by email.
26/6/18 @ 4.57pm	confirmed with Caroline final Ag \$17767.40, 5 days.
	cred \$1648.70, 82)

Singer

Taufik

REF: FCL

ASSIGNMENT

From:

Date: 18.12.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFS 6666T

at Workshop m/s

Performance

of

303 Alexander Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Han

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS Wp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFS 6666T

Yr Regn:

2017 July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 540I

c.c.

2498

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

6181

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WRAJB320106459829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/30 R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/12/2017 530

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Taufik

Pis see me.

Jmanta
26/6.Jmanta
8/8/2018

Date/Time, File Pass to?



Preli. Report

1) 08/12/2017 Taufik



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation:

3 - RS - \$:

Photo: 08/12/2017

Other: 8/8/2018

915 = 135

170 + 135

50

50

98

98

98

98

98

98

98

98

98

Report Format:

7P

Lump Sum / I.B.I. (\$)

17767.40

503



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023641/T1qd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8780L	Veh. Inspected	SFS 6666T
Policy No.		Coverage (\$)	0.00
Claim No.	D17011424MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	13/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/12/2017	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011424MFSH
Our Ref: CS/FCI17023641/T1qd3

Date: 19 December 2017

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SFS 6666T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/12/2017 at the premises of M/s PERFORMANCE MOTOR LIMITED, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>14,305.20</u> .
Revised Estimate Amount	: S\$ <u>10,219.30</u> .
"Check" Items Amount	: S\$ <u>2,748.90</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Taufikh
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	12-12-2017	Our Ref No.	D17011424MFSH
Accident Date	10-12-2017	Claim Type.	Third Party
Insured Vehicle	SH8780L	Third Party Vehicle.	SFS6666T
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE		
Contact Person.	CAROLINE		
Contact No.	63190174/ 0	Fax No.	64794601
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	MAY CHUA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231762)



PRI Documents



Close



PRI Header Details

Claim No	D17011424MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PERFORM/
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEN Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8780L	TP Vehicle No	SFS6666T
PRI Recieved Date	12-12-2017 05:09:18 PM	Surveyor Appointed Date	12-12-2017 05:50:42 PM	Surveyor Accept Date	13-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-12-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 26 June 2018 4:57 PM
To: 'PBSP'; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: FINAL REPORT / SFS6666T

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$17,767.40 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 22 June 2018 7:39 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Re: FINAL REPORT / SFS6666T

URGENT REMINDER

From: PBSP
Sent: Monday, 26 March 2018 5:23:43 PM
To: Taufikh (LKK Auto)
Cc: 'Shiau Chan (LKKAUTO)'
Subject: Re: FINAL REPORT / SFS6666T

Urgent reminder

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 19 December, 2017 5:12 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011424MFSH/1
Attachments: CSFCI17023641T1qd3.pdf

Dear May,

Enclosed herewith preliminary advice of SFS 6666T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 13 December, 2017 10:29 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011424MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 12 December, 2017 5:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; MAYCHUA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011424MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Mon 18/12 @ 9.30am
S2R

SFS6666T

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559N GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

12 DEC 2017

Estimate No. : b1 45119
Date Estimated : 11/12/2017
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Poh Min Yuan
66 Jalan Gumilang

Singapore 668905

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFS6666T	G459829	21/07/2017	540iA	0

DESCRIPTION

To replace rear bumper & attachments, boot lid including to knock out tail panel and dented area caused by the accident

To respray rear bumper, boot lid and tail panel

To carry out body cavity preservation.
(Per panel).

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To check electrical wiring systems and lightings at the rear section for proper function.

To replace front seat crash-active head restraint air bags including reset and conduct check for function.

Sundries.

Total Labour 1: 8,658.00

DESCRIPTION

TAILGATE ALUMINIUM
REAR BUMPER CARRIER
EXHAUST SUPPORT
REAR BUMPER COVER (M)
REAR BUMPER LH GUIDE (M)

QTY	PRIC	VALUE
1	1,657.10	1,657.10
1	774.15	774.15
1	46.30	46.30
1	172.15	172.15
1	53.05	53.05

Handwritten notes and calculations:
1200
2975
2550
3442 1868- 2537
100 118.00
5617 661.00
451 531.00
231 2307 271.00
301 150 177.00
451 531.00
nee 150.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559N GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45119
Date Estimated : 11/12/2017
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFS6666T	G459829	21/07/2017	540iA	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER RH GUIDE (M)	1	53.05	53.05
REAR BUMPER CENTRE GUIDE (M)	1	58.55	58.55
REAR BUMPER PANEL PRIMED (M)	1	1,549.00	1,549.00
LETTERING 540I	1	61.05	61.05
PLAQUE 74MM	1	67.80	67.80
GROMMET	2	0.75	1.50
(DG) REPAIR KIT CRASH ACTIVE HEAD R	2	155.90	311.80
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	42.10
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	40.50
ULTRASONIC SENSOR BLUESTONE (C2Y)	2	374.60	749.20
DECOUPING RING PDC TORQUE CONVERTER	2	4.95	9.90

Total Parts : 5,647.20

Claims CO / 3rd Party / Uninsured Losses / Direct Settlement

Reg No. 18/12/17 21530

Date/Time 18/12/17 21530

Surveyor's Name Taufik

Surveyor's Tel 97498749

Authorized Date WP

RESURVEY BY Taufik @ (Khanj. 30m)

No. of Work Days 56-7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	8,658.00
Parts	:	5,647.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,001.36
Grand Total	:	15,306.56

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

12/12/17
17243.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45119
Date Estimated : 11/12/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Poh Min Yuan
66 Jalan Gumilang

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 668905

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SFS6666T	G459829	21/07/2017	540iA	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
* To replace rear bumper and attachments, boot lid, rear silencer LH/RH heat insulation, rear underbody panelling include making good the tail end panel, rear LH/RH fenders and knocking out dents caused by the accident	2975.00		2,975.00			
* To respray rear bumper, boot lid, tail end panel and rear LH/RH fenders	3992.00		3,992.00			
To carry out body cavity preservation. (Per panel).	100.00		100.00			
* To replace boot lid smart opener top sensor line, smart opener control units include programming and conducting checks for proper function	561.00		561.00			
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function.	451.00		451.00			
* To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00			
* To reconnect electrical components and wirings at the rear section include conducting checks for proper function	301.00		301.00			
To replace front seat crash-active head restraint air bags including reset and conduct check for function.	451.00		451.00			
# To replace rear silencer with exhaust flap include alignment and conducting checks for leak	451.00		451.00			(A) ne
Sundries	150.00		150.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.75	2.00		5.50
# TRANSMISSION BRACKET *	55.80	1.00		55.80

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

# CLAMPING BUSH *	131.95	1.00	131.95	ltg bt -
# RH TAILPIPE TRIM CHROME *	144.10	1.00	144.10	ltg ad -
# REAR SILENCER W/EXHAUST FLAP *	2,211.30	1.00	2,211.30	ltg bt -
TAILGATE ALUMINIUM	1,657.10	1.00	1,657.10	
REAR BUMPER CARRIER	774.15	1.00	774.15	
EXHAUST SUPPORT	46.30	1.00	46.30	
REAR BUMPER COVER (M)	172.15	1.00	172.15	
REAR BUMPER CENTRE GUIDE (M)	58.55	1.00	58.55	
REAR BUMPER PANEL PRIMED (M)	1,549.00	1.00	1,549.00	
LETTERING 540I	61.05	1.00	61.05	
PLAQUE 74MM	67.80	1.00	67.80	
GROMMET	0.75	2.00	1.50	
# REAR SILENCER LH HEAT INSULATION *	157.75	1.00	157.75	ltg bt -
# REAR SILENCER RH HEAT INSULATION *	157.75	1.00	157.75	ltg bt -
# UNDERBODY PANELLING REAR *	41.30	1.00	41.30	ltg de -
(DG) REPAIR KIT CRASH ACTIVE HEAD R	155.90	2.00	311.80	
SENSOR WIRE FOR SMART OPENER TOP	42.10	1.00	42.10	
# CONTROL UNIT SMART OPENER *	457.45	1.00	457.45	ltg org ✓

SUPPLEMENTARY ITEMS

Total Labour :	9,663.00
Total Parts :	8,104.40
Total Labour & Parts :	17,767.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	17,767.40
GST @7%:	1,243.72
Grand Total :	19,011.12

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45119
Date Estimated : 11/12/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Poh Min Yuan
66 Jalan Gumilang

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 668905

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SFS6666T	G459829	21/07/2017	540iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace rear silencer with exhaust flap include alignment and conducting checks for leak	451.00		451.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.75	2.00		5.50 <i>net</i> ✓
# TRANSMISSION BRACKET *	55.80	1.00		55.80 <i>de</i> ✓
# CLAMPING BUSH *	131.95	1.00		131.95 <i>br</i> ✓
# RH TAILPIPE TRIM CHROME *	144.10	1.00		144.10 <i>cut</i> ✓
# REAR SILENCER W/EXHAUST FLAP *	2,211.30	1.00		2,211.30 <i>br</i> ✓
# REAR SILENCER LH HEAT INSULATION *	157.75	1.00		157.75 <i>br</i> ✓
# REAR SILENCER RH HEAT INSULATION *	157.75	1.00		157.75 <i>br</i> ✓
# UNDERBODY PANELLING REAR *	41.30	1.00		41.30 <i>de</i> ✓
# CONTROL UNIT SMART OPENER *	457.45	1.00		457.45 <i>com</i> ✓

Total Labour :	451.00
Total Parts :	3,362.90
Total Labour & Parts :	3,813.90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023641/T1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8780L	Veh. Inspected	SFS 6666T	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011424MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	BMW 540I	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBAJB32010G459829	Colour	GREY	
Odometer	6181	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/30 R20	GOODYEAR	6 mm	
L/H Front Tyre	275/30 R20	GOODYEAR	6 mm	
R/H Rear Tyre	275/30 R20	GOODYEAR	6 mm	
L/H Rear Tyre	275/30 R20	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/12/2017	Inspection Date	18/12/2017	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFS 6666T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	TAILGATE ALUMINIUM (SN)	DENTED	1,657.10	1,657.10
1	REAR BUMPER CARRIER (SN)	BENT	774.15	774.15
1	EXHAUST SUPPORT (SN)	DEFORMED	46.30	46.30
1	REAR BUMPER COVER (M)(SN)	DEFORMED	172.15	172.15
1	REAR BUMPER LH GUIDE (M)(SN)	NOT NECESSARY	53.05	-
1	REAR BUMPER RH GUIDE (M)(SN)	NOT NECESSARY	53.05	-
1	REAR BUMPER CENTRE GUIDE (M)(SN)	DEFORMED	58.55	58.55
1	REAR BUMPER PANEL PRIMED (M)(SN)	DEFORMED	1,549.00	1,549.00
1	LETTERING 540I (SN)	NECESSARY	61.05	61.05
1	PLAQUE 74MM (SN)	NECESSARY	67.80	67.80
2	GROMMET (SN)	NECESSARY	1.50	1.50
2	(DG) REPAIR KIT CRASH ACTIVE HEAD R (SN)	CUT	311.80	311.80
1	SENSOR WIRE FOR SMART OPENER TOP (SN)	DISTORTED	42.10	42.10
1	SENSOR WIRE FOR SMART OPENER BOTTOM (SN)	NOT NECESSARY	40.50	-
2	ULTRASONIC SENSOR BLUESTONE (C2Y)(SN)	NOT NECESSARY	749.20	-
2	DECOUPING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	9.90	-
2	EXPANDING NUT (ADDITIONAL)(SN)	NECESSARY	5.50	5.50
1	TRANSMISSION BRACKET (ADDITIONAL)(SN)	DEFORMED	55.80	55.80
1	CLAMPING BUSH (ADDITIONAL)(SN)	BENT	131.95	131.95
1	RH TAILPIPE TRIM CHROME (ADDITIONAL)(SN)	CUT	144.10	144.10
1	REAR SILENCER W/EXHAUST FLAP (ADDITIONAL)(SN)	BENT	2,211.30	2,211.30
1	REAR SILENCER LH HEAT INSULATION (ADDITIONAL) (SN)	BENT	157.75	157.75
1	REAR SILENCER RH HEAT INSULATION (ADDITIONAL) (SN)	BENT	157.75	157.75
1	UNDERBODY PANELLING REAR (ADDITIONAL)(SN)	DEFORMED	41.30	41.30
1	CONTROL UNIT SMART OPENER (ADDITIONAL)(SN)	CRACKED	457.45	457.45
			9,160.10	8,254.40

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR SILENCER WITH EXHAUST FALP INCLUDE ALIGNMENT AND CONDUCTING CHECKS FOR LEAK (ADDITIONAL).		451.00	451.00
	TO REPLACE REAR BUMPER & ATTACHMENTS, BOOT LID INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED CAUSED BY THE ACCIDENT.		3,400.00	2,975.00
	TO RESPRAY REAR BUMPER, BOOT LID AND TAIL PANEL.		3,992.00	3,992.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.		661.00	561.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.		531.00	451.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	231.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		301.00	301.00
	TO REPLACE FRONT SEAT CRASH-ACTIVE HEAD RESTRAINT AIR BAGS INCLUDING RESET AND CONDUCT CHECK FOR FUNCTION.		531.00	451.00
			10,256.00	9,513.00
	GRAND TOTAL		19,416.10	17,767.40
	RECOMMENDED COST OF REPAIRS			17,767.40

Report Ref No. CS/FCI17023641/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.