

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AXA17023681/T1PA3Q2

**Date:** 04/02/2021

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1866285

**Claimant**

**Vehicle No :** SJK2279Z

**Insured Vehicle No :**

SGG7765K

Date of Loss: 06/12/2017

Nature of Claim:

TP

Claim No: C0462807

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SJK2279Z**

Make & Model:

MERCEDES-BENZ C180, 1.6 (A)

Engine No:

27195231044002

Reg. Date:

13/10/2008 (Man. Year: 2008)

Chassis No:

WDD2040462A176913

Colour:

Silver

Odometer:

163960 km

Engine Capacity:

1796 cc

Market Value/New Car

N/A

Price:

Sum Insured (\$\$):

**Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:

225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side:

Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,162.40	0.00	2,162.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	520.00	560.00	51.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>3,242.40</b>	<b>520.00</b>	<b>2,722.40</b>	<b>83.96</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:

13/12/2017

Date Inspected:

13/02/2018 Inspected At:

XINYA AUTO SERVICES PTE LTD

BLK

1002 BUKIT MERAH LANE 3 #01-75

SINGAPORE 159719

Estimated Period of Repair:

2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)
<b>Parts:</b>	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJK2279Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Repair	1,452.00 FL	*- FL
2	1		*FRONT BUMPER RETAINER (CONSISTENT)	Not Necessary	23.00 FL	*- FL
3	1		*FRONT BUMPER BEAM (CONSISTENT)	Not Necessary	165.00 FL	*- FL
4	1		*FRONT HEADLAMP (CONSISTENT)	Not Necessary	1,063.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,703.00</b>	<b>0.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	540.60	0.00
<b>Total Parts (\$\$)</b>	<b>2,162.40</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE & REPLACE FRONT BUMPER ,HEADLAMP AND TO PANEL BEAT AND ALIGN	New	600.00	250.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER AND OTHER AFFECTED AREA	New	400.00	250.00
3	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP	New	80.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>1,080.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >