


| | | | | |
|--|--|-----------------------|--------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023695/K1vbn2 | | | | |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: 03-01-2018 |  |
| | | | Code: INC4 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SKU 8437E | Veh. Inspected | SHC 3019S | |
| Policy No. | 5092414844 | Coverage (\$) | 0.00 | |
| Claim No. | MT/0973342-002 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 13/12/2017 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI SONATA | c.c | 1991 | |
| Engine No. | HIDDEN | Year of Reg. | 2011 | |
| Chassis No. | KMHET41VMBA804058 | Colour | BLUE | |
| Odometer | 430212 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 215/60 R16 | MAXXIS | 7 mm | |
| L/H Front Tyre | 215/60 R16 | MAXXIS | 7 mm | |
| R/H Rear Tyre | 215/60 R16 | MAXXIS | 7 mm | |
| L/H Rear Tyre | 215/60 R16 | MAXXIS | 7 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 11/12/2017 | Inspection Date | 13/12/2017 | |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | | |