Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI17023704/UQD3E2

3 Anson Road, #16-00 Springleaf Tower Singapore 079909

Date: 09/02/2018

REFERENCE

Insured/Claimant: TAY CHENG HAI Policy No: DMPCSN3100311701

Date of Loss: 07/12/2017 Nature of Claim: OD Claim No: SNM17D07018C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG8932R

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRX229956

Reg. Date: 18/10/2012 (Man. Year: 2012) Chassis No: MR053REE104148937

Colour: Black Odometer: 88292 km

Engine Capacity: 1598 cc Market Value/New Car Price: \$\$53,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
Front Right Side: Dunlop 7 mm
Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,289.40	829.05	460.35	35.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,047.71	814.93	232.78	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,337.11	1,643.98	693.13	29.66
- Excess (S\$)	500.00	0.00	500.00	100.00
(S\$)	1,837.11	1,643.98	193.13	10.51
+ GST 7.00/7.00% (S\$)	128.60	115.08	13.52	10.51
Nett Amount (S\$)	1,965.71	1,759.06	206.65	10.51

INSPECTION

Date of Assignment: 13/12/2017 Present Location: Specialists Motor Pte Ltd (HQ)

Date Inspected: 14/12/2017 Inspected At: Blk 3018A Ubi Road 1, #01-24/25/26

Singapore 408711

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Feb 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKG8932R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BUMPER SUPPORT (WCP)	Repair	150.00 F	*-F
2	1	NA	*FRONT BUMPER (WCP)	Dented/Deformed	220.00 F	*220.00 F
3	1	NA	*FRT BMPR RETAINER LH (WCP)	Bent	22.00 F	*22.00 F
4	1	NA	*FRT BMPR RETAINER RH (WCP)	Bent	22.00 F	*22.00 F
5	1	NA	*FRT BUMPER CLAMP KIT (WCP)	Not Necessary	25.00 F	*-F
6	1	NA	*GRILLE (WCP)	Cracked	130.00 F	*130.00 F
7	1	NA	*GRILLE BADGE (WCP)	Necessary	25.00 F	*25.00 F
8	1	NA	*INNER FRT PANEL CPL (WCP)	Repair	190.00 F	*-F
9	1	NA	*L/F BUMPER BRACKET (WCP)	Bent	22.00 F	*22.00 F
10	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	180.00 F	*180.00 F
11	1	NA	*SPECIALIST AUDATEX FEE		42.00 F	*42.00 FS
12	1	NA	*SPECIALIST FRT NUMBER PLATE	Bent	50.00 F	*35.00 FS
13	1	NA	*SPECIALIST WASH CAR&TEST DRIVE	Not Necessary	50.00 F	*-F
14	1	NA	*SUNDRY PARTS	Necessary	100.00 F	*100.00 FS
F=Fra	nchise	part. S=SpcN	ett.			
				Sub Total (S\$)	1,228.00	798.00
	+ Margin on L,N Items 5.00/5.00% (S\$) _				61.40	31.05
				Total Parts (S\$)	1,289.40	829.05

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	Total Paint Labour	New	593.40	501.40
2	Total Paint Materials	New	210.51	198.53
3	Total Panel/Mechanical Labour	New	243.80	115.00
		Gross Labour Cost (S\$)	1,047.71	814.93
	Report v	was unsubmitted during this print-out.		

< END OF ESTIMATES >