

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

AXA - LSUM

TS

VEHICLE NO : SHD 4352S

DATE 11/12/2017

MAKE :

MODEL : HYUNDAI SONATA

11:40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper X repair			\$ 578.40	
	Rear Bumper Clip X			\$ 22.00	
	Rear Bumper Protector (RH) X repair			\$ 38.00	
	Tail Lamp (RH) —			\$ 344.00	
	SUB TOTAL			\$ 982.40	
	LESS 20%			\$ 196.48	
	DISCOUNTED TOTAL			\$ 785.92	
	Rear Bumper Advertisement Logo —			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) —		\$ 100.00	\$ 200.00	Nett
				\$ 250.00	
	Labour Charge				
	Panel Beating			\$ 350.00	200
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 50.00	20
	Remove/Refix Reverse Sensor			\$ 120.00	X
	TOTAL LABOUR			\$ 720.00	
	ESTIMATE TOTAL			\$ 1,755.92	
Ka/lu 10/11/17 13/12/17 1070 km 2 P.A.T.S 45 After Repair photo					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) for resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					