

ASSIGNMENT

ASSIGNMENT

REF CS3/MSG17021046/Wrb-1²²

12/10/17

Surveyor Wilson

ASSIGNMENT (Office)

From (Person)

Katherine Wong

MSIG

Date/Time 14.12.2017

Estimated Cost

OD TP WS TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No

SLP 4394K

Insured

SKT 7543T

at Workshop to

Allswell Motor Traders

Tel: 66791146

of

25 Defu Lane 9, 539266

Policy No

S28969887SMF

Claim No

535069

Sum Insured

Excess

DOA 31/10/2017

Make of Veh

(Client's Record)

CA / REV / REP. REV 24 HRS

'up'

RCD Estimate

Date/Time 2:28pm 3/11/17

Person Contacted

Ben

Vehicle ID DLT

Date/Time

Action/Instruction (X) Estimate

Do Not Finalize

SLP 4394K - X

SKT 7543T - X

Dismantle Part: 06.11.2017

After repair: 14.11.2017

25.11.17 4:58pm Email to Katherine Wong thru Marimen

Submit LE & S, 350/- and 6 days. (Red. 1250/-, 19%)



19/12/2017

RECEIVED 10 DEC 2017

Survey Department Check List (Case Handler)

Reference No. : C83/MSG17021046/Wrb-1
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer				
C	Excess				

Surveyor (Wilson): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No				
C	Regn Month/Year				
N	Vehicle Type				
N	Make & Model				
C	Engine Capacity. (C.C)				
N	Colour				
C	Odometer. (Sp.Reading)				
C	Chassis No				
N	General Condition				
N	Steering				
N	Brake				
N	Modification (Modi)				
C	Tyre Size				
N	Tyre Make				
C	Tyre Balance				
C	Date of Inspection				
N	Survey held				
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Alina 19/12/17
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG17021046/Wrb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 14-12-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 7543T	Veh. Inspected	SLP 4394K	
Policy No.	S28969887SMF	Coverage (\$)	0.00	
Claim No.	535069	Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	14/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/10/2017	Inspection Date	14/12/2017	
Survey held at	25 DEFU LANE 9			
Repairer	ALLSWELL MOTOR TRADERS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017		03 Nov 2017 14:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN GIM CHUAN HENRY, ID: S1556130J		
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD, Co. Reg. No.: 201432541Z		
Vehicle Reg. No.:	SLP4394K	Date of Loss:	31/10/2017 19:00 - :59
Claim Type:	TP / 535069	Policy/Cover Note No.:	S28969887SMF (Comprehensive) Coverage: 23/06/2017 - 22/06/2018
Vehicle Reg. No. (Insured):	SKT7543T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 04/11/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No: 53178015K

Automobile Inspection Report

To: Allswell Leasing & Limousine Pte Ltd 100 Jalan Sultan #02-41 Sultan Plaza Singapore 199001		Date	17/11/2017
		Reference No	CAS/17-11/044
<u>General Information</u>			
Registration No.	SLP 4394K		
Accident Date	31/10/2017		
<u>Particulars of Damaged Vehicle</u>			
Colour	Silver	Make & Model	Honda Grace 1.5 LX
Engine Capacity	1496 cc	Pre-Accident Condition	Good
Mileage (KM)	032645	Engine No.	LEB5259688
Chassis No	GM41109667	Steering	In Order
Registration Date	05/06/2017	Brake	In Order
<u>Tyre Condition</u>			
	Size	Make	Balance
R/H Front Tyre	185/60R15	DUNLOP	90%
L/H Front Tyre	185/60R15	DUNLOP	90%
R/H Rear Tyre	185/60R15	DUNLOP	90%
L/H Rear Tyre	185/60R15	DUNLOP	90%
<u>Inspection</u>			
Repairer	Allswell Motor Traders 25 Defu Lane 9, Singapore 539266		
<u>Adjustment And Recommendation Cost Of Repair</u>			
Repairer's Estimate	S\$10,555.00		
Revised Amount	S\$6,600.00		
Less Excess	:-		
Nett Total	S\$6,600.00		
<u>Remarks</u>			
(A) Survey was done on 03/11/2017			
(B) Re-survey was done on 06/11/2017			
(C) Re-survey after repair was done on 14/11/2017			
(D) The survey was conducted entirely on WITHOUT PREJUDICE basis.			
(E) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Rear bootlid	Dented/Buckled	965.20	965.20
2	1pc	Rear bootlid 'Grace' emblem	Necessary	64.50	64.50
3	1pc	Rear bootlid 'Hybrid' emblem	Necessary	70.60	70.60
4	1pc	Rear bootlid 'logo' emblem	Necessary	54.70	54.70
5	2pcs	Rear bootlid hinge @ \$93.40	Repair	186.80	-
6	1pc	Rear bootlid inner upholstery trim	Serviceable	140.50	-
7	1pc	Rear bootlid mechanism lock	Bent/Jammed	164.40	164.40
8	2pcs	Rear bootlid reflector lamp @ \$353.50	Grazed/Cracked <i>LH RH-NN</i>	707.00	707.00 <i>353.50</i>
9	2pcs	Rear bootlid rubber guide stopper @ \$14.50	Necessary	29.00	29.00 <i>X NN</i>
10	1pc	Rear bootlid weatherstrip	Distorted	187.90	187.90
11	1pc	Rear bumper	Dented/Broken	1,291.00	1,291.00
12	2pcs	Rear bumper inner side shield @ \$126.00	N/S Torn	252.00	126.00
13	2pcs	Rear bumper side retainer @ \$34.90	N/S Broken	69.80	34.90
14	1pc	Rear end panel	Dented/Buckled	819.60	819.60
15	1pc	Rear end panel inner top garnish	Deformed	280.50	280.50
16	1pc	Rear end panel lock striker	Bent	25.00	25.00 <i>X NN</i>
17	1pc	Rear L.H fender	Repair	871.00	-
18	1pc	Rear L.H fender inner air vent	Twisted/Broken	56.70	56.70
19	1pc	Rear L.H fender inner upholstery trim	Distorted	312.00	312.00
20	2pcs	Rear taillamp inner panel @ \$105.50	N/S Dented	211.00	105.50
21	2pcs	Rear taillamp @ \$442.00	Grazed/Cracked <i>LH RH-NN</i>	884.00	884.00 <i>442</i>
22	1pc	Rear windscreen moulding	Not Necessary	55.00	-
23	1pc	Rear foam tool tray	Broken	334.10	334.10 <i>X NN</i>
24	1pc	Spare tyre L.H side panel	Dented/Buckled	161.90	161.90 <i>X R</i>
25	1pc	Spare tyre panel inner top cardboard	Dented/Deformed	270.80	270.80
Less 20%				8,465.00	6,945.30
Sub total				(1,693.00)	(1,389.06)
				6,772.00	5,556.24
<u>PARTS REPLACEMENT SPECIAL NETT ITEMS</u>					
1	1set	Rear bootlid inner upholstery trim clip	Necessary	36.00	36.00 <i>20</i>
2	1set	Rear bumper clip	Necessary	55.00	55.00 <i>30</i>

Constant Appraiser Services

Vehicle No : SLP 4393K

Our ref : CAS/17-11/044

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT SPECIAL</u>						
<u>NETT ITEMS (CONT'D)</u>						
3	1set	Rear humpet reverse sensor	Damaged	280.00	220.00	200
4	1set	Rear LII fender inner upholstery trim clip	Necessary	38.00	38.00	25
5	1pc	Rear windscreen sealant	Not Necessary	100.00	-	
6	1set	Rear bumper inner side shield clip LII	Necessary	52.00	52.00	30
7	1set	Rear end panel inner top garnish clip	Necessary	32.00	32.00	20
Sub total				7,365.00	5,989.24	
<u>LABOUR & MISC. CHARGES</u>						
1		Labour to repair & replace damaged parts		1,200.00	900.00	800
2		Spray painting on affected area		1,300.00	1,000.00	900
3		Remove & refix rear windscreen glass	Not Necessary	140.00	-	
4		Remove & refix rear trim board & garnish		120.00	80.00	60
5		Remove & refix rear seat & carpet		120.00	100.00	X
6		Check wiring system		80.00	40.00	30
7		Remove & renew reverse sensor		80.00	60.00	50
8		Spray anti rust on affected area		150.00	90.00	60
Grand total				10,555.00	8,259.24	
Recommended cost of lump sum repair (To its pre-accident condition)					6,600.00	

6 days

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$6,600.00 on a contractual basis. Under normal circumstances, the repair period would be about 9 (Nine) working days.

Yours faithfully,

Constant Appraiser Services

Lim Yohg Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

02 NOV 2017

535069

MAMT17144415 / Allswell Motor Traders - HO
ENTRY DATE & TIME: 01/11/2017 14:41

TP GIA Report

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 01/11/2017 14:41
 Date Of Accident 31/10/2017 19:50
 Exact Location Of Accident NEW UPPER CHANGI ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLP4394K
 Insured/Policyholder
 Name Of Registered Owner ALLSWELL LEASING & LIMOUSINE PTE.LTD.
 Co Reg No 201432541Z
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-64625405
 Vehicle Particulars
 Manufacturer HONDA
 Model GRACE-1.5 HYBRID DX CVT ABS D/AIRBAG (A)
 Exact Purpose for which vehicle was being used at time of accident PHV GRAB
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE HIRE
 Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy YES
 Policy Number 5087620250
 Cover Note Number
 Driver
 Name of Driver TAN HOCK CHYE
 NRIC No S18217720
 Date Of Birth 18/03/1967
 Occupation OUTDOOR
 Date Of Driving Pass 23/07/1988
 Driving Experience 29 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-87427752
 Fax Number
 Contact Number
 Email Address NOEMAIL

02 NOV 2017

Address BLK 218, PASIR RIS STREET 21, #02-158.
 Postcode 510218
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER & LEASEE
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] REPORT NO: T/20171101/2041
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

accident happened along new upper changi road at 19:48hr on 31/10/2017 involving SLB506E (front car), SLP4394K (middle car) and SKT7543T (rear car). While travelling along new upper changi road in heavy traffic, I was in a middle lane of a 3 lane road. (left side is bus lane). Front car SLB506E jammed brake and I followed as well and managed to stop my car in time. However, vehicle SKT7543T who was driving on the bus lane filtered out to the middle lane and crashed into the left hand rear of my car causing my car to jerk forward hitting SLB506E. I sustained minor injury and have seen a doctor...

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKT7543T
 Vehicle Make/Model/Colour NISSAN SELPHY
 Details Of Properties
 Name of Driver HENRY TAN GIM CHUAN
 NRIC/Passport Number S1556130J
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)
 Details of Witness
 Name
 Phone Number

02 NOV 2017

Email Address

02 NOV 2017

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIX Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and in copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form, and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Attorney General of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary medical costs relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external issues of statistics/mail packages); and/or
 - (v) complying with applicable law in connection with, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be acted outside of Singapore, for one or more of the above purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud prevention, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date: 02/11/2017




Driver's Signature
(Driver must be present at the time of signing)
Date: 02/11/2017

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Sketch Plan Pg. 2

NEW UPPER CHANGI ROAD



A = SLB506E

B = SLP4394K

C = SKT7543T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ACCIDENT HAPPENED ALONG NEW UPPER CHANGI ROAD AT 19:48 HR ON 31/10/2017 INVOLVING SLB506E (FRONT CAR), SLP4394K (MIDDLE CAR) AND SKT7543T (REAR CAR) (VIDEO EVIDENCE AVAILABLE)

While travelling along New Upper Changi Rd, in heavy traffic I was in the middle lane of a 3 lane road (left lane is bus lane). Front car SLB506E jammed brake and I followed as well and managed to stop my car. However, vehicle SKT7543T who was driving on the bus lane fitted out to the middle lane and crashed into the left hand rear of my car, causing my car to jerk forward to hit SLB506E (Photos and Videos have been ~~given~~ provided).

I sustained minor injury and have seen doctor.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Beli
Policeholder's Signature
Date & Time:



Kang
Driver's Signature
(If driver is not the policeholder)
Date & Time:

Beli
Reporting Centre Personnel's Signature
Name:
NAIC/TIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017		03 Nov 2017 14:09 Edit Adj Rpt	S\$5,350.00 Edit Estimates	S\$5,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN GIM CHUAN HENRY, ID: S1556130J		
Main Claimant:	ALLSWELL LEASING & LIMOUSINE PTE LTD, Co. Reg. No.: 201432541Z		
Vehicle Reg. No.:	SLP4394K	Date of Loss:	31/10/2017 19:00 - :59
Claim Type:	TP / 535069	Policy/Cover Note No.:	S28969887SMF (Comprehensive) Coverage: 23/06/2017 - 22/06/2018
Vehicle Reg. No. (Insured):	SKT7543T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 04/11/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

*SLP4394K (535069)
[SKT7543T]

TP

ALLSWELL LEASING & LIMOUSINE PTE LTD

Oct 31 2017 7:00PM

[TAN GIM CHUAN HENRY]

Allswell Motor Traders

Upload Documents Upload Photos Compose New Letter			View Use Viewer	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 12:13	Odometer Reading	Load JPG	☒
2	12/12/17 12:13	General View	Load JPG	☒
3	12/12/17 12:13	General View	Load JPG	☒
4	12/12/17 12:13	Chassis Number	Load JPG	☒
5	12/12/17 12:13	General View	Load JPG	☒
6	12/12/17 12:13	General View	Load JPG	☒
7	12/12/17 12:13	General View	Load JPG	☒
8	12/12/17 12:13	General View	Load JPG	☒
9	12/12/17 12:13	General View	Load JPG	☒
10	12/12/17 12:13	General View	Load JPG	☒
11	12/12/17 12:13	General View	Load JPG	☒
12	12/12/17 12:13	General View	Load JPG	☒
13	12/12/17 12:13	General View	Load JPG	☒
14	12/12/17 12:13	General View	Load JPG	☒
15	12/12/17 12:13	General View	Load JPG	☒
16	12/12/17 12:13	General View	Load JPG	☒
17	12/12/17 12:13	General View	Load JPG	☒
18	12/12/17 12:13	General View	Load JPG	☒
19	12/12/17 12:13	General View	Load JPG	☒
20	12/12/17 12:13	General View	Load JPG	☒
21	12/12/17 12:13	General View	Load JPG	☒
22	12/12/17 12:13	General View	Load JPG	☒
23	12/12/17 12:13	General View	Load JPG	☒
24	12/12/17 12:13	General View	Load JPG	☒
25	12/12/17 12:13	General View	Load JPG	☒
26	12/12/17 12:13	General View	Load JPG	☒
27	12/12/17 12:13	General View	Load JPG	☒
28	12/12/17 12:13	General View	Load JPG	☒
29	12/12/17 12:13	General View	Load JPG	☒
30	12/12/17 12:13	General View	Load JPG	☒
31	12/12/17 12:13	General View	Load JPG	☒
32	12/12/17 12:13	General View	Load JPG	☒
33	12/12/17 12:13	General View	Load JPG	☒
34	12/12/17 12:13	General View	Load JPG	☒
35	12/12/17 12:13	General View	Load JPG	☒
36	12/12/17 12:13	General View	Load JPG	☒
37	12/12/17 12:13	General View	Load JPG	☒
38	12/12/17 12:13	General View	Load JPG	☒

39	12/12/17 12:13	General View		Load JPG	☒
40	12/12/17 12:13	General View		Load JPG	☒
41	12/12/17 12:13	General View		Load JPG	☒
42	12/12/17 12:13	General View		Load JPG	☒
43	12/12/17 12:13	General View		Load JPG	☒
44	12/12/17 12:13	General View		Load JPG	☒
45	12/12/17 12:13	General View		Load JPG	☒
46	12/12/17 12:13	General View		Load JPG	☒
47	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
48	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
49	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
50	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
51	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
52	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
53	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
54	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
55	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
56	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
57	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
58	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
59	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
60	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
61	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
62	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
63	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
64	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
65	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
66	12/12/17 12:13	Photographs of Damaged Parts		Load JPG	☒
67	12/12/17 12:13	Photo After Spray		Load JPG	☒
68	12/12/17 12:13	Photo After Spray		Load JPG	☒
69	12/12/17 12:13	Photo After Spray		Load JPG	☒
70	12/12/17 12:13	Photo After Spray		Load JPG	☒
71	12/12/17 12:13	Photo After Spray		Load JPG	☒
72	12/12/17 12:13	Photo After Spray		Load JPG	☒
73	12/12/17 12:13	Photo After Spray		Load JPG	☒
74	12/12/17 12:13	Photo After Spray		Load JPG	☒
75	12/12/17 12:13	Photo After Spray		Load JPG	☒
76	12/12/17 12:13	Photo After Spray		Load JPG	☒
77	12/12/17 12:13	Photo After Spray		Load JPG	☒
78	12/12/17 12:13	Photo After Spray		Load JPG	☒
79	12/12/17 12:13	Photo After Spray		Load JPG	☒
80	12/12/17 12:13	Photo After Spray		Load JPG	☒
81	12/12/17 12:13	Photo After Spray		Load JPG	☒
82	12/12/17 12:13	Photo After Spray		Load JPG	☒
83	12/12/17 12:13	Photo After Spray		Load JPG	☒
84	12/12/17 12:13	Photo After Spray		Load JPG	☒
85	12/12/17 12:13	Photo After Spray		Load JPG	☒
86	12/12/17 12:13	Photo After Spray		Load JPG	☒
87	12/12/17 12:13	Photo After Spray		Load JPG	☒
88	12/12/17 12:13	Photo After Spray		Load JPG	☒
89	12/12/17 12:13	Photo After Spray		Load JPG	☒

90	12/12/17 12:13	Photo After Spray		Load JPG	☒
91	12/12/17 12:13	Photo After Spray		Load JPG	☒
92	12/12/17 12:13	Photo After Spray		Load JPG	☒
93	12/12/17 12:13	Photo After Spray		Load JPG	☒
94	12/12/17 12:13	Photo After Spray		Load JPG	☒
95	12/12/17 12:13	Photo After Spray		Load JPG	☒
96	12/12/17 12:13	Photo After Spray		Load JPG	☒
97	12/12/17 12:13	Photo After Spray		Load JPG	☒
98	12/12/17 12:13	Photo After Spray		Load JPG	☒
Documentation					
			1 per page		☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/11/17 14:29	Fax From Third Party		Load PDF	
2	02/11/17 14:29	OI GIA Rep - SKT7543T		Load PDF	
3	02/11/17 14:29	TP GIA Rep - SLP4394K		Load PDF	
4	23/11/17 08:53	OI police report From:TP BI - Reg. No: SLP4394K, Claimant: Tan Hock Chye		Load PDF	
5	24/11/17 17:11	Survey report		Load PDF	
6	24/11/17 17:13	Survey Photot		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/12/17 09:53	Invoice		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17021046/WRBE2-1
 Date: 20/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	S28969887SMF
Claimant Vehicle No :	SLP4394K	Insured Vehicle No :	SKT7543T
Date of Loss:	31/10/2017	Nature of Claim:	TP
			Claim No: 535069

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP4394K		
Make & Model:	HONDA GRACE, 1.5 HYBRID DX CVT ABS D/AIRBAG (A)	Engine No:	LEB5259688
Reg. Date:	05/06/2017 (Man. Year: 2017)	Chassis No:	GM41109667
Colour:	Silver	Odometer:	32645 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,365.00	4,804.84	2,560.16	34.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	1,900.00	1,290.00	40.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,555.00	6,704.84	3,850.16	36.48
Approved Total (Overridden) (S\$)		5,350.00		
(S\$)	10,555.00	5,350.00	5,205.00	49.31
+ GST 7.00/7.00% (S\$)	738.85	374.50	364.35	49.31
Nett Amount (S\$)	11,293.85	5,724.50	5,569.35	49.31

INSPECTION

Date of Assignment:	03/11/2017		
Date Inspected:	03/11/2017	Inspected At:	Allswell Motor Traders (HQ) 25 Defu Lane 9 Singapore 539266

Estimated Period of Repair: 6.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2017)
Parts:	192	HONDA GRACE 1.5 HYBRID DX CVT ABS D/AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP4394K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented / Buckled	965.20 FL	*965.20 FL
2	1		*REAR BOOTLID GRACE EMBLEM	Necessary	64.50 FL	*64.50 FL
3	1		*REAR BOOTLID HYBRID EMBLEM	Necessary	70.60 FL	*70.60 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	54.70 FL	*54.70 FL
5	2		*REAR BOOTLID HINGE	Repair	186.80 FL	*- FL
6	1		*REAR BOOTLID INNER UPHOLSTERY TRIM	Serviceable	140.50 FL	*- FL
7	1		*REAR BOOTLID MECHANISM LOCK	Bent / Jammed	164.40 FL	*164.40 FL
8	1		*REAR BOOTLID REFLECTOR LAMP	N/S Grazed/Cracked	707.00 FL	*353.50 FL
9	2		*REAR BOOTLID RUBBER GUIDE STOPPER	Not Necessary	29.00 FL	*- FL
10	1		*REAR BOOTLID WEATHERSTRIP	Distorted	187.90 FL	*187.90 FL
11	1		*REAR BUMPER	Dented / Broken	1,291.00 FL	*1,291.00 FL
12	1		*REAR BUMPER INNER SIDE SHIELD	N/S Torn	252.00 FL	*126.00 FL
13	1		*REAR BUMPER SIDE RETAINER	N/S Broken	69.80 FL	*34.90 FL
14	1		*REAR END PANEL	Dented / Buckled	819.60 FL	*819.60 FL
15	1		*REAR END PANEL INNER TOP GARNISH	Deformed	280.50 FL	*280.50 FL
16	1		*REAR END PANEL LOCK STRIKER	Not Necessary	25.00 FL	*- FL
17	1		*REAR LH FENDER	Repair	871.00 FL	*- FL
18	1		*REAR LH FENDER INNER AIR VENT	Twisted / Broken	56.70 FL	*56.70 FL
19	1		*REAR LH FENDER INNER UPHOLSTERY TRIM	Distorted	312.00 FL	*312.00 FL
20	1		*REAR TAILLAMP INNER PANEL	N/S Dented	211.00 FL	*105.50 FL
21	1		*REAR TAILLAMP	N/S Grazed / Cracked	884.00 FL	*442.00 FL
22	1		*REAR WINDSCREEN MOULDING	Not Necessary	55.00 FL	*- FL
23	1		*SPARE TYRE LH SIDE PANEL	Repair	161.90 FL	*- FL
24	1		*SPARE TYRE PANEL INNER TOP CARDBOARD	Dented / Deformed	270.80 FL	*270.80 FL
25	1		*SET REAR BOOTLID INNER UPHOLSTERY TRIM CLIP	Necessary	36.00 FS	*20.00 FS
26	1		*SET REAR BUMPER CLIP	Necessary	55.00 FS	*30.00 FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
28	1		*SET REAR LH FENDER INNER UPHOLSTERY TRIM CLIP	Necessary	38.00 FS	*25.00 FS
29	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*SET REAR BUMPER INNER SIDE SHIELD CLIP LH	Necessary	52.00 FS	*30.00 FS
31	1		*SET REAR END PANEL INNER TOP GARNISH CLIP	Necessary	32.00 FS	*20.00 FS
32	1		*REAR FOAM TOOL TRAY	Not Necessary	334.10 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **9,058.00** **5,924.80**
 - List Item Discount on L Items 20.00/20.00% (\$\$) **1,693.00** **1,119.96**

Total Parts (\$\$) **7,365.00** **4,804.84**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REPAIR & REPLACE DAMAGED PARTS	New	1,200.00	800.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,300.00	900.00
3	REMOVE & REFIX REAR WINDSCREEN GLASS	New	140.00	0.00
4	REMOVE & REFIX REAR TRIM BOARD & GARNISH	New	120.00	60.00
5	REMOVE & REFIX REAR SEAT & CARPET	New	120.00	0.00
6	CHECK WIRING SYSTEM	New	80.00	30.00
7	REMOVE & RENEW REVERSE SENSOR	New	80.00	50.00
8	SPRAY ANTTI RUST ON AFFECTED AREA	New	150.00	60.00
Gross Labour Cost (S\$)			3,190.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >