



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3735C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER RE-INFORCEMENT	SERVICEABLE	318.80	-
1	REAR BUMPER UNDER COVER	CUT	552.60	552.30
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-270.40	-
	LESS 25% DISCOUNT		-	-143.57
			1,081.60	430.73
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
			135.70	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	200.00
	SPRAY PAINTING CHARGE.		200.00	180.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
			770.00	380.00
GRAND TOTAL			1,987.30	810.73

RECOMMENDED COST OF REPAIRS				810.73
------------------------------------	--	--	--	---------------

Report Ref No. CC3/EQ117023744/K1ea3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.