Estimate Repair List

Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

13 December 2017

HHTPClaims17-107

Type of Claim: Third Party

1,134.20

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #09-16 AIG Building Singapore 079120

ACCIDENT INVOLVING SLD 7134 M & SKL 2222 U ON 10/12/2017 ALONG TUAS SECONDLINK AT ABOUT 1600 HOURS

Insured

KOH BOON KEING

Vehicle Registration No

SLD 7134 M

Vehicle Make

TOYOTA

Vehicle Model

ALPHARD

Vehicle Chassis No

JTEGD21H208216948

Policy No

5095366774

Date of Accident

10/12/2017

			Amount S\$	
To dismantle & repair front bumper and front LH fender.		\$	500.00	700
To perform wire checking.		\$	20.00	\checkmark
To dismantle & refit front bumper sensor.		\$	40.00	30
To spray front bumper and front LH fender.	7% GST	\$ \$ \$	500.00 1,060.00 74.20	400 .

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.
15/12/2017.
- Part by part repair.
- Photo before & after paint.

Authorised by Claims Dept Mrs Tan @ 9639 9195

Total