

ASS. REC. BY:

REF: CS/FCI17023765/Kgd3

Surveyor:
AWS

ASSIGNMENT (Office)

From (Person): Sifheera

of FCI

Date/Time: 3:04pm @ 14/12/17

Estimated Cost: Bill to: OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5403C

Insured: SHB 35522

at Workshop m/s: Trans - Cab

Tel: 6287 6666

of No. 2 AMK Strt 63

Claim No: D17011515MFSH

Policy No: D-18077907MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 12/12/17

CA / REV / REP. / REV 24 HRS (up)

15/12/17

Date/Time: 3:20pm @ 14/12/17

Person Contacted: jiong how

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	D.O.A.
	SHC 5403C - NA/MSG16011731/h4	D.O.A: 23/06/2016
18/12/17 @	SHB 35522 - cc3 / AIG17001183 / H7eq3q2	D.O.A: 16/01/2017
	4.36pm Revised to Sifheera by email.	

ASSIGNMENT

From: _____ Date: 15/12/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 5403C

at Workshop m/s Trans-Cab

of No. 2 AMK Street 63

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 5403C Yr Regn: 11 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Perash Latitude cc 1995

Colour: White / Red A/C Insured / Std / NI / NA

Sp Reading: 262874 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIE/ABL 15AUC 2795P3

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Falken 215/60R16

R: King Kong

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal: 7 mm

R/Bal: 8 mm

L/Bal: 7 mm

L/Bal: 8 mm

D.O.A: 12/10/17

D.O.I: 15/12/17

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/12 File pass to Catherine.

4 11 Day @ 9300 (Rate \$ 33467.00, 78%)

RECEIVED 12 DEC 2017

Date/Time File Pass to?

18/12/17

Prel. Report

Final Report

Date/Time File Return to?

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee

Transportation

Photo

Draw

OTR

19/12/17

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format: TP

Lump Sum / I.B.K. / \$ 9300

32x15-480

170 + 480

50

21

721



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023765/Kqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3552Z	Veh. Inspected	SHC 5403C
Policy No.		Coverage (\$)	0.00
Claim No.	D17011515MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	14/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/12/2017	Inspection Date	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	14-12-2017	Our Ref No. D17011515MFSH
Accident Date	12-12-2017	Claim Type. Third Party
Insured Vehicle	SHB3552Z	Third Party Vehicle. SHC5403C
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	JIONG HOW NG	
Contact No.	62876666/ 0	Fax No. 62877764
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231895)



PRI Documents



Close



PRI Header Details

Claim No	D17011515MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & TRANS-CA
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : JIONG HOW NG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62877764 EmailId: JIONGHOW.NG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3552Z	TP Vehicle No	SHC5403C
PRI Recieved Date	14-12-2017 05:15:27 PM	Surveyor Appointed Date	14-12-2017 03:03:26 PM	Surveyor Accept Date	14-12-2017 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	14-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 18 December, 2017 4:36 PM
To: 'Claim Workflow System'; assignments
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011515MFSH/1
Attachments: CSFCI17023765Kqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SHC 5403C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 December, 2017 3:22 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011515MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 14 December, 2017 3:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011515MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011515MFSH

Date: 18 December 2017

Our Ref: CS/FCI17023765/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5403C

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/12/2017 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>42,767.07</u>
Revised Estimate Amount	: S\$ <u>9,300.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	3878K
Vehicle Details	
Vehicle No.	SHC5403C
Vehicle to be Exported	Yes
Intended De-registration Date	14 Dec 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2014
Engine No.	M9R8839C002012
Chassis No.	VF1ABL15AUC279593
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	04 Nov 2014
First Registration Date	04 Nov 2014
Transfer Count	0
Actual ARF Paid	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 Nov 2022
PARF Rebate Amount	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date	03 Nov 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$51,337.00
COE Rebate Amount	\$31,362.00
Total Rebate Amount	\$40,735.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Dec 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2017 10:17
Date Of Accident	12/12/2017 17:25
Exact Location Of Accident	AIRPORT BLVD TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5403C
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	


Driver

Name of Driver	CHAN CHEW CHWEE
NRIC No	S1329913G
Date Of Birth	01/09/1958
Occupation	OUTDOOR
Date Of Driving Pass	08/03/1976
Driving Experience	41 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97368780
Fax Number	
Contact Number	
EMail Address	NOEMAIL

DETAILS OF INJURED PERSON 1

Name CHAN CHEW CHWEE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHC5403C
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

— please refer to G4 report —

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Handwritten Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5403C -

Not Authored

AAD1712-120

11/12/17 893001

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC5403C - JHOW
VF1ABL15AUC279593
RENAULT
LATITUDE
12.12.2017
FCIL

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Pr</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Pr</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>D/S</i> 113.47 ✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$ <i>Sm</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$ <i>Sm</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$ <i>Sm</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$ <i>Sm</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$ <i>CM Pr</i> 44.99 ✓
9	1 BUMPER REFLECTOR LH	\$ <i>Pr</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$ <i>Pr</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>Pr</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>D/S</i> 225.95 ✓
13	1 BOOT REAR	\$ <i>Pr</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$ <i>Sm</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$ <i>D/S Pr</i> 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$ <i>CM</i> 493.35 ✓
17	1 BOOT REFLECTOR LAMP RH	\$ <i>Sm</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$ <i>Pr</i> 225.36 ✓
19	1 BOOT BADGE	\$ <i>Pr</i> 225.36 ✓
20	1 BOOT STRUT LH	\$ <i>Sm</i> 276.08
21	1 BOOT STRUT RH	\$ <i>Sm</i> 276.08
22	1 BOOT HINGE LH	\$ <i>Pr</i> 367.84
23	1 BOOT HINGE RH	\$ <i>Pr</i> 367.84
24	1 BOOT INNER TRIM	\$ <i>Sm</i> 586.45
25	1 BOOT SWITCH	\$ <i>Sm</i> 168.13
26	1 BOOT LOCK	\$ <i>Pr</i> 202.67
27	1 BOOT LOCK CATCH	\$ <i>Pr</i> 74.40
28	2 LICENCE PLATE LAMP	\$ <i>Sm</i> 50.52
29	2 BOOT RUBBER PLUG	\$ <i>Sm</i> 221.81
30	1 FENDER PANEL INNER TRIM REAR LH	\$ <i>Sm</i> 671.45
31	1 FENDER PANEL REAR LH	\$ <i>Pr</i> 3,299.13
32	1 WHEELARCH REAR LH	\$ <i>Sm</i> 543.47
33	1 FENDER PANEL INNER TRIM REAR RH	\$ <i>Sm</i> 671.45
34	1 FENDER PANEL REAR RH	\$ <i>Pr</i> 3,299.13

X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5403C -

AAD1712-120

35	1	WHEELARCH REAR RH	\$	Sn	543.47	X
36	1	TAILLAMP RH	\$	Sn	552.55	X
37	1	TAILLAMP PANEL RH	\$	n	986.70	X
38	1	TAILLAMP LH	\$	n	552.55	✓
39	1	TAILLAMP PANEL LH	\$	n	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	Di	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	n	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	n	7,489.05	X
45	1	EXHAUST CAP REAR	\$	n	230.49	X

TOTAL	\$	<u>35,868.94</u>	35268.92
10%	\$	<u>3,586.89</u>	- 3586.89
	\$	<u>32,282.05</u>	32282.03

Special Nett

1	1SET	PARKING AID	\$	Short	700.00	✓
2	1SET	REAR BUMPER CLIP	\$	n	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	n	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	n	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	n	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	n	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	n	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	n	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	n	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	n	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	n	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	n	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	n	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	n	35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	n	35.00	X
17	1	FENDER INNER TRIM CLIP LH	\$	n	28.00	X
18	1	FENDER INNER TRIM CLIP LH	\$	n	28.00	X
19	1	TAILLAMP CLIP RH	\$	n	5.00	X
20	1	TAILLAMP CLIP LH	\$	n	5.00	✓
21	2	REAR WINDSCREEN SELANT	\$	n	80.00	X
22	1	WINDSCREEN MOULDING	\$	Sn	100.00	X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Sn	100.00	X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5403C -

AAD1712-120

25 1 SPARE TYRE

	\$	<i>330.00 X</i>
TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>8801</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 <i>7001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 } <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 }
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 } <i>601</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 }
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Towing Fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5403C -

AAD1712-120

	TOTAL	\$	8,260.00
(PARTS BY PARTS)	Over All Total	\$	42,767.07
Repair Days			

20 Days

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023765/Kqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3552Z	Veh. Inspected	SHC 5403C
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17011515MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	14/12/2017
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC279593	Colour	WHITE / RED
Odometer	262874	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	7 mm
L/H Front Tyre	215/60 R16	FALKEN	7 mm
R/H Rear Tyre	215/60 R16	LING LONG	8 mm
L/H Rear Tyre	215/60 R16	LING LONG	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/12/2017	Inspection Date	15/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5403C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	CRACKED	44.99	44.99
1	BUMPER REFLECTOR LH	BROKEN	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	DISTORTED	225.95	225.95
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHETSTRIP	DISTORTED / DENTED	323.05	323.05
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CS/FCI17023765/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	DISTORTED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,586.89	-987.75
			32,282.03	8,889.72
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	700.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-

Report Ref No. CS/FC117023765/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SELANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	SERVICEABLE	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	SERVICEABLE	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	930.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	880.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		2,800.00	700.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.)	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI17023765/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.}		170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.}		170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGSM ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			8,260.00	1,820.00
	GRAND TOTAL		42,767.05	11,639.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,300.00

Report Ref No. CS/FCI17023765/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.