

ASS. REC. BY:

REF: CS/FCI 17023789/Rtd302 Special Instruction:

Surveyor
CWS

Rasul

ASSIGNMENT (Office)

From (Person):

Aung Yin Ming

of

FCI

Date/Time:

4:49pm @ 14/12/17

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 8810M

Insured:

SHC 7045P

at Workshop m/s

Performance

Tel:

63190174

of

303 Alexandra Road

Policy No:

Claim No:

D17011458 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

23052018

H.O.D. Endorsement:

Date/Time:

5:35pm @ 14/12/17

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SLD 8810M -x

SHC 7045P - NS / INC 14003659 / Cgbd1

D.O.A.: 21/02/2014

Part by Part \$4547 (led: 4630 est: 50%)

Q&A
P&M

REF:

06533

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 8810M

at Workshop m/s PERFORMANCE

of

Insured:

FCU/MP

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLD 8810M

Yr Regn: 2016 Jun

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W X6

C.C: 2979

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

58436

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA Ku220X00 P55563

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/50R19

R:

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/12/17

D.O.I.

24/05/18

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 27 AUG 2018

Date/Time, File Pass to?

27/8 Typst

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

170
50
50
39

309

Report Format :

Lump Sum / I.B.I: (\$

4547



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-0007198-R

Affiliated to Federation Internationale Des Experts En Auto			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CL			
Insured Veh.	SHC 7045P	Veh. Inspected	810M
Policy No.		Coverage (\$)	0.0
Claim No.	D17011458MFSH	Excess (\$)	0.0
Assign From	CWS (AUNG YIN MIN)	Assign Date	2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	
R/H Front Tyre			
L/H Front Tyre			
R/H Rear Tyre			
L/H Rear Tyre			
4. Description of Damages			
5. General Information			
Accident Date	14/12/2017	Inspection Date	14
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PRE-CHOICE" BASIS B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORIZED			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	12-12-2017	Our Ref No. D17011458MFSH
Accident Date	10-12-2017	Claim Type. Third Party
Insured Vehicle	SHC7045P	Third Party Vehicle. SLD8810M
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231793)



PRI Documents



Close



PRI Header Details

Claim No	D17011458MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PERFORM/
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEN Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7045P	TP Vehicle No	SLD8810M
PRI Recieved Date	12-12-2017 06:36:44 PM	Surveyor Appointed Date	14-12-2017 04:48:13 PM	Surveyor Accept Date	14-12-2017 0.

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-12-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

12 DEC 2017

Estimate No. : b1 45126
Date Estimated : 12/12/2017
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Chen Guoyao, Jeremy
61 Andrews Terrace

Singapore 757415

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD8810M	0P55563	01/06/2016	X6 xDrive35i	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

Spray painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

To replace rear PDC sensor wire harness including reset and checks for proper function.

To remove and install exhaust pipe, heat shield and propeller shaft to facilitate repairs.

Sundries.

VALUE

850 1,700.00

934 1,088.00

150 177.00

Xm 239? 266.00

Xm 451? 531.00

80? 150.00

Total Labour 1: 3,862.00

DESCRIPTION

Tailpipe tip chrome
RR BUMPER RH MOUNT
REAR BOTTOM COVER
REAR BUMPER CARRIER
RR BUMPER RH CORNER MOUNT
RR BUMPER CENTRE MOUNT
REAR BUMPER TRIM PANEL
REAR BUMPER CLADDING (PDC)
Trim panel, bumper
RH REAR FOG LIGHT/REFLECTOR
ULTRASONIC SENSOR BLACK
DECOUPING RING PDC TORQUE CONVERTER

QTY PRIC

1	128.40
1	197.45
1	186.65
1	766.50
1	141.65
1	197.45
1	1,401.45
1	367.90
1	404.95
1	83.55
4	242.65
4	4.95

VALUE

52 128.40

CM 197.45

186.65

766.50

141.65

197.45

436.50 1,401.45

377.10 367.90

SVC 404.95

CM 83.55

Xm 970.60

Xm 19.80

Total Parts : 4,866.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45126
Date Estimated : 12/12/2017
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD8810M	OP55563	01/06/2016	X6 xDrive35i	0

Claims OD / 2nd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 24/05/18 @ 1735 Excess S\$ _____

Surveyor's Name RAKUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	3,862.00
Parts	:	4,866.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	610.98
Grand Total	:	<u>9,339.33</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45126
Date Estimated : 12/12/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chen Guoyao, Jeremy
61 Andrews Terrace

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 757415

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLD8810M	0P55563	01/06/2016	X6 xDrive35i	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident		850.00		850.00
To spray paint rear bumper		934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.		150.00		150.00
Sundries.		80.00		80.00

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	2.95	15.00		44.25
REAR BOTTOM COVER	186.65	1.00		186.65
REAR BUMPER TRIM PANEL	1,436.50	1.00		1,436.50
REAR BUMPER CLADDING (PDC)	377.10	1.00		377.10
# REAR BUMPER BOTTOM TRIM PANEL (V6) *	404.95	1.00		404.95
RH REAR FOG LIGHT/REFLECTOR	83.55	1.00		83.55

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	2,533.00
Total Labour & Parts :	4,547.00
Deduction for Excess :	
Total Repair Costs less Excess:	4,547.00
GST @7%:	318.29
Grand Total :	4,865.29

9177.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45126
Date Estimated : 12/12/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Chen Guoyao, Jeremy
61 Andrews Terrace

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 757415

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLD8810M	OP55563	01/06/2016	X6 xDrive35i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	2.95	15.00		44.25
# REAR BUMPER BOTTOM TRIM PANEL (V6) *	404.95	1.00		404.95

Total Labour :	
Total Parts :	449.20
Total Labour & Parts :	449.20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023789/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7045P	Veh. Inspected	SLD 8810M	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011458MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	14/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	BMW X6	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBAKU220X00P55563	Colour	WHITE	
Odometer	58436	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/50 R19	GOODYEAR	6 mm	
L/H Front Tyre	255/50 R19	GOODYEAR	6 mm	
R/H Rear Tyre	255/50 R19	GOODYEAR	6 mm	
L/H Rear Tyre	255/50 R19	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/12/2017	Inspection Date	24/05/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 8810M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILPIPE PIPE CHROME (SN)	SERVICEABLE	128.40	-
1	RR BUMPER RH MOUNT (SN)	SERVICEABLE	197.45	-
1	REAR BOTTOM COVER (SN)	CRACKED	186.65	186.65
1	REAR BUMPER CARRIER (SN)	SERVICEABLE	766.50	-
1	RR BUMPER RH CORNER MOUNT (SN)	SERVICEABLE	141.65	-
1	RR BUMPER CENTRE MOUNT (SN)	SERVICEABLE	197.45	-
1	REAR BUMPER TRIM PANEL (SN)	DEFORMED	1,436.50	1,436.50
1	REAR BUMPER CLADDING (PDC)(SN)	CRACKED	377.10	377.10
1	TRIM PANEL BUMPER (SN)	SERVICEABLE	404.95	-
1	RH REAR FOG LIGHT/REFLECTOR (SN)	CRACKED	83.55	83.55
4	ULTRASONIC SENSOR BLACK (SN)	SERVICEABLE	970.60	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	SERVICEABLE	19.80	-
15	BLIND RIVET (SN)(ADDITIONAL)	NECESSARY	44.25	44.25
1	REAR BUMPER BOTTOM TRIM PANEL (V6) (SN) (ADDITIONAL)	CUT	404.95	404.95
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
			5,509.80	2,613.00
LABOUR				
REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT.			1,700.00	850.00
SPRAY PAINTING REAR BUMPER.			1,038.00	934.00
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.			177.00	150.00
TO REPLACE REAR PDC SENSOR WIRE HARNESS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION.		NOT NECESSARY	266.00	-
TO REMOVE AND INSTALL EXHAUST PIPE,HEAT SHIELD AND PROPELLER SHAFT TO FACILITATE REPAIRS.		NOT NECESSARY	531.00	-
			3,712.00	1,934.00
GRAND TOTAL			9,221.80	4,547.00
RECOMMENDED COST OF REPAIRS				4,547.00

Report Ref No. CS/FCI17023789/R1td3n2



Report Ref No. CS/FCI17023789/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.