

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5135A
Ref. No : BUS/09/17/5015
Reg. Date : 07/09/2016
Vehicle Type : DOUBLE DECK
Make : VOLVO
Model : Volvo B9TL DD
Name of Driver : Chen Han Chong
Type of Accident : HEAD TO REAR
Date / Time of Accident : 15/09/2017 09:50:00 AM
Accident Reported Date / Time : 15/09/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093821
Special Instruction to ARC, if any :
SG5135A - FRONT LEFT HEADLIGHT BROKEN
XD5018L (TP) - TP INSURED WITH NTUC
Prepared Date : 20/09/2017 09:24:06 AM

