

ASS. REC. BY:

REF: CS/FCI 17024000 /R1qd3n2

Special Instruction:

Surveyor:

Raul

ASSIGNMENT (Office)

CWS

From (Person):

Aung Yin Ming

of

FCI

Date/Time: 2:54pm @ 19/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFG 196K

Insured:

SHC 7595T

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

015072707MFSH

Claim No:

D17011625 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'DS'

21/12/17

H.O.D. Endorsement:

Date/Time:

2:54pm @ 19/12/17

Person Contacted:

Caroline

Vehicle IN OUT

Date/Time	Action/Instruction	Estimate
	SFG 196K ✓	
	SHC 7595T ✓	
21/12/17 @ 4:30pm	revised to Aung Yin Ming by email.	
25/1/18 @ 12:12pm	Confirmed with Caroline final fig \$5175.85, 5 days.	
	(Red \$ 10073.75, 66%).	

Barrow *Person*

REF: **PCI**

53063

ASSIGNMENT

From: _____ Date: **21/12/17**

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: **SFG 196K**

at Workshop m/s: **Performance**
of **303 Alexandra Road**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **wp**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SFG 196K** Yr Regn: **2010 P603**

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: **B.M.W 318i 2-OL** c.o. **1995**

Colour: **BLACK** A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: **039102** T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: **WDAPF 72000A 793505**

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: **NII** / ☒ STD A/Rim / ☐ or

Tyre Size: F: **205/55R16**
R: _____

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
☐ TOYO / ☐ YOKO or

Front

R/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **15/12/17**

Survey held at **PERFORMANCE**

Des. of Damages: Frt ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Rear

R/Bal. **6** mm

L/Bal. **6** mm

D.O.I. **21/12/17**

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 JAN 2018

Date/Time. File Pass to?

1) **23/1/18**

Date/Time. File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation

☐ S - RS ☐ SI

Photos **OSP**

Others **26/1/18**

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: **TP**

Lump Sum / I.B.I: (\$ **5125.85**)

5x15 = 75

170+75

50

50

57

402



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FC117024000/R1qd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7595T	Veh. Inspected	SFG 196K
Policy No.		Coverage (\$)	0.00
Claim No.	D17011625MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/12/2017	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

Remarks

5a.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011625MFSH

Date: 27th December 2017

Our Ref: CS/FCI17024000/R1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFG 196K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/12/2017 at the premises of M/s PERFORMANCE MOTORS LIMITED. and have the following to report:-

Workshop Estimate Amount	: S\$ 15,149.60 .
Revised Estimate Amount	: S\$ 4,783.30 .
"Check" Items Amount	: S\$ 2,562.60 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Mohd Rasul
Automotive Assessor

Survey Department Check List (Case Handler)

Reference No. : CG/KU/702400/1919d3
Policy Type: OD / TP / RES / TL / EVA

SFG 196K

Case Handler

Typist

Admin (Nivitha): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Ravi): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓		
---	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓		
✓		
✓		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓		
---	--	--

Check By:

Ch 25/1/18
Case Handler Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	18-12-2017	Our Ref No. D17011625MFSH
Accident Date	15-12-2017	Claim Type. Third Party
Insured Vehicle	SHC7595T	Third Party Vehicle. SFG196K
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232063)



PRI Documents



Close X

PRI Header Details

Claim No	D17011625MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PERFORM/
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEN Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7595T	TP Vehicle No	SFG196K
PRI Recieved Date	18-12-2017 08:38:59 PM	Surveyor Appointed Date	19-12-2017 02:52:57 PM	Surveyor Accept Date	19-12-2017 0.

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 25 January 2018 12:12 PM
To: 'PBSP'; Rasul (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SFG196K

Dear Caroline,

Confirm final fig \$5,125.85 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Friday, 12 January 2018 6:18 PM

To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: FINAL REPORT / SFG196K

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 3,913.00

Total Parts : 1,212.85

Total Labour & Parts : 5,125.85

Repair days: 5

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 27 December, 2017 4:30 PM
To: 'Claim Workflow System'; assignments
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011625MFSH/1
Attachments: CSFCI17024000R1qd3.pdf

Dear Yin Min,

Enclosed herewith preliminary advice of SFG 196K.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: Admin-D (LKKAUTO)
Sent: Tuesday, 19 December, 2017 3:01 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011625MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

 **Vivitha** | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 19 December, 2017 2:53 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; AUNGYINMIN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011625MFSH/1

Dear Sir/Mdm,

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

18 DEC 2017

Estimate No. : b1 45174
Date Estimated : 15/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Tan Lek Hiok Linda
16 Greenwood Lane

Singapore 286944

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFG196K	A793505	05/02/2010	318i/4 (A)	0

DESCRIPTION

VALUE

To replace rear bumper, tail panel and include knocking
cause out by the accident

1700 5,950.00

painting rear bumper, tail panel, left rear fender,
right rear fender, trunk floor

1603 1602 4,082.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To carry out body cavity preservation.
(For cut panel).

X 451? 531.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 X 177.00

Sundries.

150 150.00

Total Labour 1: 11,338.00

DESCRIPTION

QTY PRIC

VALUE

RR RH TRUNK FLOOR
TAIL END PANEL
RR BUMPER CARRIER
RR BUMPER CTR GUIDE
RR BUMPER CTR BOTTOM GUIDE
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER TOW HOOK COVER
RR BUMPER TOW HOOK COVER
RR BUMPER (PDC)
RR TRUNK FLOOR STORAGE TRAY

1 251.40
1 809.40
1 413.90
1 30.85
1 61.20
1 55.65
1 55.65
1 19.30
1 19.30
1 1,082.00
1 68.75

251.40
809.40
413.90
30.85
61.20
55.65
55.65
19.30
19.30
1,082.00
68.75

Performance Motors Limited

A member of the Sime Darby Group
Co., Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190628 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45174
Date Estimated : 15/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFG196K	A793505	05/02/2010	318i/4 (A)	0

DESCRIPTION	QTY	PRIC	VALUE
DECOUPLING RING PDC TORQUE CONVERTE	4	4.95	m 19.80
BUMPER PDC SENSOR (SCHWARZ)- ELBOW	4	231.10	m 924.40
Total Parts :			3,811.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey 5 days

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 21/12/17 @ 1330 Excess S\$ _____
Surveyor's Name Rame Sign _____
Surveyor's Tel 90010068 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend 5 days

Claims OD / 3rd Party / Uninsured losses / Direct Settlement
Regn No. _____ Claim No. _____
Date & Time _____ Excess S\$ _____
Surveyor's Name _____ Sign _____
Surveyor's Tel _____ Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement
Regn No. _____ Claim No. _____
Date & Time _____ Excess S\$ _____
Surveyor's Name _____ Sign _____
Surveyor's Tel _____ Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend _____

Labour 1	:	11,338.00
Parts	:	3,811.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,060.47
Grand Total	:	16,210.07

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45174
Date Estimated : 15/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Tan Lek Hiok Linda
16 Greenwood Lane

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 286944

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SFG196K	A793505	05/02/2010	318i/4 (A)	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# UNDERFLOOR COATING ACTIV.CHARCOAL *	69.65	1.00		69.65 <i>gm</i>

Total Labour :	
Total Parts :	69.65
Total Labour & Parts :	69.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45174
Date Estimated : 15/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Tan Lek Hiok Linda
16 Greenwood Lane

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 286944

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SFG196K	A793505	05/02/2010	318i/4 (A)	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To replace rear bumper and attachments include making good the tail end panel and knocking out dents caused by the accident	1700.00		1,700.00		
To spray paint rear bumper and tail end panel	1603.00		1,603.00		
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00		
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00		
* To remove and install PDC assembly to facilitate repairs include conducting checks for proper function	150.00		150.00		
Sundries.	80.00		80.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER CTR BOTTOM GUIDE	61.20	1.00		61.20
RR BUMPER (PDC)	1,082.00	1.00		1,082.00
# UNDERFLOOR COATING ACTIV.CHARCOAL *	69.65	1.00		69.65 (h)

SUPPLEMENTARY ITEMS

Total Labour :	3,913.00
Total Parts :	1,212.85
Total Labour & Parts :	5,125.85
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,125.85
GST @7%:	358.81
Grand Total :	5,484.66




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024000/R1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7595T	Veh. Inspected	SFG 196K	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011625MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	19/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W 318I 2.0L	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAPF72000A793505	Colour	BLACK	
Odometer	39102	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2017	Inspection Date	21/12/2017	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFG 196K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RR RH TRUNK FLOOR (SN)	SERVICEABLE	251.40	-
1	TAIL END PANEL (SN)	TO REPAIR SEE LABOUR	809.40	-
1	RR BUMPER CARRIER (SN)	SERVICEABLE	413.90	-
1	RR BUMPER CTR GUIDE (SN)	SERVICEABLE	30.85	-
1	RR BUMPER CTR BOTTOM GUIDE (SN)	CRACKED	61.20	61.20
1	RR BUMPER LH GUIDE (SN)	SERVICEABLE	55.65	-
1	RR BUMPER RH GUIDE (SN)	SERVICEABLE	55.65	-
1	RR BUMPER TOW HOOK COVER (SN)	SERVICEABLE	19.30	-
1	RR BUMPER TOW HOOK COVER (SN)	REPEATED	19.30	-
1	RR BUMPER (PDC)(SN)	DEFORMED	1,082.00	1,082.00
1	RR TRUNK FLOOR STORAGE TRAY (SN)	SERVICEABLE	68.75	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	19.80	-
4	BUMPER PDC SENSOR (SCHWARZ)-ELBOW (SN)	NOT NECESSARY	924.40	-
1	UNDERFLOOR COATING ACTIV.CHARCOAL (ADDITIONAL)(SN)	CRACKED	69.65	69.65
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
			4,031.25	1,292.85
	LABOUR			
	TO REPLACE REAR BUMPER, TAIL PANEL AND INCLUDE KNOCKING CAUSED OUT BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF TAIL END PANEL .		5,950.00	1,700.00
	PAINTING REAR BUMPER, TAIL PANEL, LEFT REAR FENDER, RIGHT REAR FENDER, TRUNK FLOOR.		4,082.00	1,603.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL).		531.00	-
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	230.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
			11,188.00	3,833.00
GRAND TOTAL			15,219.25	5,125.85
RECOMMENDED COST OF REPAIRS				5,125.85

Report Ref No. CS/FCI17024000/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.