

### CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
Mr CHEW LOCK PIN	Cust No/Name	KCV06133/Mr Chew Lock Pin		
17 Serangoon Garden Way	Reg No/Reg Date	SLP2379T / 30/05/2017		
Singapore 555928	Date In/Mileage	18/12/2017/ 0		
	Chassis No	JMYXTGF3WHZ002299		
	Engine No	4B12TC2975		
Contact No Mobile:92343874 Mrs CHEW	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)		
	Colour/Trim	D01 / BK		

Account No	Terms	Date/Time Printed	CSE	Operator	- William	WIP No	
CSM00001	Cash	19/12/2017/ 08:29	DS	218 / MarsLer		49267	
		Description of Good	s / Service	es	Qty	Unit Price Disc%	Amount
M SUNDRY	19504					ree	35.0
C & C LO	GO:					,,,	
4 SUNDRY						res	45.0
MIVEC EM						21.1	
MIPNT880	T	CE REAR REVERSE SENS	OD.			Sheb	280.0
MIPNT880		CE KENK KEVEKSE SENS	OUR				20.0
	The state of the s	G & WIRING SYSTEM ON	REAR ACC	TOENT AFFECTED		60	80.0
AREAS			THE THOU	TOTAL PARTE OF THE			
MIPNT880							250.0
		GRAM TAILGATE AUTO F	OLDING SY	STEM			
MIPNT880		AND				7	300.0
		ATE GLASS				244	
MIPNT880		KIT ON TAILGATE GLA				nei	100.0
MIPNT880		KIT ON TAILGATE GLA	22				
		OOL SOLAR FILM ON TA	TIGATE GLA	221		17	220.0
MIPNT8808		32 33200 1 120 00 10	ILONIE GE	100		2 -	1200.0
TO REMOVE	AND RE-	INSTALL TRIMMING AN	D CAPERTIN	NG TO GIVE		300	1200.0
WAY ACCES	SS REPAIR	ON REAR ACCIDENT A					
MIPNT8808						180	600.0
		XHAUST MUFFLER ASSY				100	
MIPNT8808		ATT COMPONENTS				300	600.0
		GATE COMPONENTS & ME	CHANISN			200	22000
		REVERSE CAMERA LENS				150	350.0
MIPNT8808		CIERDE CAPICION ELIIS				2 44	3000.0
TO REPLAC	E TAILGA	TE AND REAR BUMPER,	ETC			2400	3000.0
-CUT AND	RE-WELD	REAR END PANEL					
		, ALIGN ON REAR ACCI	DENT AFFEC	TED AREAS		I COMPANIENCE CONTROL OF THE PARTY OF THE PA	
MIPNT8808						150	300.0
		KIT ON NEW PANEL				100 m	
-TO CONDU	CT WATER	LEAK TEST ON REAR /	ACCIDENT A	FFECTED AREAS 420		1	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
Mr CHEW LOCK PIN	Cust No/Name KCV06133/Mr Chew Lock Pin			
17 Serangoon Garden Way	Reg No/Reg Date SLP2379T / 30/05/2017			
Singapore 555928	Date In/Mileage 18/12/2017/ 0			
	Chassis No JMYXTGF3WHZ002299			
	Engine No 4812TC2975			
Contact No Mobile:92343874 Mrs CHEW	Make/Model MIT/OUTLANDER 2.4 CVT AWD	(E44)		
	Colour/Trim DO1 / BK	1		

	Terms	Date/Time Printed	CSE	Operator	No. 10 Personal Control of the Contr	WIP No	9	
CSM00001	Cash	19/12/2017/ 08:29	DS	218 / MarsLer		49267		
S MIPNT980	00	Description of Good	s / Service	es	Qty	Unit Price	Disc%	Amount
		DEAD ACCIDENT ASSE				,	680	2520.0
M JJ6410D2	THITING ON	REAR ACCIDENT AFFE	CTED AREA	S		,	000	
4 JJ6410D3		FACE, RR BUI	MPER W/FL		1.00	873.00	10.00	785.7
4 JJ6410D3		LH BRACKET,		24-	1.00	11.00	10.00	9.9
JJ6410B8		RH BRACKET,	RR BUMPE	( C )	1.00	11.00	10.00	9.9
1 JJ6512A6		RH REINFORCE	MENT, RR	34 ~	1.00	74.00	10.00	66.6
JJMR3289		INNER CLIP,			1.00	3.00	10.00	2.7
JJMU4880		CLIP, SPLASH		nu -	10.00	3.00	10.00	27.0
JJ6415A0		CLIP, RR BUMF		M	10.00	2.00	10.00	18.0
JJ7407A3		EXTENSION, A		21	1.00	219.00	10.00	197.1
JJ7407A3		LH MOULDING,			1.00	100.00	10.00	90.0
JJ580186		RH MOULDING,	RR BUMP	100	1.00	100.00	10.00	90.0
JJ5808A1:		PANEL ASSY,		DD/184	1.00	924.00	10.00	831.6
JJ5805A3(		LATCH, TAILG			1.00	447.00	10.00	402.3
JJ5805A31		GLASS, TAILGA		n1 X	1.00	708.00	10.00	637.2
JJ5805A31		UPR DAM, TAIL		rec	1.00	12.00	10.00	10.8
JJ5805A31		SIDE DAM, TAI		ne -	2.00	26.00	10.00	46.8
JJMB81444		LWR DAM, TAIL		me -	1.00	39.00	10.00	35.10
JJMR46228		FASTENER, WIN	DSHIELD	nu -	4.00	6.00	10.00	21.60
JJ5802A60		STOPPER, WIND	SHIELD G	nu -	2.00	3.00	10.00	5.40
JJ5802A60		LH GAS SPRIN	G, TAILG	11X	1.00	186.00	10.00	167.40
JJ5815A06		RH GAS SPRIN	G, TAILG	11 X	1.00	186.00	10.00	167.40
JJ8337A13		WEATHERSTRIP	, TAILGA	7n.	1.00	201.00		180.90
JJ8331A18		RH REFLECTOR	, TAIL L	cue _	1.00	94.00		84.60
JJ8330817		RH LAMP ASSY		?	1.00	477.00		429.30
JJMN15984		RHR LAMP ASS	r, COMBI	7	1.00	565.00		508.50
JJ7415A40		MARK, OUTLANDS	nu		1.00	17.00		15.30
JJ8637A17				-47	1.00	90.00		81.00
JJ8637B11		BUZZER, KEYLE		2	1.00	86.00		77.40
JJ5257A87		ANTENNA, KEYL		21,00	1.00	91.00		81.90
JJ1571866		PANEL, RR END	CT MAY!	304500	1.00	235.00		211.50
NOTES		MUFFLER, EXHAU	SI MAIN	n x	1.00	573.00	10.00	515.70

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### **ESTIMATE**

		Owner Name & Vehicle Info
Invoice Name & Address  Mr CHEW LOCK PIN 17 Serangoon Garden Way	Reg No/Reg Date	18/12/2017/
Singapore 555928	Chassis No	JMYXTGF3WHZ002299 4B12TC2975 MIT/OUTLANDER 2.4 CVT AWD (E44)
Contact No Mobile:92343874 Mrs CHEW	Colour/Trim	D01 / BK

Co	ntact No	Hobiterses			Colour/Trim	D01	- /	DK.	
				005	Operator		WIP No		A WAR
Account No	Terms	Date/Time Pr		CSE	218 / MarsLer		49267		
CSM00001	Cash	19/12/2017/	08:29	DS		Qty	Unit Price	Disc%	Amount
		Description	of Goods	2 OF DUNC	GOL & RIVERVALE ROA				
OWNER CL	AIMING 1 REPLACE	Z/ZOT/ ALONG HIRD PARTY MENT CAR TP INS :	EQ	St.	Alk ph. Behu 7 Le 20/. V/	the Repa To resurv To displa Parts pri Third car No illeta Supplert is subject Acknowled Signature Date:	2	wing: ray painting during result confirmation Without Praja allowed	dice" basis red and re Company
Confirm	& accepto	ed by				Specia	ard Menu alist Job s(Lub,etc)		0. 0. 9,800. 0. 80.

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Stimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include a stimated costs quoted are excluding GST. We would mention that the above estimate is payed be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair sor replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the windscreen in the event of inadvertent breakage in the course of renewil cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewil the rubber seal or other repair requiring the removal of the windscreen.

Page 3 of 3