

ASS. PEO. BY:

REF: CS/C T17024014 / Ard3e21 Special Instruction:

SURVIVOR
Mentimen

Adrian

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

18/12/17 @ 6:03pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 4827E

Insured:

at Workshop m/s

Auto N cars

Tel:

6555 2909

of

Blk 1, Kaki Bukit Ave 6 # 01-04 Autobay

Policy No:

DMCVSN1557061601

Claim No:

SNM17D07057C01

Sum Insured:

Excess:

\$ 4,500

Make of Veh:

D.O.A.

2/12/2017

(Client's Record)

CA /

☒ REV

/ REP. / REV 24 HRS

Daria

H.O.D. Endorsement:

Date/Time:

9:43am @ 19/12/17

Person Contacted:

Janyden

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction
	(✓) Estimate
	Economical to Repair Consistency of Damage
	GBE 4827E - X
26/12/17	Sent preli through mentimen ; Repairer agree to repair not more than \$35k (L/s)
	Mandate approve ; Inform Repairer through email & phone
	* Canopy is not coverage in the policy

REF: CT1

ASSIGNMENT

From: _____ Date: 19/12/17
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: GBE 4827E
 at Workshop mis: Auto N Cars
 of BK1, Kaki Bukit Ave 6 #01-04 Autobay
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: \$ 4,500.00
 (Client's Record)
 Make of Veh: _____

Survey Revert Economical to repair consistency of
 (Policy Condition) Damage

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 25 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / ☒ REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBE4827E Yr Regn: 2015 JRC
 Type: M.Car / M.Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Dyna cc 2982
 Colour: Silves. A/O: Insured / Std / NI / NA
 Sp. Reading: / T-Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFAT3SY80K2055US
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modl: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15C Firemax
 R: 155R12C B/S
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 04 mm
 L/Bal. 06 mm L/Bal. 04 mm
 D.O.A. _____ D.O.I. 19/12/17
 Survey held at Auto N Car
 Des. of Damages ☒ Frt ☒ Rear / O/S / N/S / ☒ U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD Chuan.

According to Advise repair days 25

MV : 65K

PV : 263K.

Nett : 387K.

7/1/18 Confirm with data

L/S 32,600.00, 25 days

Red: \$ 30,649.58, 48%.

RECEIVED 7 JAN 2018

Date/Time File Pass to?

☐

Preli. Report

☒

Final Report

Days Of Repair: 25Resurvey No. of Trip: 2

Survey Fee:

220

Transportation:

S-RS \$

Photos

Others

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech. Insp \$☐ Weekend \$Report Format: ODLump Sum / H.B. \$ 32,600.00

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17024014/Ard3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 19-12-2017		
		Code : CTI		
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	GBE 4827E	
	Policy No. DMCVSN1557061601	Coverage (\$)	0.00	
	Claim No. SNM17D07057C01	Excess (\$)	4,500.00	
	Assign From MERIMEN (CHONG BOON SEN)	Assign Date	19/12/2017	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 02/12/2017	Inspection Date	19/12/2017	
	Survey held at AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-04 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.			
5a. Remarks				
	A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Dec 2017 Sendback Est	15 Dec 2017 17:02 S\$63,249.58	18 Dec 2017 18:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TECK WEI LEASING (S) PTE LTD, Co. Reg. No.: 201408056W		
Vehicle Reg. No.:	GBE4827E	Date of Loss:	02/12/2017 06:00 - :59
Claim Type:	OD / SNM17D07057C01	Policy/Cover Note No.:	DMCVSN1557061601 (Comprehensive)
		Excess:	S\$4,500.00
Repairer:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/12/2017]		
Driver/Custodian:	VICTOR SUSAI A/L SUR IMUTHU @ SAVARIMUTHU (30 / Male), NRIC: G8256311W, Tel: +6598304519		
Adj Asg. Remarks:	SURVEY REVERT ECONOMICAL TO REPAIR CONSISTENCY OF DAMAGE		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 20 Dec 2017

Preliminary Advice

Vehicle No	: GBE4827E	Accident Date	: 02/12/2017
Make	: TOYOTA DYNA 150 MANUAL 3SEATER	Policy No.	: DMCVSN1557061601
Assignment Date	: 18/12/2017	Excess	: S\$4,500.00
Date of Inspection	: 19/12/2017	Est. Duration of Repair	: 25.00
Inspection At	: AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and undercarriage portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	63,249.58
Revised Amount	:S\$	27,809.53
Check Items (Estimated)	:S\$	34,735.05
Total	:S\$	62,544.58
Lump Sum Repair (Estimate)	:S\$	35,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	26,238.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,762.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly advice whether the canopy is coverage in the policy.

Volkswagen Centre Singapore

Service Tax Invoice No. SV12P04714



SERVICE ORDER NO: 12IP0098

SERVICE CUSTOMER NO.: CV000052

SERVICE CUSTOMER NAME: HSBC INSURANCE (S) PTE LTD

TELEPHONE NO.:

ADDRESS: 10 Eunos Road 8
#11-01 Singapore Post Centre
Singapore

Biz Reg. No. S3103069E
GST No. M20098505-2

VEH NO.:

SJT6868A

DATE:

01/03/12

VIN NO.:

WVWZZZ1KZ9W547802

GEARBOX CODE:

LQZ

MODEL:

Golf A6 GTI (DSG) 5 Door+4KF.P

SA:

Kong Charmaine

Pickup:

KM : 36,293

Engine No.:

Next Appointment Date :

Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
19	DOOR INSULATOR	1.00	PCS	20.20	28
20	RHR FENDER	1.00	PCS	527.00	14.54
21	WHEEL HOUSING REAR RH	1.00	PCS	122.98	379.44
22	RRH FENDER AIR VENT	1.00	PCS	43.01	88.55
23	REAR BUMPER	1.00	PCS	1,007.00	30.97
24	REAR BUMPER CENTER BRACKET	1.00	PCS	74.00	725.04
25	TAILLAMP BRACKET RH	1.00	PCS	34.18	53.28
26	REAR BUMPER BRACKET RH	1.00	PCS	34.18	24.61
27	REVERSE SENSOR BRACKET	2.00	PCS	9.00	24.61
28	REVERSE SENSOR BRACKET	2.00	PCS	9.00	12.96
29	PARKING SENSOR O RING	2.00	PCS	0.12	12.96
30	SENSOR	2.00	PCS	108.00	0.17
31	TAILLIGHT OUTER RH	1.00	PCS	207.00	155.52
32	DETROIT 18" ALUMINIUM SHINY	1.00	PCS	654.21	149.04
33	RHR WHEEL BEARING	1.00	PCS	370.93	471.03
34	RHR WHEEL BEARING HOUSING	1.00	PCS	537.68	267.07
35	RUBB MOUNT	1.00	PCS	19.29	387.13
36	REAR LOWER SPOILER	1.00	PCS	254.00	13.89
					182.88

20/12/17 the proceed. Celina

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 20 Dec 2017

Preliminary Advice

Vehicle No	: GBE4827E	Accident Date	: 02/12/2017
Make	: TOYOTA DYNA 150 MANUAL 3SEATER	Policy No.	: DMCVSN1557061601
Assignment Date	: 18/12/2017	Excess	: S\$4,500.00
Date of Inspection	: 19/12/2017	Est. Duration of Repair	: 25.00
Inspection At	: AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and undercarriage portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	63,249.58
Revised Amount	:S\$	27,809.53
Check Items (Estimated)	:S\$	34,735.05
Total	:S\$	62,544.58

Lump Sum Repair (Estimated)	:S\$	35,000.00
-----------------------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	26,238.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,762.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly advice whether the canopy is coverage in the policy.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC INSURANCE (SINGAPORE) PL
10 EUNOS ROAD 8,
#11-01 SINGAPORE POST CENTRESINGAPORE
408600
ATTN:LOW YONG YEOW

Ref: CS/HSB12001146/T1vp

Date: 13/03/2012

Code: HSB2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJT 6868A
Policy No. 11552858	Coverage (\$)	0.00
Claim No.	Excess (\$)	2,500.00
Assign From LOW YONG YEOW	Assign Date	17/01/2012

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WWWZZZ1KZ9W547802	Colour	BLUE
Odometer	36296 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/01/2012	Inspection Date	17/01/2012
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197		

5a. Remarks

A)THE MARKET VALUE IS S\$125,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------

Janice Lee (LKKAuto)

From: Darla Balingit <darla@autoncars.com.sg>
Sent: Wednesday, December 20, 2017 4:22 PM
To: Janice Lee (LKKAuto)
Subject: Re: GBE 4827E CHINA OD

Dear janice,

We would like to confirm repair cost at lumpsum \$35k for GBE4827E.

Thank you!

On Wed, Dec 20, 2017 at 2:30 PM, Janice Lee (LKKAuto) <JaniceLee@lkkauto.com> wrote:

Dear Darla,

Kindly advice the repair cost at Lumpsum not more than \$35k.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--

Best Regards,
Darla Balingit
Auto N Cars Services Pte Ltd

m: +65 8499 3326

	Continuation Page 6		
S/No	Description	Raised By	Action By
8.	In the Motor Accident Guide ,we may have cases 60% ,70% instead of 50, 100 which what BOLA will help you all to understands. We will pass around the Motor Accident Guide book. Similar to BOLA , this means for Non GIA. Example : Give me one (1) " NON GIA workshop – : Progressive Workshop @Kaki Bukit is non - authorise "Non- GIA workshop mostly are " crocodile workshop". If any of this workshop claiming against AXA , BOLA don't apply accept for "chain collision case", the repairer to be informed, if claiming against AXA. They may settle at Global sum of 50% or 60%, 70% . Motor Accident Guide is under common law. Alternatively they will pass to lawyer go for CDR – Court Dispute Resolution. Familiarise yourself whose is "authorised" or "not authorised".	Bryan	All Surveyors
9.	Asher mentioned : for our information In " Merimen System" – All AXA cases . AXA will indicate TP repairer is "ARC" or "NON-ARC". Bryan mentioned: "This information should not be relate to our surveyors . We need to inform the repairer whether they get 100% or otherwise." To note : All surveyor moving forward to inform workshop whether to follow BOLA or MAG.	Bryan	All Surveyors

Print Received Message

This mail is associated with :

GBE4827E (SNM17D07057C01)

OD

Dec 2 2017 6:00AM

[TECK WEI LEASING (S) PTE LTD]

Auto N Cars Services Pte Ltd

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 26/12/2017
15:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$35000.00) - GBE4827E - Claim Handler: Chong Boon Sen

Approved:35000.00.

Maggie Liew

From: pauline [pauline@oraclelaw.sg]
Sent: Monday, 21 May, 2012 9:48 AM
To: Maggie Liew
Subject: RE: Our Ref: SB/PO/Acc/2012-6781 Your Ref: CC7/AIG12001194/M1ab3]

Without Prejudice Save As To Costs

Dear Maggie

ACCIDENT INVOLVING SGS 8853U, SKA 6420X & SGG 9658Z ON 16-01-2012

Referring to your offer dated 18 May 2012.

Strictly for amicable settlement purpose, we are instructed to make a counter-proposal on a global sum of S\$11,800.00 (all-in) as full and final settlement of our client's claim.

Kindly let us have your acceptance of our client's said global offer **within the next ten (10) days from the date hereof** failing which we have instructions to commence legal proceedings without further reference to you.

Regards

Pauline Ong
M/s Oracle Law Corporation

From: Maggie Liew [mailto:maggieliew@lkkauto.com]
Sent: Friday, May 18, 2012 3:10 PM
To: pauline
Subject: RE: Our Ref: SB/PO/Acc/2012-6781 Your Ref: CC7/AIG12001194/M1ab3]

WITHOUT PREJUDICE (SAVE AS TO COSTS)

Dear Pauline,

We refer to your email of 11/05/2012.

Subject to our principal's approval, we propose to settle your client's claim as follows:-

1. Cost of Repairs	\$ 8,200.00 (in lieu of re-inspection)
2. Loss of Use (14days x \$50)	\$ 700.00
3. Survey Report Fees	\$ 564.00 (agreed)
4. GIA Search Fees	\$ - (subject to proof)
5. LTA Search Fees	\$ 5.35 (agreed)
6. Costs	\$ 650.00 (as per NIMA Protocol)
Total	<u>\$10,119.35</u>

We further advise that our revised offer herein is considered very fair and reasonable.

Kindly revert.

Best regards,
Maggie Liew
LKK Auto Consultants Pte Ltd
DID: 6742 0347
Fax: 6741 4108
E-mail: maggieliew@lkkauto.com

Print Received Message

This mail is associated with :

GBE4827E (SNM17D07057C01)

OD

Dec 2 2017 6:00AM

[TECK WEI LEASING (S) PTE LTD]

Auto N Cars Services Pte Ltd

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 26/12/2017
15:57 PM.
To LKK_HQ
Subject Re: GBE4827E (SNM17D07057C01)

Dear Janice,

Rear Canopy is not insured (\$2860).

Thank you.

<-- Original Message -->

From: LKK_HQ

To: CHINA_TAIPING; boonsen.chong@sg.cntaiping.com

Sent On: 26/12/2017 03:48 PM

Subject: GBE4827E (SNM17D07057C01)

Dear Boon Sen,

Kindly advice whether the canopy is coverage in the policy.

Thank you.

Regards,
Janice

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, December 26, 2017 4:14 PM
To: Darla Balingit
Cc: SUR
Subject: GBE 4827E CTI OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBE 4827E (excess \$4,500/-)**. Please note that **repair cost not more than Lump Sum \$35,000.00 and the Canopy is NOT coverage in the policy.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.


Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2017 16:26
Date Of Accident	02/12/2017 06:50
Exact Location Of Accident	AYER RAJAH AVENUE TOWARDS DOVER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE4827E
Insured/Policyholder	
Name Of Registered Owner	TECK WEI LEASING (S) PTE LTD
Co Reg No	201408056W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91119581

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 MANUAL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1557061601
Cover Note Number	

Driver

Name of Driver	VICTOR SUSAI A/L SUR IMUTHU @ SAVARIMUTHU
Passport No/FIN	G8256311W
Date Of Birth	28/07/1987
Occupation	OUTDOOR
Date Of Driving Pass	22/09/2017
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98304519
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT MERAH WEST NPC
 Police Station Address ROAD: 500 BUKIT MERAH VIEW #01-01 , POSTCODE: 159682 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number LAMPPOST
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address


DETAILS OF INJURED PERSON 1

Name VICTOR SUSAI A/L SUR IMUTHU @ SAVARIMUTHU
Approximate Age
Injuries Sustain
Injured person in which vehicle? GBE4827E
Were seat belts worn?
Was injured conveyed to hospital by ambulance? YES
Address
Postcode

Sketch Plan Pg. 1

'SKETCH PLAN

A: GBI4827E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

~~PLEASE REFER TO POLICE REPORT 7/2017/207/2010~~

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

12/12/2017

Sketch Plan #2 Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

Report No. T/20171207/2010

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/12/2017 08:24	Vide Report No.:	Station Diary No.: 19
--	------------------	--------------------------

Informant's Particulars

Name of Informant: VICTOR SUSAI A/L SUR IMUTHU @ SAVARIMUTHU			Address:		
ID Type / ID No.: NRIC NO / G8256311W			Contact No.: Home/Office: Mobile: 98304519		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 30	Date of Birth: 28/07/1987	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: OPERATION EXECUTIVE			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Government Property	Drink Drive: No	Date/Time of Accident: 02/12/2017 06:50	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 AYER RAJAH AVENUE DOVER ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Lamp Post				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE4827E	PICK-UP	TOYOTA	TOYOTA DYNA 150 MANUAL	Silver	Totally Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

Report No. T/20171207/2010.

CONTINUATION OF REPORT

Driver			
Name	VICTOR SUSAI A/L SUR IMUTHU @ SAVARIMUTHU	ID No.	G8256311W
Related Vehicle	GBE4827E (PICK-UP)	Contact No.	98304519
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	02/12/2017	Date Discharge	03/12/2017
No. of Days granted Medical Leave	90	Degree of Injury	Serious

Brief Details.

On the above mentioned date, time and place, I was driving along Ayer Rajah Ave towards Dover Rd when I lost my focus and ram into a lamp post along Ayer Rajah Ave. I was then conveyed to National University Hospital from 02/12/2017 to 03/12/2017 and was given 90 days MC. I suffered a cut on my head and received 06 stitches from treatment at the hospital. My vehicle was turned upside down after the incident and the windows were shattered. My vehicle was seriously damaged and I have an in-car-vehicle camera in my vehicle that captured the incident.

I am lodging this report due to damage to government property and my MC is more than 03 days.



**SINGAPORE
POLICE FORCE**



T/20171207/2010

3 of 3

Report No. T/20171207/2010

Police Station Of Origin:
Bukit Merah West N.P.C
500 Bukit Merah View #01-01 SINGAPORE
159682
Tel No: 1800-3779999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
D /
Sgt 2 DANIEL HO WEI CONG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SSI KASMAWATI BTE SAMIAN
Contact No.: 65476179

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
07/12/2017 08:24

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	8056W

Vehicle Details

Vehicle No.:	GBE4827E
Vehicle to be Exported:	Yes
Intended De-registration Date:	19 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2572150
Chassis No.:	JTFAT35Y80K205525
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	16 Dec 2015
First Registration Date:	16 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$1,248.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	15 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,849.00
COE Rebate Amount:	\$26,238.00
Total Rebate Amount:	\$26,238.00

The information contained herein is correct as at 19 Dec 2017



UP TO
64% OFF*
CAR INSURANCE

✓ Starting from \$411.69*
✓ Receive \$50 CapitaVouchers*
T&Cs apply.

BUY NOW

income

Username / Email Add

password

f Connect

 Sign Up New Account
 Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Best bin Loan, Trade In Are
 Welcome! 100% Deposit Refund
 For Unapproved Loan.
 Classic Credit



Browse by Category

Sort by Date Posted

20 results/page

9 vehicles

Toyota Dyna

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Dyna		Any	Any	2015	Any	Any	Any	Available
	Toyota Dyna	150	\$58,800	\$8,090 /yr	25-Mar-2015	2,982 cc	-	Truck	Available
Fuel Type: Diesel Cheapest In The Market! 1 Owner Only, Low Miles, No Need Repair, Good Condition And Well Maintenance, Regular Servicing Done, Price Negotiable, High Loan With Lowest Interest Rate Available, High Trad... ABWIN Bus Pte Ltd Posted: 04-Dec-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota									
									
									
	Toyota Dyna	150	-	N.A	13-May-2015	2,982 cc	188,692 km	Truck	Available
Fuel Type: Diesel Auction Closing Time: 20th Dec 2017 at 11:00 PM This Vehicle Is GST Chargeable, Kindly Download The GST Chargeable Tender Form At This Link: Http://goo.gl/ZvupBS Posted: 14-Dec-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota									
									
									
	Toyota Dyna	150	-	N.A	13-May-2015	2,982 cc	-	Truck	Available
Fuel Type: Diesel Auction Closing Time: 20th Dec 2017 at 11:00 PM This Vehicle Is GST Chargeable, Kindly Download The GST Chargeable Tender Form At This Link: Http://goo.gl/ZvupBS Posted: 14-Dec-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota									
									
									
	Toyota Dyna	150	\$66,800	\$8,960 /yr	02-Jun-2015	2,982 cc	48,094 km	Truck	Available
Fuel Type: Diesel One Owner. Low Mileage. Tip Top Condition. Like New. See To Believe. Don't Miss. Index Credit Posted: 17-Dec-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota									
									

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Toyota Dyna 150

\$59,800

\$7,900 /yr

13-Jul-2015

2,982 cc

65,000 km

Truck

Available

Fuel Type: Diesel

Registered Only In 2015, This Vehicle Has Been Very Well Maintained. Owner Sold This Due To Winding Up Of Business. The Upholstery Is Still In It's Original Condition. Very Well Maintained And Comes W...

Car (S) Pte Ltd

Posted: 19-Dec-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota



Toyota Dyna 150

\$62,000

\$8,150 /yr

29-Jul-2015

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Registered Only In 2015, This Vehicle Has Been Very Well Maintained. Owner Sold This Due To Business Closedown. Good Condition.

Posted: 06-Dec-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota



Toyota Dyna 150

\$60,800

\$7,970 /yr

03-Aug-2015

2,982 cc

-

Truck

Available

Fuel Type: Diesel

In House Finance Available, Pls Call For Vieing.

Posted: 19-Nov-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota



12/19/2017

Used Toyota Dyna Car & Used Cars & Vehicles Singapore - sgCarMart

	Toyota Dyna 150 Fuel Type: Diesel One Careful Owner. Well Kept. No Repair Need. Call Now. Don't Miss. Loan / Trade In Available. Posted: 15-Nov-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$64,800	\$8,490 /yr	06-Aug-2015	2,982 cc	-	Truck	Available	 Details
	Toyota Dyna 150 Fuel Type: Diesel Toyota Dyna Up For Sale Now. Clean And Well Maintained Interior And Exterior. Most Recognizable Truck For Day To Day Duties. Call Me Now. Posted: 18-Oct-2017 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$70,800	\$9,250 /yr	14-Aug-2015	2,982 cc	17,840 km	Truck	Available	 Details

Save this search criteria, to get email alerts whenever a match is found.

MakeModelPriceDepreciationReg DateEng CapMileageVeh TypeStatus

For old advertisements, view Expired ads20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Dyna, Toyota Dyna Singapore, used Toyota Dyna Singapore, used Toyota Dyna, used vehicles Singapore or even buy used Toyota Dyna Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
 - New Car
 - Used Car
 - Sell Car
 - Motoring Directory
 - Products Guide
 - Article
 - Forum
 - Tool & Tip
- About Us
 - Careers
 - Contact Us
 - Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare



- This Beast Worse Than Any Other Beast
- Liverpool 2017/18: YNWA with Klopp
- Uncle Terry's Movie Reviews

Username / Email Add
 password
 Connect

» Sign Up New Account
 » Forgot Password

Post an Advertisement
 Sell It yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

COE 08/2027 MX-



100% Original And Stock
 Condition. One Lady Owner For
 10 Years. Immaculate unit.
 Direct Owner. [View Car](#)



Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

14 vehicles

Toyota Dyna

Advanced Search



Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Dyna	Any	Any	2016	Any	Any	Any	Available
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Well Maintained, See To Believe, Almost New. \$0 Drive Away, 100% Loan Available, High Trade In. Call Now For More Details. Posted: 04-Dec-2017 Tags: 2016 Toyota Dyna, 2016 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$67,888	\$8,430 /yr	08-Jan-2016	2,982 cc	33,547 km	Truck	Available PREMIUM AD Details
	Toyota Dyna 150 Fuel Type: Diesel Low Deposit, Well Kept. In House Loan Available. Trade In Always Welcome! Posted: 11-Nov-2017 Tags: 2016 Toyota Dyna, 2016 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$62,800	\$7,780 /yr	12-Jan-2016	2,982 cc	-	Truck	Available Details
	Toyota Dyna 150 Fuel Type: Diesel Insurance Until March 2018, Direct Owner. Call To View, Auto Engine Wash And Well Maintained. Posted: 16-Nov-2017 Tags: 2016 Toyota Dyna, 2016 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$72,000	\$8,740 /yr	14-Mar-2016	2,982 cc	80,500 km	Truck	Available DIRECT OWNER Details
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, 10 Foot Full Canopy Lorry, New Paintwork, Very Good Condition, Agent Maintained & Under Warranty, Easy In House Loan Available, Trade In Welcome, Call Now! Posted: 09-Dec-2017 Tags: 2016 Toyota Dyna, 2016 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$68,888	\$8,340 /yr	22-Mar-2016	2,982 cc	-	Truck	Available Details
Car Buying	Car Selling	Car Aftermarket		Buying a pre-owned car, but Unsure of its Condition? Get a STA Car Evaluation				
Car Ownership	On The Move	Lifestyle						
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Best Selling Toyota Dyna 10 Feet Lorry Come With Canopy. 100% Loan Available, \$0 Drive Away, High Trade In. Act Fast, Don't Miss It, Call Now. Posted: 04-Dec-2017 Tags: 2016 Toyota Dyna, 2016 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$68,888	\$8,320 /yr	29-Mar-2016	2,982 cc	-	Truck	Available Details
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Best Selling Toyota Dyna 10 Feet Lorry. Like New, Showroom Condition. 100% Loan Available, \$0 Drive Away. High Trade In. Act Fast, Don't Miss It, Call Now For More Details. Posted: 23-Nov-2017 Tags: 2016 Toyota Dyna, 2016 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$69,888	\$8,440 /yr	01-Apr-2016	2,982 cc	-	Truck	Available Details
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Low Mileage, \$0 Drive Away, Almost New, Most Reliable Commercial Lorry. High Trade In. Don't Miss It. Call Now! Posted: 14-Dec-2017 Tags: 2016 Toyota Dyna, 2016 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota	\$70,888	\$8,410 /yr	23-May-2016	2,982 cc	18,523 km	Truck	Available PREMIUM AD Details
Toyota Dyna 150		\$67,800	\$8,030 /yr	27-May-2016	2,982 cc	-	Truck	Available

**AUTO N CARS SERVICES
PTE LTD
AUTOBAY @ BLK 1 #01-04
KAKI BUKIT AVE 6
417883**

**Claim Reference: 077912170D
Assessment Number: ANC00183
Version: AUTONCAR/1
Date Calculated: 15/12/2017 08:47**

**Full Report - V1
Registration: GBE4827E
Printed: 15/12/2017 16:48**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Darla Belingit	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	OTHER	Repairs Authorised:	TBA
Claim Reference:	077912170D	Estimated Repair Time:	
Policy Number:	DMCVSN1557061601	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Dyna
Sub Model:	150
Model Sheet Number:	Y1N 03
Registration:	GBE4827E
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%


Model Specs

AIR CONDITIONING	FRT ELECTRIC WINDOWS
PLATFORM	SINGLE CAB
3.0 LTR 80KW	5-SPEED
PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

AUTO N CARS SERVICES PTE LTD**Claim Reference: 077912170D****Full Report - V1****Assessment Number: ANC00183****Registration: GBE4827E****Version: AUTONCAR/1****Printed: 15/12/2017 16:48****Date Calculated: 15/12/2017 08:47****Addresses****Cost Summary**

Total Labour	\$6,412.40
Total Paint/Material	\$446.97
Total Parts	\$55,698.21
Total of Additional Costs	\$692.00
Excess:	TBA
Grand Total Exc GST:	\$63,249.58
7 % GST:	\$4,427.47
Grand Total Inc GST:	\$67,677.05

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /**Guide Number Repair Details**

	WU	Cost Price (\$)
NO NUMBER R + R DUMPING LINKAGE	9.0	41.40
NO NUMBER R + R CAB	30.0	138.00
NO NUMBER RENEW FRONT PANEL	60.0	276.00
NO NUMBER R + R BADGE "DYNA"	2.0	9.20
520011) R + R FRONT BUMPER	4.0	18.40
520011) RENEW FRONT BUMPER (REMOVED)	2.0	9.20
751011 R + R RADIATOR GRILLE	2.0	9.20
810051 ZAX R + R L/HEADLAMP	3.0	13.80
810051 ZAX R + R R/HEADLAMP	3.0	13.80
810151A ADJUST HEADLAMPS	3.0	13.80
NO NUMBER R + R L/F LOWER CLOSING PANEL	1.0	4.60
NO NUMBER R + R R/F LOWER CLOSING PANEL	1.0	4.60
NO NUMBER R + R L/LOWER PROTECTING COVER	2.0	9.20
NO NUMBER R + R R/LOWER PROTECTING COVER	2.0	9.20
NO NUMBER RENEW FRONT FLOOR PANEL	72.0	331.20
NO NUMBER RENEW FRONT END PANEL	20.0	92.00
NO NUMBER RENEW L/F FLOOR CLOSING PANEL	21.0	96.60
NO NUMBER RENEW ROOF	70.0	322.00
554011) R + R WINDSCREEN	14.0	64.40
INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS		
554051 R + R REAR SCREEN	6.0	27.60
670051) R + R LEFT FRONT DOOR	6.0	27.60
NO NUMBER RENEW L/A-PILLAR	80.0	368.00
NO NUMBER R + R L/F STEP	3.0	13.80
NO NUMBER RENEW L/INNER A-PILLAR	20.0	92.00

AUTO N CARS SERVICES PTE LTD

Claim Reference: 077912170D
Assessment Number: ANC00183
Version: AUTONCAR/1
Date Calculated: 15/12/2017 08:47

Full Report - V1
Registration: GBE4827E
Printed: 15/12/2017 16:48

NO NUMBER	RENEW L/R CORNER PILLAR	65.0	299.00
670051)	RENEW L/F DOOR	12.0	55.20
	(DOOR REMOVED)		
	INCLUDES: CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
752051	R + R LEFT MIRROR	4.0	18.40
670201)	R + R L/F DOOR HINGE/S	2.0	9.20
NO NUMBER	R + R L/DOOR LOCK CATCH	1.0	4.60
NO NUMBER	R + R L/B-PILLAR BADGE	2.0	9.20
NO NUMBER	R + R CAB PROTECTIVE GRILLE	16.0	73.60
NO NUMBER	R + R RIGHT LOADING LID	5.0	23.00
670051)	R + R RIGHT FRONT DOOR	6.0	27.60
NO NUMBER	RENEW R/A-PILLAR	80.0	368.00
NO NUMBER	R + R R/F STEP BOARD	3.0	13.80
NO NUMBER	RENEW R/INNER A-PILLAR	20.0	92.00
NO NUMBER	RENEW R/R CORNER PILLAR	65.0	299.00
670051)	RENEW R/F DOOR	12.0	55.20
	(DOOR REMOVED)		
	INCLUDES: CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
752051	R + R RIGHT MIRROR	4.0	18.40
670201)	R + R R/F DOOR HINGE/S	2.0	9.20
NO NUMBER	R + R R/DOOR LOCK CATCH	1.0	4.60
NO NUMBER	R + R R/B-PILLAR BADGE	2.0	9.20
743201)	R + R HEADLINING	5.0	23.00
	INCLUDES: R + R INSIDE MIRROR, PILLAR TRIMS AND SEAT BELTS		
NO NUMBER	R + R L/F LOWER DOOR SEAL	2.0	9.20
NO NUMBER	R + R R/F LOWER DOOR SEAL	2.0	9.20
743511)	R + R FRONT FLOOR CARPET	2.0	9.20
711041 ZAX	R + R L/SEAT	2.0	9.20
711041 ZAX	R + R R/SEAT	2.0	9.20
743521)	R + R L/R FLOOR CARPET	8.0	36.80
743521)	R + R R/R FLOOR CARPET	8.0	36.80
743521)	R + R REAR FLOOR CARPET	6.0	27.60
870031)	R + R HEATING CPL	12.0	55.20
870151	R + R BLOWER (HEATER REMOVED)	5.0	23.00
NO NUMBER	R + R EVAPORATOR	4.0	18.40
NO NUMBER	R + R ENGINE CONTROL UNIT	4.0	18.40
550451)	R + R INSTRUMENT PANEL	9.0	41.40
550451)	RENEW INSTRUMENT PANEL (REMOVED)	4.0	18.40
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)	2.0	9.20
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)	1.0	4.60
850171)	R + R WIPER LINKAGE	1.0	4.60
NO NUMBER	R + R INSTRUMENT PANEL WIRING	10.0	46.00
160011)	R + R RADIATOR	10.0	46.00
	INCLUDES: R + R FAN, FAN BLADE AND EXPANSION TANK, BLEED COOLING SYSTEM		
160011)	RENEW RADIATOR (RADIATOR REMOVED)	1.0	4.60
171021	R + R AIR CLEANER BRACKET	2.0	9.20
271011)	R + R ALTERNATOR	8.0	36.80
463011)	R + R BOOSTER	3.0	13.80
461101)	R + R BRAKE MASTER CYLINDER	2.0	9.20

AUTO N CARS SERVICES PTE LTD

Claim Reference: 077912170D
Assessment Number: ANC00183
Version: AUTONCAR/1
Date Calculated: 15/12/2017 08:47

Full Report - V1
Registration: GBE4827E
Printed: 15/12/2017 16:48

	INCLUDES: BLEED BRAKE SYSTEM		
151011	R + R OIL STRAINER	7.0	32.20
NO NUMBER	R + R OIL DIPSTICK GUIDE	2.0	9.20
111261	R + R FRONT ENGINE MOUNTING	14.0	64.40
110051)	R + R CYLINDER HEAD	29.0	133.40
170171)	DETACH + REFIT EXHAUST SYSTEM	3.0	13.80
170171)	R + R FRONT EXHAUST PIPE	4.0	18.40
420091)	R + R LEFT FRONT WHEEL	1.0	4.60
420091)	R + R RIGHT FRONT WHEEL	1.0	4.60
420091)	R + R FRONT WHEEL	1.0	4.60
420091A	R + R L/F WHEEL/TYRE	3.0	13.80
442151 ZAX	R + R STEERING SHAFT	2.0	9.20
441101	R + R STEERING WHEEL	2.0	9.20
NO NUMBER	DETACH + REFIT STEERING SPINDLE	5.0	23.00
NO NUMBER	REMOVE AND REFIT STRG GUIDE LEVER	4.0	18.40
444401)	R + R STEERING BOX	22.0	101.20
NO NUMBER	DETACH + REFIT LEFT FRONT STABILIZER	1.0	4.60
NO NUMBER	DETACH + REFIT RIGHT FRONT STABILIZER	1.0	4.60
430011)	R + R L/F UPPER CONTROL ARM	6.0	27.60
430011)	R + R R/F UPPER CONTROL ARM	6.0	27.60
430011)	R + R UPPER WISHBONE (ADD/WORK)	7.0	32.20
430051A)	R + R L + R LWR STEERING AXLE	8.0	36.80
430051)	R + R L/F LOWER CONTROL ARM (WHEEL REM)	9.0	41.40
430051)	R + R R/F LOWER CONTROL ARM (WHEEL REM)	9.0	41.40
NO NUMBER	R + R FRONT STABILIZER	3.0	13.80
434211)	R + R L/F CONTROL ARM	16.0	73.60
434211)	R + R R/F STEERING KNUCKLE	16.0	73.60
434211)	R + R FRONT STEERING KNUCKLE L+R	6.0	27.60
420091)	R + R L/R AND R/R WHEEL	2.0	9.20
420091)	R + R LEFT REAR WHEEL	1.0	4.60
420091)	R + R LEFT REAR TYRE/WHEEL	2.0	9.20
NO NUMBER	R + R CONDENSER	8.0	36.80
NO NUMBER	R + R COMPRESSOR-/CONDENSER PIPE	3.0	13.80
NO NUMBER	R + R COMPRESSOR-/EVAPORATOR PIPE	3.0	13.80
NO NUMBER	R + R DRYER	3.0	13.80
NO NUMBER	R + R FAN HOUSING	2.0	9.20
002889	DRAIN AND REFILL AIR CONDITIONING	7.0	32.20
NO NUMBER	R + R FAN BLADE	2.0	9.20
NO NUMBER	R + R FAN MOTOR	2.0	9.20
NN	REAR CANOPY R&R / NEW PARTS	30.0*	138.00
NN	RADIATOR FAN CLUTCH R&R / NEW PARTS	5.0*	23.00
2385	REPAIR UPPER GUIDE RAIL	5.0*	23.00
7141	CHECK L/F BRAKE DISC	2.0*	9.20

LABOUR COST

Total Work Units	1,118.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	111.8HRS	\$5,142.80
Paint Labour	27.6HRS	\$1,269.60
Total Labour	139.4HRS	\$6,412.40

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

AUTO N CARS SERVICES PTE LTD

Claim Reference: 077912170D
Assessment Number: ANC00183
Version: AUTONCAR/1
Date Calculated: 15/12/2017 08:47

Full Report - V1
Registration: GBE4827E
Printed: 15/12/2017 16:48

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
281	FRONT BUMPER NEW PART PAINTING	12.0	
413	COMPL LWR FRT PANEL NEW PART PAINTING	30.0	
418	UPPER FRONT PANEL NEW PART PAINTING	8.0	
889	L/F LOWER END PANEL NEW PART PAINTING	6.0	
890	R/F LOWER END PANEL NEW PART PAINTING	6.0	
911	L/OUTER A-PILLAR NEW PART PAINTING	18.0	
912	R/OUTER A-PILLAR NEW PART PAINTING	18.0	
931	FRONT PANEL SURFACE PAINT	5.0	
935	L/INNER A-PILLAR SURFACE PAINT	4.0	
936	R/INNER A-PILLAR SURFACE PAINT	4.0	
1481	LEFT DOOR NEW PART PAINTING	16.0	
1482	RIGHT DOOR NEW PART PAINTING	16.0	
2103	L/R CORNER PILLAR NEW PART PAINTING	13.0	
2104	R/R CORNER PILLAR NEW PART PAINTING	13.0	
2296	FRONT FLOOR PANEL SURFACE PAINT	8.0	
2301	L/F FLOOR SIDE PANELS SURFACE PAINT	4.0	
2351	ROOF NEW PART PAINTING	49.0	
5406	R/DROP SIDE NEW PART PAINTING	21.0	
LABOUR COST - PAINT			
	TIME (PAINT)	251.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	276.0	
	Total Paintwork Labour	27.6HRS	\$1,269.60
MATERIAL COST - PAINT			
	New Part Painting		\$382.02
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$36.35
	Total Excluding Pearlescent Uplift		\$446.97
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$446.97

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	A/C CONDENSER BRKT <i>2nd</i>	Renew		0%	250.00*
1000	1	AC COND SUPP BRKT <i>2nd</i>	Renew		0%	75.00*
8411	1	ALTERNATOR <i>Charged</i>	27060 30131		0%	950.00*2
481	1	BADGE <i>new</i>	75315 25010		0%	38.00*
484	1	BADGE "DYNA" <i>new</i>	75311 25051		0%	30.00*
5389	1	CAB PROTECT GRILLE <i>missy</i>	65400 25720		0%	580.00*
1000	1	CABIN SAFETY LOCK <i>2nd</i>	Renew		0%	220.00*
4366	1	COMBI INSTRUMENT <i>missy</i>	83800 25370		0%	650.00*
7417	1	COMBINATION SWITCH <i>2nd</i>	84310 37350		0%	450.00*
413	1	COMPL LWR FRT PANEL <i>Disled</i>	55700 37310		0%	580.00*
3887	1	COMPR/CONDENSER TUBE <i>new</i>	88711 25390		0%	420.00*
4465	1	CONDENSER <i>Disled</i>	88461 25050		0%	380.00*
4485	1	COOLING FAN <i>Disled</i>	88453 37010		0%	70.00*
2552	1	CTR INSTR PANEL TRIM <i>new</i>	55405 37141		0%	185.00*
7853	1	DRIVE BELT TENSIONER <i>new</i>	16620 30031		0%	80.00*
4467	1	DRYER BOTTLE <i>new</i>	88471 34010		0%	95.00*
417	1	END MOULDING <i>new</i>	53928 37011		0%	130.00*

AUTO N CARS SERVICES PTE LTD

Claim Reference: 077912170D

Assessment Number: ANC00183

Version: AUTONCAR/1

Date Calculated: 15/12/2017 08:47

Full Report - V1

Registration: GBE4827E

Printed: 15/12/2017 16:48

9661	1	ENGINE CONTROL UNIT <i>could</i>	89661 25170	0%	2,850.00* <i>2</i>
1000	1	F/ROOF INN PANEL <i>Dishd</i>	Renew	0%	205.00* <i>✓</i>
7793	1	FAN <i>Ren</i>	16361 67020	0%	217.00* <i>✓</i>
4469	1	FAN HOUSING <i>could</i>	88454 25060	0%	195.00* <i>✓</i>
4487	1	FAN MOTOR <i>Ren</i>	85550 25050	0%	140.00* <i>✓</i>
281	1	FRONT BUMPER <i>Dishd</i>	52101 25908	0%	280.00* <i>✓</i>
4875	1	FRONT FLOOR CARPET <i>Ren</i>	58510 3V050B0	0%	210.00* <i>✓</i>
2296	1	FRONT FLOOR PANEL <i>Dishd</i>	58111 37308	0%	850.00* <i>✓</i>
931	1	FRONT PANEL <i>Dishd</i>	57408 25343	0%	480.00* <i>✓</i>
7261	1	FRONT STABILISER <i>Ren</i>	48811 25041	0%	250.00* <i>✓</i>
1000	1	FUSE BOX <i>could</i>	Renew	0%	230.00* <i>✓</i>
1000	1	GEARBOX MTG <i>could</i>	Renew	0%	95.00* <i>✓</i>
2600	1	GLOVEBOX <i>Dishd</i>	55550 37011B0	0%	195.00* <i>✓</i>
411	1	GRILLE <i>Missing</i>	53111 25060A0	0%	180.00* <i>✓</i>
4957	1	HEADLINING <i>could</i>	63311 25093B0	0%	210.00* <i>✓</i>
4415	1	HEATER BLOWER CPL <i>could</i>	87130 37151	0%	1,100.00* <i>✓</i>
4411	1	HEATER CPL <i>could</i>	87150 25060	0%	1,780.00* <i>✓</i>
9589	1	INSTR PANEL WIRING <i>Ren</i>	82131 2E230	0%	480.00* <i>✓</i>
4331	1	INSTRUMENT PANEL <i>Dishd</i>	55301 37012B0	0%	680.00* <i>✓</i>
4335	1	INSTRUMENT PNL TRIM <i>could</i>	55320 25020B0	0%	35.00* <i>✓</i>
2560	1	INSTRUMENT SUPPORT <i>could</i>	55330 37025	0%	380.00* <i>✓</i>
2419	1	L/A-PILLAR COVER <i>could</i>	62212 37012B0	0%	35.00* <i>✓</i>
1000	1	L/DOOR GLASS INN <i>Dishd</i>	DRAIN CHANNEL	0%	45.00* <i>✓</i>
1000	1	L/DOOR GLASS OUT <i>could</i>	WEATHERSTRIP	0%	95.00* <i>✓</i>
1743	1	L/DOOR MIRROR GLASS <i>Shutter</i>	87901 36030	0%	98.00* <i>✓</i>
1000	1	L/DOOR PILLAR WSTRIP <i>could</i>	Renew	0%	105.00* <i>✓</i>
1000	1	L/DOOR RUBB BEADING <i>could</i>	Renew	0%	195.00* <i>✓</i>
1509	1	L/DOOR SEAL <i>Ren</i>	67862 37021	0%	98.00* <i>✓</i>
887	1	L/END MOULDING <i>Ren</i>	53922 25011	0%	58.00* <i>✓</i>
489	1	L/F BADGE <i>not in</i>	75362 35090	0%	50.00* <i>✓</i>
1000	1	L/F DOOR ASH TRAY <i>Ren</i>	Renew	0%	48.00* <i>✓</i>
1505	1	L/F DOOR CHECK <i>could</i>	68610 37030	0%	70.00* <i>✓</i>
1565	1	L/F DOOR OUT HANDLE <i>could</i>	69220 37020	0%	110.00* <i>✓</i>
1711	1	L/F DOOR TRIM <i>could</i>	67620 37180B4	0%	380.00* <i>✓</i>
1519	1	L/F DOOR WINDOW <i>Shutter</i>	68102 37140	0%	250.00* <i>✓</i>
2301	1	L/F FLOOR SIDE PANEL <i>Ren</i>	58336 25010	0%	350.00* <i>✓</i>
1571	1	L/F INN DOOR HANDLE <i>could</i>	69206 37010B0	0%	45.00* <i>✓</i>
7057	1	L/F INN WHEEL BRG <i>Ren</i>	90368 49084	0%	150.00* <i>✓</i>
1495	1	L/F LOWER DOOR HINGE <i>could</i>	68710 37020	0%	55.00* <i>✓</i>
889	1	L/F LOWER END PANEL <i>Ren</i>	53802 37021	0%	95.00* <i>✓</i>
7053	1	L/F LWR AXLE ARM <i>could</i>	48069 25021	0%	350.00* <i>✓</i>
2443	1	L/F LWR D/FRAME SEAL <i>Ren</i>	53827 37010	0%	58.00* <i>✓</i>
897	1	L/F MUDFLAP <i>could</i>	53881 25030	0%	110.00* <i>✓</i>
7061	1	L/F OUT WHEEL BRG <i>Ren</i>	90368 49084	0%	150.00* <i>✓</i>
7087	1	L/F SHOCK ABSORBER <i>could</i>	48511 29845	0%	90.00* <i>✓</i>
5007	1	L/F STEERING KNUCKLE <i>could</i>	43202 25070	0%	850.00* <i>✓</i>
2205	1	L/F STEP <i>could</i>	51772 37080	0%	130.00* <i>✓</i>
2207	1	L/F STEP COVER <i>could</i>	51774 37010	0%	135.00* <i>✓</i>
7049	1	L/F UPPER AXLE LINK <i>could</i>	48067 29175	0%	570.00* <i>✓</i>
1487	1	L/F UPPER DOOR HINGE <i>could</i>	68730 37010	0%	55.00* <i>✓</i>
885	1	L/F UPPER END PANEL <i>Ren</i>	87945 37020A0	0%	95.00* <i>✓</i>
1545	1	L/F WINDOW MOTOR <i>could</i>	85720 37090	0%	205.00* <i>✓</i>
1547	1	L/F WINDOW REGULATOR <i>could</i>	69802 37063	0%	180.00* <i>✓</i>
563	1	L/HEADLAMP TRIM <i>Missing</i>	81193 37050	0%	20.00* <i>✓</i>

AUTO N CARS SERVICES PTE LTD

Claim Reference: 077912170D
Assessment Number: ANC00183
Version: AUTONCAR/1
Date Calculated: 15/12/2017 08:47

Full Report - V1
Registration: GBE4827E
Printed: 15/12/2017 16:48

7761	1	RADIATOR <i>replaced</i>	16400 30230	0%	1,932.00* ✓
1000	1	RADIATOR FAN CLUTCH <i>renew</i>	Renew	0%	766.00* ✓
7767	1	RADIATOR SHROUD <i>renew</i>	16711 30010	0%	237.00* ✓
1000	1	REAR CANOPY <i>renew</i>	Renew	0%	2,500.00* ✓
3159	1	REAR SCREEN BOND KIT <i>renew</i>	PZ49I 00C1131	0%	38.18U ✓
2083	1	REAR SCREEN INN SEAL <i>renew</i>	64831 37041	0%	32.32U ✓
1000	1	RH CANOPY CANVAS <i>renew</i>	Renew	0%	180.00* ✓
8622	1	RIGHT ENGINE SUPPORT <i>renew</i>	12311 30091	0%	150.00* ✓
1482	1	RIGHT FRONT DOOR <i>disbld</i>	67001 25051	0%	950.00* ✓
562	1	RIGHT HEADLAMP ASSY <i>renew</i>	81130 37170	0%	320.00* ✓
4662	1	RIGHT SEAT BELT <i>renew</i>	73210 37210B0	0%	516.00* ✓
2351	1	ROOF <i>disbld</i>	63111 37120	0%	580.00* ✓
1000	1	ROOF LIGHT <i>renew</i>	Renew	0%	45.00* ✓
3884	1	RR COMPR/EVAPOR PIPE <i>renew</i>	88712 25510	0%	550.00* ✓
2812	1	SHIFT LINKAGE <i>renew</i>	54801 25080	0%	500.00* ✓
7359	1	STEERING COLUMN CPL <i>renew</i>	45250 25670	0%	3,950.00* ✓
6041	1	STRG GUIDE LEVER <i>renew</i>	45390 25010	0%	450.00* ✓
385	1	UPP RAD GRILLE SEAL <i>renew</i>	53119 37020	0%	35.00* ✓
418	1	UPPER FRONT PANEL <i>renew</i>	55078 37070	0%	130.00* ✓
1436	1	WASHER RESERVOIR <i>renew</i>	85315 37090	0%	80.00* ✓
1401	1	WINDSCREEN <i>shattered</i>	56111 37120	0%	750.00* ✓
1411	1	WINDSCREEN BOND KIT <i>renew</i>	PZ49I 00C1131	0%	38.18U ✓
1410	1	WINDSCREEN SEAL <i>renew</i>	56121 25040	0%	140.00* ✓
1450	1	WIPER MOTOR <i>renew</i>	85070 37190	0%	65.00* ✓
1000	1	WIPER TANK HOSE <i>renew</i>	Renew	0%	15.00* ✓

f: OEM Parts	Sub Total	\$52,950.68
g: Original	Mark Up From Cost (5 %)	\$2,647.53
h: Secondhand	Sundry Parts (Fixed)	\$100.00
p: Parallel	Total Parts	\$55,698.21
x: Exchange		

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NO PLATE <i>renew</i>	0%	\$40.00 ✓
IU BRACKET <i>renew</i>		\$15.00 ✓
L/DOOR REG <i>renew</i>	0%	\$20.00 ✓
STICKER		
L/F TYRE RIM <i>at</i>		\$180.00 ✓
L/R TYRE RIM <i>at</i>	0%	\$120.00 ✓
L/F TYRE <i>at</i>		\$255.00 180. ✓
R/DOOR REG <i>renew</i>	0%	\$20.00 ✓
STICKER		
AUDATEX FEE	SPECIALIST	\$42.00 ✓
Total Extras		\$692.00

Final Calculation

Total Parts	\$55,698.21
Labour	
Total Panel/Mechanical	\$5,142.80
Total Paintwork	\$1,269.60
Total Labour	\$6,412.40
Additional Costs	
Corr Prot Materials External	\$0.00

AUTO N CARS SERVICES PTE LTD

Claim Reference: 077912170D

Assessment Number: ANC00183

Version: AUTONCAR/1

Date Calculated: 15/12/2017 08:47

Full Report - V1

Registration: GBE4827E

Printed: 15/12/2017 16:48

1577	1	L/INN DOOR LOCK <i>Failed</i>	69320 37060	0%	210.00*
935	1	L/INNER A-PILLAR <i>Dislod</i>	61024 37090	0%	320.00*
2801	1	L/LOCKING CLIP <i>Ren</i>	54990 25020	0%	280.00* 20
2417	1	L/LOWER DRIP RAIL <i>Ren</i>	67864 37011	0%	90.00*
911	1	L/OUTER A-PILLAR <i>Dislod</i>	61132 37063	0%	420.00*
2103	1	L/R CORNER PILLAR <i>Rps</i>	61612 37112	0%	350.00*
2437	1	L/SUN VISOR <i>Ren</i>	74320 25060B0	0%	95.00*
1597	1	L/WINDOW CHANNEL <i>Dislod</i>	68151 37030	0%	158.00*
1000	1	L/WING MIRROR ARM	Renew	0%	250.00*
1000	1	L/WING MIRROR CVR	<i>Missing</i> (HALF ROUND)	0%	25.00*
1000	1	L/WING MIRROR ROUND	Renew	0%	38.00*
8621	1	LEFT ENGINE SUPPORT <i>Dislod</i>	12315 30091	0%	150.00* 2
1481	1	LEFT FRONT DOOR	67002 37322	0%	950.00*
561	1	LEFT HEADLAMP ASSY <i>Missing</i>	81170 37171	0%	320.00*
1707	1	LEFT SPEAKER <i>Dislod</i>	86160 37120	0%	80.00*
1000	1	LH CANOPY CANVAS <i>Ren</i>	Renew	0%	180.00*
4337	1	LWR INSTR PANEL TRIM <i>Ren</i>	55458 37011B0	0%	95.00*
4940	1	R/A-PILL GRAB HANDLE <i>Ren</i>	74610 95405B1	0%	48.00*
2420	1	R/A-PILLAR COVER <i>Dislod</i>	62211 37012B0	0%	35.00*
1746	1	R/COWL PANEL COVER <i>Ren</i>	67495 37010	0%	55.00*
1738	1	R/DOOR MIRROR ASSY <i>Dislod</i>	87910 25040	0%	180.00*
1000	1	R/DOOR OUT WSTRIP <i>Ren</i>	Renew	0%	95.00*
1000	1	R/DOOR RUBB BEADING <i>Ren</i>	Renew	0%	195.00*
1510	1	R/DOOR SEAL <i>Ren</i>	67861 37021	0%	98.00*
5406	1	R/DROP SIDE <i>Dislod</i>	65500 25051	0%	1,550.00*
888	1	R/END MOULDING <i>Ren</i>	53921 25011	0%	58.00*
490	1	R/F BADGE <i>Ren</i>	75362 35090	0%	50.00*
1506	1	R/F DOOR CHECK <i>But</i>	68610 37030	0%	70.00*
1778	1	R/F DOOR FRAME SEAL <i>Ren</i>	62313 37041B0	0%	105.00*
1566	1	R/F DOOR OUT HANDLE <i>Ren</i>	69210 37020	0%	110.00*
1712	1	R/F DOOR TRIM <i>Dislod</i>	67610 25090B0	0%	380.00* 2
1520	1	R/F DOOR WINDOW <i>Shattered</i>	68101 37130	0%	250.00*
7058	1	R/F INN WHEEL BRG <i>Ren</i>	90368 49084	0%	150.00*
7054	1	R/F LOWER AXLE ARM <i>Ren</i>	48068 25021	0%	350.00*
1496	1	R/F LOWER DOOR HINGE <i>But</i>	68730 37010	0%	55.00*
890	1	R/F LOWER END PANEL <i>Ren</i>	53801 37021	0%	95.00*
2444	1	R/F LWR D/F FRAME SEAL <i>Ren</i>	53827 37010	0%	58.00*
7062	1	R/F OUT WHEEL BRG <i>Ren</i>	90368 49084	0%	150.00*
7088	1	R/F SHOCK ABSORBER <i>Ren</i>	48511 29845	0%	90.00*
5008	1	R/F STEERING KNUCKLE <i>Ren</i>	43201 25080	0%	850.00*
2206	1	R/F STEP <i>Ren</i>	51771 25021	0%	130.00*
2208	1	R/F STEP COVER <i>Ren</i>	51773 37020	0%	135.00*
7050	1	R/F UPPER AXLE LINK <i>Ren</i>	48066 29175	0%	590.00*
1488	1	R/F UPPER DOOR HINGE <i>But</i>	68710 37020	0%	55.00*
886	1	R/F UPPER END PANEL <i>Ren</i>	87915 37020A0	0%	95.00*
1548	1	R/F WINDOW REGULATOR <i>Ren</i>	69801 37063	0%	180.00*
1578	1	R/INN DOOR LOCK <i>Failed</i>	69310 37070	0%	210.00*
936	1	R/INNER A-PILLAR <i>Dislod</i>	61023 37040	0%	320.00*
2802	1	R/LOCKING CLIP <i>Ren</i>	54980 25010	0%	280.00* 20
912	1	R/OUTER A-PILLAR <i>Dislod</i>	61131 37083	0%	420.00*
2104	1	R/R CORNER PILLAR <i>Rps</i>	61611 37142	0%	350.00*
2438	1	R/SUN VISOR <i>Dislod</i>	74310 25220B0	0%	95.00*
1598	1	R/WINDOW CHANNEL <i>But</i>	68141 37030	0%	158.00*
7300	1	RACK/PINION STEERING <i>Not Nec</i>	44200 25030	0%	4,340.00*

AUTO N CARS SERVICES PTE LTD

Claim Reference: 077912170D
Assessment Number: ANC00183
Version: AUTONCAR/1
Date Calculated: 15/12/2017 08:47

Full Report - V1
Registration: GBE4827E
Printed: 15/12/2017 16:48

Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$692.00	
Total of Additional Costs		\$692.00
Total Paint/Material Costs		\$446.97
Grand Total Excludes GST		\$63,249.58
GST @ 7 %		\$4,427.47
Grand Total Includes GST		\$67,677.05

Assessment Notes

Adrian Cj

19/12/17.

Not Authorised, Excess \$4500.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Dec 2017 Sendback Est	15 Dec 2017 17:02 \$663,249.58	18 Dec 2017 18:03 Edit Adj Rpt	\$32,600.00 Edit Estimates	\$32,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TECK WEI LEASING (S) PTE LTD, Co. Reg. No.: 201408056W		
Vehicle Reg. No.:	GBE4827E	Date of Loss:	02/12/2017 06:00 - :59
Claim Type:	OD / SNM17D07057C01	Policy/Cover Note No.:	DMCVSN1557061601 (Comprehensive)
		Excess:	S\$1,500.00
Repairer:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 28/12/2017]		
Driver/Custodian:	VICTOR SUSAI A/L SUR IMUTHU @ SAVARIMUTHU (30 / Male), NRIC: G8256311W, Tel: +6598304519		
Adj Asg. Remarks:	SURVEY REVERT ECONOMICAL TO REPAIR CONSISTENCY OF DAMAGE		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- CHINA_TAIPING (26/12/2017): Re: GBE4827E (SNM17D07057C01)
- CHINA_TAIPING (26/12/2017): Alert - Adj Mandate Approved (S\$35000.00) - GBE4827E - Claim Handler: Chong Boon...

ALL ASSOCIATED TASKS ☐

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBE4827E (SNM17D07057C01)
OD
Dec 2 2017 6:00AM
[TECK WEI LEASING (S) PTE LTD]
Auto N Cars Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser ▼](#)

Assessment Reports			1 per page ▼	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 16:56	Accident Statement	Load HTM	
2	15/12/17 17:02	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 14:55	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 16:50	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	12/12/17 16:50	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	12/12/17 16:50	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	12/12/17 16:50	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	12/12/17 16:50	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	12/12/17 16:50	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	12/12/17 16:50	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	12/12/17 16:50	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	12/12/17 16:54	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 16:28	General View	Load PDF	
2	20/02/18 15:47	General View	Load JPG	☒
3	20/02/18 15:47	General View	Load JPG	☒
4	20/02/18 15:47	Chassis Number	Load JPG	☒
5	20/02/18 15:47	General View	Load JPG	☒
6	20/02/18 15:47	General View	Load JPG	☒
7	20/02/18 15:47	General View	Load JPG	☒
8	20/02/18 15:47	General View	Load JPG	☒
9	20/02/18 15:47	General View	Load JPG	☒
10	20/02/18 15:47	General View	Load JPG	☒
11	20/02/18 15:47	General View	Load JPG	☒
12	20/02/18 15:47	General View	Load JPG	☒
13	20/02/18 15:47	General View	Load JPG	☒
14	20/02/18 15:47	General View	Load JPG	☒
15	20/02/18 15:47	General View	Load JPG	☒
16	20/02/18 15:47	General View	Load JPG	☒
17	20/02/18 15:47	General View	Load JPG	☒

18	20/02/18 15:47	General View		Load JPG	
19	20/02/18 15:47	General View		Load JPG	
20	20/02/18 15:47	General View		Load JPG	
21	20/02/18 15:47	General View		Load JPG	
22	20/02/18 15:47	General View		Load JPG	
23	20/02/18 15:47	General View		Load JPG	
24	20/02/18 15:47	General View		Load JPG	
25	20/02/18 15:47	General View		Load JPG	
26	20/02/18 15:47	General View		Load JPG	
27	20/02/18 15:47	General View		Load JPG	
28	20/02/18 15:47	General View		Load JPG	
29	20/02/18 15:47	General View		Load JPG	
30	20/02/18 15:47	General View		Load JPG	
31	20/02/18 15:47	General View		Load JPG	
32	20/02/18 15:47	General View		Load JPG	
33	20/02/18 15:47	General View		Load JPG	
34	20/02/18 15:47	General View		Load JPG	
35	20/02/18 15:47	General View		Load JPG	
36	20/02/18 15:47	General View		Load JPG	
37	20/02/18 15:47	General View		Load JPG	
38	20/02/18 15:47	General View		Load JPG	
39	20/02/18 15:47	General View		Load JPG	
40	20/02/18 15:47	General View		Load JPG	
41	20/02/18 15:47	General View		Load JPG	
42	20/02/18 15:47	General View		Load JPG	
43	20/02/18 15:47	General View		Load JPG	
44	20/02/18 15:47	General View		Load JPG	
45	20/02/18 15:47	General View		Load JPG	
46	20/02/18 15:47	General View		Load JPG	
47	20/02/18 15:47	General View		Load JPG	
48	20/02/18 15:47	General View		Load JPG	
49	20/02/18 15:47	General View		Load JPG	
50	20/02/18 15:47	General View		Load JPG	
51	20/02/18 15:47	General View		Load JPG	
52	20/02/18 15:47	General View		Load JPG	
53	20/02/18 15:47	General View		Load JPG	
54	20/02/18 15:47	General View		Load JPG	
55	20/02/18 15:47	General View		Load JPG	
56	20/02/18 15:47	General View		Load JPG	
57	20/02/18 15:47	General View		Load JPG	
58	20/02/18 15:47	General View		Load JPG	
59	20/02/18 15:47	General View		Load JPG	
60	20/02/18 15:47	General View		Load JPG	
61	20/02/18 15:47	General View		Load JPG	
62	20/02/18 15:47	General View		Load JPG	
63	20/02/18 15:47	General View		Load JPG	
64	20/02/18 15:47	General View		Load JPG	
65	20/02/18 15:47	General View		Load JPG	

66	20/02/18 15:47	General View	1	Load JPG	☒
67	20/02/18 15:47	General View	1	Load JPG	☒
68	20/02/18 15:47	General View	1	Load JPG	☒
69	20/02/18 15:47	General View	1	Load JPG	☒
70	20/02/18 15:47	General View	1	Load JPG	☒
71	20/02/18 15:47	General View	1	Load JPG	☒
72	20/02/18 15:47	General View	1	Load JPG	☒
73	20/02/18 15:47	General View	1	Load JPG	☒
74	20/02/18 15:47	General View	1	Load JPG	☒
75	20/02/18 15:47	General View	1	Load JPG	☒
76	20/02/18 15:47	General View	1	Load JPG	☒
77	20/02/18 15:47	General View	1	Load JPG	☒
78	20/02/18 15:47	General View	1	Load JPG	☒
79	20/02/18 15:47	General View	1	Load JPG	☒
80	20/02/18 15:47	General View	1	Load JPG	☒
81	20/02/18 15:47	General View	1	Load JPG	☒
82	20/02/18 15:47	General View	1	Load JPG	☒
83	20/02/18 15:47	General View	1	Load JPG	☒
84	20/02/18 15:47	General View	1	Load JPG	☒
85	20/02/18 15:47	General View	1	Load JPG	☒
86	20/02/18 15:47	General View	1	Load JPG	☒
87	20/02/18 15:47	General View	1	Load JPG	☒
88	20/02/18 15:47	General View	1	Load JPG	☒
89	20/02/18 15:47	General View	1	Load JPG	☒
90	20/02/18 15:47	General View	1	Load JPG	☒
91	20/02/18 15:47	General View	1	Load JPG	☒
92	20/02/18 15:47	General View	1	Load JPG	☒
93	20/02/18 15:47	General View	1	Load JPG	☒
94	20/02/18 15:47	General View	1	Load JPG	☒
95	20/02/18 15:47	General View	1	Load JPG	☒
96	20/02/18 15:47	General View	1	Load JPG	☒
97	20/02/18 15:47	General View	1	Load JPG	☒
98	20/02/18 15:47	General View	1	Load JPG	☒
99	20/02/18 15:47	General View	1	Load JPG	☒
100	20/02/18 15:47	General View	1	Load JPG	☒
101	20/02/18 15:47	General View	1	Load JPG	☒
102	20/02/18 15:47	General View	1	Load JPG	☒
103	20/02/18 15:47	General View	1	Load JPG	☒
104	20/02/18 15:47	General View	1	Load JPG	☒
105	20/02/18 15:47	General View	1	Load JPG	☒
106	20/02/18 15:47	General View	1	Load JPG	☒
107	20/02/18 15:47	General View	1	Load JPG	☒
108	20/02/18 15:47	General View	1	Load JPG	☒
109	20/02/18 15:47	General View	1	Load JPG	☒
110	20/02/18 15:47	General View	1	Load JPG	☒
111	20/02/18 15:47	General View	1	Load JPG	☒
112	20/02/18 15:47	General View	1	Load JPG	☒
113	20/02/18 15:47	Reinspection Photo	1	Load JPG	☒

114	20/02/18 15:47	Reinspection Photo		Load JPG	
115	20/02/18 15:47	Reinspection Photo		Load JPG	
116	20/02/18 15:47	Reinspection Photo		Load JPG	
117	20/02/18 15:47	Reinspection Photo		Load JPG	
118	20/02/18 15:47	Reinspection Photo		Load JPG	
119	20/02/18 15:47	Reinspection Photo		Load JPG	
120	20/02/18 15:47	Reinspection Photo		Load JPG	
121	20/02/18 15:47	Reinspection Photo		Load JPG	
122	20/02/18 15:47	Reinspection Photo		Load JPG	
123	20/02/18 15:47	Reinspection Photo		Load JPG	
124	20/02/18 15:47	Reinspection Photo		Load JPG	
125	20/02/18 15:47	Reinspection Photo		Load JPG	
126	20/02/18 15:47	Reinspection Photo		Load JPG	
127	20/02/18 15:47	Reinspection Photo		Load JPG	
128	20/02/18 15:47	Reinspection Photo		Load JPG	
129	20/02/18 15:47	Reinspection Photo		Load JPG	
130	20/02/18 15:47	Reinspection Photo		Load JPG	
131	20/02/18 15:47	Reinspection Photo		Load JPG	
132	20/02/18 15:47	Reinspection Photo		Load JPG	
133	20/02/18 15:47	Reinspection Photo		Load JPG	
134	20/02/18 15:47	Reinspection Photo		Load JPG	
135	20/02/18 15:47	Reinspection Photo		Load JPG	
136	20/02/18 15:47	Reinspection Photo		Load JPG	
137	20/02/18 15:47	Reinspection Photo		Load JPG	
138	20/02/18 15:47	Reinspection Photo		Load JPG	
139	20/02/18 15:47	Reinspection Photo		Load JPG	
140	20/02/18 15:47	Reinspection Photo		Load JPG	
141	20/02/18 15:47	Reinspection Photo		Load JPG	
142	20/02/18 15:47	Reinspection Photo		Load JPG	
143	20/02/18 15:47	Reinspection Photo		Load JPG	
144	20/02/18 15:47	Reinspection Photo		Load JPG	
145	20/02/18 15:47	Reinspection Photo		Load JPG	
146	20/02/18 15:47	Reinspection Photo		Load JPG	
147	20/02/18 15:47	Reinspection Photo		Load JPG	
148	20/02/18 15:47	Reinspection Photo		Load JPG	
149	20/02/18 15:47	Reinspection Photo		Load JPG	
150	20/02/18 15:47	Reinspection Photo		Load JPG	
151	20/02/18 15:47	Reinspection Photo		Load JPG	
152	20/02/18 15:47	Reinspection Photo		Load JPG	
153	20/02/18 15:47	Reinspection Photo		Load JPG	
154	20/02/18 15:47	Reinspection Photo		Load JPG	
155	20/02/18 15:47	Reinspection Photo		Load JPG	
156	20/02/18 15:47	Reinspection Photo		Load JPG	
157	20/02/18 15:47	Reinspection Photo		Load JPG	
158	20/02/18 15:47	Reinspection Photo		Load JPG	
159	20/02/18 15:47	Reinspection Photo		Load JPG	
160	20/02/18 15:47	Reinspection Photo		Load JPG	
161	20/02/18 15:47	Reinspection Photo		Load JPG	

162	20/02/18 15:47	Reinspection Photo		Load JPG	
163	20/02/18 15:47	Reinspection Photo		Load JPG	
164	20/02/18 15:47	Reinspection Photo		Load JPG	
165	20/02/18 15:47	Reinspection Photo		Load JPG	
166	20/02/18 15:47	Reinspection Photo		Load JPG	
167	20/02/18 15:47	Reinspection Photo		Load JPG	
168	20/02/18 15:47	Reinspection Photo		Load JPG	
169	20/02/18 15:47	Reinspection Photo		Load JPG	
170	20/02/18 15:47	Reinspection Photo		Load JPG	
171	20/02/18 15:47	Reinspection Photo		Load JPG	
172	20/02/18 15:47	Reinspection Photo		Load JPG	
173	20/02/18 15:47	Reinspection Photo		Load JPG	
174	20/02/18 15:47	Reinspection Photo		Load JPG	
175	20/02/18 15:47	Reinspection Photo		Load JPG	
176	20/02/18 15:47	Reinspection Photo		Load JPG	
177	20/02/18 15:47	Reinspection Photo		Load JPG	
178	20/02/18 15:47	Reinspection Photo		Load JPG	
179	20/02/18 15:47	Reinspection Photo		Load JPG	
180	20/02/18 15:47	Reinspection Photo		Load JPG	
181	20/02/18 15:47	Reinspection Photo		Load JPG	
182	20/02/18 15:47	Reinspection Photo		Load JPG	
183	20/02/18 15:47	Reinspection Photo		Load JPG	
184	20/02/18 15:47	Reinspection Photo		Load JPG	
185	20/02/18 15:47	Reinspection Photo		Load JPG	
186	20/02/18 15:47	Reinspection Photo		Load JPG	
187	20/02/18 15:47	Reinspection Photo		Load JPG	
188	20/02/18 15:47	Reinspection Photo		Load JPG	
189	20/02/18 15:47	Reinspection Photo		Load JPG	
190	20/02/18 15:47	Reinspection Photo		Load JPG	
191	20/02/18 15:47	Reinspection Photo		Load JPG	
192	20/02/18 15:47	Reinspection Photo		Load JPG	
193	20/02/18 15:47	Reinspection Photo		Load JPG	
194	20/02/18 15:47	Reinspection Photo		Load JPG	
195	20/02/18 15:47	Reinspection Photo		Load JPG	
196	20/02/18 15:47	Reinspection Photo		Load JPG	
197	20/02/18 15:47	Reinspection Photo		Load JPG	
198	20/02/18 15:47	Reinspection Photo		Load JPG	
199	20/02/18 15:47	Reinspection Photo		Load JPG	
200	20/02/18 15:47	Reinspection Photo		Load JPG	
201	20/02/18 15:47	Reinspection Photo		Load JPG	
202	20/02/18 15:47	Reinspection Photo		Load JPG	
203	20/02/18 15:47	Reinspection Photo		Load JPG	
204	20/02/18 15:47	Reinspection Photo		Load JPG	
205	20/02/18 15:47	Reinspection Photo		Load JPG	
206	20/02/18 15:47	Reinspection Photo		Load JPG	
207	20/02/18 15:47	Reinspection Photo		Load JPG	
208	20/02/18 15:47	Reinspection Photo		Load JPG	
209	20/02/18 15:47	Reinspection Photo		Load JPG	

210	20/02/18 15:47	Reinspection Photo	1	Load JPG	
211	20/02/18 15:47	Reinspection Photo	1	Load JPG	
212	20/02/18 15:47	Reinspection Photo	1	Load JPG	
213	20/02/18 15:47	Reinspection Photo	1	Load JPG	
214	20/02/18 15:47	Reinspection Photo	1	Load JPG	
215	20/02/18 15:47	Reinspection Photo	1	Load JPG	
216	20/02/18 15:47	Reinspection Photo	1	Load JPG	
217	20/02/18 15:47	Reinspection Photo	1	Load JPG	
218	20/02/18 15:47	Reinspection Photo	1	Load JPG	
219	20/02/18 15:47	Reinspection Photo	1	Load JPG	
220	20/02/18 15:47	Reinspection Photo	1	Load JPG	
221	20/02/18 15:47	Reinspection Photo	1	Load JPG	
222	20/02/18 15:47	Reinspection Photo	1	Load JPG	
223	20/02/18 15:47	Reinspection Photo	1	Load JPG	
224	20/02/18 15:47	Reinspection Photo	1	Load JPG	
225	20/02/18 15:47	Reinspection Photo	1	Load JPG	
226	20/02/18 15:47	Reinspection Photo	1	Load JPG	
227	20/02/18 15:47	Reinspection Photo	1	Load JPG	
228	20/02/18 15:47	Reinspection Photo	1	Load JPG	
229	20/02/18 15:47	Reinspection Photo	1	Load JPG	
230	20/02/18 15:47	Reinspection Photo	1	Load JPG	
231	20/02/18 15:47	Reinspection Photo	1	Load JPG	
232	20/02/18 15:47	Reinspection Photo	1	Load JPG	
233	20/02/18 15:47	Reinspection Photo	1	Load JPG	
234	20/02/18 15:47	Reinspection Photo	1	Load JPG	
235	20/02/18 15:47	Reinspection Photo	1	Load JPG	
236	20/02/18 15:47	Reinspection Photo	1	Load JPG	
237	20/02/18 15:47	Reinspection Photo	1	Load JPG	
238	20/02/18 15:47	Reinspection Photo	1	Load JPG	
239	20/02/18 15:47	Reinspection Photo	1	Load JPG	
240	20/02/18 15:47	Reinspection Photo	1	Load JPG	
241	20/02/18 15:48	Reinspection Photo	1	Load JPG	
242	20/02/18 15:48	Reinspection Photo	1	Load JPG	
243	20/02/18 15:48	Reinspection Photo	1	Load JPG	
244	20/02/18 15:48	Reinspection Photo	1	Load JPG	
245	20/02/18 15:48	Reinspection Photo	1	Load JPG	
246	20/02/18 15:48	Reinspection Photo	1	Load JPG	
247	20/02/18 15:48	Reinspection Photo	1	Load JPG	
248	20/02/18 15:48	Reinspection Photo	1	Load JPG	
249	20/02/18 15:48	Reinspection Photo	1	Load JPG	
250	20/02/18 15:48	Reinspection Photo	1	Load JPG	
251	20/02/18 15:48	Reinspection Photo	1	Load JPG	
Documentation			1 per page ▼		
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 16:48	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	12/12/17 16:48	Sketch Plan #2 [Linked Accident Report Documents]	1	Load TIF	
3	12/12/17 16:51	IC & DL	1	Load TIF	

		[Linked Accident Report Documents]			
4	12/12/17 16:51	INS CERT [Linked Accident Report Documents]		Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/12/17 15:09	GBE 4827E MARKED ESTIMATE		Load PDF	

Linked Accident Report Documents

View

View In Browser

Assessment Reports			1 per page		
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 16:56	Accident Statement		Load HTM	
Photos/Images			3 per page		
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 16:50	Accident Photo		Load JPG	
2	12/12/17 16:50	Accident Photo		Load JPG	
3	12/12/17 16:50	Accident Photo		Load JPG	
4	12/12/17 16:50	Accident Photo		Load JPG	
5	12/12/17 16:50	Accident Photo		Load JPG	
6	12/12/17 16:50	Accident Photo		Load JPG	
7	12/12/17 16:50	Accident Photo		Load JPG	
8	12/12/17 16:50	Accident Photo		Load JPG	
9	12/12/17 16:54	Accident Photo		Load JPG	
Documentation			1 per page		
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 16:48	Sketch Plan		Load TIF	
2	12/12/17 16:48	Sketch Plan #2		Load TIF	
3	12/12/17 16:51	IC & DL		Load TIF	
4	12/12/17 16:51	INS CERT		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

//

Show Remarks To: ☒ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI17024014/ARD3E2**Date:** 12/03/2018**REFERENCE**

Insured/Claimant: **TECK WEI LEASING (S) PTE LTD** Policy No: **DMCVSN1557061601**
Date of Loss: **02/12/2017** Nature of Claim: **OD** Claim No: **SNM17D07057C01**

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE4827E**
Make & Model: **TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)** Engine No: **1KD2572150**
Reg. Date: **16/12/2015 (Man. Year: 2015)** Chassis No: **JTFAT35Y80K205525**
Colour: **Silver** Odometer: **0 km**
Engine Capacity: **2982 cc**
Market Value/New Car Price: **S\$65,000.00**
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): **Yes** Footbrake (Serviceable): **Yes**
Handbrake (Serviceable): **Yes** Engine Modification: **No** Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: **195 R15C** Rear Tyre Size: **155 R12C**
Front Left Side: **Firemax 6 mm** Rear Left Side: **Bridgestone 4 mm**
Front Right Side: **Firemax 6 mm** Rear Right Side: **Bridgestone 4 mm**

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,390.21	33,996.41	22,393.80	39.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,859.37	6,859.37	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	63,249.58	40,855.78	22,393.80	35.41
Approved Total (Overridden) (S\$)		32,600.00		
- Excess (S\$)	0.00	4,500.00	-4,500.00	
(S\$)	63,249.58	28,100.00	35,149.58	55.57
+ GST 7.00/7.00% (S\$)	4,427.47	1,967.00	2,460.47	55.57
Nett Amount (S\$)	67,677.05	30,067.00	37,610.05	55.57

INSPECTION

Date of Assignment: **18/12/2017** Present Location: **Auto N Cars Services Pte Ltd (HQ)**
Date Inspected: **19/12/2017** Inspected At: **Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit**
Estimated Period of Repair: **25.0 days** **Singapore 417883**

Adjuster: ADRIAN LING**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Mar 2018)

Parts: N/A TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE4827E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*A/C CONDENSER BRKT (WCP)	Distorted	250.00 F	*250.00 F
2	1		*AC COND SUPP BRKT (WCP)	Distorted	75.00 F	*75.00 F
3	1		*ALTERNATOR (WCP)	Cracked	950.00 F	*950.00 F
4	1		*BADGE (WCP)	Necessary	38.00 F	*38.00 F
5	1		*BADGE DYNA (WCP)	Necessary	30.00 F	*30.00 F
6	1		*CAB PROTECT GRILLE (WCP)	Missing	580.00 F	*580.00 F
7	1		*CABIN SAFETY LOCK (WCP)	Damaged	220.00 F	*220.00 F
8	1		*COMBI INSTRUMENT (WCP)	Cracked	650.00 F	*650.00 F
9	1		*COMBINATION SWITCH (WCP)	Damaged	450.00 F	*450.00 F
10	1		*COMPL LWR FRT PANEL (WCP)	Distorted	580.00 F	*580.00 F
11	1		*COMPR/CONDENSER TUBE (WCP)	Not Necessary	420.00 F	*- F
12	1		*CONDENSER (WCP)	Distorted	380.00 F	*380.00 F
13	1		*COOLING FAN (WCP)	Distorted	70.00 F	*70.00 F
14	1		*CTR INSTR PANEL TRIM (WCP)	Cracked	185.00 F	*185.00 F
15	1		*DRIVE BELT TENSIONER (WCP)	Not Necessary	80.00 F	*- F
16	1		*DRYER BOTTLE (WCP)	Not Necessary	95.00 F	*- F
17	1		*END MOULDING (WCP)	Not Necessary	130.00 F	*- F
18	1		*ENGINE CONTROL UNIT (WCP)	Cracked	2,850.00 F	*2,850.00 F
19	1		*F/ROOF INN PANEL (WCP)	Distorted	205.00 F	*205.00 F
20	1		*FAN (WCP)	Not Necessary	217.00 F	*- F
21	1		*FAN HOUSING (WCP)	Cracked	195.00 F	*195.00 F
22	1		*FAN MOTOR (WCP)	Not Necessary	140.00 F	*- F
23	1		*FRONT BUMPER (WCP)	Distorted	280.00 F	*280.00 F
24	1		*FRONT FLOOR CARPET (WCP)	Torn	210.00 F	*210.00 F
25	1		*FRONT FLOOR PANEL (WCP)	Distorted	850.00 F	*850.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRONT PANEL (WCP)	Distorted	480.00 F	*480.00 F
27	1		*FRONT STABILISER (WCP)	Not Necessary	250.00 F	*- F
28	1		*FUSE BOX (WCP)	Cracked	230.00 F	*230.00 F
29	1		*GEARBOX MTG (WCP)	Damaged	95.00 F	*95.00 F
30	1		*GLOVEBOX (WCP)	Distorted	195.00 F	*195.00 F
31	1		*GRILLE (WCP)	Missing	180.00 F	*180.00 F
32	1		*HEADLINING (WCP)	Crumpled	210.00 F	*210.00 F
33	1		*HEATER BLOWER CPL (WCP)	Cracked	1,100.00 F	*1,100.00 F
34	1		*HEATER CPL (WCP)	Cracked	1,780.00 F	*1,780.00 F
35	1		*INSTR PANEL WIRING (WCP)	Not Necessary	480.00 F	*- F
36	1		*INSTRUMENT PANEL (WCP)	Distorted	680.00 F	*680.00 F
37	1		*INSTRUMENT PNL TRIM (WCP)	Cracked	35.00 F	*35.00 F
38	1		*INSTRUMENT SUPPORT (WCP)	Bent	380.00 F	*380.00 F
39	1		*L/A-PILLAR COVER (WCP)	Deformed	35.00 F	*35.00 F
40	1		*L/DOOR GLASS INN (WCP)	Distorted	45.00 F	*45.00 F
41	1		*L/DOOR GLASS OUT (WCP)	Cut	95.00 F	*95.00 F
42	1		*L/DOOR MIRROR GLASS (WCP)	Shattered	98.00 F	*98.00 F
43	1		*L/DOOR PILLAR WSTRIP (WCP)	Cut	105.00 F	*105.00 F
44	1		*L/DOOR RUBB BEADING (WCP)	Cut	195.00 F	*195.00 F
45	1		*L/DOOR SEAL (WCP)	Necessary	98.00 F	*98.00 F
46	1		*L/END MOULDING (WCP)	Not Necessary	58.00 F	*- F
47	1		*L/F BADGE (WCP)	Not Necessary	50.00 F	*- F
48	1		*L/F DOOR ASH TRAY (WCP)	Not Necessary	48.00 F	*- F
49	1		*L/F DOOR CHECK (WCP)	Bent	70.00 F	*70.00 F
50	1		*L/F DOOR OUT HANDLE (WCP)	Damaged	110.00 F	*110.00 F
51	1		*L/F DOOR TRIM (WCP)	Cracked	380.00 F	*380.00 F
52	1		*L/F DOOR WINDOW (WCP)	Shattered	250.00 F	*250.00 F
53	1		*L/F FLOOR SIDE PANEL (WCP)	Repair	350.00 F	*- F
54	1		*L/F INN DOOR HANDLE (WCP)	Damaged	45.00 F	*45.00 F
55	1		*L/F INN WHEEL BRG (WCP)	Necessary	150.00 F	*150.00 F
56	1		*L/F LOWER DOOR HINGE (WCP)	Bent	55.00 F	*55.00 F
57	1		*L/F LOWER END PANEL (WCP)	Not Necessary	95.00 F	*- F
58	1		*L/F LWR AXLE ARM (WCP)	Bent	350.00 F	*350.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
59	1		*L/F LWR D/F RAME SEAL (WCP)	Necessary	58.00 F	*58.00 F
60	1		*L/F MUDFLAP (WCP)	Deformed	110.00 F	*110.00 F
61	1		*L/F OUT WHEEL BRG (WCP)	Necessary	150.00 F	*150.00 F
62	1		*L/F SHOCK ABSORBER (WCP)	Bent	90.00 F	*90.00 F
63	1		*L/F STEERING KNUCKLE (WCP)	Bent	850.00 F	*850.00 F
64	1		*L/F STEP (WCP)	Distorted	130.00 F	*130.00 F
65	1		*L/F STEP COVER (WCP)	Distorted	135.00 F	*135.00 F
66	1		*L/F UPPER AXLE LINK (WCP)	Bent	570.00 F	*570.00 F
67	1		*L/F UPPER DOOR HINGE (WCP)	Bent	55.00 F	*55.00 F
68	1		*L/F UPPER END PANEL (WCP)	Not Necessary	95.00 F	*- F
69	1		*L/F WINDOW MOTOR (WCP)	Damaged	205.00 F	*205.00 F
70	1		*L/F WINDOW REGULATOR (WCP)	Damaged	180.00 F	*180.00 F
71	1		*L/HEADLAMP TRIM (WCP)	Missing	20.00 F	*20.00 F
72	1		*L/INN DOOR LOCK (WCP)	Jammed	210.00 F	*210.00 F
73	1		*L/INNER A-PILLAR (WCP)	Distorted	320.00 F	*320.00 F
74	1		*L/LOCKING CLIP (WCP)	Necessary	280.00 F	*20.00 F
75	1		*L/LOWER DRIP RAIL (WCP)	Not Necessary	90.00 F	*- F
76	1		*L/OUTER A-PILLAR (WCP)	Distorted	420.00 F	*420.00 F
77	1		*L/R CORNER PILLAR (WCP)	Repair	350.00 F	*- F
78	1		*L/SUN VISOR (WCP)	Not Necessary	95.00 F	*- F
79	1		*L/WINDOW CHANNEL (WCP)	Distorted	158.00 F	*158.00 F
80	1		*L/WING MIRROR ARM (WCP)	Missing	250.00 F	*250.00 F
81	1		*L/WING MIRROR CVR (WCP)	Missing	25.00 F	*25.00 F
82	1		*L/WING MIRROR ROUND (WCP)	Missing	38.00 F	*38.00 F
83	1		*LEFT ENGINE SUPPORT (WCP)	Damaged	150.00 F	*150.00 F
84	1		*LEFT FRONT DOOR (WCP)	Distorted	950.00 F	*950.00 F
85	1		*LEFT HEADLAMP ASSY (WCP)	Missing	320.00 F	*320.00 F
86	1		*LEFT SPEAKER (WCP)	Damaged	80.00 F	*80.00 F
87	1		*LH CANOPY CANVAS (WCP)	Not Necessary	180.00 F	*- F
88	1		*LWR INSTR PANEL TRIM (WCP)	Not Necessary	95.00 F	*- F
89	1		*R/A-PILL GRAB HANDLE (WCP)	Not Necessary	48.00 F	*- F
90	1		*R/A-PILLAR COVER (WCP)	Distorted	35.00 F	*35.00 F
91	1		*R/COWL PANEL COVER (WCP)	Not Necessary	55.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
92	1		*R/DOOR MIRROR ASSY (WCP)	Distorted	180.00 F	*180.00 F
93	1		*R/DOOR OUT WSTRIP (WCP)	Cut	95.00 F	*95.00 F
94	1		*R/DOOR RUBB BEADING (WCP)	Cut	195.00 F	*195.00 F
95	1		*R/DOOR SEAL (WCP)	Cut	98.00 F	*98.00 F
96	1		*R/DROP SIDE (WCP)	Dented	1,550.00 F	*1,550.00 F
97	1		*R/END MOULDING (WCP)	Not Necessary	58.00 F	*- F
98	1		*R/F BADGE (WCP)	Not Necessary	50.00 F	*- F
99	1		*R/F DOOR CHECK (WCP)	Bent	70.00 F	*70.00 F
100	1		*R/F DOOR FRAME SEAL (WCP)	Cut	105.00 F	*105.00 F
101	1		*R/F DOOR OUT HANDLE (WCP)	Cut	110.00 F	*110.00 F
102	1		*R/F DOOR TRIM (WCP)	Deformed	380.00 F	*380.00 F
103	1		*R/F DOOR WINDOW (WCP)	Shattered	250.00 F	*250.00 F
104	1		*R/F INN WHEEL BRG (WCP)	Not Necessary	150.00 F	*- F
105	1		*R/F LOWER AXLE ARM (WCP)	Not Necessary	350.00 F	*- F
106	1		*R/F LOWER DOOR HINGE (WCP)	Bent	55.00 F	*55.00 F
107	1		*R/F LOWER END PANEL (WCP)	Not Necessary	95.00 F	*- F
108	1		*R/F LWR D/F RAME SEAL (WCP)	Necessary	58.00 F	*58.00 F
109	1		*R/F OUT WHEEL BRG (WCP)	Not Necessary	150.00 F	*- F
110	1		*R/F SHOCK ABSORBER (WCP)	Not Necessary	90.00 F	*- F
111	1		*R/F STEERING KNUCKLE (WCP)	Not Necessary	850.00 F	*- F
112	1		*R/F STEP (WCP)	Not Necessary	130.00 F	*- F
113	1		*R/F STEP COVER (WCP)	Not Necessary	135.00 F	*- F
114	1		*R/F UPPER AXLE LINK (WCP)	Not Necessary	590.00 F	*- F
115	1		*R/F UPPER DOOR HINGE (WCP)	Bent	55.00 F	*55.00 F
116	1		*R/F UPPER END PANEL (WCP)	Not Necessary	95.00 F	*- F
117	1		*R/F WINDOW REGULATOR (WCP)	Damaged	180.00 F	*180.00 F
118	1		*R/INN DOOR LOCK (WCP)	Jammed	210.00 F	*210.00 F
119	1		*R/INNER A-PILLAR (WCP)	Distorted	320.00 F	*320.00 F
120	1		*R/LOCKING CLIP (WCP)	Necessary	280.00 F	*20.00 F
121	1		*R/OUTER A-PILLAR (WCP)	Distorted	420.00 F	*420.00 F
122	1		*R/R CORNER PILLAR (WCP)	Repair	350.00 F	*- F
123	1		*R/SUN VISOR (WCP)	Deformed	95.00 F	*95.00 F
124	1		*R/WINDOW CHANNEL (WCP)	Damaged	158.00 F	*158.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
125	1		*RACK/PINION STEERING (WCP)	Not Necessary	4,340.00 F	*- F
126	1		*RADIATOR (WCP)	Cracked	1,932.00 F	*1,932.00 F
127	1		*RADIATOR FAN CLUTCH (WCP)	Not Necessary	766.00 F	*- F
128	1		*RADIATOR SHROUD (WCP)	Cracked	237.00 F	*237.00 F
129	1		*REAR CANOPY (WCP)	Not Necessary	2,500.00 F	*- F
130	1		*REAR SCREEN BOND KIT (WCP)	Necessary	38.18 F	*38.18 F
131	1		*REAR SCREEN INN SEAL (WCP)	Necessary	32.32 F	*32.32 F
132	1		*RH CANOPY CANVAS (WCP)	Not Necessary	180.00 F	*- F
133	1		*RIGHT ENGINE SUPPORT (WCP)	Not Necessary	150.00 F	*- F
134	1		*RIGHT FRONT DOOR (WCP)	Distorted	950.00 F	*950.00 F
135	1		*RIGHT HEADLAMP ASSY (WCP)	Cracked	320.00 F	*320.00 F
136	1		*RIGHT SEAT BELT (WCP)	Not Necessary	516.00 F	*- F
137	1		*ROOF (WCP)	Distorted	580.00 F	*580.00 F
138	1		*ROOF LIGHT (WCP)	Not Necessary	45.00 F	*- F
139	1		*RR COMPR/EVAPOR PIPE (WCP)	Not Necessary	550.00 F	*- F
140	1		*SHIFT LINKAGE (WCP)	Not Necessary	500.00 F	*- F
141	1		*STEERING COLUMN CPL (WCP)	Not Necessary	3,950.00 F	*- F
142	1		*STRG GUIDE LEVER (WCP)	Not Necessary	450.00 F	*- F
143	1		*UPP RAD GRILLE SEAL (WCP)	Not Necessary	35.00 F	*- F
144	1		*UPPER FRONT PANEL (WCP)	Bent	130.00 F	*130.00 F
145	1		*WASHER RESERVOIR (WCP)	Not Necessary	80.00 F	*- F
146	1		*WINDSCREEN (WCP)	Shattered	750.00 F	*750.00 F
147	1		*WINDSCREEN BOND KIT (WCP)	Necessary	38.18 F	*38.18 F
148	1		*WINDSCREEN SEAL (WCP)	Necessary	140.00 F	*60.00 F
149	1		*WIPER MOTOR (WCP)	Not Necessary	65.00 F	*- F
150	1		*WIPER TANK HOSE (WCP)	Not Necessary	15.00 F	*- F
151	1		*Sundry Parts	Necessary	100.00 FS	*100.00 FS
152	1		*FRT NO PLATE	Bent	40.00 FS	*40.00 FS
153	1		*IU BRACKET	Necessary	15.00 FS	*15.00 FS
154	1		*L/DOOR REG STICKER	Necessary	20.00 FS	*20.00 FS
155	1		*L/F TYRE RIM	Cut	180.00 FS	*180.00 FS
156	1		*L/R TYRE RIM	Cut	120.00 FS	*120.00 FS
157	1		*L/F TYRE	Cut	255.00 FS	*180.00 FS
158	1		*R/DOOR REG STICKER	Necessary	20.00 FS	*20.00 FS
159	1		*AUDATEX FEE		42.00 FS	*42.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	53,742.68	32,411.68
+ Margin on L,N Items 5.00/5.00% (\$\$)	2,647.53	1,584.73

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					56,390.21	33,996.41
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Panel/Mechanical	New	5,142.80	5,142.80
2	Total Paintwork	New	1,269.60	1,269.60
3	Total Paint/Material Costs	New	446.97	446.97
Gross Labour Cost (S\$)			6,859.37	6,859.37

Report was unsubmitted during this print-out.

< END OF ESTIMATES >