

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2018)
Parts:	143	TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG6379M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID (CONSISTENT)	Buckled	781.20 F	*781.20 FL
2	2		*REAR BOOT LID HINGES (CONSISTENT)	Not Necessary	365.00 F	*- FL
3	1		*REAR BOOT LID EMBLEM LOGO (CONSISTENT)	Not Necessary	61.00 F	*- FL
4	1		*REAR BOOT LID AXIO LOGO (CONSISTENT)	Necessary	61.00 F	*61.00 FL
5	1		*REAR BOOT LID X LOGO (CONSISTENT)	Necessary	53.90 F	*53.90 FL
6	1		*REAR BOOT LID CENTER MOULDING (CONSISTENT)	Not Necessary	171.20 F	*- FL
7	2		*REAR BOOT LID NUMBER PLATE LAMP (CONSISTENT)	Not Necessary	167.80 F	*- FL
8	1		*REAR BOOT LID NUMBER PLATE (CONSISTENT)	Not Necessary	50.00 F	*- FL
9	1		*REAR BOOT LID INNER LOCK (CONSISTENT)	Damaged	181.10 F	*181.10 FL
10	1		*REAR BOOT LID INNER RUBBER (CONSISTENT)	Cut	182.75 F	*182.75 FL
11	1		*REAR BOOT LID INNER TRIM BOARD (CONSISTENT)	Not Necessary	381.20 F	*- FL
12	10		*REAR BOOT LID INNER TRIM BOARD CLIPS (CONSISTENT)	Not Necessary	65.00 F	*- FL
13	2		*REAR TAIL LAMP (CONSISTENT)	Cracked	650.00 F	*650.00 FL
14	2		*REAR TAIL LAMP CLIPS (CONSISTENT)	Necessary	34.00 F	*34.00 FL
15	1		*REAR TAIL LAMP PANEL (CONSISTENT)	O/s Dented	365.00 F	*182.50 FL
16	1		*REAR BUMPER (CONSISTENT)	Deformed	680.20 F	*680.20 FL
17	2		*REAR BUMPER SIDE BRACKET OUTER (CONSISTENT)	Necessary	263.50 F	*97.00 FL
18	2		*REAR BUMPER SIDE BRACKET INNER (CONSISTENT)	Damaged	243.00 F	*105.00 FL
19	10		*REAR BUMPER CLIPS (CONSISTENT)	Necessary	65.00 F	*30.00 FL
20	2		*REAR BUMPER BRACKET (CONSISTENT)	Dented	111.20 F	*111.20 FL
21	1		*REAR END PANEL (CONSISTENT)	Dented	581.20 F	*581.20 FL
22	1		*REAR END PANEL TOP GARNISH (CONSISTENT)	Deformed	160.90 F	*160.90 FL
23	2		*REAR FENDER INNER TRIM BOARD (CONSISTENT)	Torn	656.00 F	*656.00 FL
24	10		*REAR FENDER INNER TRIM BOARD CLIPS (CONSISTENT)	Necessary	65.00 F	*65.00 FL
25	2		*REAR FENDER (CONSISTENT)	Repair	1,962.00 F	*- FL
26	1		*REAR SPARE TYRE PANEL (CONSISTENT)	Repair	681.35 F	*- FL
27	1		*REAR SPARE TYRE PANEL SEALANT (CONSISTENT)	Not Necessary	250.00 F	*- FL
28	1		*REAR SPARE TYRE PANEL TOP COVER (CONSISTENT)	Deformed	381.35 F	*381.35 FL
29	1		*REAR EXHAUST (CONSISTENT)	Bent	980.20 F	*880.10 FL
30	2		*REAR TAIL LAMP INNER SPONGE (CONSISTENT)	Necessary	167.00 FS	*40.00 FS
31	1		*REAR BUMPER REVERSE SENSOR (CONSISTENT)	Damaged	350.00 FS	*200.00 FS
32	1		*GUM (CONSISTENT)		50.00 FS	*- FS

Report was unsubmitted during this print-out.