


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF2T  
Ref. No : TAX/12/17/2046  
Reg. Date : 03/11/2017  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS4  
Name of Driver : ZERIS DOUGLAS  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 07/12/2017 09:25:00 PM  
Accident Reported Date / Time : 08/12/2017 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024093662  
Special Instruction to ARC, if any :  
SJW6888B  
Prepared Date : 18/12/2017 09:29:38 AM



**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian.

19/12/2017.

- Part by part repair.

- Photo After Paint.

90036121

sebastian.yang@lkkauto.com.

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU103573728

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 1,245.35	1,245.35
Other Charges	: 460.00	0.00
<b>TOTAL</b>	<b>: 2,979.35</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sign Off Date	: 18/12/2017 03:48:55 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 18/12/2017 03:48:55 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	338.00	0.00 <i>200</i>
<b>Total Labour</b>	<b>338.00</b>	<b>0.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 <i>200</i>
TO RESPRAY FRONT FENDER LH	378.00	0.00 <i>200</i>
TO RESPRAY VIEW MIRROR	180.00	0.00 <i>50</i>
<b>Total Spray Painting &amp; Panel Beating</b>	<b>936.00</b>	<b>0.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 <i>X</i>
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 <i>X</i>
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 <i>30</i>
TO REPLACE SUNDRY PARTS	100.00	0.00 <i>20</i>
TO WASH AND VACUUM	60.00	0.00 <i>X</i>
<b>Total Other Costs</b>	<b>460.00</b>	<b>0.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace R	No
5380247100			FENDER SUB-ASSY, FR , LH	1	933.10	25.00	699.82	Replace	Replace R	No
7537447140			EMBLEM, SIDE PANEL ( HYBRID)	1	52.90	25.00	39.67	Replace	Replace ✓ NED	No
8794547060A1			COVER, OUTER MIRROR, LH	1	89.50	25.00	67.12	Replace	Replace R	No
TOTAL MATERIALS							1,178.25	1,178.23		
TOTAL MATERIALS(Discounted)							1,245.35	1,245.35		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									