

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 28 Dec 2017

Preliminary Advice

Insured Vehicle No	: SGF1312D		
TP Vehicle No	: GBF5199Y	Accident Date	: 12/12/2017
Make	: TOYOTA HIACE	Assignment Date	: 19/12/2017
Date of Inspection	: 27/12/2017	Est. Duration of Repair	: 3.00
Inspection At	: AUTO WHEELS MOTORWORKS PTE LTD (HQ) 48 TOH GUAN ROAD EAST ENTERPRISE #04-142 SINGAPORE 608586		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,382.83
Revised Amount	:S\$	1,527.55
Check Items (Estimated)	:S\$	250.00
Total	:S\$	1,777.55

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.