

ASS. REC. BY:

REF: CS/FCI17024047/K19d3<sup>n2</sup>

Special Instruction:

Supervisor: kalvin ASSIGNMENT (Office)

From (Person): aws Sithara of FCI Date/Time: 1:37pm @ 19/12/17

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6033E Insured: SHA 9731P

at Workshop m/s Premier Automotive Tel: 65446671

of 23 Changi South Ave 2 # 03-02

Policy No: D-15072707MFSH Claim No: D17011626MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 15/12/17  
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 2:18pm @ 19/12/17 Person Contacted: Gary Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6033E-NA/DAI17023903/r3 D.O.A. : 15/12/2017
	SHA 9731P-CC4/AXA15014100/H1243C2 D.O.A. : 17/08/2015
<u>20/12/17 @</u>	<u>2:57pm</u> revised to sithara by email.

Kalvin

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC/Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % S.Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Vehicle No: SHC6033E Reg: 13 Jun 2014  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / T/O / Prime Mover /  
 Truck / Trailer /  
 Make: KIA optima cc: 1600  
 Colour: silver A/C: Ins / Std / NI / NA  
 Sp. Reading: 34776 T/Radio: Ins / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 O No: 1CNA6M414MES46384  
 Gen. Cond: Good / PO / Poor / Burnt  
 Steering: Ins / Jammed / Leaked / Burnt or  
 Brake: Ins / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD / rim or  
 Tyre Size: F: 205/65R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /  
 TOYO / YOKO or: Ashtelley  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R.Bal. 7 mm R.Bal. 7 mm  
 L.Bal. 7 mm L.Bal. 7 mm  
 D.O.A. 15/12/12 D.O.I. 19/12/12  
 Survey held at: Premis  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Front / Rear  
 The U/C / Chassis frame / Body Structure affected due to collision

Date	Time	Action / Instruction
10/1/12		Checked up \$5000 / 5 days (Red \$ 7673.80, 61%) FCZ

RECEIVED 12 JAN 2012

Date/Time File Pass to?  : Preli. Report  
 10/1/12  : Final Report  
 Date/Time File Return to? \_\_\_\_\_  
 Days Of Repair: 5  
 Resurvey No. of Trip: 1  
 Add Fee:  Site Insd \$ \_\_\_\_\_  
 Interven \$ \_\_\_\_\_  
 Tech Ins \$ \_\_\_\_\_  
 Repairs \$ \_\_\_\_\_  
 Survey Fee Transportation \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Other \_\_\_\_\_  
 Report Format: TP  
 Lump Sum: 5000  

2X15=30
170+30
50
50
53
353



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17024047/K1qd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-12-2017



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9731P	Veh. Inspected	SHC 6033E
Policy No.		Coverage (\$)	0.00
Claim No.	D17011626MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	19/12/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	15/12/2017	Inspection Date	19/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Survey Department Check List (Case Handler)

Reference No. : CS/KC17024042/K19d3  
 Policy Type: OD/TP/TP RES/TL/EVA

SHC 6037E

Case Handler

Typist

**Admin** ( Nivetha ): Case handler to make sure all Information created by the assignment team are ACCURATE.

**(1) Office Assign Form**

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA/REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

**Surveyor** ( Calvin ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C Damaged Vehicle Photographs Uploaded	✓			
--	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N ALL Parts condition	✓			
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair	✓			
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C Resurvey photo Uploaded	✓			
---------------------------	---	--	--	--

Check By: [Signature] 11/1/18  
 Case Handler Date

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	18-12-2017	<b>Our Ref No.</b> D17011626MFSH
<b>Accident Date</b>	15-12-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA9731P	<b>Third Party Vehicle.</b> SHC6033E
<b>Survey Location</b>	23 CHANGI SOUTH AVENUE 2 #03-02	
<b>Contact Person.</b>	GARY SHI	
<b>Contact No.</b>	62148880/ 65446671	<b>Fax No.</b> 62141511
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SITHARA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232064)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D17011626MFSH	<b>Policy No</b>	D-15072702MFSH	<b>Claimant S.No &amp; Name</b>	1 & PREMIER , LTD
<b>Workshop Name</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GARY SHI)	<b>Survey Location &amp; Contact Details</b>	23 CHANGI SOUTH AVENUE 2 #03-02 <b>Mobile:</b> 65446671 , <b>Phone:</b> 62148880 , <b>Fax:</b> 6214151: <b>EmailId:</b> GARY.SHI@PREMIERTAXI.COM		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE:		
<b>Insured Name</b>	CITYCAB PTE LTD	<b>Insured Vehicle No</b>	SHA9731P	<b>TP Vehicle No</b>	SHC6033E
<b>PRI Recieved Date</b>	18-12-2017 09:25:34 PM	<b>Surveyor Appointed Date</b>	19-12-2017 01:36:43 PM	<b>Surveyor Accept Date</b>	19-12-2017 0.

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	19-12-2017	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 20 December, 2017 2:52 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** SITHARA@FIRST-INSURANCE.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D17011626MFSH/1  
**Attachments:** CSFCI17024047K1qd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SHC 6033E.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 19 December, 2017 2:34 PM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@first-insurance.com.sg](mailto:cwsmotorclaims@first-insurance.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SITHARA@FIRST-INSURANCE.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D17011626MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]  
**Sent:** Tuesday, 19 December, 2017 1:36 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [SITHARA@FIRST-INSURANCE.COM.SG](mailto:SITHARA@FIRST-INSURANCE.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D17011626MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011626MFSH

Date: 20 December 2017

Our Ref: CS/FCI17024047/K1qd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6033E**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/12/2017 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,673.80</u>
Revised Estimate Amount	: S\$ <u>5,156.40</u>
"Check" Items Amount	: S\$ <u>1,857.90</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the front and rear portion.



Yours faithfully

Kalvin Ang  
Automotive Assessor

Text size + -

### Enquire Transaction History

#### Transaction History Details

Log Date/Time:	13 Jun 2014 / 09:12:39	Receipt No.:	AACCK001-AX239-140613-000006
Asset Type:	Vehicle	Transaction Amount:	\$70,018.00
Asset ID:	SHC6033E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140613091239018880		

Vehicle No.:	SHC6033E
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	13 Jun 2014
Original Registration Date:	13 Jun 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5463514
Engine No.:	D4FDDH309735
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$20,028.00
Minimum PARF Benefit:	\$7,524.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	13 Jun 2014 09:12:39
COE No.:	2014061301001196G
COE Expiry Date:	12 Jun 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$57,338.00
Lifespan Expiry Date:	12 Jun 2022
Owner ID Type:	Company

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

19-Dec-17

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6033 E

1 pc	Boot lid <i>Paint</i>	\$	1,119.00
1 pc	Boot lid lock <i>X sue</i>	\$	99.00
1 pc	Bootlid lock cable <i>X sue</i>	\$	35.00
1 pc	Bootlid striker <i>X sue</i>	\$	21.00
1 pc	Bootlid emblem <i>— sue</i>	\$	27.00
1 pc	Bootlid CRDi <i>— sue</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X sue</i>	\$	96.00
1 pc	Boot lid lower garnish <i>X repair</i>	\$	290.00
2 pcs	Bootlid hinge @\$66 <i>X repair</i>	\$	132.00
1 pc	End panel <i>X repair</i>	\$	250.00
1 pc	End panel garnish <i>X sue</i>	\$	74.00
1 pc	Rear muffler assy <i>X sue</i>	\$	1,009.00
1 pc	Rear exhaust pipe hanger <i>X sue</i>	\$	49.00
1 pc	Rear bumper <i>— Paint</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X ✓ sue</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @\$29 <i>X sue</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>✓ sue</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>✓ sue</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @\$53.00 <i>✓ sue</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @\$18.00 <i>✓ sue</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @\$18 <i>✓ sue</i>	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @\$46.00 <i>X sue</i>	\$	92.00
1 pc	Bonnet grille <i>— sue</i>	\$	386.00
1 pc	Front bumper <i>— Paint</i>	\$	531.00
1 pc	Front bumper emblem <i>— sue</i>	\$	44.00
1 pc	Front bumper centre grille <i>— sue</i>	\$	174.00
1 pc	Front bumper inner lower garnish <i>X sue</i>	\$	134.00
1 pc	Front bumper tow hook cover <i>X sue</i>	\$	14.00
1 pc	Front bumper lip <i>X sue</i>	\$	52.00
1 pc	Front bumper lower stiffer <i>X sue</i>	\$	134.00
1 pc	Front bumper inner sponge <i>✓ sue</i>	\$	110.00
1 pc	Front bumper reinforcement <i>X repair</i>	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @\$16.00 <i>X sue</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @\$16.00 <i>X sue</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @\$16.00 <i>X sue</i>	\$	32.00
2 pcs	n/s & o/s headlamp @\$1028.00 <i>X sue</i>	\$	2,056.00
		\$	9,242.00
	Less 10%	\$	924.20
		\$	8,317.80

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6033 E**

**S/NETT**

1 set	Rear bumper clips — <i>nc</i>	\$	48.00
1 set	End panel inner garnish clips <i>X 11</i>	\$	30.00
1 set	Bootlid lower garnish clips <i>X 11</i>	\$	60.00
1 set	Bootlid stickers — <i>nc</i>	\$	100.00
1 set	Reverse sensor — <i>skate</i>	\$	<del>280.00</del> 200
1 pc	Front no. plate with casing — <i>part</i>	\$	<del>50.00</del> 35
1 pc	Front bumper clips — <i>nc</i>	\$	48.00
	Sundry <i>nc</i>	\$	<del>50.00</del> 20
	To dismantle / replace exhaust pipe	\$	<del>120.00</del> 50 <i>X 11</i>
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	<del>120.00</del> 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> 50
	To top up aircon gas	\$	<del>120.00</del> <i>X 11</i>
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the <del>the</del> end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard panel, etc	\$	<del>1,400.00</del> <sup>800</sup>
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, front bumper, bonnet grille	\$	<del>1,500.00</del> <sup>1080</sup>
	To apply rustproofing on the repaired and replaced panels.	\$	<del>250.00</del> <sup>50</sup> <i>X 50</i>
		\$	<u>12,673.80</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Kalin (UCKY)*

*M 19/12/07 1610hrs.*

*5 Days*

*4/5*

*After Repair photo*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC117024047/K1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9731P	Veh. Inspected	SHC 6033E
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17011626MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	19/12/2017
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5463514	Colour	SILVER
Odometer	347760	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	ACHILLES	7 mm
L/H Front Tyre	205/65 R16	ACHILLES	7 mm
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/12/2017	Inspection Date	19/12/2017
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6033E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOT LID	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK	SERVICEABLE	99.00	-
1	BOOTLID LOCK CABLE	SERVICEABLE	35.00	-
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
2	BOOTLID HINGE @\$66.00	TO REPAIR SEE LABOUR	132.00	-
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	END PANEL GARNISH	SERVICEABLE	74.00	-
1	REAR MUFFLER ASSY	SERVICEABLE	1,009.00	-
1	REAR EXHAUST PIPE HANGER	SERVICEABLE	49.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	CRACKED	108.00	108.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	SERVICEABLE	92.00	-
1	BONNET GRILLE	CRACKED	386.00	386.00
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER CENTRE GRILLE	CRACKED	174.00	174.00
1	FRONT BUMPER INNER LOWER GARNISH	SERVICEABLE	134.00	-

Report Ref No. CS/FCI17024047/K1qd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER TOW HOOK COVER	SERVICEABLE	14.00	-
1	FRONT BUMPER LIP	SERVICEABLE	52.00	-
1	FRONT BUMPER LOWER STIFFER	SERVICEABLE	134.00	-
1	FRONT BUMPER INNER SPONGE	TORN	110.00	110.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	328.00	-
2	FRONT BUMPER O/S & N/S SIDE RETAINER @\$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S UPPER BRACKET @\$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @\$16.00	SERVICEABLE	32.00	-
2	N/S & O/S HEADLAMP @\$1028.00	SERVICEABLE	2,056.00	-
	LESS 10% DISCOUNT		-924.20	-422.30
			8,317.80	3,800.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	FRONT NO PLATE WITH CASING (SN)	DENTED	50.00	35.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			666.00	451.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE/REPLACE EXHAUST PIPE.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO TOP UP AIRCON GAS.	NOT NECESSARY	120.00	-

Report Ref No. CS/FCI17024047/K1qd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO HEAT/WELD,CUT-OFF THE END PANEL,INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE FLOORBOARD PANEL,ETC.INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH,BOOTLID HINGE,END PANEL AND FRONT BUMPER REINFORCEMENT.		1,400.00	800.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID,BOOTLID LOWER GARNISH,REAR BUMPER,FLOORBOARD COMPARTMENT,END PANEL,FRONT BUMPER,BONNET GRILLE.		1,500.00	1,080.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		250.00	50.00
			3,690.00	2,000.00
<b>GRAND TOTAL</b>			<b>12,673.80</b>	<b>6,251.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,000.00</b>

Report Ref No. CS/FCI17024047/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.