

22/05/2017

ASS. REC. BY:

REF: CS/MSG17024059/Kvd3n2

Special Instruction:

ASSIGNMENT (Office)

SUPERVISOR:

Meimien

From (Person): Katherine Wong of MSIG Date/Time: 19/12/17 @ 4:08pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 5879P

Insured:

SKC 6833C

at Workshop m/s

S & H Motor

Tel:

6453 4730

of 160 Sin Ming Drive #07-02

Policy No:

27912077DMA

Claim No:

541282

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/12/2017

CA / REV / REP. / REV 24 HRS

(up)

20/12/2017

H.O.D. Endorsement:

Date/Time:

4:57pm @ 19/12/17

Person Contacted:

Cynthia

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SJV 5879P - CC4/AXA17017336/Sub3s2

D.O.A. : 31/08/2017

SKC 6833C - X

10/5/18

@ 4:03pm

① 2302-50 email confirmed with Doris (Real 114430, 3370)

(No LS)

10/5

REF: MSIG

ASSIGNMENT

From: _____ Date: 20/12/2017

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 5879P

at Workshop m/s S & H Motor
of 160 Sin Ming Drive #07-02

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.13.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJV 5879P Yr Regn: 02 10

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: _____

Make: *1 Honda Tucson* i.c.c. 1 PPPColour: *M. P. White* A/O: Insured / Std / NI / NA

Sp. Reading: 190686 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *KM11 JUD13 MBU 046862*Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size: F: 205/80R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 14/12/17

D.O.I. 20/12/17

Survey held at ☒Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/12 File pass to Catherine

21/12/17 Rev preli in merimen.

RECEIVED 11 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 11/5 - typist

Report Format: Merimen

Lump Sum / I.B.I. (\$) 2302.50

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

10

210

Survey Department Check List (Case Handler)

Reference No.: CS/MSG 170 24059/Kvd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 10/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17024059/Kvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 19-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKC 6833C	Veh. Inspected	SJV 5879P
Policy No.	27912077DMA	Coverage (\$)	0.00
Claim No.	541282	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/12/2017	Inspection Date
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 21 Dec 2017

Preliminary Advice

Insured Vehicle No :	SKC6833C	Accident Date	: 14/12/2017
TP Vehicle No :	SJV5879P	Assignment Date	: 19/12/2017
Make :	HYUNDAI TUCSON	Est. Duration of Repair	: 6.00
Date of Inspection :	20/12/2017		
Inspection At :	S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,605.69
Revised Amount	:S\$	1,643.20
Check Items (Estimated)	:S\$	1,338.80
Total	:S\$	2,982.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2017 14:54 Sendback Est	18 Dec 2017 15:08 S\$3,369.80	19 Dec 2017 16:08 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEE LAY KHIM CYNTHIA (LI LIQIN CYNTHIA), ID: S7721808D		
Main Claimant:	POK SAI SUAN, ID: S7536980H		
Vehicle Reg. No.:	SJV5879P	Date of Loss:	14/12/2017 19:00 - :59
Claim Type:	TP / 541282	Policy/Cover Note No.:	27912077DMA (Comprehensive) Coverage: 05/06/2017 - 04/06/2018
Vehicle Reg. No. (Insured):	SKC6833C	Policy No. (Claimant):	
		Excess:	
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/12/2017]		
Driver/Custodian (Insured):	LEE LAY KHIM CYNTHIA (LI LIQIN CYNTHIA) (), NRIC: S7721808D		
Adj Asg. Remarks:	please survey. car is in, Thank You.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Transfer Fee

Vehicle Details

Vehicle No.	SJV5879P
Vehicle Type	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	HYUNDAI
Vehicle Model	LM TUCSON 2.0L AUTO ABS D/AB S/R
Chassis No.	KMHJU81BMBU046862
Propellant	Petrol
Engine No.	G4KD9A288247
Engine Capacity	1998 cc
Maximum Power Output	122.0 kW (163 bhp)
Maximum Laden Weight	1980 kg
Unladen Weight	1403 kg
Year Of Manufacture	2010
Original Registration Date	01 Feb 2010
Lifespan Expiry Date	-
COE Category	B - Car (1601cc & above)
Quota Premium	\$19,190.00
COE Expiry Date	31 Jan 2020
Road Tax Expiry Date	31 Jan 2018
PARF Eligibility Expiry Date	31 Jan 2020
Inspection Due Date	31 Jan 2019
Intended Transfer Date	15 Dec 2017
CO2 Emission	-

The current road tax expiry is 31 Jan 2018. You may renew the road tax from 01 Nov 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 31 Jan 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 01 Feb 2018 to 31 Jul 2018)

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
----------------------------	---------------------	---------------------------



TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY

Policy No:

Vehicle Reg. **SJV5879P**

No.:

Party At UNKNOWN

Fault:

Driver (TP): POK SAI SUAN

Ref. No:

Date of Loss: 14/12/2017

Driveable?

Driver (Insured): LEE LAY KHIM
CYNTHIA

Make/Model: HYUNDAI TUCSON, 2.0 (A)

Vehicle Reg. Date: 01/02/2010

Vehicle WHITE

Colour:

Engine No: G4KD9A288247

Chassis No: KMHJU81BMBU046862

Odometer: 0 KM

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) *7 6 days*

*Not Authorised
Returning B4 pricing*

Description of AS ACCIDENT REPORT.
Accident/Loss

Present S & H MOTOR PTE LTD (SIN MING)
Location:

COST OF CLAIMS

Parts

Miscellaneous Items

Labour

Paintwork Labour

Towing

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

	Amount
Acknowledged by Repairer	1,449.80
Signature:	260.00
Date:	1,660.00
	0.00
	0.00

Gross Total (\$\$)	3,369.80
+ GST 7.00% (\$\$)	235.89
Nett Amount (\$\$)	3,605.69

This claim is handled by: MYINT MYINT THAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Dec 2017)

Parts: M1-SUV HYUNDAI TUCSON 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/SJV5879P/18/12/2017 15:08

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Rear Bumper	0.00	0.00	*265.00 F	✓
2	1		*Rear bumper reinforcement	0.00	0.00	*155.00 F	7
3	1		*RH bumper reflector	0.00	0.00	*68.00 F	✓
4	1		*LH bumper reflector	0.00	0.00	*68.00 F	X
5	1		*Rear bumper bomttom black cover	0.00	0.00	*240.00 F	✓
6	1		*Rear RH bumper retainer	0.00	0.00	*30.00 F	✓
7	1		*Rear LH bumper retainer	0.00	0.00	*30.00 F	X
8	1		*Rear body end panel	0.00	0.00	*295.00 F	7
9	1		*Tail door weather strip	0.00	0.00	*58.00 F	7
10	1		*Rear tailgate Hyundai badge	0.00	0.00	*30.00 F	X
11	1		*Rear tailgate Tucson badge	0.00	0.00	*32.00 F	X
12	1		*RH rear bumper tow cover	0.00	0.00	*19.00 F	✓
13	1		*Rear bumper clips	0.00	0.00	*28.00 F	✓

F=Franchise part.

Sub Total (S\$)	1,318.00
+ Margin on L,N Items 10.00% (S\$)	131.80
Total Parts (S\$)	1,449.80

S & H Motor Pte Ltd/SJV5879P/18/12/2017 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Bumper parking sensors	CTA 260.00 ^{200.00}
Sub Total (S\$)			260.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To spray painting the rear accident and repair areas	New	800.00 ⁶⁰⁰
2	Labour to remove , check for inner damaged, jack out rear body end panel, cut out end damaged panel, rewelding, renew, panel beating, install and adjust rear body, bumper alignment.	New	780.00 ⁷⁴⁸⁰
3	To remove and jack out rear exhaust box , repair and readjust exhaust alignment.	New	80.00 ⁶⁰
Gross Labour Cost (S\$)			1,660.00

S & H Motor Pte Ltd/SJV5879P/18/12/2017 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Dec 2017)
 Parts: M1-SUV HYUNDAI TUCSON 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: S & H Motor Pte Ltd/SJV5879P/18/12/2017 15:08
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear Bumper	0.00	0.00	*265.00 F
2	1		*Rear bumper reinforcement	0.00	0.00	*155.00 F
3	1		*RH bumper reflector	0.00	0.00	*68.00 F
4	1		*LH bumper reflector	0.00	0.00	*68.00 F
5	1		*Rear bumper bottom black cover	0.00	0.00	*240.00 F
6	1		*Rear RH bumper retainer	0.00	0.00	*30.00 F
7	1		*Rear LH bumper retainer	0.00	0.00	*30.00 F
8	1		*Rear body end panel	0.00	0.00	*295.00 F
9	1		*Tail door weather strip	0.00	0.00	*58.00 F
10	1		*Rear tailgate Hyundai badge	0.00	0.00	*30.00 F
11	1		*Rear tailgate Tucson badge	0.00	0.00	*32.00 F
12	1		*RH rear bumper tow cover	0.00	0.00	*19.00 F
13	1		*Rear bumper clips	0.00	0.00	*28.00 F

F=Franchise part.

Sub Total (S\$) 1,318.00
 + Margin on L,N Items 10.00% (S\$) 131.80
 Total Parts (S\$) 1,449.80

S & H Motor Pte Ltd/SJV5879P/18/12/2017 15:08. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Rear bumper sponge. - 670.00

8 2302.50

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Bumper parking sensors	260.00 <i>260.00</i>
Sub Total (S\$)			260.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To spray painting the rear accident and repair areas	New	800.00 <i>600.00</i>
2	Labour to remove , check for inner damaged, jack out rear body end panel, cut out end damaged panel, rewelding, renew, panel beating, install and adjust rear body, bumper alignment.	New	780.00 <i>480.00</i>
3	To remove and jack out rear exhaust box , repair and readjust exhaust alignment.	New	80.00 <i>60.00</i>
Gross Labour Cost (S\$)			1,660.00

S & H Motor Pte Ltd/SJV5879P/18/12/2017 15:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jan 2018)

Parts: M1-SUV HYUNDAI TUCSON 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/SJV5879P/18/01/2018 10:16

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper sponge	0.00	0.00	70.00F
Sub Total (\$\$)						70.00
+ Margin on L,N Items 10.00% (\$\$)						7.00
Total Parts (\$\$)						77.00

S & H Motor Pte Ltd/SJV5879P/18/01/2018 10:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 8398 3846 Fax: 8297 0863 (Accounts)

100% *in situ* detection of *Y. enterocolitica* in swine

— **1907** **1908** **1909** **1910** **1911** **1912** **1913** **1914** **1915** **1916** **1917** **1918** **1919** **1920** **1921** **1922** **1923** **1924** **1925** **1926** **1927** **1928** **1929** **1930** **1931** **1932** **1933** **1934** **1935** **1936** **1937** **1938** **1939** **1940** **1941** **1942** **1943** **1944** **1945** **1946** **1947** **1948** **1949** **1950** **1951** **1952** **1953** **1954** **1955** **1956** **1957** **1958** **1959** **1960** **1961** **1962** **1963** **1964** **1965** **1966** **1967** **1968** **1969** **1970** **1971** **1972** **1973** **1974** **1975** **1976** **1977** **1978** **1979** **1980** **1981** **1982** **1983** **1984** **1985** **1986** **1987** **1988** **1989** **1990** **1991** **1992** **1993** **1994** **1995** **1996** **1997** **1998** **1999** **2000** **2001** **2002** **2003** **2004** **2005** **2006** **2007** **2008** **2009** **2010** **2011** **2012** **2013** **2014** **2015** **2016** **2017** **2018** **2019** **2020** **2021** **2022** **2023** **2024** **2025** **2026** **2027** **2028** **2029** **2030** **2031** **2032** **2033** **2034** **2035** **2036** **2037** **2038** **2039** **2040** **2041** **2042** **2043** **2044** **2045** **2046** **2047** **2048** **2049** **2050** **2051** **2052** **2053** **2054** **2055** **2056** **2057** **2058** **2059** **2060** **2061** **2062** **2063** **2064** **2065** **2066** **2067** **2068** **2069** **2070** **2071** **2072** **2073** **2074** **2075** **2076** **2077** **2078** **2079** **2080** **2081** **2082** **2083** **2084** **2085** **2086** **2087** **2088** **2089** **2090** **2091** **2092** **2093** **2094** **2095** **2096** **2097** **2098** **2099** **2100** **2101** **2102** **2103** **2104** **2105** **2106** **2107** **2108** **2109** **2110** **2111** **2112** **2113** **2114** **2115** **2116** **2117** **2118** **2119** **2120** **2121** **2122** **2123** **2124** **2125** **2126** **2127** **2128** **2129** **2130** **2131** **2132** **2133** **2134** **2135** **2136** **2137** **2138** **2139** **2140** **2141** **2142** **2143** **2144** **2145** **2146** **2147** **2148** **2149** **2150** **2151** **2152** **2153** **2154** **2155** **2156** **2157** **2158** **2159** **2160** **2161** **2162** **2163** **2164** **2165** **2166** **2167** **2168** **2169** **2170** **2171** **2172** **2173** **2174** **2175** **2176** **2177** **2178** **2179** **2180** **2181** **2182** **2183** **2184** **2185** **2186** **2187** **2188** **2189** **2190** **2191** **2192** **2193** **2194** **2195** **2196** **2197** **2198** **2199** **2200** **2201** **2202** **2203** **2204** **2205** **2206** **2207** **2208** **2209** **2210** **2211** **2212** **2213** **2214** **2215** **2216** **2217** **2218** **2219** **2220** **2221** **2222** **2223** **2224** **2225** **2226** **2227** **2228** **2229** **2230** **2231** **2232** **2233** **2234** **2235** **2236** **2237** **2238** **2239** **2240** **2241** **2242** **2243** **2244** **2245** **2246** **2247** **2248** **2249** **2250** **2251** **2252** **2253** **2254** **2255** **2256** **2257** **2258** **2259** **2260** **2261** **2262** **2263** **2264** **2265** **2266** **2267** **2268** **2269** **2270** **2271** **2272** **2273** **2274** **2275** **2276** **2277** **2278** **2279** **2280** **2281** **2282** **2283** **2284** **2285** **2286** **2287** **2288** **2289** **2290** **2291** **2292** **2293** **2294** **2295** **2296** **2297** **2298** **2299** **2300** **2301** **2302** **2303** **2304** **2305** **2306** **2307** **2308** **2309** **2310** **2311** **2312** **2313** **2314** **2315**

INV NO : 8091550

DATE	28/12/2017	PAGE	1
FROM	30 Days Net	S.A-ESP/AM	Lau Gee Chai
CUSTOMER REF	SJV 4879P	C.R-EE	50649

DELIVER TO:

S & H MOTOR PTE LTD
160, SIN MING DRIVE, #07-02
SIN MING AUTO CITY,
SINGAPORE 575722



GST REG. NO.: M2-0090432-6 CO REG. NO.: 198905613E CO REG. NO.: 198905613E

ACCOUNT NUMBER: SHMOTOR1 TIME:17:08

S & H MOTOR P'K LTD.

T60 SIN MING DRIVE #07-02

STN MTNG APTG CITY

SIN MING AUTO CL
SINGAPORE 575722

575722

Telephone No. : 64534730

PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 HY86611-2S080	COVER-RR BUMPER (UPR)	4D-97E	1 PC	265.00	265.00
2 HY86630-2S010	RAIL ASSY-RR BUMPER	3P-02G	1 PC	155.00	155.00
3 HY92406-2S100	REFLECTOR,RR BFR RH	1L-10G	1 PC	68.00	68.00
4 HY86690-2S000	COVER-RR BUMPER LWR	4E-01F	1 PC	240.00	240.00
5 HY86620-2S010	RA BFR SPONGE	2D-2AA	1 PC	70.00	70.00
6 HY86517-2S000	CAP-RR HOOK	1K-05G	1 PC	19.00	19.00
7 HY86590-2S000	CLIP-BUMPER	1L-10C	10 PCS	2.80	28.00
8 HY86614-2S000	REBARACKET RR BUMPER STD	1K-06K	1 PC	30.00	30.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION


GOODS SOLD ARE NOT RETURNABLE.
OVERDUE ACCOUNTS SHALL
BEAR INTEREST AT LOB'S PREVAILING
FINANCING RATE.

CASH INVOICE MUST BE
PAID WITHIN 7 DAYS
SHOW DATE OF INVOICE

STUDY & PROGRAMS

12

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN CHEE AUTO PTE LTD.



EE: MIN CHEE AUTO PTE LTD.

Table 1. *Salmonella* serotypes and phage types isolated from broilers and turkeys

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024059/KVD3N2

Date: 14/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27912077DMA
Claimant Vehicle No :	SJV5879P	Insured Vehicle No :	SKC6833C
Date of Loss:	14/12/2017	Nature of Claim:	TP
		Claim No:	541282

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV5879P	Engine No:	G4KD9A288247
Make & Model:	HYUNDAI TUCSON, 2.0 (A)	Chassis No:	KMHJU81BMBU046862
Reg. Date:	01/02/2010 (Man. Year: 2010)	Odometer:	140686 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,526.80	962.50	564.30	36.96
Miscellaneous Items	260.00	200.00	60.00	23.08
Labour	1,660.00	1,140.00	520.00	31.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,446.80	2,302.50	1,144.30	33.20
+ GST 7.00/7.00% (S\$)	241.28	161.18	80.10	33.20
Nett Amount (S\$)	3,688.08	2,463.68	1,224.40	33.20

INSPECTION

Date of Assignment:	19/12/2017 Present Location:	S & H Motor Pte Ltd (Sin Ming)
Date Inspected:	20/12/2017 Inspected At:	S & H Motor Pte Ltd (Sin Ming)
		160 Sin Ming Drive #07-02, Sin Ming
		AutoCity
		Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2018)
Parts: M1-SUV	HYUNDAI TUCSON 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJV5879P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear Bumper (WCP)	Buckled	265.00 F	*265.00 F
2	1		*Rear bumper reinforcement (WCP)	Bent	155.00 F	*155.00 F
3	1		*RH bumper reflector (WCP)	Cracked	68.00 F	*68.00 F
4	1		*LH bumper reflector (WCP)	Serviceable	68.00 F	*- F
5	1		*Rear bumper bomttom black cover (WCP)	Bent	240.00 F	*240.00 F
6	1		*Rear RH bumper retainer (WCP)	Distorted	30.00 F	*30.00 F
7	1		*Rear LH bumper retainer (WCP)	Serviceable	30.00 F	*- F
8	1		*Rear body end panel (WCP)	Repair	295.00 F	*- F
9	1		*Tail door weather strip (WCP)	Serviceable	58.00 F	*- F
10	1		*Rear tailgate Hyundai badge (WCP)	Not Necessary	30.00 F	*- F
11	1		*Rear tailgate Tucson badge (WCP)	Not Necessary	32.00 F	*- F
12	1		*RH rear bumper tow cover (WCP)	Necessary	19.00 F	*19.00 F
13	1		*Rear bumper clips (WCP)	Necessary	28.00 F	*28.00 F
Supplementary #1						
14	1		*Rear bumper sponge (WCP)	Cracked	70.00 F	*70.00 F

F=Franchise part.

Sub Total (\$\$)	1,388.00	875.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	138.80	87.50
Total Parts (\$\$)	1,526.80	962.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Bumper parking sensors Cracked	260.00	200.00
Sub Total (S\$)			260.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To spray painting the rear accident and repair areas	New	800.00	600.00
2	Labour to remove , check for inner damaged, jack out rear body end panel, cut out end damaged panel, rewinding, renew, panel beating, install and adjust rear body, bumper alignment.	New	780.00	480.00
3	To remove and jack out rear exhaust box , repair and readjust exhaust alignment.	New	80.00	60.00
Gross Labour Cost (S\$)			1,660.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >