

ESTEEM PERFORMANCE PTE LTD

Date: 19/12/17

.0		
Repair Estimates	SLQ 4110 H	
Parts (a) Cost / List Price Items	\$ 6,485.20	
Plus/Less25%	\$ 1,621.30	
Total of Cost / List	\$ 4,863.90	1001 Northank
(b) Nett Price Items	\$ 359.00	Not Northenker Resorry B& pains
Less10%	\$ 35.90	1 Be pains
Total of Nett Item	\$ 323.10	LKK Auto Consultants hence notify
(c) Special Nett Items		• To resurvey before/after parawait
Total Parts Cost	\$ 5,187.00	Parts prices are subject to assist
Labour	\$ 3,310.00	No illegal modification(s) is allowed.
Total	\$ 8,497.00	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
The above total will be subjected to 7	% G.S.T.	Acknowledged by Repairer Signature: Date:
Name of Surveyor	Ken	nerh
Company	. (1	Clc
Survey conducted on	: 19/12	//
Remarks By Surveyor		
(a) The repair of this vehicle is a	uthorized / is not authorized until furthe	er notice.
(b) Recommended Days of Repa	air :05	day(s)
(c) Resurvey	: Required / Not Required	
(d) Excess	:\$_	

(e) Signature of surveyor



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569538.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg

Spare Parts

Vehicle No. Make & Model:

Chassis No

SLQ 4110 H TOYOTA ALTIS

MR053REH104559973

Submit By Year Manufacture Carmen Lim 2016

Engine No.

Cost	11	ist

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	CRACIA	2	\$359.00	N	
2	Rear bumper	Bu	1	\$496.30		
3	Rear bumper clip	M	10	\$40.00		
4	Rear bumper side retainer LH	Dij	1	\$104.40		
5	Rear bumper side retainer RH	0,1	1	\$104.40		
6	Rear bumper bracket LH	R	1	\$76.20		
7	Rear bumper bracket RH		1	\$76.20		7
8	Rear bumper reinforcement	B	1	\$386.60		
9	Bootlid	R	1	\$861.70		×
10	Bootlid lock	R	1	\$369.20		×
11	Bootlid emblem	na	1	\$51.40		
12	Wording "COROLLA"	M	1	\$47.80		
13	Wording "ALTIS"	M	1	\$49.60		
14	Bootlid chrome	Su	1	\$275.40		×
15	Bootlid lamp LH	Sm	1	\$281.60		~
16	Bootlid lamp RH	Pn	1	\$281.60		X
17	Tail end panel	By	1	\$679.20		
18	Tail end panel garnish	mg pi	1	\$227.80		
19	Tail end panel garnish clip	M	8	\$28.00		
20	Boot weatherstrip	Dillas	1	\$194.20		
21	Tail lamp LH		1	\$351.75		7
22	Tail lamp RH		1	\$351.75		7
23	Spare tyre well panel	R	1	\$780.90		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Spare Parts

Vehicle No. Make & Model:

SLQ 4110 H

TOYOTA ALTIS MR053REH104559973

Submit By Year Manufacture : Carmen Lim 2016

Engine No. Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Spare tyre board Cng	1	\$369.20		
25					
26					
27					
28					
29		-			
30					
31					-
32					
33			-		
34					
35					
36					
37					_
38				-	
39		-			
40		-		-	
41					
42		-		-	
43	·				
44		-			
45		-		-	
46	tu de de acte accommanded to be renaired, the			·	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, 1nd Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Websiter; www.esteemperf.com.sg

Labour

Vehicle No.	:	SLQ 4110 H	Submit By	:	Carmen Lim	
Make & Model	:	TOYOTA ALTIS	Year of Manufacture :		2016	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, BOOTLID, END PANEL,		
	SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,200.00	7001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, BOOTLID, END PANEL,		P
	SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,400.00	fou
3	To check wiring	\$50.00	201
4	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	601
5	To tuff coat.	\$150.00	301
6	To transfer boot mechanism to new boot	\$120.00	X
7	To conduct water leakage tests to ensure proper air and		
	sealing	\$120.00	201
8	To remove & refit reverse sensor	\$120.00	501

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.