

RVS Allied Global Pte Ltd
Office: 50 Tagore Lane 05-06 TG (S787494)
Workshop : 8 Woodlands Industrial Park E3 (S757786)
Reg :201703521G
Tel :9668 9668

Sebastian. 26/12/2017.
- Lump Sum Repair.
- Photo After Paint.
90036121
sebastian.yeang@lkkauto.com
8 days.

Our Ref: TP/CB77H/0027

18/12/17

Aik Shen Bus Service

QUOTATION

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Dear Sir,
Cost of Repair to Vehicle CB77H
With reference to the above-mentioned, we are pleased to quote as follows:-

DOA :14/12/2017

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front Windscreen ✓ CRK .	1	5,300.00	5,300.00
2.	Front Bumper ✓ CRK .	1	1,800.00	1,800.00
3.	Front Panel ✓ BT	1	2,400.00	2,400.00
4.	Side View Mirror (LH) ✓ DMG .	1	560.00	560.00
5.	Head Lamp (LH) ✓ CRK .	1	380.00	380.00
6.	Sealant ✓ NEC .	6	25.00	150.00
7.	Spray Painting on Rear Affected Area with Artwork	1	1,200.00	1,200.00
8.	Labour & Misc. Charges: To remove the affected parts & all relevant attachment & fittings to commence repairs; cut & weld the necessary parts as listed above; panel beat & reshapes the affected areas; replace the damaged components, reinstall & realign all necessary parts	1	2,200.00	2,200.00
SUB-TOTAL				S\$13,990.00

800 .

1500 .

Thanks you.
Yours faithfully,
STEVEN

Steven Tan
Claims Executive

Additional : Rain cutter \$200 ✓ Defome .
LH side Wiper Arm \$180 ✓ DMG .